

(1) For any main gear side brace stud found cracked, prior to further flight, replace the cracked stud with an FAA-approved serviceable part (part numbers referenced in the table in paragraph (b) of this AD or FAA-approved equivalent) in accordance with the instructions contained in the Landing Gear section of the applicable maintenance manual, and accomplish one of the following, as applicable:

(i) Reinspect and replace (as necessary) as specified in paragraph (b) of this AD; or

(ii) For the affected Models PA28R-180, PA28R-200, PA28R-201, PA28R-201T, PA32R-300, PA34-200, and PA34-200T airplanes, the P/N 95299-00 or 95299-02 main gear side brace studs are no longer manufactured. Install a new main gear side brace stud bracket assembly, P/N 95643-06,

P/N 95643-07, P/N 95643-08, or P/N 95643-09, as applicable. No repetitive inspections will be required by this AD for these affected airplane models when this bracket assembly is installed; or

(iii) For the affected Models PA28R-180, PA28R-200, PA28R-201, PA28R-201T, PA32R-300, PA34-200, and PA34-200T airplanes, ream the existing two-piece bushings, P/N 67026-6, to an inside diameter of .624-inch to .625-inch, rechamfer the bushings, and install the 5/8-inch stud, P/N 78717-02. No repetitive inspections will be required by this AD when this action is accomplished. If the bushings cannot be reamed while installed in the bracket (i.e., the brackets are loose), then install a main gear side brace bracket assembly, P/N 95643-06, P/N 95643-07, P/N 95643-08, or P/N

95643-09, as applicable. No repetitive inspections will be required by this AD when this bracket assembly is installed.

(2) For any main gear side brace stud not found cracked, prior to further flight, reinstall the uncracked stud in accordance with the instructions contained in the Landing Gear section of the applicable maintenance manual, and reinspect and replace (as necessary) as specified in paragraph (b) of this AD.

(b) Reinspect both the left and right main gear side brace studs, using Type I (fluorescent) liquid penetrant or magnetic particle inspection methods. Replace any cracked stud or reinstall any uncracked stud as specified in paragraphs (a)(1) and (a)(2) of this AD, respectively:

Part No. installed	TIS inspection interval (hours)	Model airplanes installed on
20829-00	1,000	PA24 and PA24-250.
22512-00	1,000	PA24-260, PA24-400, PA30, and PA39.
95299-00 or 95299-02.	500	PA28R-180, PA28R-200, PA28R-201, PA28R-201T, PA32R-300, PA34-200, and PA34-200T.

Note 5: Accomplishing the actions of this AD does not affect the requirements of AD 77-13-21, Amendment 39-3093. The tolerance inspection requirements of that AD still apply for Piper PA24, PA30, and PA39 series airplanes.

(c) Owners/operators of the affected Models PA28R-180, PA28R-200, PA28R-201, PA28R-201T, PA32R-300, PA34-200, and PA34-200T airplanes may accomplish one of the following at any time to terminate the repetitive inspection requirement of this AD:

(1) Install a main gear side brace bracket assembly, P/N 95643-06, P/N 95643-07, P/N 95643-08, or P/N 95643-09, as applicable, which contains the 5/8-inch diameter main gear side brace stud, P/N 78717-02, and the one-piece bushing, P/N 67026-12; or

(2) Ream the existing two-piece bushings, P/N 67026-6, to an inside diameter of .624-inch to .625-inch, rechamfer the bushings, and install the 5/8-inch stud, P/N 78717-02. If the bushings cannot be reamed while installed in the bracket (i.e., the brackets are loose), then install a main gear side brace bracket assembly, P/N 95643-06, P/N 95643-07, P/N 95643-08, or P/N 95643-09, as applicable.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) An alternative method of compliance or adjustment of the initial or repetitive compliance times that provides an equivalent level of safety may be approved by the Manager, Atlanta Aircraft Certification Office (ACO), Campus Building, 1701 Columbia Avenue, Suite 2-160, College Park, Georgia 30337-2748. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 6: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(f) Alternative methods of compliance approved in accordance with AD 95-20-07, Amendment 39-9386, are considered approved as alternative methods of compliance with this AD.

(g) Information related to this AD may be inspected at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri.

(h) This amendment supersedes AD 95-20-07, Amendment 39-9386.

Appendix to Docket No. 96-CE-09-AD—Information To Determine Main Gear Side Brace Stud Assembly Part Number (P/N)

—The P/N 95643-00/-01/-02/-03 bracket assembly contains the 9/16-inch diameter main gear side brace stud, P/N 95299-00/-02, and a two-piece bushing, P/N 67026-6.

—The P/N 95643-06/-07/-08/-09 bracket assembly contains the 5/8-inch diameter main gear side brace stud, P/N 78717-02, and a one-piece bushing, P/N 67026-12.

—Both the one-piece and the two-piece bushing have a visible portion of the bushing flange, i.e., bushing shoulder.

—Whether a one-piece or two-piece bushing is installed may be determined by measuring the outside diameter of the bushing flange with a micrometer (jaws of the caliper must be 3/32-inch or less). The two-piece bushing will have an outside diameter of 1.00 inch and the one-piece bushing will have an outside diameter of 1.128 to 1.130 inches.

—The one-piece bushing contains a visible chamfer in the center of the bushing, and the chamfer in the two-piece bushing is not visible when the stud is installed.

—If P/N 95643-00/-01/-02/-03 bracket assembly is installed or the above

information cannot be utilized, the main gear side brace stud will need to be removed from the bracket to determine the shank diameter and main gear side brace stud P/N.

—P/N 95299-00 and P/N 95299-02 main gear side brace studs are 9/16-inch in diameter.

—P/N 95643-00/-01/-02/-03 bracket assembly may have been modified to accommodate the 5/8-inch diameter main gear side brace stud, P/N 78717-02.

Issued in Kansas City, Missouri, on April 19, 1996.

Henry A. Armstrong,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-10167 Filed 4-24-96; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 95-NM-115-AD]

Airworthiness Directives; McDonnell Douglas Model DC-8 Series Airplanes Equipped With Swivel-Type Bogie Beams on the Main Landing Gears

AGENCY: Federal Aviation Administration, DOT.

ACTION: Supplemental notice of proposed rulemaking; reopening of comment period.

SUMMARY: This document revises an earlier proposed airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-8 series airplanes, that would have required an inspection to detect cracking of the swivel bogie beam lugs, and repair, if necessary. For airplanes on which no cracking is

found, that proposed AD also would have required an inspection to detect corrosion of the swivel pin lug surfaces and bores, and modification of the forward bogie beams. That proposal was prompted by reports indicating that swivel pin lugs of the main landing gear (MLG) have failed due to cracks resulting from stress corrosion. The actions specified by this proposed AD are intended to prevent such stress corrosion, which could result in failure of the swivel-type bogie beam of the MLG; this condition could result in collapse of the MLG during landing. This action revises the proposed rule by adding certain repair requirements.

DATES: Comments must be received by May 16, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-115-AD, 1601 Lind Avenue SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from McDonnell Douglas Corporation, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Department C1-L51 (2-60). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT: Mike Lee, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5325; fax (310) 627-5210.

SUPPLEMENTARY INFORMATION:
Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained

in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-115-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-115-AD, 1601 Lind Avenue SW., Renton, Washington 98055-4056.

Discussion

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add an airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-8 series airplanes, was published as a notice of proposed rulemaking (NPRM) in the Federal Register on November 1, 1995 (60 FR 55496). That NPRM would have required a magnetic particle inspection to detect cracking of the swivel bogie beam lugs, and repair, if necessary. For airplanes on which no cracking is found, that NPRM also would have required an inspection to detect corrosion of the swivel pin lug surfaces and bores, and modification of the forward bogie beams. That NPRM was prompted by reports indicating that swivel pin lugs of the main landing gear (MLG) have failed due to cracks resulting from stress corrosion. That condition, if not corrected, could result in failure of the swivel-type bogie beam of the MLG, which could result in collapse of the MLG during landing.

Since the issuance of that NPRM, the manufacturer has advised the FAA that the dimensions of the reworked swivel pin lugs of Group I airplanes may exceed the limits specified in the service information cited. The NPRM addressed this condition for Group II airplanes, and included a requirement for the repair of Group II airplanes on which the dimensions of the reworked

swivel pin lugs exceed the limits specified in the proposed rule.

However, the NPRM did not contain a similar repair requirement for Group I airplanes. The FAA has determined that such an "on condition" repair requirement is also necessary for Group I airplanes, and has added this requirement to paragraphs (b)(2)(i) and (b)(2)(ii) of this supplemental NPRM.

Since this change expands the scope of the originally proposed rule, the FAA has determined that it is necessary to reopen the comment period to provide additional opportunity for public comment.

The FAA also has revised paragraph (a) of this proposed rule to clarify that the magnetic particle inspection is a "one-time" requirement.

There are approximately 148 McDonnell Douglas Model DC-8 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 97 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 83 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$483,060, or \$4,980 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the

location provided under the caption
ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 95–NM–115–AD.

Applicability: Model DC–8 airplanes equipped with main landing gears having swivel type bogie beams on which the swivel pin lugs have not been nickel plated, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the swivel-type bogie beam of the main landing gear (MLG) due to stress corrosion, which could result in collapse of the MLG during landing, accomplish the following:

(a) Perform a one-time magnetic particle inspection to detect cracking of the swivel bogie beam lugs, in accordance with McDonnell Douglas DC–8 Service Bulletin 32–182, dated January 20, 1995; McDonnell Douglas Service Bulletin DC8–32–182, Revision 01, dated July 21, 1995, or Revision 02, dated August 30, 1995; at the later of the times specified in paragraphs (a)(1) and (a)(2) of this AD.

(1) Prior to the accumulation of 11,600 total flight hours, or within 10 years since the installation of the forward bogie beam of the MLG, whichever occurs first.

(2) Prior to the accumulation of 2,000 flight hours, or 2 years after the effective date of this AD, whichever occurs first.

(b) If no cracking is detected during the inspection required by paragraph (a) of this AD, prior to further flight, perform a visual inspection to detect corrosion in the swivel pin lug surfaces and bores, in accordance with McDonnell Douglas DC–8 Service Bulletin 32–182, dated January 20, 1995; or McDonnell Douglas Service Bulletin DC8–32–182, Revision 01, dated July 21, 1995, or Revision 02, dated August 30, 1995.

Note 2: Particular attention should be paid to the lubrication of the swivel pin lug and the lower swivel pin bushing during regular normal maintenance.

(1) If no corrosion is detected, prior to further flight, accomplish paragraph (b)(1)(i), (b)(1)(ii), (b)(1)(iii), or (b)(1)(iv) of this AD, as applicable, in accordance with the service bulletin.

(i) For Group I airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin.

(ii) For Group I airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin.

(iii) For Group II airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin.

(iv) For Group II airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin.

(2) If any corrosion is detected, prior to further flight, accomplish paragraph (b)(2)(i), (b)(2)(ii), (b)(2)(iii), or (b)(2)(iv), as applicable, in accordance with the service bulletin.

(i) For Group I airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin. If the dimensions of the reworked swivel pin lug exceed the limits specified in Table I of the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate.

(ii) For Group I airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group I airplanes) as Condition 2 of the Accomplishment Instructions of the service

bulletin. If the dimensions of the reworked swivel pin lug exceed the limits specified in Table I of the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(iii) For Group II airplanes on which the forward bogie beam has not been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 1 of the Accomplishment Instructions of the service bulletin. If the dimensions of the reworked swivel pin lug exceed the limits specified in Table I of the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(iv) For Group II airplanes on which the forward bogie beam has been modified previously: Modify the forward bogie beam in accordance with the actions specified (for Group II airplanes) as Condition 2 of the Accomplishment Instructions of the service bulletin. If the dimensions of the reworked swivel pin lug exceed the limits specified in Table I of the service bulletin, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(c) If any cracking is detected during the inspection required by paragraph (a) of this AD, prior to further flight, repair in accordance with a method approved by the Manager, Los Angeles ACO.

(d) As of the effective date of this AD, no forward bogie beam swivel pin lug shall be installed on any airplane, unless that swivel pin lug has been modified in accordance with McDonnell Douglas DC–8 Service Bulletin 32–182, dated January 20, 1995; or McDonnell Douglas Service Bulletin DC8–32–182, Revision 01, dated July 21, 1995, or Revision 02, dated August 30, 1995.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 19, 1996.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96–10208 Filed 4–24–96; 8:45 am]

BILLING CODE 4910–13–U