

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 96-NM-246-AD; Amendment 39-9778; AD 96-21-02]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) series airplanes. This action requires revising the Airplane Flight Manual (AFM) to require the flight crew to check, and reset, if necessary, certain instrument settings prior to each takeoff and after any event during which generators are switched. This amendment is prompted by reports indicating that the co-pilot's air data reference system has intermittently failed following the switching of power between generators. The actions specified in this AD are intended to prevent uncommanded changes in certain instrument settings on the co-pilot's display, which, if not corrected, can result in confusion among the flight crew about the correct position and flight configuration of the airplane.

DATES: Effective October 15, 1996.

Comments for inclusion in the Rules Docket must be received on or before December 9, 1996.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 96-NM-246-AD, 1601 Lind Avenue, SW., Renton, 98055-4056.

The information concerning this AD may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, Engine & Propeller Directorate, 10 Fifth Street, Third Floor, Valley Stream, New York.

FOR FURTHER INFORMATION CONTACT: Peter Cuneo, Aerospace Engineer, FAA, New York Aircraft Certification Office, ANE-172, Engine and Propeller Directorate, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7506; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION: Transport Canada Aviation, which is the airworthiness authority for Canada, recently notified the FAA that an unsafe condition may exist on certain Bombardier Model CL-600-2B19 (Regional Jet Series 100) series airplanes. Transport Canada Aviation advises that it has received reports indicating that there has been intermittent failure of the co-pilot's air data reference system on some of these airplanes. This failure has occurred after the transfer of power between generators, and has resulted in uncommanded changes in the settings of the barometric altimeter, altitude pre-selector, V-speed, and speed bug on the co-pilot's instrument display. This condition, if not corrected, could result in confusion among the flight crew about the correct position and flight configuration of the airplane.

Actions by Transport Canada Aviation

Transport Canada Aviation issued Canadian airworthiness directive CF-96-16, dated September 23, 1996, in order to assure the continued airworthiness of these airplanes in Canada. That directive advises the flight crew to "check and reset, as required, the barometric altimeter setting, altitude pre-selector, V-speed, and speed bug settings before takeoff and after any generator switching events."

FAA's Conclusions

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, Transport Canada Aviation has kept the FAA informed of the situation described above. The FAA has examined the findings of Transport Canada Aviation, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to prevent uncommanded changes in the settings of the barometric altimeter, altitude pre-selector, V-speed, and speed bug on the co-pilot's instrument display. This AD requires revising the Limitations Section of the FAA-approved Airplane Flight Manual

(AFM) to require the flight crew to check the settings of these instruments, and reset these settings, as necessary, prior to each takeoff and after any event during which generators are switched.

Interim Action

This action is considered to be interim action until final action is identified. At that time, the FAA may consider further rulemaking.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 96-NM-246-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

96-21-02 Bombardier, Inc. (Formerly Canadair): Amendment 39-9778. Docket 96-NM-246-AD.

Applicability: Model CL-600-2B19 (Regional Jet Series 100) series airplanes; having serial numbers 7003 and subsequent; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or

repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent uncommanded changes in the settings of the barometric altimeter, altitude pre-selector, V-speed, and speed bug on the co-pilot's instrument display, which could result in confusion among the flight crew about the correct position and flight configuration of the airplane, accomplish the following:

(a) Within 3 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following statement. This may be accomplished by inserting a copy of this AD in the AFM.

"Prior to each takeoff and after any event during which generators are switched, check the settings of the barometric altimeter, altitude pre-selector, V-speed, and speed bug. If any discrepancy is detected, reset, as necessary."

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on October 15, 1996.

Issued in Renton, Washington, on October 1, 1996.

Darrell M. Pederson,
Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 96-25671 Filed 10-7-96; 8:45 am]
BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 96-AWP-18]

Amendment of Class D Airspace; Hayward, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the Class D airspace area at Hayward, CA. The development of a Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 28L has made this action necessary. The intended effect of this action is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Hayward Air Terminal, Hayward, CA.

EFFECTIVE DATE: 0901 UTC December 5, 1996.

FOR FURTHER INFORMATION CONTACT: William Buck, Airspace Specialist, Operations Branch, AWP-530, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation Boulevard, Lawndale, California 90261, telephone (310) 725-6556.

SUPPLEMENTARY INFORMATION:

History

On July 29, 1996, the FAA proposed to amend part 71 of the Federal Aviation Regulations (14 CFR part 71) by amending the Class D airspace area at Hayward, CA (61 FR 39367). This action will provide adequate controlled airspace to accommodate a GPS SIAP to RWY 28L at Hayward Air Terminal, Hayward, CA.

Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments to the proposal were received. Class D airspace designations are published in paragraph 5000 of FAA Order 7400.9D dated September 4, 1996, and effective September 16, 1996, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designations listed in this document will be published subsequently in this Order.

The Rule

The amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) amends the Class D airspace area at Hayward, CA. The development of a GPS SIAP to RWY 28L has made this action necessary. The effect of this action will provide adequate airspace for aircraft executing the GPS RWY 28L SIAP at Hayward Air Terminal, Hayward, CA.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44