

feather the propeller, and consequent reduced controllability of the airplane; accomplish the following:

(a) Within 90 days after the effective date of this AD, replace electrical relays 15KF and 16KF having part number (P/N) DON405M520U5NL with relays having P/N 2504MY1, in accordance with Dornier Service Bulletin SB-328-61-138, dated November 13, 1995.

(b) As of the effective date of this AD, no person shall install relays 15KF and 16KF having P/N DON405M520U5NL on any airplane.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in German airworthiness directive 96-002, dated January 8, 1996.

Issued in Renton, Washington, on December 5, 1997.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 97-32425 Filed 12-10-97; 8:45 am]
BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97-NM-190-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Mystere-Falcon 50 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Dassault Model Mystere-Falcon 50 series airplanes. This proposal would require a one-time inspection of the clearances around the wiring harnesses

of the right-hand electrical cabinet, and readjustment of the clearances, if necessary. This proposal would also require installation of protective strips on the wiring harnesses and equipment supports. This proposal is prompted by issuance of mandatory continued airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent interference between the wiring harnesses and adjacent equipment, support brackets, and structural elements, which could cause an electrical short circuit resulting in fire, and consequent loss of electrical power to essential flight systems.

DATES: Comments must be received by January 12, 1998.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-190-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, New Jersey 07606. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments,

in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 97-NM-190-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-190-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on all Dassault Model Mystere-Falcon 50 series airplanes. The DGAC advises that it received a report of an in-flight incident, in which interference between a wiring harness cable and an equipment support bracket resulted in an electrical short. This condition, if not corrected, could result in fire and loss of electrical power to essential flight systems.

Explanation of Relevant Service Information

Dassault has issued Service Bulletin F50-256 (F50-20-5), Revision 1, dated December 22, 1996, which describes procedures for a one-time inspection (measurement) of the clearances between the wiring harnesses and the equipment, support brackets, and structural elements between fuselage frames 9 and 11, on the right-hand electrical cabinet; and adjustment of these clearances, if necessary. Additionally, the service bulletin describes procedures for installation of Teflon protective strips on the wiring harnesses and rubber protective strips on the rear edges of the equipment supports. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 96-094-017(B)R1, dated December 18, 1996, in order to assure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously.

Cost Impact

The FAA estimates that 155 Dassault Model Mystere-Falcon 50 series airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 6 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$355 per airplane. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$110,825, or \$715 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT

Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Dassault Aviation: Docket 97–NM–190–AD.

Applicability: All Model Mystere-Falcon 50 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent interference between the wiring harnesses and adjacent equipment, support brackets, and structural elements, which could cause an electrical short circuit resulting in fire, and consequent loss of electrical power to essential flight systems; accomplish the following:

(a) Within 6 months or 300 flight hours after the effective date of this AD, whichever occurs first, accomplish the requirements of paragraphs (a)(1), (a)(2), and (a)(3) of this AD in accordance with Dassault Service Bulletin

F50–256 (F50–20–5), Revision 1, dated December 22, 1996.

(1) Perform a one-time inspection of the clearances between the wiring harnesses and the adjacent equipment, support brackets, and structural elements. If any clearance is outside the limits specified in the service bulletin, prior to further flight, readjust the clearances in accordance with the service bulletin.

(2) Install Teflon protective strips on the wiring harnesses in the vicinity of the equipment supports.

(3) Install rubber protective strips to the rear edges of the equipment supports.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM–116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM–116.

(c) Special flight permits may be issued in accordance with § 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directive 96–094–017(B)R1, dated December 18, 1996.

Issued in Renton, Washington, on December 5, 1997.

John J. Hickey,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 97–32423 Filed 12–10–97; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 97–NM–145–AD]

RIN 2120–AA64

Airworthiness Directives; Saab Model SAAB 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB 2000 series airplanes. This proposal would require repetitive visual inspections to detect discrepancies of the bushing installation