

Dated: December 15, 1998.

**Scott E. Thomas,**

*Acting Chairman, Federal Election Commission.*

[FR Doc. 98-33548 Filed 12-17-98; 8:45 am]

BILLING CODE 6715-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 98-NM-301-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A300-600 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A300-600 series airplanes. This proposal would require removal of the fuel level sensing amplifier (FLSA) of the trim tank system, modification of the polarization pin code in the electronics bay, and installation of a new, improved FLSA. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent continuous aft transfer of fuel due to the FLSA not supplying electrical power to the trim tank overflow sensor, which could result in potential loss of fuel during flight.

**DATES:** Comments must be received by January 19, 1999.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-301-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Norman B. Martenson, Manager,

International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-301-AD." The postcard will be date stamped and returned to the commenter.

##### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-301-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

##### Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Airbus Model A300-600 series airplanes. The DGAC advises that, on airplanes equipped with a trim tank system and with a certain fuel level sensing amplifier (FLSA), electrical power is not being supplied to the trim tank overflow sensor during flight. This condition is caused by the existing design of the FLSA, and could result in fuel loss from the trim tank during flight. Such fuel

loss could occur if all of the following conditions are present:

- Failure of the high-level sensor or associated circuits of the trim tank while the trim tank is empty; and
- Balance of the airplane such that the center of gravity with no fuel on board is 24 percent mean aerodynamic chord of the wing or further forward of that location; and
- Fuel weight of the airplane before departure is greater than 20,000 kilograms (44,000 pounds), which is the minimum amount of fuel required to fill the trim tank.
- Lack of electrical power to the trim tank overflow sensor, if not corrected, could result in continuous aft transfer of fuel, and potential loss of fuel during flight.

##### Explanation of Relevant Service Information

The manufacturer has issued Airbus Service Bulletin A300-28-6055, Revision 01, dated July 24, 1998, which describes procedures for removal of the FLSA of the trim tank system, modification of the polarization pin code in the electronics bay, and installation of a new, improved FLSA. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 98-249-252(B), dated July 1, 1998, in order to assure the continued airworthiness of these airplanes in France.

##### FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

##### Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified

in the service bulletin described previously.

### Cost Impact

The FAA estimates that 61 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 3 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would be supplied by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the actions proposed by this AD on U.S. operators is estimated to be \$10,980, or \$180 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

### Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Airbus Industrie:** Docket 98-NM-301-AD.

**Applicability:** Model A300-600 series airplanes on which Airbus Modification 4801 was accomplished during production and on which Airbus Modification 10778 (reference Airbus Service Bulletin A300-31-6051, dated June 28, 1996) has been accomplished; except those airplanes on which Airbus Modification 11683 (reference Airbus Service Bulletin A300-28-6055, dated January 28, 1997, and Revision 01, dated July 24, 1998) has been accomplished; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent continuous aft transfer of fuel due to the fuel level sensing amplifier (FLSA) not supplying electrical power to the trim tank overflow sensor, which could result in potential loss of fuel during flight, accomplish the following:

(a) Except as provided by paragraph (b) of this AD, within 2 months after the effective date of this AD, remove the FLSA of the trim tank system, modify the polarization pin code in the electronics bay, and install a new, improved FLSA, in accordance with Airbus Service Bulletin A300-28-6055, Revision 01, dated July 24, 1998.

**Note 2:** Accomplishment of the actions specified in paragraph (a) of this AD, prior to the effective date of this AD, in accordance with Airbus Service Bulletin A300-28-6055 dated January 28, 1997, is considered acceptable for compliance with the applicable actions specified in this AD.

(b) For airplanes on which Airbus Service Bulletin A300-31-6051, dated June 28, 1996, is accomplished after the effective date of this AD: Concurrent with the accomplishment of Airbus Service Bulletin A300-31-6051, accomplish the actions required by paragraph (a) of this AD, in accordance with Airbus Service Bulletin A300-28-6055, Revision 01, dated July 24, 1998.

(c) As of the effective date of this AD, no person shall install a FLSA having part number 722-295-2, on any airplane.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 4:** The subject of this AD is addressed in French airworthiness directive 98-249-252(B), dated July 1, 1998.

Issued in Renton, Washington, on December 14, 1998.

**Darrell M. Pederson,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 98-33539 Filed 12-17-98; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 39

[Docket No. 97-NM-244-AD]

RIN 2120-AA64

### Airworthiness Directives; McDonnell Douglas Model DC-9 Series Airplanes, and Model MD-88 and MD-90-30 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Supplemental notice of proposed rulemaking.

**SUMMARY:** This document revises an earlier proposed airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-9-80 series airplanes, and Model MD-88 and MD-90-30 airplanes, that would have required replacement of the lanyard assembly pins of the evacuation slides with solid stainless steel pins. That proposal was prompted by a report that, due to stress corrosion on the lanyard pins, the arms of the lanyard assembly of the evacuation slide were found to be frozen. This new action revises the proposed rule by expanding the applicability of the proposed rule to