

subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent an internal electrical short in the engine ignition switch, which could result in smoke in the flight compartment, accomplish the following:

#### Inspection and Corrective Action

(a) Within 8 months after the effective date of this AD, visually inspect the engine ignition switch to determine what type of switch (rotary or toggle) is installed in the hinged forward overhead switch panel, in accordance with McDonnell Douglas Service Bulletin DC9-74-001, dated May 23, 1997, or McDonnell Douglas Alert Service Bulletin DC9-74A001, Revision 01, dated October 26, 1998.

(1) If the switch is a toggle type, no further action is required by this AD.

(2) If the switch is a rotary type, prior to further flight, determine the switch part number in accordance with the service bulletin.

(i) If the switch has part number 79-2318 (5D0423-2) or 79-2355, no further action is required by this AD.

(ii) If the switch has any part number other than that identified in paragraph (a)(2)(i) of this AD, prior to further flight, replace the engine ignition switch with a new design ignition switch in accordance with the service bulletin.

#### Spares Affected

(b) As of the effective date of this AD, no person shall install a five position rotary ignition type switch, part number 79-2055 (5D0423-1), 69-1967, 53306-033, or 3600-3076, on any airplane.

#### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

#### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 6, 1999.

**D.L. Riggins,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-17863 Filed 7-13-99; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 99-NM-34-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100) Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Bombardier Model CL-600-2B19 (Regional Jet Series 100) series airplanes. This proposal would require revising the Airplane Flight Manual to provide the flightcrew with modified procedures and limitations for operating in icing conditions. This proposal is prompted by an accident report indicating that possible accretion of ice on the wings of the airplane, due to the wing anti-ice system not being activated by the flightcrew, could have contributed to the source of the accident. The actions specified by the proposed AD are intended to prevent undetected accretion of ice on the wings, which could result in reduced controllability of the airplane during normal icing conditions.

**DATES:** Comments must be received by August 13, 1999.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-34-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station A, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane

Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

#### FOR FURTHER INFORMATION CONTACT:

Rodrigo J. Huete, Test Pilot, Systems and Flight Test Branch, ANE-172, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7518; fax (516) 568-2716.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-34-AD." The postcard will be date stamped and returned to the commenter.

#### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-34-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### Discussion

On December 6, 1997, an accident occurred on a Model CL-600-2B19 (Regional Jet Series 100) series airplane. The Canadian Transportation Safety Board (CTSB) report indicated that possible accretion of ice on the wings due to the wing anti-ice system not

being activated by the flightcrew could have contributed to the source of the accident. Investigation revealed that the procedure in the Canadair Regional Jet Airplane Flight Manual (AFM) that was in effect at the time of the accident specified that the wing anti-ice system be activated when ice was detected by the ice detection system. Upon further analysis and validation, it was determined that "icing conditions" (defined in the AFM) should be used as the primary means for the flightcrew to determine when to activate the wing anti-ice system below 22,000 feet mean sea level (MSL), and that ice detectors should be used only as a backup. Undetected accretion of ice on the wings could result in reduced controllability of the airplane during normal icing conditions.

#### Explanation of Service Information

Canadair Regional Jet Temporary Revision (TR) RJ/61-2, dated October 30, 1998, was issued in order to assure the continued airworthiness of these airplanes in Canada. That TR describes procedures for amending the Limitations, Normal Procedures, and Emergency Procedures sections of the AFM to provide the flightcrew with modified procedures and limitations for operating in icing conditions.

#### U.S. Type Certification of the Airplane

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement.

#### Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this proposed AD would require revising the Limitations, Normal, and Emergency Procedures sections of the FAA-approved AFM to provide the flightcrew with modified procedures and limitations for operating in icing conditions. The actions would be required to be accomplished in accordance with the service information described previously.

#### Cost Impact

The FAA estimates that 133 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed AFM revision, and that the average labor rate is \$60 per work hour. Based on these

figures, the cost impact of the AFM revision proposed by this AD on U.S. operators is estimated to be \$7,980, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

#### Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Bombardier, Inc.** (Formerly Canadair):  
Docket 99-NM-34-AD.

**Applicability:** All Model CL-600-2B19 (Regional Jet Series 100) series airplanes, certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent undetected accretion of ice on the wings, which could result in reduced controllability of the airplane during normal icing conditions, accomplish the following:

#### AFM Revision

(a) Within 10 days after the effective date of this AD: Revise the FAA-approved Canadair Regional Jet Airplane Flight Manual (AFM) by inserting a copy of the pages specified in paragraphs (a)(1), (a)(2), and (a)(3) of this AD into the AFM.

(1) Revise the Limitations Section to include pages 2 and 3 of Canadair Regional Jet Temporary Revision (TR) RJ/61-2, dated October 30, 1998.

(2) Revise the Emergency Procedures Section to include pages 4 through 6 inclusive of Canadair Regional Jet TR RJ/61-2, dated October 30, 1998.

(3) Revise the Normal Procedures Section to include pages 7 through 27 inclusive of Canadair Regional Jet TR RJ/61-2, dated October 30, 1998.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, New York ACO.

**Note 1:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

#### Special Flight Permits

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 7, 1999.

**Vi L. Lipski,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-17862 Filed 7-13-99; 8:45 am]

BILLING CODE 4910-13-U