

overlap or conflict with this proposed rule. However, red seedless grapefruit must meet the requirements as specified in the U.S. Standards for Grades of Florida Grapefruit (7 CFR 51.760 through 51.784) issued under the Agricultural Marketing Act of 1946 (7 U.S.C. 1621 through 1627).

The committee's meeting was widely publicized throughout the citrus industry and all interested persons were invited to attend the meeting and participate in committee deliberations on all issues. Like all committee meetings, the April 6, 1999, meeting was a public meeting and all entities, both large and small, were able to express views on this issue. Interested persons are invited to submit information on the regulatory and informational impacts of this action on small businesses.

A 15-day comment period is provided to allow interested persons to respond to this proposal. Fifteen days is deemed appropriate because this rule would need to be in place as soon as possible since handlers will begin shipping grapefruit in September. In addition, because of the nature of this rule, handlers need time to consider their allotment and how best to service their customers. Also, the industry has been discussing this issue for some time, and the committee has kept the industry well informed. It has also been widely discussed at various industry and association meetings. Interested persons have had time to determine and express their positions. This action is similar to those taken in the previous two seasons, and it was unanimously recommended by the committee. All written comments timely received will be considered before a final determination is made on this matter.

List of Subjects in 7 CFR Part 905

Grapefruit, Marketing agreements, Oranges, Reporting and recordkeeping requirements, Tangelos, Tangerines.

For the reasons set forth in the preamble, 7 CFR part 905 is proposed to be amended as follows:

PART 905—ORANGES, GRAPEFRUIT, TANGERINES, AND TANGELOS GROWN IN FLORIDA

1. The authority citation for 7 CFR part 905 continues to read as follows:

Authority: 7 U.S.C. 601–674.

2. Section 905.350 is revised to read as follows:

§ 905.350 Red seedless grapefruit regulation.

This section establishes the weekly percentages to be used to calculate each

handler's weekly allotment of small sizes. If the minimum size in effect under § 905.306 for red seedless grapefruit is size 56, handlers can fill their allotment with size 56, size 48, or a combination of the two sizes such that the total of these shipments are within the established weekly limits. If the minimum size in effect under § 905.306 for red seedless grapefruit is 48, handlers can fill their allotment with size 48 red seedless grapefruit such that the total of these shipments is within the established weekly limits. The weekly percentages for sizes 48 and/or 56 red seedless grapefruit grown in Florida, which may be handled during the specified weeks are as follows:

Week	Weekly percentage
(a) 9/20/99 through 9/26/99	25
(b) 9/27/99 through 10/3/99	25
(c) 10/4/99 through 10/10/99	25
(d) 10/11/99 through 10/17/99	25
(e) 10/18/99 through 10/24/99	25
(f) 10/25/99 through 10/31/99	25
(g) 11/1/99 through 11/7/99	25
(h) 11/8/99 through 11/14/99	25
(i) 11/15/99 through 11/21/99	25
(j) 11/22/99 through 11/28/99	25
(k) 11/29/99 through 12/5/99	25

Dated: August 23, 1999.

Bernadine M. Baker,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 99–22253 Filed 8–25–99; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99–NE–30–AD]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce Limited Dart Series Turboprop Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Rolls-Royce Limited Dart series turboprop engines. This proposal would require a one-time visual inspection of the interior of the switch to determine the type of low torque switch, and removal from service of unapproved Klixon low torque switches and replacement with serviceable parts. This

proposal is prompted by the discovery of unapproved low torque switches in fleet operation. The actions specified by the proposed AD are intended to prevent possible low torque switch failure, which could result in failure of a propeller to auto-feather following an engine power loss, resulting in possible loss of control of the airplane due to high asymmetric drag.

DATES: Comments must be received by September 27, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 99–NE–30–AD, 12 New England Executive Park, Burlington, MA 01803–5299. Comments may also be submitted to the Rules Docket by using the following Internet address: “9-ane-adcomment@faa.gov”.

Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Rolls-Royce Limited, Attn: Dart Engine Service Manager, East Kilbride, Glasgow G74 4PY, Scotland; telephone: +44 1355–220–200, fax: +44 1141–778–432.

This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: James Lawrence, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803–5299; telephone (781) 238–7176, fax (781) 238–7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by

interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NE-30-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-NE-30-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom (UK), recently notified the Federal Aviation Administration (FAA) that an unsafe condition may exist on Rolls-Royce Limited (R-R) Dart 506, 510, 511, 514, 525, 526, 529, 530, 531, 532, 535, 542, and 552 series turboprop engines. The CAA advises that in 1976, failure of a low torque switch resulted in a fatal military airplane accident. The investigation revealed problems with the low torque switch that were resolved in a subsequent airworthiness action.

Recently, however, the CAA has determined that a number of unapproved, Klixon low torque switches, part number (P/N) 6PS-25-1, are in service. These low torque switches have not been tested by R-R and are not approved for use by R-R or the CAA on R-R Dart series turboprop engines, and are of a different design than the approved, capsule and snap diaphragm assembly low torque switches. All low torque switches sense reduction gearbox torque pressure, which is related to engine power output, and is set to trigger at a predetermined pressure. While there have been no failures to date of the unapproved Klixon low torque switches, the CAA and R-R cannot determine whether the switch will function properly. The low torque switch remains dormant until an emergency situation, and there are no functional preflight checks of the low torque switch system to ensure safe operation. This condition, if not corrected, could result in failure of a propeller to auto-feather following an engine power loss, resulting in possible

loss of control of the airplane due to high asymmetric drag.

Service Information

R-R has issued Service Bulletin (SB) No. Da61-13, dated December 1996, that specifies procedures for performing a visual inspection of the interior of the switch to determine the type of low torque switch, and removal from service of unapproved Klixon low torque switches and replacement with serviceable parts. Externally, the Klixon low torque switches are indistinguishable from the approved low torque switches. The CAA classified this SB as mandatory and issued AD 002-12-96 in order to assure the airworthiness of these engines in the UK.

This engine model is manufactured in the UK and is type certificated for operation in the United States under the provisions of Section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other engines of the same type design registered in the United States, the proposed AD would require a one-time visual inspection of the interior of the switch to determine the type of low torque switch, and removal from service of unapproved Klixon low torque switches and replacement with approved low torque switches. This action would be required within 3 months after the effective date of this AD. The actions would be required to be accomplished in accordance with the SB described previously.

Economic Analysis

There are approximately 890 engines of the affected design in the worldwide fleet. The FAA estimates that 139 engines installed on aircraft of US registry would be affected by this proposed AD, that it would take approximately 2 work hours per engine to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$12,500 per engine. Based on these figures, the total cost

impact of the proposed AD on US operators is estimated to be \$1,754,180.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Rolls-Royce Limited: Docket No. 99-NE-30-AD.

Applicability: Rolls-Royce Limited (R-R) Dart 506, 510, 511, 514, 525, 526, 529, 530, 531, 532, 535, 542, and 552 series turboprop engines, installed on but not limited to Gulfstream Aerospace Corp. G-159, British Aerospace HS 748, Fokker Aircraft F.27, Mitsubishi Heavy Industries YS-11, General Dynamics (Convair) 640 and 600 series, and Vickers Armstrongs (Aircraft Limited) Viscount.

Note 1: This airworthiness directive (AD) applies to each engine identified in the

preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For engines that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of a propeller to auto-feather following an engine power loss, resulting in possible loss of control of the airplane due to high asymmetric drag, accomplish the following:

(a) Within 3 months after the effective date of this AD, accomplish the following in accordance with the Action section of R-R Service Bulletin (SB) No. Da61-13, dated December 1996:

(1) Remove the switch cover, visually inspect the interior of the switch and replace the switch cover, all in accordance with the accomplishment instructions of the SB.

(2) If a Klixon low torque switch, part number (P/N) 6PS-25-1, is installed, prior to further flight remove the Klixon low torque switch from service and replace with an approved low torque switch.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office (ECO). Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, ECO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the ECO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Burlington, Massachusetts, on August 19, 1999.

David A. Downey,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 99-22194 Filed 8-25-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

14 CFR Part 382

49 CFR Part 27

[Docket OST-99-6159; Notice No: 5]

RIN 2105-AC81

Nondiscrimination on the Basis of Disability in Air Travel: Nondiscrimination on the Basis of Handicap in Programs and Activities Receiving or Benefiting from Federal Financial Assistance

AGENCY: Office of the Secretary, DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Department is proposing to amend its rules implementing the Air Carrier Access Act of 1986 and section 504 of the Rehabilitation Act of 1973 concerning the provision of equipment to facilitate the boarding by individuals with disabilities on aircraft where level-entry boarding is not now available. The proposed rule would require air carriers and airports to work jointly to make lifts or other boarding devices available for aircraft, of whatever size, where level-entry loading bridges or existing lifts are not present.

DATES: Comments are requested on or before November 24, 1999. Late-filed comments will be considered to the extent practicable.

ADDRESSES: Comments should be sent to Docket Clerk, Docket No. OST-99-6159, Department of Transportation, 400 7th Street, SW., Room PL-401, Washington, DC, 20590. Comments will be available for inspection at this address from 10 a.m. to 5:30 p.m., Monday through Friday, and are also viewable through the Dockets Management System (DMS) portion of the Department's web (www.dot.gov). Commenters may also submit comments electronically. Commenters who wish to do so should follow the instructions on the DMS site. Commenters who wish the receipt of their comments to be acknowledged should include a stamped, self-addressed postcard with their comments. The Docket Clerk will date-stamp the postcard and mail it back to the commenter.

FOR FURTHER INFORMATION CONTACT:

Robert C. Ashby, Deputy Assistant General Counsel for Regulation and Enforcement, Department of Transportation, 400 7th Street, SW., Room 10424, Washington, DC, 20590. (202) 366-9306 (voice); (202) 755-7687 (TDD).

SUPPLEMENTARY INFORMATION: On November 1, 1996, the Department

published a final rule requiring airports and airlines to work together to ensure that lifts were available to provide level-entry boarding for passengers with disabilities who were flying on small commuter aircraft. This rule applied to aircraft with a seating capacity of 19-30 passengers. The final rule, and the proposal that led to it, did not address the issue of level entry boarding for aircraft with 31 or more seats.

The original 1990 Air Carrier Access Act (ACAA) rule provided that, with an exception relevant only to the small commuter aircraft category, carriers must use "ramps, mechanical lifts, or other devices (not normally used for freight)" to provide boarding assistance, where level-entry boarding by loading bridge or mobile lounge was not available (14 CFR 382.39(a)(2)). The term "other devices" has been interpreted to include boarding chairs carried up aircraft stairs by carrier personnel.

Carrying passengers up stairs in a boarding chair is generally viewed as an undesirable way of providing access, for reasons having to do with the dignity, safety, and comfort of passengers. (It also increases risks to carrier personnel involved.) Consequently, the Department is proposing in this notice to require carriers to make lifts available for boarding assistance to any aircraft with a seating capacity of 31 seats or more where level-entry boarding by loading bridge or mobile lounge is not available. This requirement would apply to medium-size commuter aircraft or regional jets that are typically boarded from the tarmac in most airports, as well as to larger jets (up to and including "jumbo jets") at those airports or gates where, for some reason, level-entry boarding is not otherwise available.

The proposed regulatory provisions parallel those for small commuter aircraft. Carriers and airports would have to work together, create an agreement, and phase in implementation of lift service over a reasonable period of time. The Department seeks comment on whether there are any situations covered by the proposal in which providing lift access would be impracticable (e.g., analogous to the "problem aircraft" exempted from the small commuter aircraft lift rule).

The lift rule for small commuter aircraft had a phased-in implementation schedule, varying by size of airport. Because the draft regulatory evaluation for this rulemaking concludes that existing lifts, or lifts being put in place in response to the small commuter aircraft lift rule, will be sufficient to meet the proposed requirements, the