

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39–11138 (64 FR 22544, April 27, 1999) and amendment 39–11154 (64 FR 23179, April 30, 1999), and by adding a new airworthiness directive (AD), to read as follows:

McDonnell Douglas: Docket 99–NM–167–AD. Supersedes AD 99–08–51, amendment 39–11138; and AD 99–09–51, amendment 39–11154.

Applicability: Model MD–11 series airplanes, as listed in McDonnell Douglas Alert Service Bulletin MD11–24A155, dated June 1, 1999; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent sparks, smoke and possible fire in the lower center cargo compartment, accomplish the following:

Phase 1: Inspection and Corrective Actions

(a) Within 30 days after the effective date of this AD, perform an inspection of the wire assembly, structure, and blankets for evidence of arcing burns and chafing damage under the center cargo compartment floor, in accordance with Phase 1 of the Work Instructions of McDonnell Douglas Alert Service Bulletin MD11–24A155, dated June 1, 1999.

(1) Condition 1. If no arcing or chafing damage is detected, prior to further flight, install protective sleeving on the wire assembly in the area of the frame in accordance with the service bulletin.

(2) Condition 2. If any damaged wire, structure, or blanket is detected, prior to further flight, accomplish the actions specified in paragraphs (a)(2)(i), (a)(2)(ii), and (a)(2)(iii) of this AD.

(i) Repair damaged wire and structure in accordance with the service bulletin.

(ii) Repair or replace any damaged blanket with a new blanket, in accordance with Chapter 25 of the Aircraft Maintenance Manual; however, insulation blankets made of metallized polyethyleneterephthalate (MPET) may not be used.

(iii) Install protective sleeving on the wire assembly in the area of the frame in accordance with the service bulletin.

Note 2: Accomplishment of the actions required by AD 99–08–51, amendment 39–11138, and AD 99–09–51, amendment 39–11154, prior to the effective date of this AD is considered acceptable for compliance with the requirements of paragraph (a) of this AD.

Phase 2: Modification

(b) Within 18 months after the effective date of this AD, accomplish the actions specified in paragraph (b)(1) or (b)(2) of this AD, as applicable, in accordance with Phase 2 of the Work Instructions of McDonnell Douglas Alert Service Bulletin MD11–24A155, dated June 1, 1999.

(1) For airplanes identified as Group 1 in the service bulletin: Install the wire assembly support bracket, clamp, and spacer.

(2) For airplanes identified as Group 2 in the service bulletin: Revise the wire assembly support bracket and clamp installation.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 24, 1999.

Vi L. Lipski,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99–22530 Filed 8–30–99; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98–NM–339–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 747–100, –200 and 747SP Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747–100, –200 and 747SP series airplanes. This proposal would require repetitive detailed visual and ultrasonic inspections to detect missing, damaged, or broken taperlock bolts in the diagonal brace underwing fittings; and corrective actions, if necessary. This proposal also would require eventual replacement of the aft 10 taperlock bolts with new bolts, which would constitute terminating action for the repetitive inspections. This proposal is prompted by reports of damaged, broken, and corroded taperlock bolts of the diagonal brace underwing fittings on the outboard strut due to stress corrosion cracking. The actions specified by the proposed AD are intended to prevent loss of the underwing fitting load path due to missing, damaged, or broken taperlock bolts, which could result in separation of the engine and strut from the airplane.

DATES: Comments must be received by October 15, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 98–NM–339–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124–2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Tamara L. Anderson, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2771; fax (425) 227–1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date

for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 98-NM-339-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 98-NM-339-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received reports indicating that damaged, broken, and corroded taperlock bolts were found on Boeing Model 747-100 and -200 series airplanes. The cause of the broken taperlock bolts is stress corrosion. The bolts are located on the diagonal brace underwing fittings on the outboard strut at the Number 1 and Number 4 pylon engine positions. This condition, if not corrected, could result in separation of the engine and strut from the airplane.

The subject taperlock bolts on Boeing Model 747SP series airplanes are identical to those on the affected Boeing Model 747-100 and -200 series airplanes. Therefore, all of these airplanes may be subjected to the same unsafe condition.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-57A2308, dated August 6, 1998, which describes procedures for repetitive detailed visual and ultrasonic inspections to detect missing, damaged, or broken taperlock bolts; and corrective actions, if necessary. The corrective actions involve performing an open hole high frequency eddy current inspection to detect cracks at the bolt hole

locations; and replacing missing, damaged, or broken taperlock bolt with a new bolt. This service bulletin also describes procedures for an optional terminating action for the repetitive inspections. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Differences Between Proposed Rule and Service Bulletin

Operators should note that, although incorporation of the terminating action specified in the referenced service bulletin is optional, this AD proposes to mandate, within 48 months after the effective date of this AD, the open hole inspection and replacement of the aft 10 taperlock bolts with new bolts specified in the referenced service bulletin as terminating action for the repetitive inspections.

The FAA has determined that long-term continued operational safety will be better assured by design changes to remove the source of the problem, rather than by repetitive inspections. Long-term inspections may not be providing the degree of safety assurance necessary for the transport airplane fleet. This, coupled with a better understanding of the human factors associated with numerous continued inspections, has led the FAA to consider placing less emphasis on inspections and more emphasis on design improvements. The proposed replacement requirement is in consonance with these conditions.

In addition, operators should note that, although the service bulletin specifies that the manufacturer must be contacted for disposition of certain conditions, this proposal would require the repair of those conditions to be accomplished in accordance with a method approved by the FAA; or in accordance with data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the FAA to make such findings. For a method to be approved, the approval letter must specifically reference this AD.

Cost Impact

There are approximately 274 airplanes of the affected design in the worldwide fleet. The FAA estimates that 122 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the proposed inspection on U.S. operators is estimated to be \$7,320, or \$60 per airplane, per inspection cycle.

It would take approximately 8 work hours per airplane to accomplish the proposed terminating action, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$8,008 per airplane. Based on these figures, the cost impact of the proposed terminating action on U.S. operators is estimated to be \$1,035,536, or \$8,488 per airplane.

The cost impact figures discussed above are based on the assumption that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing: Docket 98–NM–339–AD.

Applicability: Model 747–100, –200, and 747SP series airplanes, line numbers 1 through 567 inclusive; equipped with aluminum diagonal brace underwing fittings; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of the underwing fitting load path due to missing, damaged, or broken taperlock bolts, which could result in separation of the engine and strut from the airplane, accomplish the following:

Repetitive Inspections

(a) Prior to the accumulation of 9,000 total flight cycles, or within 18 months after the effective date of this AD, whichever occurs later, accomplish the actions required by paragraphs (a)(1) and (a)(2) of this AD in accordance with Boeing Alert Service Bulletin 747–57A2308, dated August 6, 1998. Thereafter, repeat the inspections at intervals not to exceed 18 months until accomplishment of the actions specified in paragraph (d) of this AD.

(1) Perform a detailed visual inspection to detect missing taperlock bolts in the diagonal brace underwing fitting at the Number 1 and Number 4 pylons.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: “An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good

lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

(2) Perform an ultrasonic inspection to detect damaged or broken taperlock bolts in the diagonal brace underwing fitting at the Number 1 and Number 4 pylons.

Corrective Actions

(b) If any missing, damaged, or broken taperlock bolt is detected during any inspection required by paragraph (a) of this AD, prior to further flight, perform the applicable corrective actions (i.e., inspection, drill/ream, and replacement) in accordance with Boeing Alert Service Bulletin 747–57A2308, dated August 6, 1998; except as provided in paragraph (c) of this AD. Replacement of any taperlock bolt with a new bolt in accordance with this paragraph constitutes terminating action for the repetitive inspections required by paragraph (a) of this AD for that bolt only.

(c) If any crack is detected during the inspection required by paragraph (b) of this AD and the damage to a bolt hole exceeds first oversize (for 0.5-inch bolts) or second oversize (for 0.4375-inch bolts); and the service bulletin specifies to contact Boeing for appropriate Action: Prior to further flight, repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate; or in accordance with a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Terminating Action

(d) Within 48 months after the effective date of this AD, accomplish the actions required by paragraphs (d)(1) and (d)(2) of this AD in accordance with Boeing Alert Service Bulletin 747–57A2308, dated August 6, 1998. Accomplishment of the actions specified in this paragraph constitutes terminating action for the repetitive inspection requirements of this AD.

(1) Prior to accomplishing the replacement required by paragraph (d)(2) of this AD, perform an open hole high frequency eddy current inspection to detect cracks at the bolt hole locations of the aft 10 taperlock bolts. If any cracking is detected, prior to further flight, perform applicable corrective actions in accordance with paragraph (c) of this AD.

(2) Replace the aft 10 taperlock bolts with new bolts in the diagonal brace underwing fitting at the Number 1 and Number 4 pylons.

Spares

(e) As of the effective date of this AD, no person shall install a bolt, part number BACB30PE() * (), or any other bolt made of 4340, 8740, or PH13–8 Mo steel, in the locations specified in this AD, on any airplane.

Alternate Method of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on August 24, 1999.

Vi L. Lipski,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99–22529 Filed 8–30–99; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98–NM–300–AD]

RIN 2120–AA64

Airworthiness Directives; Mitsubishi Model YS–11 and YS–11A Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Mitsubishi Model YS–11 and YS–11A series airplanes. This proposal would require repetitive removal of the spinner; repetitive detailed visual inspections of the propeller hub to detect fatigue cracking; and replacement of a propeller hub with a new propeller hub, if necessary. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to detect and correct fatigue cracking of the propeller hub, which could cause the loss of the propeller.

DATES: Comments must be received by September 30, 1999.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114,