

approved by the Manager, FAA, Boston Aircraft Certification Office (ACO), 12 New England Executive Park, Burlington, Massachusetts 01803. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Boston ACO.

Note 5: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Boston ACO.

(i) All persons affected by this directive may obtain copies of the document referred to herein upon request to REVO, Incorporated, P.O. Box 312, One High Street, Sanford, Maine 04073; or may examine this document at the FAA, Central Region, Office of the Regional Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Appendix to Docket No. 99-CE-27-AD Inspection Results Report

Report the following information to:
Manager, Boston Aircraft Certification Office,
Engine and Propeller Directorate, Aircraft
Certification Service, Federal Aviation
Administration, 12 New England Executive
Park, Burlington, MA 01803-5299, Fax: (781)
238-7199.

Operator/Repair Station _____
Aircraft Model _____
Aircraft S/N _____
Date of Inspection _____

Identify Operational Use (Estimate):

Take-off/Landings:
Water, % of Total ____
Land, % of Total ____

Parking
Water, % of Time ____
Land, % of Time ____

Note: Add additional pages for the
following for each part inspected.

Part No. _____

Inspection

Dye Penetrant:

Pass ____
Fail ____
N/A ____

If a crack is found, indicate the approximate
location on the part and the length of the
crack in inches:

Part Time-In Service (TIS) (Hours):

Estimated ____
Actual ____
Unknown ____
At Retirement ____

Log Book entry for Part No. _____, is (date)
_____, at retirement hours _____.

Issued in Kansas City, Missouri, on
September 29, 1999.

Michael K. Dahl,

*Acting Manager, Small Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 99-25920 Filed 10-5-99; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-223-AD]

RIN 2120-AA64

Airworthiness Directives; Short Brothers Model SD3-60 SHERPA, SD3-SHERPA, and SD3-30 Series Airplanes

AGENCY: Federal Aviation
Administration, DOT.

ACTION: Notice of proposed rulemaking
(NPRM).

SUMMARY: This document proposes the
adoption of a new airworthiness
directive (AD) that is applicable to all
Short Brothers Model SD3-60 SHERPA,
SD3-SHERPA, and SD3-30 series
airplanes. This proposal would require
replacement of existing oxygen system
"O" rings with improved wear-resistant
"O" rings. This proposal is prompted by
issuance of mandatory continuing
airworthiness information by a foreign
civil airworthiness authority. The
actions specified by the proposed AD
are intended to prevent the loss of
oxygen from the aircraft oxygen system,
which could result in an insufficient
supply of oxygen being provided to the
airplane flight crew and passengers in
the event of an emergency.

DATES: Comments must be received by
November 5, 1999.

ADDRESSES: Submit comments in
triplicate to the Federal Aviation
Administration (FAA), Transport
Airplane Directorate, ANM-114,
Attention: Rules Docket No. 99-NM-
223-AD, 1601 Lind Avenue, SW.,
Renton, Washington 98055-4056.
Comments may be inspected at this
location between 9:00 a.m. and 3:00
p.m., Monday through Friday, except
Federal holidays.

The service information referenced in
the proposed rule may be obtained from
Short Brothers, Airworthiness &
Engineering Quality, P.O. Box 241,
Airport Road, Belfast BT3 9DZ,
Northern Ireland. This information may
be examined at the FAA, Transport
Airplane Directorate, 1601 Lind
Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:
Norman B. Martenson, Manager,
International Branch, ANM-116, FAA,
Transport Airplane Directorate, 1601
Lind Avenue, SW., Renton, Washington
98055-4056; telephone (425) 227-2110;
fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to
participate in the making of the
proposed rule by submitting such
written data, views, or arguments as
they may desire. Communications shall
identify the Rules Docket number and
be submitted in triplicate to the address
specified above. All communications
received on or before the closing date
for comments, specified above, will be
considered before taking action on the
proposed rule. The proposals contained
in this notice may be changed in light
of the comments received.

Comments are specifically invited on
the overall regulatory, economic,
environmental, and energy aspects of
the proposed rule. All comments
submitted will be available, both before
and after the closing date for comments,
in the Rules Docket for examination by
interested persons. A report
summarizing each FAA-public contact
concerned with the substance of this
proposal will be filed in the Rules
Docket.

Commenters wishing the FAA to
acknowledge receipt of their comments
submitted in response to this notice
must submit a self-addressed, stamped
postcard on which the following
statement is made: "Comments to
Docket Number 99-NM-223-AD." The
postcard will be date stamped and
returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this
NPRM by submitting a request to the
FAA, Transport Airplane Directorate,
ANM-114, Attention: Rules Docket No.
99-NM-223-AD, 1601 Lind Avenue,
SW., Renton, Washington 98055-4056.

Discussion

The Civil Aviation Authority (CAA),
which is the airworthiness authority for
the United Kingdom, recently notified
the FAA that an unsafe condition may
exist on all Short Brothers Model SD3-
60 SHERPA, SD3-SHERPA, and SD3-30
series airplanes. The CAA advises that
service experience has shown that
certain "O" rings of the airplane oxygen
system are prone to unexpected
deterioration. This condition, if not
corrected, could result in an insufficient
supply of oxygen being provided to the
airplane flight crew and passengers in
the event of an emergency.

Explanation of Relevant Service Information

Short Brothers has issued Service
Bulletins SD360 Sherpa-35-2, dated
February 25, 1999 (for Model SD3-60
Sherpa series airplanes); SD3 Sherpa-
35-3, Revision 1, dated May 5, 1999 (for

Model SD3 Sherpa series airplanes); and SD330-35-1, dated February 25, 1999 (for Model SD3-30 series airplanes). These service bulletins describe procedures for replacement of existing oxygen system "O" rings with improved wear-resistant "O" rings.

Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition. The CAA classified these service bulletins as mandatory and issued British airworthiness directives 007-02-99 (for Model SD3-60 Sherpa series airplanes), 006-02-99 (for Model SD3 Sherpa series airplanes), and 008-02-99 (for Model SD3-30 series airplanes), in order to assure the continued airworthiness of these airplanes in the United Kingdom.

FAA's Conclusions

These airplane models are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously.

Cost Impact

The FAA estimates that 62 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 50 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would be provided by the manufacturer at no cost to operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$186,000, or \$3,000 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would

accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Short Brothers PLC: Docket 99-NM-223-AD.

Applicability: All Model SD3-60 SHERPA, SD3-SHERPA, and SD3-30 series airplanes; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the

owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the loss of oxygen from the aircraft oxygen system, accomplish the following:

(a) Within 24 months after the effective date of this AD, replace oxygen system "O" rings, part number (P/N) MS28778, with improved wear-resistant "O" rings, P/N MS9068, in accordance with Shorts Service Bulletins SD360 Sherpa-35-2, dated February 25, 1999 (for Model SD3-60 Sherpa series airplanes); SD3 Sherpa-35-3, Revision 1, dated May 5, 1999 (for Model SD3 Sherpa series airplanes), and SD330-35-1, dated February 25, 1999 (for Model SD3-30 series airplanes); as applicable.

(b) As of the effective date of this AD, no person shall install an oxygen system "O" ring, P/N MS28778, on any airplane.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in British airworthiness directives 007-02-99 (for Model SD3-60 Sherpa series airplanes), 006-02-99 (for Model SD3 Sherpa series airplanes), and 008-02-99 (for Model SD3-30 series airplanes).

Issued in Renton, Washington, on September 30, 1999.

D. L. Rigglin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 99-26087 Filed 10-5-99; 8:45 am]

BILLING CODE 4910-13-P