

a location where the requirements of this AD can be accomplished.

## Appendix 1

Excerpt from an FAA Memorandum to the Director—Airworthiness and Technical Standards of ATA, dated March 20, 1992.

### “(1) Indication System:

(a) The indication system must monitor the closed, latched, and locked positions, directly.

(b) The indicator should be *amber* unless it concerns an outward opening door whose opening during takeoff could present an immediate hazard to the airplane. In that case the indicator must be *red* and located in plain view in front of the pilots. An aural warning is also advisable. A display on the master caution/warning system is also acceptable as an indicator. For the purpose of complying with this paragraph, an immediate hazard is defined as significant reduction in controllability, structural damage, or impact with other structures, engines, or controls.

(c) Loss of indication or a false indication of a closed, latched, and locked condition must be improbable.

(d) A warning indication must be provided at the door operators station that monitors the door latched and locked conditions directly, unless the operator has a visual indication that the door is fully closed and locked. For example, a vent door that monitors the door locks and can be seen from the operators station would meet this requirement.

### (2) Means to Visually Inspect the Locking Mechanism:

There must be a visual means of directly inspecting the locks. Where all locks are tied to a common lock shaft, a means of inspecting the locks at each end may be sufficient to meet this requirement provided no failure condition in the lock shaft would go undetected when viewing the end locks. Viewing latches may be used as an alternate to viewing locks on some installations where there are other compensating features.

### (3) Means to Prevent Pressurization:

All doors must have provisions to prevent initiation of pressurization of the airplane to an unsafe level, if the door is not fully closed, latched and locked.

### (4) Lock Strength:

Locks must be designed to withstand the maximum output power of the actuators and maximum expected manual operating forces treated as a limit load. Under these conditions, the door must remain closed, latched and locked.

### (5) Power Availability:

All power to the door must be removed in flight and it must not be possible for the flight crew to restore power to the door while in flight.

### (6) Powered Lock Systems:

For doors that have powered lock systems, it must be shown by safety analysis that inadvertent opening of the door after it is fully closed, latched and locked, is extremely improbable.”

Issued in Renton, Washington, on November 4, 1999.

**D. L. Riffin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-29474 Filed 11-10-99; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 97-NM-232-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Boeing Model 727 Series Airplanes Modified in Accordance With Supplemental Type Certificate SA1767SO or SA1768SO**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 727 series airplanes that have been converted from a passenger to a cargo-carrying (“freighter”) configuration. This proposal would require, among other actions, installation of a fail-safe hinge, redesigned main deck cargo door warning and power control systems, and 9g cargo barrier. This proposal is prompted by the FAA’s determination that the main deck cargo door hinge is not fail-safe; that certain main deck cargo door control systems do not provide an adequate level of safety; and that the main deck cargo barrier is not structurally adequate during an emergency landing. The actions specified by the proposed AD are intended to prevent structural failure of the main deck cargo door hinge or failure of the cargo door system, which could result in the loss or opening of the cargo door while the airplane is in flight, rapid decompression, and structural damage to the airplane; and to prevent failure of the main deck cargo barrier during an emergency landing, which could injure occupants.

**DATES:** Comments must be received by December 27, 1999.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-232-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this

location by appointment only between the hours of 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. **FOR FURTHER INFORMATION CONTACT:** Paul Sconyers, Associate Manager, Airframe and Propulsion Branch, ACE-117A, FAA, Small Airplane Directorate, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, Suite 450, Atlanta, Georgia 30349; telephone (770) 703-6076; fax (770) 703-6097.

#### **SUPPLEMENTARY INFORMATION:**

#### **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 97-NM-232-AD.” The postcard will be date stamped and returned to the commenter.

#### **Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 97-NM-232-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### **Discussion**

Supplemental Type Certificate (STC) SA1767SO (held by FedEx) specifies a design for a main deck cargo door, associated cargo door cutout, and door systems. STC SA1768SO (held by FedEx) specifies a design for a Class “E” cargo interior with a cargo restraint barrier net. As discussed in notice of proposed rulemaking (NPRM), Rules

Docket No. 97-NM-09-AD [the final rule, AD 98-26-18, amendment 39-19961, was published in the **Federal Register** on January 12, 1999 (64 FR 1994)], which is applicable to certain Boeing Model 727 series airplanes that have been converted from a passenger to a cargo-carrying ("freighter") configuration, the FAA has conducted a design review of Boeing Model 727 series airplanes modified in accordance with STC's SA1767SO and SA1768SO and has identified several potential unsafe conditions. [Results of this design review are contained in "FAA Freighter Conversion STC Review, Report Number 2, dated October 16-18, 1996," hereinafter referred to as "the Design Review Report," which is included in the Rules Docket for this NPRM.] This NPRM proposes corrective action for three of those potential unsafe conditions that relate to the following three areas: main deck cargo door hinge, main deck cargo door systems, and main deck cargo barrier.

#### Main Deck Cargo Door Hinge

In order to avoid catastrophic structural failure, it has been a typical industry approach to design outward opening cargo doors and their attaching structure to be fail-safe (*i.e.*, designed so that if a single structural element fails, other structural elements are able to carry resulting loads). Another potential design approach is safe-life, where the critical structure is shown by analyses and/or tests to be capable of withstanding the repeated loads of variable magnitude expected in service for a specific service life. Safe-life is usually not used on critical structure because it is difficult to account for manufacturing or in-service accidental damage. For this reason, plus the fact that none of the STC holders have provided data in support of this approach, the safe-life approach will not be discussed further regarding the design and construction of the main deck cargo door hinge.

Structural elements such as the main deck cargo door hinge are subject to severe in-service operating conditions that could result in corrosion, binding, or seizure of the hinge. These conditions, in addition to the normal operational loads, can lead to early and unpredictable fatigue cracking. If a main deck cargo door hinge is not a fail-safe design, a fatigue crack could initiate and propagate longitudinally undetected, which could lead to a complete hinge failure. A possible consequence of this undetected failure is the opening of the main deck cargo door while the airplane is in flight. Service experience indicates that the opening of a cargo door while

the airplane is in flight can be extremely hazardous in a variety of ways including possible loss of flight control, severe structural damage, or rapid decompression, any of which, could lead to loss of the airplane.

The design of the main deck cargo door hinge must be in compliance with Civil Air Regulations (CAR) part 4b, including CAR part 4b.270, which requires, in part, that catastrophic failure or excessive structural deformation, which could adversely affect the flight characteristics of the airplane, is not probable after fatigue failure or obvious partial failure of a single principal structural element. One common feature of a fail-safe hinge design is a division of the hinge into multiple segments such that, following failure of any one segment, the remaining segments would support the redistributed load.

The main deck cargo door installed in accordance with STC SA1767SO is supported by latches along the bottom of the door and one continuous hinge along the top. This single-piece hinge is considered a critical structural element for this STC. A crack that initiates and propagates longitudinally along the hinge line of the continuous hinge will eventually result in failure of the entire hinge, because there is no segmenting of the hinge to interrupt the crack propagation and support the redistributed loads. Failure of the entire hinge can result in the opening of the main deck cargo door while the airplane is in flight.

As discussed in the Design Review Report, an inspection of one Boeing Model 727 series airplane modified in accordance with STC's SA1767SO and SA1768SO revealed a number of fasteners with both short edge margins and short spacing in the cargo door cutout external doublers. Some edge margins were as small as one fastener diameter. Fasteners that are placed too close to the edge of a structural member or spaced too close to an adjacent fastener can result in inadequate joint strength and stress concentrations, which may result in fatigue cracking of the skin. If such defects were to exist in the structure of the door or the fuselage to which the main deck cargo door hinge is attached, the attachment of the hinge could fail, and consequently cause the door to open while the airplane is in flight.

Since unsafe conditions have been identified that are likely to exist or develop on other products of this same type design, this proposed AD would require, within 250 flight cycles after the effective date of the AD, a one-time detailed visual inspection of the

external surface of the main deck cargo door hinge (both fuselage and door side hinge elements) to detect cracks, and repair, if necessary. Accomplishment of this inspection will ensure that the subject airplanes are not in immediate risk of hinge failure.

In addition, the proposed AD would require a detailed visual inspection of the mating surfaces of both the hinge and the door skin and external fuselage doubler underlying the hinge to detect cracks or other discrepancies (*e.g.*, double or closely drilled holes, corrosion, chips, scratches, or gouges). The proposed AD also would require installation of a main deck cargo door hinge that complies with the applicable requirements of CAR part 4b, including fail-safe requirements. Accomplishment of this detailed visual inspection will ensure the integrity of the door and fuselage structure to which the hinge is attached. The proposed compliance time for this inspection and installation is within 36 months or 4,000 flight cycles after the effective date of this AD, whichever occurs first. The compliance time is based on the FAA's assessment of the reasonable amount of time to redesign, manufacture, and install a fail-safe hinge. This time is in consideration of the 18-month time period estimated by the Boeing 727 industry working group, which includes operators, affected STC holders, and engineering organizations, to develop FAA-approved redesigns. These actions would be required to be accomplished in accordance with a method approved by the FAA.

#### Main Deck Cargo Door Systems

In early 1989, two transport airplane accidents were attributed to cargo doors coming open during flight. The first accident involved a Boeing 747 series airplane in which the cargo door separated from the airplane, and damaged the fuselage structure, engines, and passenger cabin. The second accident involved a McDonnell Douglas DC-9 series airplane in which the cargo door opened but did not separate from its hinge. The open door disturbed the airflow over the empennage, which resulted in loss of flight control and consequent loss of the airplane. Although cargo doors have opened occasionally without mishap during takeoff, these two accidents serve to highlight the extreme potential dangers associated with the opening of a cargo door while the airplane is in flight.

As a result of these cargo door opening accidents, the Air Transport Association (ATA) of America formed a task force, including representatives of the FAA, to review the design,

manufacture, maintenance, and operation of airplanes fitted with outward opening cargo doors, and to make recommendations to prevent inadvertent cargo door openings while the airplane is in flight. A design working group was tasked with reviewing 14 CFR part 25.783 [and its accompanying Advisory Circular (AC) 25.783-1, dated December 10, 1986] with the intent of clarifying its contents and recommending revisions to enhance future cargo door designs. This design group also was tasked with providing specific recommendations regarding design criteria to be applied to existing outward opening cargo doors to ensure that inadvertent openings would not occur in the current transport category fleet of airplanes.

The ATA task force made its recommendations in the "ATA Cargo Door Task Force Final Report," dated May 15, 1991 (hereinafter referred to as "the ATA Final Report"). On March 20, 1992, the FAA issued a memorandum to the Director-Airworthiness and Technical Standards of ATA (hereinafter referred to as "the FAA Memorandum"), acknowledging ATA's recommendations and providing additional guidance for purposes of assessing the continuing airworthiness of existing designs of outward opening doors. The FAA Memorandum was not intended to upgrade the certification basis of the various airplanes, but rather to identify criteria to evaluate potential unsafe conditions demonstrated on in-service airplanes. Appendix 1 of this AD contains the specific paragraphs from the FAA Memorandum that set forth the criteria to which the outward opening doors should be shown to comply.

Applying the applicable requirements of CAR part 4b and design criteria provided by the FAA Memorandum, the FAA has reviewed the original type design of major transport airplanes, including Boeing 727 airplanes equipped with outward opening doors, for any design deficiency or service difficulty. Based on that review, the FAA identified unsafe conditions and issued, among others, the following AD's:

- For certain McDonnell Douglas Model DC-9 series airplanes: AD 89-11-02, amendment 39-6216 (54 FR 21416, May 18, 1989);
- For all Boeing Model 747 series airplanes: AD 90-09-06, amendment 39-6581 (55 FR 15217, April 23, 1990);
- For certain McDonnell Douglas Model DC-8 series airplanes: AD 93-20-02, amendment 39-8709 (58 FR 471545, October 18, 1993);
- For certain Boeing Model 747-100 and -200 series airplanes: AD 96-01-51,

amendment 39-9492 (61 FR 1703, January 23, 1996); and

- For certain Boeing Model 727-100 and -200 series airplanes: AD 96-16-08, amendment 39-9708 (61 FR 41733, August 12, 1996).

Using the criteria specified in the ATA Final Report and the FAA Memorandum as evaluation guides, the FAA conducted an engineering design review and inspection of an airplane modified in accordance with STC's SA1767SO and SA1768SO held by FedEx. The FAA identified a number of unsafe conditions with the main deck cargo door systems of these STC's. The FAA design review team determined that the design data of these STC's did not include a safety analysis of the main deck cargo door systems.

As specified in the criteria contained in Appendix 1 of this AD, for powered lock systems on the main deck cargo door, it must be shown by safety analysis that inadvertent opening of the door after it is fully closed, latch, and locked is extremely improbable. However, the FAA is aware of two events in which the main deck cargo door opened during flight. These events occurred on FedEx passenger/freighter conversion STC's in October 1996, and March 1995. These events are referenced in the Design Review Report.

For airplanes modified in accordance with STC's SA1767SO or SA1768SO, the FAA considers the following four specific design deficiencies of the main deck cargo door systems to be unsafe:

#### 1. Indication System

The main deck cargo door indication system for STC's SA1767SO and SA1768SO uses a warning light at the door operator's control panel and a light at the flight engineer's panel. Both of these lights indicate the status of the cargo door latch and lock positions, but do not indicate either the door open or closed status. All three conditions (*i.e.*, door closed, latched, and locked) must be monitored directly so that the door indication system cannot display either "latched" before the door is closed or "locked" before the door is latched. If a sequencing error caused the door to latch and lock without being fully closed, the subject indication system, as designed, would not alert the door operator or the flight engineer of this condition. As a result, the airplane could be dispatched with the main deck cargo door unsecured, which could lead to the cargo door opening while the airplane is in flight and possible loss of the airplane.

The light on the flight engineer's panel is labeled "MAIN CARGO" and is displayed in red since it indicates an

event that requires immediate pilot action. However, if the flight engineer is temporarily away from his station, a door unsafe warning indication could be missed by the pilots. In addition, the flight engineer could miss such an indication by not scanning the panel. As a result, the pilots and flight engineer could be unaware of, or misinterpret, an unsafe condition and could fail to respond in the correct manner. Therefore, an indicator light must be located in front of and in plain view of both pilots since one of the pilot's stations is always occupied during flight operations.

The main deck cargo door indication system of STC's SA1767SO and SA1768SO does not have a level of reliability that is considered adequate for safe operation. Many components are exposed to the environment during cargo loading operations and may be contaminated by precipitation, dirt, and grease, or damaged by foreign objects or cargo loading equipment. As a result, wires, switches, and relays can fail, jam, or short circuit and cause a loss of indication or a false indication to the door operator and flight crew. The design logic of the indication system (*i.e.*, lights which extinguish when the door is locked) will, in the event of a single point failure that would extinguish the light, result in an erroneous "safe" indication regardless of actual door status.

The design of STC's SA1767SO and SA1768SO has a "Press-to-Test" red warning light on the control panel of the main deck cargo door located near the L-1 door. The design of the monitoring system of the main deck cargo door does not include separate lights to provide the door operator with door close, latch, and lock status. The electrical wiring design of the close, latch, and lock sensors of the door monitoring system are wired in parallel instead of in series. In parallel, two sensors could be sensing "unsafe" and the third sensor could be sensing "safe." If this situation were to occur, the sensors would not illuminate the red warning light on the door control panel or at the flight engineer's panel. Therefore, the "Press-to-Test" feature is adequate to check the light bulb functionality, but is not adequate to check the cargo door closed, latched, and locked functions and status without annunciator lights for those three functions.

#### 2. Means to Visually Inspect the Locking Mechanism

The single view port of the main deck cargo door installed in accordance with STC SA1767SO is intended to allow the flight crew to conduct a visual

inspection of the door locking mechanism. This view port is used in conjunction with the door warning system and should provide a suitable "back-up" in the event that the main deck cargo door warning system malfunctions.

The door locking mechanism is an assembly comprised of multiple lock pins (one for each of the door latches) connected by linkages to a common lock shaft. Although an indicator flag attached to the lock shaft can be seen through the view port when the shaft is in the "locked" position, a failure between the shaft and the pins could go undetected, because this flag is attached to the lock shaft and not the actual lock pins. If such a failure goes undetected, the airplane may be dispatched with the main deck cargo door warning system inoperative and the door not fully closed, latched, and locked, which could lead to a main deck cargo door opening while the airplane is in flight and possible loss of the airplane. Therefore, the FAA finds that the subject view port is not a suitable back-up when the cargo door warning system malfunctions.

As discussed in the ATA Final Report and the FAA Memorandum, there must be a means of directly inspecting each lock or, at a minimum, the locks at each end of the lock shaft of certain designs, such that a failure condition in the lock shaft would be detectable.

### *3. Means to Prevent Pressurization to an Unsafe Level*

Boeing 727-200 airplanes modified in accordance with STC SA1767SO are configured to utilize the existing fuselage pressurization outflow valve for the purpose of preventing pressurization of the airplane to an unsafe level in the event that the main deck cargo door is not closed, latched, and locked. The FAA design review of these modified Boeing 727-200 airplanes (documented in the Design Review Report) identified single point failures in the door control/outflow valve interface that could result in the valve not sensing and responding to an unsafe door condition. In addition, the FAA found no data to substantiate that the outflow valve location and size could prevent pressurization to an unsafe level.

With the current design, it is possible that the outflow valve may not perform its intended function when utilized for the purpose of preventing pressurization of the airplane in the event of an unsecured door. This condition could result in cabin pressurization forcing an unsecured door open while the airplane is in flight and possible loss of the airplane.

Boeing 727-100 airplanes modified in accordance with the subject STC's have no means of preventing pressurization in the event that the main deck cargo door is not closed, latched, and locked, and therefore, have a higher risk of a cargo door opening while the airplane is in flight and possible loss of the airplane.

### *4. Powered Lock Systems*

The main deck cargo door control system for STC SA1767SO that utilizes electrical interlock switches is designed to remove door control power (electrical and hydraulic) prior to flight and to prevent inadvertent door openings. The occurrence of an in-flight door opening event on airplanes modified in accordance with STC SA1767SO, as identified in the Design Review Report, indicates the likelihood that there may be latent and/or single point failures that can restore or continue to allow power to the door controls and cause inadvertent door openings. The failure modes may be found in the electrical portion of the door control panel, which, in turn, activates the door control hydraulics. The potential for the occurrence of these failure conditions is increased by the harsh operating environment of freighter airplanes. Door system components are routinely exposed to precipitation, dirt, grease, and foreign object intrusion, all of which increase the likelihood of damage. As a result, wires, switches, and relays have a greater potential to fail or short circuit in such a way as to allow the cargo door to be powered open without an operator's command and regardless of electrical interlock positions.

A systems safety analysis would normally evaluate and resolve the potential for these types of unsafe conditions. However, the design data for STC SA1767SO do not include a systems safety analysis to specifically identify these failure modes and do not show that an inadvertent opening is extremely improbable. The need for a system safety analysis is identified in the ATA Final Report and the FAA Memorandum.

Since unsafe conditions have been identified that are likely to exist or develop on other products of this same type design, this proposed AD would require, within 60 days after the effective date, revising the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) Supplement to provide the flight crew with procedures for ensuring that all power is removed from the main deck cargo door prior to dispatch of the airplane, and that the main deck cargo door is closed, latched,

and locked prior to dispatch of the airplane; and installing any associated placards.

In addition, the proposed AD would require, within 36 months after the effective date of the AD, incorporation of redesigned main deck cargo door systems (e.g., warning/monitoring, power control, view ports, and means to prevent pressurization to an unsafe level if the main deck cargo door is not closed, latched, and locked), including any associated procedures and placards that comply with the applicable requirements of CAR part 4b and design criteria of the ATA Final Report and the FAA Memorandum. Design data provided in support of the door systems redesign should include a Systems Safety Analysis and Instructions for Continued Airworthiness that are acceptable to the FAA. Accomplishment of the incorporation of redesigned main deck cargo door systems will prevent rapid decompression and/or structural damage to the airplane as a result of loss or opening of the cargo door while the airplane is in flight. The compliance time is based on the FAA's assessment of the reasonable amount of time to incorporate redesigned main deck cargo door systems. This time is in consideration of the 18-month time period estimated by the Boeing 727 industry working group, which includes operators, affected STC holders, and engineering organizations, to develop FAA-approved redesigns.

These actions would be required to be accomplished in accordance with a method approved by the FAA.

### **Cargo Restraint Barrier**

In order to ensure the safety of occupants during emergency landing conditions, the FAA first established in 1934, a set of inertia load factors used to design the structure for restraining items of mass in the fuselage. Because the airplane landing speeds have increased over the years as the fleet has transitioned from propeller to jet design, inertia load factors were changed as specified in CAR part 4b.260. Experience has shown that an airplane designed to this regulation has a reasonable probability of protecting its occupants from serious injury in an emergency landing. The 727 passenger airplane was designed to these criteria which specified an ultimate inertia load requirement of 9g in the forward direction. These criteria were applied to the seats and structure restraining the occupants, including the flight crew, as well as other items of mass in the fuselage.

When the 727 passenger airplane is converted to carry cargo on the main

deck, a cargo barrier is required, since most cargo containers and the container-to-floor attaching devices are not designed to withstand emergency landing loads. In fact, the FAA estimates that the container-to-floor attaching devices will only support approximately 1.5g's to 3g's in the forward direction. Without a 9g cargo barrier, it is probable that the loads associated with an emergency landing would cause the cargo to be unrestrained and impact the occupants of the airplane, which could result in serious injury or death.

The structural inadequacy of the cargo barrier was evident to the FAA during its review in October 1997 of a Boeing 727 modified in accordance with STC SA1767SO. The observations revealed that the design of the net restraint barrier floor attachment and circumferential supporting structure does not provide adequate strength to withstand the 9g forward inertia load generated by the main deck cargo mass, nor does it provide a load path to effectively transfer the loads from the restraint barrier to the fuselage structure of the airplane. These observations are supported by data contained in "ER 2785, Structural Substantiation of the 50k 9g Bulkhead Restraint System in Support of STC SA1543SO PN 53-1292-401 for the 9g Bulkhead 53-1980-300 Assembly with Upper Attachment Structure, Lower Attachment Structure, Floor Shear Web Structure, Seat Track Splice Fittings, Seat Tracks, and Seat Track Splices," dated September 29, 1996, by M. F. Daniel. Although this report was specific to STC SA1543SO, the FAA has determined that the data are applicable to airplane modified in accordance with STC ST00015AT because the design principles for attachment of the barriers in both STC's are the same. The report reveals that structural deficiencies were found in the net attach plates and floor attachment structure of the cargo barrier. The data show large negative margins of safety, which indicate that the inertia load capability of the cargo barrier is closer to 2g than the required 9g in the forward direction. From these analyses, it is evident that the cargo restraint barrier would not be capable of preventing serious injury to the occupants during an emergency landing event with the full allowable cargo load.

Since unsafe conditions have been identified that are likely to exist or develop on other products of this same type design, this proposed AD would require installation of a main deck cargo barrier that complies with the applicable requirements of CAR part 4b. Accomplishment of the installation will prevent serious injury to the occupants

in the event of an emergency landing. The proposed compliance time for the installation is within 36 months or 4,000 flight cycles after the effective date of the AD, whichever occurs first. This compliance time is based on the FAA's assessment of the reasonable amount of time to redesign, manufacture, and install the cargo barrier. This time is in consideration of the 18-month time period estimated by the Boeing 727 industry working group, which includes operators, affected STC holders, and engineering organizations, to develop and get FAA-approved redesigns.

#### **Regulatory Evaluation Summary**

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

This analysis examines the cost of a proposed AD that would require the installation of a fail-safe hinge, redesigned main deck cargo door warning and power control systems, and a 9g cargo barrier on Boeing Model 727 series airplanes that have been modified in accordance with STC's held by FedEx. As discussed above, the FAA has determined that the main deck cargo door hinge is not fail-safe, that certain main deck cargo door control systems do not provide an adequate level of safety, and that the main deck cargo barrier is not structurally adequate during a minor crash landing.

Approximately 117 U.S.-registered Boeing Model 727 series airplanes operated by FedEx would be affected by the proposed AD. The following discussion addresses, in sequence, the actions in this proposed rulemaking and the estimated cost associated with each of these actions. An analysis of the cost is also available in Rules Docket No. 97-NM-232-AD.

#### **1. Main Deck Cargo Door Hinge**

Since unsafe conditions have been identified that are likely to exist or develop on other modified Boeing Model 727 series airplanes, paragraph (a) of the proposed AD would require, within 250 flight cycles after the effective date of this AD, a one-time detailed visual inspection to detect cracks of the external surface of the main deck cargo door hinge. FedEx estimates that this inspection would

take 14 work hours. At a mechanic's burdened labor rate of \$60 per work hour, the cost per airplane would be \$840, or \$98,280 for FedEx's fleet of 117 affected Boeing Model 727 series airplanes.

Paragraph (b)(1) of the proposed AD would require, within 36 months or 4,000 cycles after the effective date of this AD, a detailed visual inspection of the mating surfaces of both the hinge and the door skin and external fuselage doubler underlying the hinge. The FAA estimates that compliance with this inspection would take 200 hours at an estimated cost of \$12,000 per airplane, or \$1.4 million for the affected fleet.

Paragraph (b)(2) of the proposed AD would require installation of a fail-safe door hinge. The compliance time for this installation would also be 36 months or 4,000 cycles after the effective date of this AD. The estimated cost to design and certificate such a hinge is \$45,000. FedEx estimates that parts for a fail-safe door hinge would cost \$2,600, while installation would cost \$11,520 per airplane for 192 hours of labor. Parts and labor for 117 affected airplanes would be \$1.7 million.

Paragraph (c) of the proposed AD would require that, if any cracks or discrepancies are detected during the inspections required by paragraph (a) or (b)(1) of the proposed AD, repairs must be made prior to further flight. The cost of these repairs is not attributable to this proposed AD.

For purposes of this analysis, the FAA assumes an effective date of July 1, 2000. The cost to comply with proposed paragraphs (a) through (c) over the 36-month compliance period is \$3.2 million, or \$2.8 million discounted to present value. The FAA assumes that the installation of the main deck cargo door hinge [paragraph (b)(1)] would be accomplished at the same time as the detailed visual inspection of fastener holes [paragraph (b)(2)]. The FAA also assumes that FedEx would perform these two activities uniformly throughout the 36-month period. Finally, the certification cost for the main deck cargo door hinge would be incurred within the first 6 months after the effective date of this AD.

#### **2. Main Deck Cargo Door Systems**

Paragraph (d) of the proposed AD would require, within 60 days after the effective date, revising the Limitations Section of the FAA-approved AFM Supplement to provide the flight crew with procedures for ensuring that all power is removed from the main deck cargo door prior to dispatch of the airplane, and that the main deck cargo door is closed, latched, and locked prior

to dispatch of the airplane. In addition, paragraph (d) of the proposed AD would require the installation of any associated placards.

FedEx assumes that an external inspection of the flushness of the cargo door, combined with an "enhanced B-check" would be an acceptable means to the FAA to ensure that the cargo door is secured prior to dispatch. Based on this assumption, FedEx estimates, before a redesigned door system is installed [see proposed paragraph (f) below], that it would take a mechanic 30 minutes to inspect for flushness of the main deck cargo door prior to dispatch. FedEx also estimates that there are 62 flights per day among the 117 affected airplanes and that these airplanes fly 260 days per year. The estimated cost per inspection would be \$30, or \$4,133 per airplane per year until the door system is changed. In addition, FedEx estimates that the setup costs for the daily inspection (*i.e.*, procedure materials for the cadre of mechanics to perform the inspection and training requirements) would be \$50,000.

B-checks on FedEx Boeing Model 727 series airplanes occur approximately twice a year. FedEx estimates the incremental cost for maintenance during this "enhanced B-check" is \$11,700 per year until the door system is changed.

Paragraph (e) of the proposed AD would require, within 36 months after the effective date of this AD, incorporation of a redesigned main deck cargo door system. FedEx estimates that the development and certification of the system would cost \$212,000. Modification parts would cost \$110,000 per airplane and labor costs would be \$34,560 per airplane. FedEx also estimates that 40 percent of the fleet would be modified during a scheduled maintenance visit. The remainder of the fleet would be out-of-service for an additional 4 days. Based on a lease rate of \$6,100 per day, FedEx estimates that the cost of down time for the fleet would be \$1.7 million over the 36-month period.

Based on FedEx's assumption that a combination of an external inspection of cargo door flushness prior to dispatch and an "enhanced" B-check every 6 months, the total cost would be \$3.2 million over 36 months. These activities would occur until incorporation of a redesigned door system. Again, the FAA assumes that the accomplishment of this incorporation would occur uniformly over the 36-month period.

The estimated cost for redesigned door systems for the fleet of 117 affected airplanes would be \$18.8 million, including \$212,000 for design and certification costs and \$1.7 million for

additional down time. The total cost to comply with proposed requirements for the main deck cargo door system is \$22.0 million, or \$19.1 million, discounted to present value.

### 3. Main Deck Cargo Barrier

Paragraph (f) of the proposed AD would require, within 36 months or 4,000 flight cycles after the effective date of this AD, installation of a main deck cargo barrier that complies with the applicable requirements of CAR part 4b. FedEx estimates that development and certification of a 9g barrier would cost \$94,500, while parts would cost \$30,000 and labor would cost \$23,040 per airplane.

The FAA assumes that FedEx would install 9g barriers in their affected fleet uniformly over the 36-month compliance period. The total non-discounted cost would be \$6.3 million, or \$5.4 million discounted to present value.

### 4. Alternative Methods of Compliance (AMOC) and Special Flight Permits

Paragraph (g) of the proposed AD would allow an AMOC or adjustment of compliance time that provides an acceptable level of safety if approved by the Manager of the Atlanta ACO. The FAA is unable to determine the cost of an AMOC, but assumes it would be less than the cost of complying with the proposed provisions in paragraphs (a) through (f) of the proposed AD.

Paragraph (h) of the proposed AD would allow special flight permits in accordance with the regulations to operate an affected airplane to a location where the requirements of the proposed AD could be accomplished.

### 5. Total Cost of the Proposed AD

The FAA estimates that the total compliance cost of the proposed AD would be \$31.6 million, or \$27.3 million discounted to present value.

The Regulatory Flexibility Act (RFA) of 1980 establishes "as a principle of regulatory issuance that agencies shall endeavor, consistent with the objective of the rule and of applicable statutes, to fit regulatory and informational requirements to the scale of the business, organizations, and governmental jurisdictions subject to regulation. To achieve that principle, the RFA requires agencies to solicit and consider flexible regulatory proposals and to explain the rationale for their actions. The RFA covers a wide range of small entities, including small businesses, not-for-profit organizations, and small governmental jurisdictions.

Agencies must perform a review to determine whether a proposed or final

rule will have a significant economic impact on a substantial number of small entities. If the determination is that it will, the Agency must prepare a regulatory flexibility analysis as described in the RFA. However, if an agency determines that a proposed or final rule is not expected to have a significant economic impact on a substantial number of small entities, section 605(b) of the RFA provides that the head of the agency may so certify and a regulatory flexibility analysis is not required. The certification must include a statement providing the factual basis for this determination, and the reasoning should be clear.

Only one operator, FedEx, is affected by this proposed AD. FedEx is not a small entity. Pursuant to the Regulatory Flexibility Act, 5 U.S.C. 605(b), the FAA certifies that this proposed AD would not have a significant economic impact on a substantial number of small entities.

Title II of the Unfunded Mandates Reform Act of 1995 (the Act), enacted as Pub. L. 104-4 on March 22, 1995, requires each Federal agency, to the extent permitted by law, to prepare a written assessment of the effects of any Federal mandate in a proposed or final agency rule that may result in the expenditure by State, local, and tribal governments, in the aggregate, or by the private sector, of \$100 million or more (adjusted annually for inflation) in any one year. Section 204(a) of the Act, 2 U.S.C. 1534(a), requires the Federal agency to develop an effective process to permit timely input by elected officers (or their designees) of State, local, and tribal governments on a proposed "significant intergovernmental mandate." A "significant intergovernmental mandate" under the Act is any provision in a Federal agency regulation that would impose an enforceable duty upon State, local, and tribal governments, in the aggregate, of \$100 million (adjusted annually for inflation) in any one year. Section 203 of the Act, 2 U.S.C. 1533, which supplements section 204(a), provides that before establishing any regulatory requirements that might significantly or uniquely affect small governments, the agency shall have developed a plan that, among other things, provides for notice to potentially affected small governments, if any, and for a meaningful and timely opportunity to provide input in the development of regulatory proposals.

This proposed AD does not contain any Federal intergovernmental or private sector mandate. Therefore, the requirements of Title II of the Unfunded

Mandates Reform Act of 1995 do not apply.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Boeing:** Docket 97–NM–232–AD.

**Applicability:** Model 727 series airplanes that have been converted from a passenger to a cargo-carrying ("freighter") configuration in accordance with Supplemental Type Certificate (STC) SA1767SO or SA1768SO; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent structural failure of the main deck cargo door hinge or failure of the cargo door system, which could result in the loss or opening of the cargo door while the airplane is in flight, rapid decompression, and structural damage to the airplane; and to prevent failure of the main deck cargo barrier during an emergency landing, which could injure occupants; accomplish the following:

#### Actions Addressing the Main Deck Cargo Door Hinge

(a) Within 250 flight cycles after the effective date of this AD, perform a detailed visual inspection of the external surface of the main deck cargo door hinge (both fuselage and door side hinge elements) to detect cracks.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific

structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(b) Within 36 months or 4,000 flight cycles after the effective date of this AD, whichever occurs first, accomplish paragraphs (b)(1) and (b)(2) of this AD.

(1) Perform a detailed visual inspection of the mating surfaces of both the hinge and the door skin and external fuselage doubler underlying the hinge to detect cracks or other discrepancies (e.g., double or closely drilled holes, corrosion, chips, scratches, or gouges). The detailed visual inspection shall be accomplished in accordance with a method approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA, Small Airplane Directorate. The requirements of this paragraph may be accomplished prior to or concurrently with the requirements of paragraph (b)(2) of this AD.

(2) Install a main deck cargo door hinge that complies with the applicable requirements of Civil Air Regulations (CAR) part 4b, including fail-safe requirements, in accordance with a method approved by the Manager, Atlanta ACO.

(c) If any crack or discrepancy is detected during the detailed visual inspection required by either paragraph (a) or (b)(1) of this AD, prior to further flight, repair in accordance with a method approved by the Manager, Atlanta ACO.

#### Actions Addressing the Main Deck Cargo Door Systems

(d) Within 60 days after the effective date of this AD, revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) Supplement by inserting therein the procedures specified in paragraphs (d)(1) and (d)(2) of this AD, and install any associated placards. The AFM revision procedures and installation of any associated placards shall be accomplished in accordance with a method approved by the Manager, Atlanta ACO.

(1) Procedures to ensure that all power is removed from the main deck cargo door prior to dispatch of the airplane. And

(2) Procedures to ensure that the main deck cargo door is closed, latched, and locked prior to dispatch of the airplane.

(e) Within 36 months after the effective date of this AD, incorporate redesigned main deck cargo door systems (e.g., warning/monitoring, power control, view ports, and means to prevent pressurization to an unsafe level if the main deck cargo door is not closed, latched, and locked), including any associated procedures and placards, that comply with the applicable requirements of CAR part 4b and criteria specified in Appendix 1 of this AD; in accordance with a method approved by the Manager, Atlanta ACO.

**Note 3:** The design data submitted for approval should include a Systems Safety Analysis and Instructions for Continued Airworthiness that are acceptable to the Manager, Atlanta ACO.

#### Actions Addressing the Main Deck Cargo Barrier

(f) Within 36 months or 4,000 flight cycles after the effective date of this AD, whichever occurs first, install a main deck cargo barrier that complies with the applicable requirements of CAR part 4.b, in accordance with a method approved by the Manager, Atlanta ACO.

**Note 4:** The maximum main deck total payload that can be carried is limited to the lesser of the approved cargo barrier weight limit, weight permitted by the approved maximum zero fuel weight, weight permitted by the approved main deck position weights, weight permitted by the approved main deck running load or distributed load limitations, or approved cumulative zone or fuselage monocoque structural loading limitations (including lower hold cargo).

#### Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time contained in this proposal that provides an acceptable level of safety may be used if approved by the Manager, Atlanta ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

**Note 5:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

#### Special Flight Permit

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Appendix 1

Excerpt from an FAA Memorandum to the Director-Airworthiness and Technical Standards of ATA, dated March 20, 1992

##### "(1) Indication System:

(a) The indication system must monitor the closed, latched, and locked positions, directly.

(b) The indicator should be *amber* unless it concerns an outward opening door whose opening during takeoff could present an immediate hazard to the airplane. In that case the indicator must be *red* and located in plain view in front of the pilots. An aural warning is also advisable. A display on the master caution/warning system is also acceptable as an indicator. For the purpose of complying with this paragraph, an immediate hazard is defined as significant reduction in controllability, structural damage, or impact with other structures, engines, or controls.

(c) Loss of indication or a false indication of a closed, latched, and locked condition must be improbable.

(d) A warning indication must be provided at the door operators station that monitors the door latched and locked conditions directly, unless the operator has a visual indication that the door is fully closed and locked. For example, a vent door that monitors the door locks and can be seen from

the operators station would meet this requirement.

(2) *Means to Visually Inspect the Locking Mechanism:*

There must be a visual means of directly inspecting the locks. Where all locks are tied to a common lock shaft, a means of inspecting the locks at each end may be sufficient to meet this requirement provided no failure condition in the lock shaft would go undetected when viewing the end locks. Viewing latches may be used as an alternate to viewing locks on some installations where there are other compensating features.

(3) *Means to Prevent Pressurization:*

All doors must have provisions to prevent initiation of pressurization of the airplane to an unsafe level, if the door is not fully closed, latched and locked.

(4) *Lock Strength:*

Locks must be designed to withstand the maximum output power of the actuators and maximum expected manual operating forces treated as a limit load. Under these conditions, the door must remain closed, latched and locked.

(5) *Power Availability:*

All power to the door must be removed in flight and it must not be possible for the flight crew to restore power to the door while in flight.

(6) *Powered Lock Systems:*

For doors that have powered lock systems, it must be shown by safety analysis that inadvertent opening of the door after it is fully closed, latched and locked, is extremely improbable."

Issued in Renton, Washington, on November 4, 1999.

**D.L. Riggin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 99-29473 Filed 11-10-99; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT

### 24 CFR Part 990

[Docket No. FR-4425-N-07]

#### Negotiated Rulemaking Committee on Operating Fund Allocation; Meetings

**AGENCY:** Office of the Assistant Secretary for Public and Indian Housing, HUD.

**ACTION:** Negotiated Rulemaking Committee Meetings.

**SUMMARY:** This document announces a meeting of the Negotiated Rulemaking Committee on Operating Fund Allocation. These meetings are sponsored by HUD for the purpose of discussing and negotiating a proposed rule that would change the current method of determining the payment of operating subsidies to public housing agencies (PHAs).

**DATES:** The committee meeting will be held on November 30, December 1, and December 2, 1999.

On November 30, 1999, the meeting will begin at approximately 2:00 pm and end at approximately 6:00 pm. On December 1, 1999, the meeting will begin at approximately 9:00 am and end at approximately 5:30 pm. On December 2, 1999, the meeting will begin at approximately 9:00 am and end at approximately 4:00 pm.

**ADDRESSES:** The committee meeting will take place at the Holiday Inn On-the-Hill, 415 New Jersey Avenue, NW, Washington, DC 20001; telephone (202) 638-1616.

#### FOR FURTHER INFORMATION CONTACT:

Steve Sprague, Acting Director, Funding and Financial Management Division, Public and Indian Housing, Room 4216, U.S. Department of Housing and Urban Development, 451 Seventh Street, SW, Washington, DC 20410-0500; telephone (202) 708-1872 (this telephone number is not toll-free). Hearing or speech-impaired individuals may access this number via TTY by calling the toll-free Federal Information Relay Service at 1-800-877-8339.

#### SUPPLEMENTARY INFORMATION:

##### I. Background

The Secretary of HUD has established the Negotiated Rulemaking Advisory Committee on Operating Fund Allocation to negotiate and develop a proposed rule that would change the current method of determining the payment of operating subsidies to PHAs. The establishment of the committee is required by the Quality Housing and Work Responsibility Act of 1996 (Pub. L. 105-276, approved October 21, 1998) (the "Public Housing Reform Act"). The Public Housing Reform Act makes extensive changes to HUD's public and assisted housing programs. These changes include the establishment of an Operating Fund for the purpose of making assistance available to PHAs for the operation and management of public housing. The Public Housing Reform Act requires that the assistance to be made available from the new Operating Fund be determined using a formula developed through negotiated rulemaking procedures.

##### II. Negotiated Rulemaking Committee Meeting

This document announces a meeting of the Negotiated Rulemaking Committee on Operating Fund Allocation. The next committee meeting will take place as described in the **DATES** and **ADDRESSES** section of this document.

The agenda planned for the committee meeting includes: (1) Work group sessions to discuss various issues related to the implementation of an Operating Fund formula; (2) full committee discussions of the work-products developed by the work groups; (3) development of draft regulatory language; and (4) the scheduling of future meetings, if necessary.

The meetings will be open to the public without advance registration. Public attendance may be limited to the space available. Members of the public may make statements during the meeting, to the extent time permits, and file written statements with the committee for its consideration. Written statements should be submitted to the address listed in the **FOR FURTHER INFORMATION** section of this notice. Summaries of committee meetings will be available for public inspection and copying at the address in the same section.

Dated: November 5, 1999.

**Harold Lucas,**

*Assistant Secretary for Public and Indian Housing.*

[FR Doc. 99-29497 Filed 11-10-99; 8:45 am]

BILLING CODE 4210-33-P

## DEPARTMENT OF TRANSPORTATION

### Coast Guard

#### 33 CFR Part 117

[CGD 11-99-013]

RIN 2115-AE47

#### Drawbridge Operation Regulations: Oakland Inner Harbor Tidal Canal, CA

**AGENCY:** Coast Guard, DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** At the request of a local citizen, the Coast Guard is considering a change in operating regulations for the drawbridges crossing the Oakland Inner Harbor Tidal Canal (Oakland Estuary), between Oakland and Alameda, California. The proposal would amend the existing operating regulations to adjust the commute hour closures to coincide with current peak traffic periods.

**DATES:** Comments must be received on or before January 11, 2000.

**ADDRESSES:** Comments may be mailed or hand-delivered to: Commander (oan), Eleventh Coast Guard District, Bldg. 50-6, Coast Guard Island, Alameda, CA 94501-5100. Comments may also be faxed to: (510) 437-5836. Comments may be e-mailed to: