

What is the cost impact of the affected airplanes on the U.S. Register? We estimate that it would take approximately 10 workhours per airplane to accomplish the proposed actions, and that the average labor rate is approximately \$60 an hour. There is no cost for parts to accomplish the proposed actions.

Based on these figures, we estimate the total cost impact of the proposed AD on U.S. operators to be \$181,800, or \$600 per airplane.

Regulatory Impact

These proposed regulations would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, FAA determines that this proposed rule would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. The FAA has placed a copy of the draft regulatory evaluation prepared for this action in the Rules Docket. You may contact the Rules Docket (at the location provided under the caption **ADDRESSES**) to get a copy of this evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. FAA amends Section 39.13 by adding a new airworthiness directive (AD) to read as follows:

Raytheon Aircraft Company (Type Certificate No. A24CE formerly held by

the Beech Aircraft Corporation):

Docket No. 2000-CE-02-AD.

(a) *What airplanes are affected by this AD?*

This AD affects the following airplanes, certificated in any category:

(1) Part I of this AD: Wing fuel quantity wiring harness attachment improvement.

Model	Serial No.
1900C	UC-1 through UC-174.
1900C (C-12J)	UD-1 through UD-6.
1900D	UE-1 through UE-331.

(2) Part II of this AD: Wiggins coupling adhesive sealing.

Model	Serial No.
1900C	UC-1 through UC-174.
1900C (C-12J)	UD-1 through UD-6.
1900D	UE-1 through UE-354.

(b) *Who must comply with this AD?*

Anyone who wishes to operate any of the above airplanes on the U.S. Register must comply with this AD.

(c) *What problem does this AD address?*

The actions specified by this AD are intended to prevent the following:

(1) Part I of this AD: chafing between the wing fuel quantity wiring harness and the internal wing harness supports at each wing rib location, which could cause the fuel quantity indication to become unreliable. This could leave the flight crew without an indication of the amount of fuel the airplane has during flight; and

(2) Part II of this AD: fuel from leaking through the wiring carry-through conduit and into the wing tip or wheel well area, which could lead to a fire or explosion.

(d) *What must I do to address this problem?* To address this problem, you must accomplish the following actions:

(1) Part I of this AD: Install a spiral wrap around the wing fuel quantity wiring harness; and

(2) Part II of this AD: Apply an adhesive sealant to the Wiggins couplings on the internal fuel tank wiring carry-through conduit.

(e) *What is the compliance time of all actions of this AD?* You must accomplish all actions of this AD at whichever of the following times that occurs first:

(1) Within the next 3 calendar months after the effective date of this AD; or

(2) Within the next 600 hours time-in-service (TIS) after the effective date of this AD.

(f) *What procedures must I use to accomplish the actions required in this AD?* You must use the procedures in Raytheon Mandatory Service Bulletin No. SB 28-3299, Issued: December, 1999, to accomplish the actions of this AD.

(g) *Can I comply with this AD in any other way?* Yes.

(1) You may use an alternative method of compliance or adjust the compliance time if:

(i) Your alternative method of compliance provides an equivalent level of safety; and

(ii) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative. Submit your request through an

FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

(2) This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(h) *Where can I get information about any already-approved alternative methods of compliance?* Contact Jeff Pretz, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4153; facsimile: (316) 946-4407.

(i) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(j) *Who should I contact if I have questions regarding the service information?* Questions or technical information related to Raytheon Mandatory Service Bulletin No. SB 28-3299, Issued: December, 1999, should be directed to Raytheon Aircraft Corporation, P.O. Box 85, Wichita, Kansas 67201-0085. This service information may be examined at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on March 14, 2000.

Carolanne L. Cabrini,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-7091 Filed 3-21-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-SW-37-AD]

Airworthiness Directives; Sikorsky Aircraft Corporation (Sikorsky) Model S-76A Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive

(AD) applicable to Sikorsky Model S-76A helicopters. The AD would require inspecting at specified intervals until installing a soft-start assembly retrofit kit on the air conditioning system to prevent a continuous flow of current through the soft-start resistor. This proposal is prompted by a report of overheating of the soft-start assembly. The actions specified by the proposed AD are intended to prevent overheating of the air conditioning soft-start assembly, damage in the lower tailcone, an electrical fire, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before May 22, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-37-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. Comments may be inspected at this location between 9:00 am and 3:00 pm, Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Sikorsky Aircraft Corporation, Attn: Manager, Commercial Tech Support, 6900 Main Street, P.O. Box 9729, Stratford, Connecticut 06615-9129, phone (203) 386-7860, fax (203) 386-4703. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

FOR FURTHER INFORMATION CONTACT:

Terry Fahr, Boston Aircraft Certification Office, 12 New England Executive Park, Burlington, MA 01803, telephone (781) 238-7155, fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments,

in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 99-SW-37-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-37-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Discussion

This document proposes adopting a new AD applicable to Sikorsky Model S-76A helicopters. The AD would require inspecting the soft-start assembly at intervals not to exceed 25 hours time-in-service until installing a soft-start assembly retrofit kit on the Aero Aire Air Conditioning System, part number (P/N) S-76A-1-2, in 120 calendar days to prevent a continuous flow of current through the soft-start resistor. This proposal is prompted by a report of overheating of the air conditioning soft-start assembly. This condition, if not corrected, could cause serious secondary damage in the lower tailcone, an electrical fire, and subsequent loss of control of the helicopter.

The FAA has reviewed Sikorsky Alert Service Bulletin 76-21-4A, dated February 24, 1998 (ASB). The ASB refers operators to procedures in Aero Aire Corp. Service Bulletins 970001, Revision A, dated September 18, 1997, for inspecting the soft-start assembly, and 970002, dated December 18, 1997, for installing a soft-start assembly retrofit kit, P/N 76SB001, on the Aero Aire Air Conditioning System, P/N S-76A-1-2, on Sikorsky Model S-76A helicopters. The ASB states the procedures are necessary to prevent overheating of the air conditioning soft-start assembly that could cause serious secondary damage in the lower tailcone.

Since an unsafe condition has been identified that is likely to exist or develop on other Sikorsky Model S-76A helicopters of the same type designs, the proposed AD would require inspecting the soft start assembly at intervals not to exceed 25 hours time-in-service until

installing a soft-start control assembly retrofit kit on the Aero Aire Air Conditioning System, P/N A-76A-1-2, within 120 calendar days. The actions would be required to be accomplished in accordance with the Aero Aire service bulletins described previously.

The FAA estimates that 9 helicopters of U.S. registry would be affected by this proposed AD, that it would take approximately 3 work hours per helicopter to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Aero Aire Service Bulletin No. 97002 states that the retrofit kit will be provided at no charge. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$1620.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Sikorsky Aircraft Corporation:

Docket No. 99–SW–37–AD.

Applicability: Model S–76A helicopters with Aero Aire Air Conditioning System, part number (P/N) S–76A–1–2, modified in accordance with Supplemental Type Certificate SH4680SW, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent overheating of the air conditioning soft-start control assembly, damage in the lower tailcone, a fire, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 25 hours time-in-service (TIS) and thereafter at intervals not to exceed 25 hours TIS, inspect the soft-start control assembly in accordance with the Accomplishment Instruction, Section III, of Aero Aire Corporation Service Bulletin No. 970001, Revision A, dated September 18, 1997, except neither contact nor return of the soft-start controller unit is required.

(b) Within 120 calendar days, install a soft start assembly retrofit kit (kit), P/N 76SB001, in accordance with the Accomplishment Instructions, Section III, of Aero Aire Corporation Service Bulletin 970002, dated December 18, 1997. Installing the kit is terminating action for the requirements of this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Boston Aircraft Certification Office, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Boston Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Boston Aircraft Certification Office.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

Issued in Fort Worth, Texas, on March 15, 2000.

Eric Bries,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 00–7112 Filed 3–21–00; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Airspace Docket No. 00–AWP–1]

Proposed Modification of Class E Airspace; Willits, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to modify the Class E airspace area at Willits, CA. A revision of Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) to Runway (RWY) 16 and RWY 34 at Ells Field-Willits Municipal Airport has made this proposal necessary. Additionally controlled airspace extending upward from 700 feet or more above the surface of the earth is needed to contain aircraft executing the GPS RWY 16 and RWY 34 SIAP to Ells Field-Willits Municipal Airport. The intended effect of this proposal is to provide adequate controlled airspace for Instrument Flight Rules (IFR) operations at Ells Field-Willits Municipal Airport, Willits, CA.

DATES: Comments must be received on or before April 17, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Attn: Manager, Airspace Branch, AWP–520, Docket No. 00–AWP–1, Air Traffic Division, 15000 Aviation Boulevard, Lawndale, California 90261.

The official docket may be examined in the Office of Regional Counsel, Western-Pacific Region, Federal Aviation Administration, Room 6007, 15000 Aviation Boulevard, Lawndale, California 90261.

An informal docket may also be examined during normal business hours at the Office of the Manager, Airspace Branch, Air Traffic Division at the above address.

FOR FURTHER INFORMATION CONTACT:

Larry Tonish, Air Traffic Airspace Specialist, Airspace Branch, AWP–520, Air Traffic Division, Western-Pacific Region, Federal Aviation Administration, 15000 Aviation

Boulevard, Lawndale, California 90261, telephone (310) 725–6539.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed below. Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with the comments a self-addressed, stamped postcard on which the following statement is made: “Comments to Airspace Docket No. 00–AWP–1.” The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Airspace Branch, Air Traffic Division, 15000 Aviation Boulevard, Lawndale, California 90261, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Airspace Branch, 15000 Aviation Boulevard, Lawndale, California 90261. Communications must identify the docket number of this NPRM. Persons interested in being placed on a mailing list for future NPRM’s should also request a copy of Advisory Circular No. 11–2A, which describes the application procedures.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 by modifying the Class E airspace area at Willits, CA. A revisions to the GPS RWY 16 and RWY 34 SIAP at Ells Field-Willits Municipal Airport has made this