

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis Airbus A300 Model B2-1A, B2-1C, B4-2C, B2K-3C, B4-103, B2-203, B4-203 airplanes modified by Electronic Cable Specialists.

1. *Protection from Unwanted Effects of High-Intensity Radiated Fields (HIRF)*. Each electrical and electronic system that performs critical functions must be designed and installed to ensure that the operation and operational capability of these systems to perform critical functions are not adversely affected when the airplane is exposed to high intensity radiated fields.

2. For the purpose of these special conditions, the following definition applies: *Critical Functions*. Functions whose failure would contribute to or cause a failure condition that would prevent the continued safe flight and landing of the airplane.

Issued in Renton, Washington, March 31, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service, ANM-100.

[FR Doc. 00-8849 Filed 4-10-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99-NM-57-AD; Amendment 39-11667; AD 2000-07-13]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 757-200 and -200PF Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 757-200 and -200PF series airplanes, that requires repetitive detailed visual inspections to detect loose fuse pins in

the outboard beam attachment and forward trunnion support on the main landing gear (MLG) and to detect corrosion on the structure adjacent to the fuse pin; and corrective actions, if necessary. This amendment also requires eventual replacement of the fuse pins with new corrosion resistant steel (CRES) fuse pins, which constitutes terminating action for the repetitive inspections. This amendment is prompted by a report of damaged fuse pins caused by corrosion. The actions specified by this AD are intended to prevent corroded fuse pins, which could result in the MLG separating from the wing, and consequent damage to the airplane and possible rupture of the wing fuel tank.

DATES: Effective May 16, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 16, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207.

This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the **Federal Register**, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

James G. Rehr, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2783; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 757-200 and -200PF series airplanes was published in the **Federal Register** on October 6, 1999 (64 FR 54227). That action proposed to require repetitive detailed visual inspections to detect loose fuse pins in the outboard beam attachment and forward trunnion support on the main landing gear (MLG) and to detect corrosion on the structure adjacent to the fuse pin; and corrective actions, if necessary. That action also proposed to require eventual replacement of the fuse pins with new corrosion resistant steel (CRES) fuse pins, which would constitute terminating action for the repetitive inspections.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

Request To Change Repetitive Inspection Interval

The commenter requests that the proposed repetitive inspection interval be changed from 3,000 flight cycles or 24 months (whichever occurs first) to either 36 months or to 3,000 flight cycles or 24 months (whichever is later). The commenter states that 3,000 flight cycles does not correspond to the 24-month calendar time. The commenter adds that 36 months would more closely reflect the amount of time it takes for its airplanes to accumulate 3,000 flight cycles.

The FAA does not concur with this request. This AD addresses corrosion of the fuse pins, which is a time-related phenomenon. Therefore, the critical element of the repetitive inspection interval in this case is the amount of calendar time that passes between inspections, rather than the number of flight cycles accumulated. Therefore, the FAA finds that the repetitive inspection interval of 3,000 flight cycles or 24 months, whichever occurs first, is appropriate to address the identified unsafe condition in a timely manner and to ensure an adequate level of safety. No change to the final rule is necessary.

Revised Service Information

Since the issuance of the proposed AD, the FAA has reviewed and approved Boeing Service Bulletin 757-57A0054, Revision 1, including Appendix A, both dated December 16, 1999. (The original issue of the service bulletin is referenced in the proposal as the appropriate source of service information for accomplishment of the actions required by this AD.) Revision 1 is essentially equivalent to the original issue; however, Revision 1 adds references to optional parts and changes certain compliance recommendations. Revision 1 recommends that, if the alloy steel fuse pins have already been replaced on an airplane that was four years (or more) old, the inspection of those pins can be extended to within four years or 6,000 flight cycles after installation. A new paragraph (b) has been added to the final rule to specify the revised compliance time for those particular airplanes.

The FAA also has revised the final rule to include Revision 1 of the service bulletin as an additional source of service information. Further, the FAA has revised references to the original

issue of the service bulletin to include Appendix A, dated November 5, 1998.

Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

There are approximately 805 airplanes of the affected design in the worldwide fleet. The FAA estimates that 350 airplanes of U.S. registry will be affected by this AD.

It will take approximately 1 work hour per airplane to accomplish the required inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the inspection required by this AD on U.S. operators is estimated to be \$21,000, or \$60 per airplane, per inspection cycle.

It will take approximately 440 work hours per airplane to accomplish the required replacement, at an average labor rate of \$60 per work hour. The manufacturer has committed previously to its customers that it will bear the cost of replacement parts. As a result, the cost of those parts are not attributable to this AD. Based on these figures, the cost impact of the replacement required by this AD on U.S. operators is estimated to be \$9,240,000, or \$26,400 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has

been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-07-13 Boeing: Amendment 39-11667. Docket 99-NM-57-AD.

Applicability: Model 757-200 and -200PF series airplanes, line numbers 1 through 806 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent corroded fuse pins, which could result in the main landing gear (MLG) separating from the wing, and consequent damage to the airplane and possible rupture of the wing fuel tank, accomplish the following:

Repetitive Inspections

(a) Perform a detailed visual inspection to detect loose fuse pins in the outboard beam attachment and forward trunnion support on the MLG and to detect corrosion on the structure adjacent to the fuse pin, in accordance with Boeing Alert Service Bulletin 757-57A0054, including Appendix A, dated November 5, 1998, or Boeing Service Bulletin 757-57A0054, Revision 1, including Appendix A, dated December 16,

1999; at the later of the times specified in paragraphs (a)(1) and (a)(2) of this AD. Thereafter, repeat the inspection at intervals not to exceed 3,000 flight cycles or 24 months, whichever occurs first, until accomplishment of paragraph (d) of this AD.

(1) Prior to 4 years since date of manufacture of the airplane; or

(2) Within 3,000 flight cycles or 24 months after the effective date of this AD, whichever occurs first.

Note 2: For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(b) For airplanes on which the alloy steel fuse pins were replaced prior to the effective date of this AD: Perform the initial inspection required by paragraph (a) of this AD within 4 years or 6,000 flight cycles after installation of the pins, whichever occurs later. Thereafter, accomplish the repetitive inspections required by paragraph (a) of this AD at the time specified in that paragraph.

Corrective Action

(c) If any loose fuse pin or corrosion on the structure adjacent to the fuse pin is detected during any inspection required by paragraph (a) of this AD, prior to further flight, perform the applicable corrective action [i.e., detailed visual inspections for cracks or corrosion, repair of discrepant parts, and replacement of fuse pin] in accordance with Boeing Alert Service Bulletin 757-57A0054, including Appendix A, dated November 5, 1998, or Boeing Service Bulletin 757-57A0054, Revision 1, including Appendix A, dated December 16, 1999. Replacement of an alloy steel fuse pin with a new corrosion resistant steel (CRES) fuse pin constitutes terminating action for the repetitive inspection requirements of paragraph (a) of this AD for that fuse pin only.

Terminating Action

(d) At the next scheduled MLG overhaul, or within 12 years after the effective date of this AD, whichever occurs first, replace all alloy steel fuse pins with new CRES fuse pins in the outboard beam attachment and forward trunnion support on the MLG in accordance with Boeing Alert Service Bulletin 757-57A0054, including Appendix A, dated November 5, 1998, or Boeing Service Bulletin 757-57A0054, Revision 1, including Appendix A, dated December 16, 1999. Accomplishment of the action specified in this paragraph constitutes terminating action for the repetitive inspection requirements of this AD.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA,

Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The actions shall be done in accordance with Boeing Alert Service Bulletin 757-57A0054, including Appendix A, dated November 5, 1998, or Boeing Service Bulletin 757-57A0054, Revision 1, including Appendix A, dated December 16, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on May 16, 2000.

Issued in Renton, Washington, on April 3, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-8685 Filed 4-10-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NE-42-AD; Amendment 39-11650; AD 2000-06-09]

RIN 2120-AA64

Airworthiness Directives; Turbomeca Arrius 1A Series Turboshaft Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to Turbomeca Arrius 1A series turboshaft engines, that requires installation of module TU63, which provides a separate supply of fuel for one of the 10 main injectors of the fuel injection system. This action is prompted by reports of unexpected

power loss during test flights. The actions specified by this AD are intended to prevent unexpected power loss, which could result in an uncommanded in-flight engine shutdown, autorotation, and forced landing.

DATES: Effective June 12, 2000. The incorporation by reference of certain publications in this rule is approved by the Director of the Federal Register as of June 12, 2000.

ADDRESSES: The service information referenced in the rule may be obtained from Turbomeca, 40220 Tarnos, France; telephone (33) 05 59 64 40 00, fax (33) 05 59 64 60 80. This information may be examined at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Glorianne Niebuhr, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7132, fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to Turbomeca Turboshaft Arrius 1A series turboshaft engines was published in the **Federal Register** on December 1, 1999 (64 FR 67206). That action proposed to require installation of module TU63, which provides a separate supply of fuel for one of the 10 main injectors of the fuel injection system. That action was prompted by reports of cracked injection wheels. That condition, if not corrected, could result in an unexpected power loss, which could result in an in-flight engine shutdown, autorotation, and a forced landing.

Comments Received

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received.

Economic Analysis

There are approximately 100 engines of the affected design in the worldwide fleet. The FAA estimates that nine engines installed on aircraft of US registry would be affected by this AD, that it would take approximately 1 work hour per engine to accomplish the actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$5,500 per engine. Based on these figures, the total cost impact of the AD on US operators is estimated to be \$50,040. The

manufacturer has advised the DGAC that they may provide module TU63 at no cost to the operator, thereby substantially reducing the cost impact of this rule.

Regulatory Impact

This rule does not have federalism implications, as defined in Executive Order 13132, because it would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Accordingly, the FAA has not consulted with state authorities prior to publication of this rule.

For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-06-09 Turbomeca: Amendment 39-11650. Docket 99-NE-42-AD.

Applicability: Turbomeca Arrius 1A series turboshaft engines, installed on but not limited to Ecureuil AD355 series helicopters.

Note 1: This airworthiness directive (AD) applies to each engine identified in the preceding applicability provision, regardless