(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on June 6, 2000.

Note 5: The subject of this AD is addressed in The Direction Generale De L'Aviation Civile (France) AD 1999–459–049(A), dated December 1, 1999.

Issued in Fort Worth, Texas, on May 15, 2000.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 00–12817 Filed 5–19–00; 8:45 am] BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-SW-43-AD; Amendment 39-11738; AD 2000-10-14]

RIN 2120-AA64

Airworthiness Directives; Bell Helicopter Textron Canada (BHTC) Model 222, 222B, 222U, and 230 Helicopters

AGENCY: Federal Aviation Administration, DOT. **ACTION:** Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for BHTC Model 222, 222B, 222U, and 230 helicopters that requires inspecting each flapping bearing to yoke attachment bolt (bolt) and replacing each bolt that shows thread damage, shank wear, or corrosion pitting with an airworthy bolt. This amendment is prompted by the discovery of a fractured bolt during a post-flight inspection. The actions specified by this AD are intended to prevent a fracture of a bolt, failure of the bearing and voke interface, and subsequent loss of control of the helicopter.

EFFECTIVE DATE: June 26, 2000.

FOR FURTHER INFORMATION CONTACT:

Sharon Miles, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193–0111, telephone (817) 222–5122, fax (817) 222–5961.

SUPPLEMENTARY INFORMATION: A

proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD for BHTC Model 222, 222B, 222U, and 230 helicopters was published in the **Federal Register** on March 1, 2000 (65 FR 11006). That action proposed to require inspecting the bolts and replacing each bolt that shows thread damage, shank wear, or corrosion with an airworthy bolt.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 101 helicopters of U.S. registry will be affected by this AD, that it will take approximately 3 work hours per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$20 per bolt. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$20,200.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a ''significant rule'' under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 2000–10–14 Bell Helicopter Textron Canada: Amendment 39–11738. Docket No. 99–SW–43–AD.

Applicability: Model 222 helicopters, serial number (S/N) 47006 through 47089; Model 222B helicopters, S/N 47131 through 47156; Model 222U helicopters, S/N 47501 through 47574; and Model 230 helicopters, S/N 23001 through 23038 inclusive, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within 150 hours time-in-service, unless accomplished previously.

To prevent the fracture of a flapping bearing to yoke attachment bolt (bolt), failure of the bearing and yoke interface, and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove one bolt at a time and inspect each bolt located as shown in Figure 1.


Note 2: For main rotor hubs installed on rotorcraft, the bolts may be removed, inspected, and installed one at a time.

Note 3: Bell Helicopter Textron Canada Alert Service Bulletins 230–98–15, 222–98–83, and 222U–98–54, all dated October 12, 1998, pertain to the subject of this AD.

(i) Clean each bolt with a cloth dampened with methyl ethyl ketone, RHO SOLV756, Desoto 110, or equivalent.

- (ii) Visually inspect each bolt and discard those that have thread damage, shank wear, or corrosion.
- (iii) Apply corrosion preventative compound MIL–C–16173 GR2, or equivalent, to the shank of the bolt only.
 - (iv) Install, torque, and lockwire each bolt.
- (v) Coat each bolt head and nut with corrosion preventative compound MIL–C– 16173 GR1 or equivalent.

BILLING CODE 4910-13-U



MAIN ROTOR HUB

FIGURE 1

BILLING CODE 4910-13C

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on June 26, 2000.

Note 5: The subject of this AD is addressed in Transport Canada (Canada) AD's CF-99–12 and CF-99–13, both dated April 21, 1999.

Issued in Fort Worth, Texas, on May 15, 2000.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 00–12818 Filed 5–19–00; 8:45 am]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-ANM-11]

Establishment of Class D Airspace; Jackson, WY

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; establishment of

effective date.

SUMMARY: This action establishes the effective date for the establishment of a Class D surface area at Jackson Hole Airport, Jackson, WY. The contractual agreements to run the Airport Traffic Control Tower (ATCT) under the FAA contract tower program have now been implemented. Operations at the ATCT will commence on May 15, 2000.

EFFECTIVE DATE: The effective date of FR Doc. 00–3382 is May 15, 2000.

FOR FURTHER INFORMATION CONTACT:

Brian Durham, ANM–520.7, Federal Aviation Administration, Docket No. 99–ANM–11, 1601 Lind Avenue S.W., Renton, Washington, 98055–4056; telephone number: (425) 227–2527.

SUPPLEMENTARY INFORMATION:

History

Airspace Docket No. 99–ANM–11, published in the **Federal Register** on

February 14, 2000 (65 FR 7287), established a Class D surface airspace area at Jackson Hole Airport, Jackson, WY. This action was originally scheduled to become effective on April 20, 2000. A delay was encountered concerning the contractual requirements for the operation of the ATCT. The length of the delay was uncertain so a delay of effective date action was effected. Contractual requirements for the ATCT have been resolved, the new effective date for operations at Jackson Hole, WY is May 15, 2000.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a significant regulatory action under Executive Order 12866; (2) is not a "significant rule" under DOT regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Establishment of Effective Date

The effective date on Airspace Docket 99–ANM–11 is hereby established as May 15, 2000.

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

Issued in Seattle, Washington, on May 4, 2000.

Charles E. Davis,

Acting Manager, Air Traffic Division, Northwest Mountain Region.

[FR Doc. 00–12823 Filed 5–19–00; 8:45 am] BILLING CODE 4910–13–M

DEPARTMENT OF TRANSPORTATION

Coast Guard

33 CFR Parts 110 and 165 [CGD05-00-002] RIN 2115-AA97, AA98

OPSAIL 2000, Delaware River, Philadelphia, PA

AGENCY: Coast Guard, DOT.

ACTION: Temporary final rule.

summary: The Coast Guard is establishing temporary regulations in the Delaware River, Philadelphia, Pennsylvania for OPSAIL 2000 activities. This action is necessary to provide for the safety of life on navigable waters before, during, and after OPSAIL 2000 events. This action will restrict vessel traffic in the Delaware River between Anchorage 9 (Mantua Creek anchorage) and the Benjamin Franklin Bridge.

DATES: This rule is effective from 8 a.m. on June 22, 2000 through 4 p.m. on June 23, 2000.

ADDRESSES: Comments and material received from the public, as well as documents indicated in this preamble as being available in the docket, are part of docket CGD05–00–002 and are available for inspection or copying at Coast Guard Marine Safety Office/Group Philadelphia, One Washington Avenue, Philadelphia, Pennsylvania 19147 between 8 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

Lieutenant Junior Grade K. Codel, Coast Guard Marine Safety Office/Group Philadelphia, (215) 271–4991.

SUPPLEMENTARY INFORMATION:

Regulatory Information

On March 28, 2000, we published a notice of proposed rulemaking (NPRM) entitled OPSAIL 2000, Delaware River, Philadelphia, PA in the **Federal Register** (65 FR 16361). We received no letters commenting on the proposed rule. No public hearing was requested and none was held.

Background and Purpose

Philadelphia OPSAIL 2000, Inc., is sponsoring OPSAIL 2000 activities in the Delaware River, Philadelphia, Pennsylvania. Planned events include the arrival of a number of international Tall Ships at Anchorage 9 (Mantua Creek anchorage) on June 22, 2000 and a Parade of Sail from that anchorage, upriver to the Benjamin Franklin Bridge on June 23, 2000.

The Coast Guard anticipates a large spectator fleet for this event. Operators should expect significant vessel congestion along the parade route.

The purpose of these regulations is to promote maritime safety and protect participants and the boating public immediately prior to, during, and after the scheduled event. The regulations will establish a clear parade route for the OPSAIL 2000 vessels, provide a safety buffer around the participating vessels while they are at anchor and in