

obstructions in accordance with Raytheon Aircraft Service Bulletin SB 34-3207, dated August 1999, and perform a general visual inspection for corrosion of the drain valve.

Note 2: For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

(d) If no corrosion of the drain valves is detected, prior to further flight, perform the actions specified in either paragraph (d)(1) or (d)(2) of this AD at the time specified.

(1) Perform the leak test specified in paragraph (a) of this AD, and thereafter, repeat the leak test requirements at intervals not to exceed 300 hours time-in-service.

(2) Prior to further flight, modify any inoperative valve in accordance with Raytheon Aircraft Service Bulletin SB 34-3282, dated August 1999. Thereafter, repeat the leak test requirements of paragraph (a) of this AD at intervals not to exceed 300 hours time-in-service. Modification of ALL the drain valves constitutes terminating action for the requirement to perform repetitive leak tests.

(e) If any drain valve is corroded, prior to further flight: Inspect the connecting tubing for corrosion and replace any corroded valve or tubing with a new or serviceable valve or tubing in accordance with Raytheon Aircraft Service Bulletin SB 34-3207, dated August 1999. Accomplish the actions of paragraph (e)(1) or (e)(2) of the AD at the time specified.

(1) Prior to further flight, perform the leak test specified in paragraph (a) of this AD, and thereafter, repeat the leak test requirements of paragraph (a) of this AD at intervals not to exceed 300 hours time-in-service.

(2) Prior to further flight, modify any replaced drain valve in accordance with Raytheon Aircraft Service Bulletin SB 34-3282, dated August 1999. Thereafter, repeat the leak test requirements of paragraph (a) of this AD at intervals not to exceed 300 hours time-in-service. Modification of ALL the drain valves constitutes terminating action for the requirement to perform repetitive leak tests.

Alternative Methods of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), ACE-116W, FAA Small Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permit

(g) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on June 13, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-15420 Filed 6-16-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-SW-68-AD]

Airworthiness Directives; Eurocopter Canada Ltd. Model BO 105 LS A-3 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the superseding of an existing airworthiness directive (AD), applicable to Eurocopter Canada Ltd. Model BO 105 LS A-3 helicopters. That AD currently requires, before further flight, creating a component log card or equivalent record, and determining the calendar age and number of flights on each tension-torsion (TT) strap, and inspecting and removing, as necessary, certain unworthy TT straps. This action would establish a life limit for certain main rotor TT straps. This proposal is prompted by an accident in which a main rotor blade (blade) separated from a Eurocopter Deutschland GMBH (ECD) Model MBB-BK 117 helicopter due to fatigue failure of a TT strap. The same part-numbered TT strap is used on the Model BO 105 LS A-3 helicopters. The actions specified by this AD are intended to prevent fatigue failure of a TT strap, loss of a blade, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before August 18, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-68-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the

Rules Docket at the following address: 9-asw-adcomments@faa.gov. Comments may be inspected at the Office of the Regional Counsel between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

Charles Harrison, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5128, fax (817) 222-5961

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 99-SW-68-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 99-SW-68-AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Discussion

On October 4, 1999, the FAA issued AD 99-20-13, Amendment 39-11371 (64 FR 56156, October 18, 1999), applicable to Eurocopter Canada Ltd. Model BO 105 LS A-3 helicopters. That AD requires, before further flight, creating a component log card or

equivalent record and determining the calendar age and number of flights on each TT strap. AD 99-20-13 also requires inspecting and removing, as necessary, certain unworthy TT straps. That action was prompted by an accident in which a blade separated from an ECD Model MBB-BK 117 helicopter due to fatigue failure of a TT strap. The same part-numbered TT strap is also used on the Eurocopter Canada Ltd. Model BO 105 LS A-3 helicopters. The requirements of that AD are intended to prevent failure of a TT strap, loss of a blade, and subsequent loss of control of the helicopter.

Since the issuance of that AD, we have determined the need to establish a life limit for the TT strap. We have also determined that the graduated inspection criteria and TT strap lives specified in the current AD are no longer necessary after a life limit is established.

Eurocopter Canada issued Alert Service Bulletin BO 105 LS A-3 No. ASB-BO 105 LS-10-10, dated September 1, 1999 (ASB). The ASB describes procedures for determining the total accumulated installation time and number of flights on each TT strap. The ASB also specifies inspecting and replacing, as necessary, certain unworthy TT straps. Transport Canada Civil Aviation, the airworthiness authority for Canada, classified this ASB as mandatory and issued AD CF-99-24R1, dated September 22, 1999, applicable to the Eurocopter Canada Model BO 105 LS A-3 helicopters to ensure the continued airworthiness of these helicopters in Canada.

Since an unsafe condition has been identified on the ECD Model MBB-BK-117 that is likely to exist or develop on Eurocopter Canada Ltd., Model BO 105 LS A-3 helicopters registered in the United States, the proposed AD would require establishing a life limit for the TT straps of 120 months or 25,000 flights, whichever occurs first.

The FAA estimates that 20 helicopters of U.S. registry would be affected by this proposed AD, that it would take approximately 16 work hours per helicopter to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$10,400 per helicopter. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$227,200.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and

the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39-11371 (64 FR 56156, October 18, 1999), and by adding a new airworthiness directive (AD), to read as follows:

Eurocopter Canada Ltd.: Docket No. 99-SW-68-AD. Supersedes AD 99-20-13, Amendment 39-11371, Docket No. 99-SW-56-AD.

Applicability: Model BO 105 LS A-3 helicopters, with part number (P/N) 2604067 (Bendix) or J17322-1 (Lord) rotor tension torsion (TT) strap, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in

accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue failure of a TT strap, loss of a main rotor blade (blade), and subsequent loss of control of the helicopter, accomplish the following:

(a) Before further flight,

(1) Create a component log card or equivalent record for each TT strap.

(2) Review the history of each helicopter and TT strap. Determine the age since initial installation on any helicopter (age) and the number of flights on each TT strap. Enter both the age and the number of flights for each TT strap on the component log card or equivalent record. When the number of flights is unknown, multiply the number of hours time-in-service (TIS) by 5 to determine the number of flights. If a TT strap has been previously used at any time on Model BO-105LS A-3 "SUPER LIFTER", BO-105 CB-5, BO-105 CBS-5, BO-105 DBS-5, or any MBB-BK 117 series helicopter, multiply the total number of flights accumulated on those other models by a factor of 1.6 and then add that result to the number of flights accumulated on the helicopters affected by this AD.

(3) Remove any TT strap from service if the total hours TIS or number of flights and age cannot be determined.

(b) Remove any TT strap, P/N 2604067 or J17322-1, that has been in service 120 months since initial installation on any helicopter or accumulated 40,000 flights (a flight is a takeoff and a landing). Replace the TT strap with an airworthy TT strap.

(c) This AD revises the Airworthiness Limitations Section of the maintenance manual by establishing a life limit for the TT strap, P/N 2604067 and J17322-1, of 120 months or 40,000 flights, whichever occurs first.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(e) Special flight permits may be issued in accordance with § 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Transport Canada Civil Aviation, Canada, AD CF-99-24R1, dated September 22, 1999.

Issued in Fort Worth, Texas, on June 9, 2000.

Eric Bries,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 00-15425 Filed 6-16-00; 8:45 am]

BILLING CODE 4910-13-U

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[AZ092-002; FRL-6718-9]

Approval and Promulgation of Implementation Plans; Arizona—Maricopa County PM-10 Nonattainment Area; Serious Area Plan for Attainment of the Annual PM-10 Standard; Reopening of Comment Period

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule; reopening of comment period.

SUMMARY: EPA is reopening the comment period for its proposed action to approve provisions of the Revised MAG 1999 Serious Area Particulate Plan for PM-10 for the Maricopa County (Phoenix) Nonattainment Area, February 2000, and the control measures on which it relies, that address the annual PM-10 national ambient air quality standard. As part of this proposal, we also proposed to grant Arizona's request to extend the Clean Air Act deadline for attaining the annual PM-10 standard in the Phoenix area from 2001 to 2006 and to approve two particulate matter rules adopted by the Maricopa County Environmental Services Department and Maricopa County's Residential Woodburning Restrictions Ordinance.

DATES: Any comments on this proposal must arrive by July 3, 2000.

ADDRESSES: Mail comments to Frances Wicher, Air Planning Office (AIR-2), U.S. Environmental Protection Agency, Region IX, 75 Hawthorne Street, San Francisco, CA 94105-3901.

FOR FURTHER INFORMATION CONTACT: Frances Wicher, Air Planning Office (AIR-4), U.S. Environmental Protection Agency, Region IX, (415) 744-1248.

SUPPLEMENTARY INFORMATION: On April 13, 2000, we proposed to approve the serious area air quality plan for attainment of the annual PM-10 standard in the Phoenix, Arizona, metropolitan area. The proposed actions are based on our initial determination that this plan complies with the Clean Air Act's requirements for attainment of

the annual PM-10 standard in serious PM-10 nonattainment areas.

Specifically, we proposed to approve the following elements of the plan as they apply to the annual PM-10 standard:

- The base year emissions inventory of PM-10 sources,
- The demonstration that the plan provides for implementation of reasonably available control measures (RACM) and best available control measures (BACM),
- The demonstration that attainment of the PM-10 annual standard by the Clean Air Act deadline of December 31, 2001 is impracticable,
- The demonstration that attainment of the PM-10 annual standard will occur by the most expeditious alternative date practicable, in this case, December 31, 2006,
- The demonstration that the plan provides for reasonable further progress and quantitative milestones,
- The demonstration that the plan includes to our satisfaction the most stringent measures found in the implementation plan of another state or are achieved in practice in another state, and can feasibly be implemented in the area,
- The demonstration that major sources of PM-10 precursors such as nitrogen oxides and sulfur dioxide do not contribute significantly to violations of the annual PM-10 standard, and
- The transportation conformity budget.

We also proposed to grant Arizona's request to extend the attainment date for the annual PM-10 standard from December 31, 2001 to December 31, 2006.

Finally, we are proposing to approve Maricopa County's fugitive dust rules, Rules 310 and 301.01, and its residential woodburning restriction ordinance.

The proposal action provided a 60 day public comment period that ended on June 12, 2000. In response to a request from City of Tempe, Arizona, we are reopening the comment period for an additional 14 days.

Dated: June 10, 2000.

Felicia Marcus,

Regional Administrator, Region IX.

[FR Doc. 00-15394 Filed 6-16-00; 8:45 am]

BILLING CODE 6560-50-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Parts 52 and 81

[CA-019-FOI, FRL-6719-2]

Clean Air Act Reclassification and Finding of Failure to Implement a State Implementation Plan; California, San Joaquin Valley Nonattainment Area; Ozone

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: EPA proposes to find that the San Joaquin Valley serious ozone nonattainment area did not attain the 1-hour ozone national ambient air quality standard by November 15, 1999, the Clean Air Act's (CAA) attainment deadline for serious ozone nonattainment areas. If EPA makes final this proposed finding, the San Joaquin Valley nonattainment area will be reclassified by operation of law to severe.

EPA also proposes to find that the approved serious area ozone State Implementation Plan for the San Joaquin Valley nonattainment area has not been fully implemented. If EPA makes final this proposed nonimplementation finding, the San Joaquin Valley Unified Air Pollution Control District will have to correct the specified deficiencies within 18 months of the final finding or be subject to sanctions pursuant to section 179(b) of the CAA.

DATES: Comments on these proposed actions must be received by July 19, 2000.

ADDRESSES: Comments may be mailed to: John Ungvarsky, Planning Office (AIR-2), Air Division, EPA Region IX, 75 Hawthorne Street, San Francisco, CA 94105; ungvarsky.john@epa.gov.

Copies of the proposed rule, the technical support document for this rulemaking, and EPA policies governing nonattainment and nonimplementation findings are contained in the docket for this rulemaking. The docket is available for inspection during normal business hours at the address listed above. A copy of this proposed rule and the TSD are also available in the air programs section of EPA Region 9's website, <http://www.epa.gov/region09>.

FOR FURTHER INFORMATION CONTACT: John Ungvarsky, Planning Office (AIR-2), Air Division, EPA Region IX, 75 Hawthorne Street, San Francisco, CA 94105, (415) 744-1286.

SUPPLEMENTARY INFORMATION: