

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000-SW-03-AD; Amendment 39-11893; AD 2000-18-08]

RIN 2120-AA64

Airworthiness Directives; MD Helicopters, Inc. Model MD-900 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive

(AD) for MD Helicopters, Inc. (MDHI) Model MD-900 helicopters that requires modifying the non-rotating swashplate assembly and re-identifying it and the swashplate assembly with new part numbers. This AD also requires creating a component history card or equivalent record to track the life of the newly identified non-rotating swashplate assembly and establishing a life limit of 1800 hours time-in-service (TIS). Additionally, this AD requires inspecting and modifying, if necessary, the longitudinal drive link assembly. This AD is prompted by reports of damage to the longitudinal drive link assembly caused by the sharp inner edge of the bushing in the non-rotating swashplate assembly. The actions specified by this AD are intended to prevent damage to the longitudinal drive link, loss of control of the main rotor system, and subsequent loss of control of the helicopter.

DATES: Effective October 19, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of October 19, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax 480-891-6782, or on the web at www.mdhelicopters.com. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Greg DiLibero, Aviation Safety Engineer, FAA, Los Angeles Aircraft Certification Office, Airframe Branch, 3960

Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5231, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD for MDHI Model MD-900 helicopters was published in the **Federal Register** on June 6, 2000 (65 FR 35869). That action proposed to require modifying the non-rotating swashplate and re-identifying it and the swashplate assembly with new part numbers. Also proposed were creating or modifying the existing component history card or equivalent record to track the life of the newly identified non-rotating swashplate assembly and establishing a life limit of 1800 hours TIS. In addition, that action proposed inspecting and modifying, if necessary, the longitudinal drive link assembly.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 28 helicopters of U.S. registry will be affected by this AD, that it will take approximately 2 work hours per helicopter to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$1164 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$35,952.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2000-18-08 MD Helicopters Inc.:

Amendment 39-11893. Docket No. 2000-SW-03-AD.

Applicability: Model MD-900 helicopters, serial numbers 0008 through 0068, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent damage to the longitudinal drive link, loss of control of the main rotor system, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within the next 100 hours time-in-service (TIS) or 3 months, whichever occurs first:

(1) Modify the non-rotating swashplate assembly, part number (P/N) 900C2010192-111, in accordance with the Accomplishment Instructions, paragraphs 2.A.(1). and 2.A.(2)., of MD Helicopters (MDHI) Service Bulletin SB900-071, dated January 10, 2000 (SB).

(2) Re-identify the swashplate assembly, P/N 900C1010004-125, as P/N 900C1010004-127, and the non-rotating swashplate assembly, P/N 900C2010192-111, as P/N 900C2010192-113 using contrasting color permanent ink. When the ink is dry, apply varnish over the P/N.

(3) Create or modify the existing component history card or equivalent record to track the life of the non-rotating

swashplate assembly, P/N 900C2010192-113. Include the hours TIS accumulated when P/N 900C2010192-113 was identified as P/N 900C2010192-111.

(4) Visually and dye-penetrant inspect the longitudinal drive link assembly, P/N 900C2010212-101, for gouging and cracking in accordance with the Accomplishment Instructions, paragraph 2.B.(1). and 2.B.(2). of the SB except that returning scrap parts to MDHI is not required by this AD.

(i) If a crack is found, before further flight, replace the longitudinal drive link assembly, P/N 900C2010212-101, with an airworthy longitudinal drive link assembly.

(ii) If gouging is found, modify the longitudinal drive link assembly, P/N 900C2010212-101, in accordance with the Accomplishment Instructions, paragraph 2.B.(3). of the SB.

(b) This AD revises the Airworthiness Limitations

Section of the applicable maintenance manual by establishing a retirement life of 1800 hours TIS for the non-rotating swashplate assembly, P/N 900C2010192-113.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Los Angeles Aircraft Certification Office.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(d) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(e) The modifications and inspections shall be done in accordance with the Accomplishment Instructions, paragraphs 2.A.(1) and 2.A.(2); 2.B.(1), and 2.B.(2), and 2.B.(3) of MD Helicopters Service Bulletin SB900-071, dated January 10, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9734, telephone 1-800-388-3378, fax 480-891-6782, or on the web at www.mdhelicopters.com. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on October 19, 2000.

Issued in Fort Worth, Texas, on September 1, 2000.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 00-23206 Filed 9-13-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-287-AD; Amendment 39-11896; AD 2000-18-11]

RIN 2120-AA64

Airworthiness Directives; Israel Aircraft Industries, Ltd., Model 1125 Westwind Astra Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Israel Aircraft Industries, Ltd., Model 1125 Westwind Astra series airplanes. This action requires revising the Airplane Flight Manual to provide the flight crew with operational guidance under certain failure conditions and a limitation not to engage the long-range navigation system during takeoff, approach, or landing. This action is necessary to prevent the loss of primary attitude and directional gyros, which relate position information to the flight crew. This action is intended to address the identified unsafe condition.

DATES: Effective September 29, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of September 29, 2000.

Comments for inclusion in the Rules Docket must be received on or before October 16, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-287-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarccomment@faa.gov. Comments sent

via fax or the Internet must contain "Docket No. 2000-NM-287-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Galaxy Aerospace Corporation, One Galaxy Way, Fort Worth Alliance Airport, Fort Worth, Texas 76177. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: The Civil Aviation Administration of Israel (CAAI), which is the airworthiness authority for Israel, notified the FAA that an unsafe condition may exist on certain Israel Aircraft Industries, Ltd., Model 1125 Westwind Astra series airplanes. The CAAI reported a recent incident in which failure of a single alternating current (AC) inverter resulted in the simultaneous in-flight failure of all primary attitude and directional gyros on board.

On these airplanes, AC power to the whole avionics system is supplied by the left inverter when the long-range navigation/flight management system is selected for navigation. When this inverter fails, all screens of the electronic flight instrument system (EFIS) could lose power. In addition, internal gyro fuses could burn out. The system to detect AC power failure is activated when the voltage drops below 65 volts. There are several inverter failure modes that could cause the voltage to drop to slightly less than 100 volts; in that case, the avionics systems could fail, but no AC power failure would be announced. The CAAI advises that proper and timely corrective action (transferring all the loads to the alternate inverter) would alleviate the problem.

In the subject incident, a single inverter failed and all EFIS screens temporarily lost power. Both primary gyros failed due to internal fuse burnout caused by low voltage. The flight crew was left with use of only the standby attitude indicator and magnetic compass to control the airplane. AC power was