

production area may initially ship sweet onions on or after September 1. The Committee also estimates that the revised Form No. 1 will continue to take approximately 25 minutes to complete. With only two handlers submitting reports on October 31 and possibly again on November 30, for example, the total additional burden on the industry for the information reporting requirements for sweet onions shipped on or after September 1 would approximate 100 minutes per year. Thus, while this rule will impose some additional reporting requirements, the burden is currently approved under OMB No. 0581-0078 by the Office of Management and Budget in accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. Chapter 35). The Agricultural Marketing Service has notified the Office of Management and Budget of this change in burden.

As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies. In addition, the Department has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

The Committee's meeting was widely publicized throughout the Walla Walla sweet onion industry and all interested persons were invited to attend the meeting and participate in Committee deliberations on all issues. Like all Committee meetings, the August 15, 2000, meeting was a public meeting and all entities, both large and small, were able to express views on this issue. Further, interested persons are invited to submit information on the regulatory and informational impacts of this action on small businesses.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ams.usda.gov/fv/moab.html>. Any questions about the compliance guide should be sent to Jay Guerber at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

After consideration of all relevant material presented, including the Committee's recommendation, and other information, it is found that this interim final rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

This rule invites comments on providing handlers more time to meet assessment and reporting requirements for Walla Walla sweet onions handled during the period September 1 through May 31 of each fiscal period. Any

comments received will be considered prior to finalization of this rule.

Pursuant to 5 U.S.C. 553, it is also found and determined upon good cause that it is impracticable, unnecessary, and contrary to the public interest to give preliminary notice prior to putting this rule into effect and that good cause exists for not postponing the effective date of this rule until 30 days after publication in the **Federal Register** because: (1) This rule provides relaxed assessment and reporting requirements for Walla Walla sweet onions handled during the period September 1 through May 31 of each fiscal period; (2) this rule needs to be effective promptly so handlers will be able to market their sweet onions on or after September 1, 2000, and be in compliance with order requirements; (3) the Committee unanimously recommended this change at a public meeting, and interested parties had an opportunity to provide input; and (4) this rule provides a 60-day comment period, and any comments received will be considered prior to finalization of this rule.

List of Subjects in 7 CFR Part 956

Marketing agreements, Onions, Reporting and recordkeeping requirements.

For the reasons set forth in the preamble, 7 CFR part 956 is amended as follows:

PART 956—SWEET ONIONS GROWN IN THE WALLA WALLA VALLEY OF SOUTHEAST WASHINGTON AND NORTHEAST OREGON

1. The authority citation for 7 CFR part 956 continues to read as follows:

Authority: 7 U.S.C. 601-674.

2. Section 956.142 is revised to read as follows:

§ 956.142 Interest charges.

For Walla Walla Sweet Onions handled prior to September 1, the Committee shall impose an interest charge on any handler who fails to pay his or her annual assessments within thirty (30) days of the due date of September 1. For Walla Walla Sweet Onions handled during the period September 1 through May 31 of each fiscal period, the Committee shall impose an interest charge on any handler who fails to pay his or her assessments within thirty (30) days of the last day of the month in which such shipments are made. The interest charge shall be 1½ percent of the unpaid assessment balance. In the event the handler fails to pay the delinquent assessment amount within 60 days following the due date, the 1½ percent

interest charge shall be applied monthly thereafter to the unpaid balance, including any accumulated interest. Any amount paid by a handler as an assessment, including any charges imposed pursuant to this paragraph, shall be credited when the payment is received in the Committee office.

3. In § 956.180, the introductory text is revised to read as follows:

§ 956.180 Reports.

Each handler shall furnish to the Committee a report containing the information in paragraphs (a), (b), and (c) of this section, except that gift box and roadside stand sales shall be exempt from paragraph (b) of this section: *Provided*, That for Walla Walla Sweet Onions handled prior to September 1, such report shall be furnished to the Committee by September 1, and that for Walla Walla Sweet Onions handled during the period September 1 through May 31 of each fiscal period, such report shall be furnished to the Committee no later than thirty (30) days after the end of the month in which such sweet onions were handled:

* * * * *

Dated: October 10, 2000.

Robert C. Keeney,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 00-26487 Filed 10-13-00; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000-NM-312-AD; Amendment 39-11928; AD 2000-20-03 R1]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2B19 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment revises an existing airworthiness directive (AD), applicable to certain Bombardier Model CL-600-2B19 series airplanes, that currently requires installation of shields for the aileron quadrants in the wheel bay of the main landing gear (MLG). This amendment revises the compliance time for the requirements of that AD. The actions specified in this AD are intended to prevent accumulation of

water, ice, or slush on the aileron quadrants and control cable pulleys in the wheel bay of the MLG, which could freeze and result in reduced controllability of the airplane.

DATES: Effective October 2, 2000.

The incorporation by reference of certain publications listed in the regulations was approved previously by the Director of the Federal Register as of October 2, 2000 (65 FR 57944, September 27, 2000).

Comments for inclusion in the Rules Docket must be received on or before October 23, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-312-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-312-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Daniel Parrillo, Aerospace Engineer, Airframe and Propulsion Branch, ANE-172, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7505; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION: On September 22, 2000, the FAA issued AD 2000-20-03, amendment 39-11914 (65 FR 57944, September 27, 2000), applicable to certain Bombardier Model CL-600-2B19 series airplanes, to require installation of shields for the aileron quadrants and control cable

pulleys in the wheel bay of the main landing gear (MLG). The actions required by that AD are intended to prevent accumulation of water, ice, or slush on the aileron quadrants and control cable pulleys in the wheel bay of the MLG, which could freeze and result in reduced controllability of the airplane.

Actions Since Issuance of Previous Rule

Since the issuance of that AD, the FAA has determined that an incorrect compliance time for the installation of the shields was inadvertently specified in AD 2000-20-03. Instead of "within 30 days after the effective date of this AD," the compliance time should read "within 45 days after the effective date of this AD."

FAA's Findings

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, Transport Canada Civil Aviation (TCAA) has kept the FAA informed of the situation described above. The FAA has examined the findings of the TCAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD revises AD 2000-20-03 to require installation of shields for the aileron quadrants in the wheel bay of the MLG within 45 days after October 2, 2000 (the effective date of AD 2000-20-03).

Determination of Rule's Effective Date

Since a situation still exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause still exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons

are invited to comment on this rule by submitting such written data, views, or arguments as they may desire.

Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-312-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined

further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39–11914 (65 FR 57944, September 27, 2000), and by adding a new airworthiness directive (AD), amendment 39–11928, to read as follows:

2000–20–03 R1 Bombardier, Inc. (Formerly Canadair): Amendment 39–11928. Docket 2000–NM–312–AD. Revises AD 2000–20–03, Amendment 39–11914.

Applicability: Model CL–600–2B19 series airplanes, serial numbers 7003 through 7323 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent reduced controllability of the airplane due to an accumulation of water, ice, and slush on the aileron quadrants and control cable pulleys in the wheel bay of the

main landing gear (MLG); accomplish the following:

Installation

(a) Within 45 days after October 2, 2000 (the effective date of AD 2000–20–03), install splash shields in the wheel bay of the MLG in accordance with Bombardier Service Bulletin 601R–27–104, dated October 15, 1999.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The installation shall be done in accordance with Bombardier Service Bulletin 601R–27–104, dated October 15, 1999. This incorporation by reference was approved previously by the Director of the **Federal Register** as of October 2, 2000 (65 FR 57944, September 27, 2000). Copies may be obtained from Bombardier Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive CF–2000–28, dated August 28, 2000.

Effective Date

(e) This amendment becomes effective on October 2, 2000.

Issued in Renton, Washington, on October 4, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00–26092 Filed 10–13–00; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–SW–25–AD; Amendment 39–11931; AD 2000–20–19]

RIN 2120–AA64

Airworthiness Directives; Eurocopter France Model AS–350B, BA, B1, B2, B3, C, D, and D1, and AS–355E, F, F1, F2 and N Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD) for Eurocopter France Model AS–350B, BA, B1, B2, C, D, and D1, and AS–355E, F, F1, and F2 helicopters. That AD currently requires inspections of the main rotor head components, the main gearbox (MGB) suspension bars, and the ground resonance prevention system components. This amendment requires those same inspections, but would also apply to Model AS–350B3 and AS–355N helicopters. This amendment is prompted by the inadvertent omission of those model helicopters from the previous AD. The actions specified by this AD are intended to prevent ground resonance due to reduced structural stiffness, which could lead to failure of a main rotor head or MGB suspension component and subsequent loss of control of the helicopter.

DATES: Effective November 20, 2000.

The incorporation by reference of certain publications listed in the regulations was approved previously by the Director of the Federal Register as of May 23, 2000 (65 FR 20721, April 18, 2000).

ADDRESSES: The service information referenced in this AD may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053–4005, telephone (972) 641–3460, fax (972) 641–3527. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Jim Grigg, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222–5490, fax (817) 222–5961.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal