

order provisions. Therefore, this rule places the decision with the individual handler as to whether the costs are outweighed by the benefits.

Individual seasons and different periods during the same season can present a fair amount of variability in production and size. This change provides handlers with some additional flexibility when packing for size to allow handlers to make some adjustments in order to maximize returns and to service customer demand. This rule will provide the opportunity for handlers to make adjustments based on market conditions. This should have a positive effect on returns.

The Committee recommended these changes to improve the marketing of Florida tomatoes. The opportunities and benefits of this rule are expected to be equally available to all tomato handlers and growers regardless of their size of operation. This action will have a beneficial impact on producers and handlers since it will allow tomato handlers more flexibility in making tomatoes available to meet consumer needs consistent with crop and market conditions.

The Committee discussed alternatives to this recommendation, including leaving the regulations as currently issued. All Committee members agreed that this change would be helpful in improving pack appearance and in providing handlers some additional flexibility. Therefore, the Committee voted to make this change rather than leave the size designation for 6x6 unchanged.

This rule will not impose any additional reporting or recordkeeping requirements on either small or large tomato handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies.

In addition, the Department has not identified any relevant Federal rules that duplicate, overlap or conflict with this rule.

Further, the Committee's meeting was widely publicized throughout the tomato industry and all interested persons were invited to attend the meeting and participate in Committee deliberations. Like all Committee meetings, the September 8, 2000, meeting was a public meeting and all entities, both large and small, were able to express their views on this issue.

Also, the Committee has a number of appointed subcommittees to review certain issues and make recommendations to the Committee.

The Committee's Marketing Subcommittee met on August 21, 2000, and discussed this issue in detail. That meeting was also a public meeting and both large and small entities were able to participate and express their views. Finally, interested persons are invited to submit information on the regulatory and informational impacts of this action on small businesses.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ams.usda.gov/fv/moab.html>. Any questions about the compliance guide should be sent to Jay Guerber at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

This rule invites comments on a change to the size requirements currently prescribed under the Florida tomato marketing order. Any comments received will be considered prior to finalization of this rule.

After consideration of all relevant material presented, including the Committee's recommendation, and other information, it is found that this interim final rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

Pursuant to 5 U.S.C. 553, it is also found and determined upon good cause that it is impracticable, unnecessary, and contrary to the public interest to give preliminary notice prior to putting this rule into effect and that good cause exists for not postponing the effective date of this rule until 30 days after publication in the **Federal Register** because: (1) The regulatory period for the 2000–2001 shipping season began October 10 and the changes should be in place as close to the beginning of the season as possible; (2) Florida tomato handlers are aware of this action which was unanimously recommended by the Committee at a public meeting and interested parties had an opportunity to provide input; (3) the packing flexibility afforded handlers can be utilized as they see fit, they will not need additional time to comply with the regulation; and (4) this rule provides a 60-day comment period and any comments received will be considered prior to finalization of this rule.

List of Subjects in 7 CFR Part 966

Marketing agreements, Reporting and recordkeeping requirements, Tomatoes.

For the reasons set forth in the preamble, 7 CFR part 966 is amended as follows:

PART 966—TOMATOES GROWN IN FLORIDA

1. The authority citation for 7 CFR part 966 continues to read as follows:

Authority: 7 U.S.C. 601–674.

§ 966.323 [Amended]

2. In § 966.323, the table to paragraph (a)(2)(i) is amended by removing “2^{27/32}” and adding “2^{29/32}” in its place.

Dated: October 31, 2000.

Robert C. Keeney,

Deputy Administrator, Fruit and Vegetable Programs.

[FR Doc. 00–28332 Filed 11–3–00; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–NM–130–AD; Amendment 39–11954; AD 2000–22–08]

RIN 2120–AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB–120 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain EMBRAER Model EMB–120 series airplanes, that requires inspections of certain components, and corrective action, if necessary. The actions specified by this AD are intended to prevent deterioration and deformation of the mass-balance weights of the aileron, which could affect the surface balance of the aileron and result in loss of aileron control and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective December 11, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 11, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket,

1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Satish Lall, Aerospace Engineer, Airframe and Propulsion Branch, ACE-117A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30337-2748; telephone (770) 703-6082; fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Model EMB-120 series airplanes, was published in the **Federal Register** on July 17, 2000 (65 FR 44013). That action proposed to require inspections of certain components, and corrective action, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that approximately 28 U.S.-registered airplanes will be required to measure the gap between the mass-balance weights and aileron hinge attachment. It will take approximately 2 work hours per airplane to accomplish the required measurement, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the required measurement on U.S. operators is estimated to be \$3,360, or \$120 per airplane, per inspection cycle.

The FAA estimates that approximately 230 U.S.-registered airplanes will be required to inspect the mass-balance weights to detect any cavity, hole, or delamination. It will take approximately 8 work hours per airplane to accomplish the required inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the required inspection on U.S. operators is estimated to be \$110,400, or \$480 per airplane.

The cost impact figures discussed above are based on assumptions that no

operator has yet accomplished any of the requirements of this AD action, and that no operator will accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

2000-22-08 Empresa Brasileira de Aeronautica S.A. (Embraer):
Amendment 39-11954. Docket 2000-NM-130-AD.

Applicability: Model EMB-120 series airplanes, serial numbers 120-0001 through 120-0333 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent deterioration and deformation of the mass-balance weights of the aileron, which could affect the surface balance of the aileron and result in loss of aileron control and consequent reduced controllability of the airplane, accomplish the following:

Measurement of Clearance and Corrective Actions

(a) For airplanes having serial numbers 120-0291, 120-0294, and 120-0296 through 120-0333 inclusive: Within 150 flight hours after the effective date of this AD, measure the clearance between the aileron mass-balance weights and attach fittings on the left and right sides of the airplane, in accordance with PART I of the Accomplishment Instructions of EMBRAER Service Bulletin 120-27-0077, Change No. 01, dated October 24, 1997.

(1) If the clearance is within the acceptable limits described in the service bulletin, thereafter, repeat the measurement at intervals not to exceed 1,000 flight hours until the actions required by paragraph (b) of this AD have been accomplished.

(2) If the clearance is outside the acceptable limits described in the service bulletin, prior to further flight, replace the affected mass-balance weight with a new, improved mass-balance weight, in accordance with PART III of the Accomplishment Instructions of the service bulletin. Such replacement terminates the requirement to accomplish paragraph (b) of this AD.

Detailed Visual Inspection and Follow-On Actions

(b) For all airplanes: Within 2,000 flight hours after the effective date of this AD, perform a one-time detailed visual inspection of the aileron mass-balance weights to detect any cavity, hole, or delamination, in accordance with PART II of the Accomplishment Instructions of EMBRAER Service Bulletin 120-27-0077, Change No. 01, dated October 24, 1997. Such inspection constitutes terminating action for the

repetitive inspections required by paragraph (a)(1) of this AD for airplanes subject to paragraph (a) of this AD.

(1) If no cavity, hole, or delamination is detected: Prior to further flight, perform a one-time detailed visual inspection to detect white powder on the surface of the mass-balance weights, in accordance with PART II of the Accomplishment Instructions of the service bulletin. If any white powder is found, remove the white powder in accordance with the service bulletin.

(2) If any cavity, hole, or delamination is found, prior to further flight, replace the affected mass-balance weight with a new, improved mass-balance weight, in accordance with PART III of the Accomplishment Instructions of the service bulletin.

Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(e) The actions shall be done in accordance with EMBRAER Service Bulletin 120-27-0077, Change No. 01, dated October 24, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sao Jose dos Campos—SP, Brazil. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Brazilian airworthiness directive 98-01-02, dated January 15, 1998.

Effective Date

(f) This amendment becomes effective on December 11, 2000.

Issued in Renton, Washington, on October 24, 2000.

Donald L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-27789 Filed 11-3-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-348-AD; Amendment 39-11955; AD 2000-22-09]

RIN 2120-AA64

Airworthiness Directives; British Aerospace (Jetstream) Model 4101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain British Aerospace (Jetstream) Model 4101 airplanes, that requires inspection of certain components, and corrective action, if necessary. The actions specified by this AD are intended to prevent loosening of the locknut holding the main landing gear (MLG) piston to the ramrod, which could result in detachment of the MLG piston from the ramrod and loss of hydraulic control of the MLG. This action is intended to address the identified unsafe condition.

DATES: Effective December 11, 2000.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of December 11, 2000.

ADDRESSES: The service information referenced in this AD may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Norman B. Martenson, Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain British Aerospace (Jetstream) Model 4101 airplanes was published in the **Federal Register** on August 29, 2000 (65 FR 52371). That action proposed to require inspection of certain components, and corrective action, if necessary.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 59 airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the inspection, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the inspection on U.S. operators is estimated to be \$3,540, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT