

■ Accordingly, part 212 of chapter I of title 8 of the Code of Federal Regulations is amended as follows:

PART 212—DOCUMENTARY REQUIREMENTS: NONIMMIGRANTS; WAIVERS; ADMISSION OF CERTAIN INADMISSIBLE ALIENS; PAROLE

■ 1. The authority citation for part 212 is revised to read as follows:

Authority: 8 U.S.C. 1101 and note, 1102, 1103, 1182 and note, 1184, 1187, 1225, 1226, 1227, 1228; Public Law 107–296, 116 Stat 2135 (6 U.S.C. 1, *et seq.*); 8 CFR part 2.

■ 2. Section 212.5 is amended by:

- a. Revising paragraph (a);
 - b. Revising paragraph (b)(3) introductory text;
 - c. Revising paragraph (b)(5);
 - d. Revising paragraph (c);
 - e. Revising paragraph (d) introductory text;
 - f. Revising paragraph (d) (1); and by
 - g. Revising paragraph (e)(2)(i).
- The revisions read as follows:

§ 212.5 Parole of aliens into the United States.

(a) The authority of the Secretary to continue an alien in custody or grant parole under section 212(d)(5)(A) of the Act shall be exercised by the Assistant Commissioner, Office of Field Operations; Director, Detention and Removal; directors of field operations; port directors; special agents in charge; deputy special agents in charge; associate special agents in charge; assistant special agents in charge; resident agents in charge; field office directors; deputy field office directors; chief patrol agents; district directors for services; and those other officials as may be designated in writing, subject to the parole and detention authority of the Secretary or his designees. The Secretary or his designees may invoke, in the exercise of discretion, the authority under section 212(d)(5)(A) of the Act.

(b) * * *

(3) Aliens who are defined as juveniles in § 236.3(a) of this chapter. The Director, Detention and Removal; directors of field operations; field office directors; deputy field office directors; or chief patrol agents shall follow the guidelines set forth in § 236.3(a) of this chapter and paragraphs (b)(3)(i) through (iii) of this section in determining under what conditions a juvenile should be paroled from detention:

* * * * *

(5) Aliens whose continued detention is not in the public interest as determined by those officials identified in paragraph (a) of this section.

(c) In the case of all other arriving aliens, except those detained under

§ 235.3(b) or (c) of this chapter and paragraph (b) of this section, those officials listed in paragraph (a) of this section may, after review of the individual case, parole into the United States temporarily in accordance with section 212(d)(5)(A) of the Act, any alien applicant for admission, under such terms and conditions, including those set forth in paragraph (d) of this section, as he or she may deem appropriate. An alien who arrives at a port-of-entry and applies for parole into the United States for the sole purpose of seeking adjustment of status under section 245A of the Act, without benefit of advance authorization as described in paragraph (f) of this section shall be denied parole and detained for removal in accordance with the provisions of § 235.3(b) or (c) of this chapter. An alien seeking to enter the United States for the sole purpose of applying for adjustment of status under section 210 of the Act shall be denied parole and detained for removal under § 235.3(b) or (c) of this chapter, unless the alien has been recommended for approval of such application for adjustment by a consular officer at an Overseas Processing Office.

(d) *Conditions.* In any case where an alien is paroled under paragraph (b) or (c) of this section, those officials listed in paragraph (a) of this section may require reasonable assurances that the alien will appear at all hearings and/or depart the United States when required to do so. Not all factors listed need be present for parole to be exercised. Those officials should apply reasonable discretion. The consideration of all relevant factors includes:

(1) The giving of an undertaking by the applicant, counsel, or a sponsor to ensure appearances or departure, and a bond may be required on Form I–352 in such amount as may be deemed appropriate;

* * * * *

(e) * * *

(2)(i) *On notice.* In cases not covered by paragraph (e)(1) of this section, upon accomplishment of the purpose for which parole was authorized or when in the opinion of one of the officials listed in paragraph (a) of this section, neither humanitarian reasons nor public benefit warrants the continued presence of the alien in the United States, parole shall be terminated upon written notice to the alien and he or she shall be restored to the status that he or she had at the time of parole. When a charging document is served on the alien, the charging document will constitute written notice of termination of parole, unless otherwise specified. Any further inspection or hearing shall be

conducted under section 235 or 240 of the Act and this chapter, or any order of exclusion, deportation, or removal previously entered shall be executed. If the exclusion, deportation, or removal order cannot be executed within a reasonable time, the alien shall again be released on parole unless in the opinion of the official listed in paragraph (a) of this section the public interest requires that the alien be continued in custody.

* * * * *

Dated: June 3, 2003.

Tom Ridge,

Secretary of Homeland Security.

[FR Doc. 03–14932 Filed 6–10–03; 2:49 pm]

BILLING CODE 4410–10–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NM–98–AD; Amendment 39–13191; AD 2003–12–06]

RIN 2120–AA64

Airworthiness Directives; Bombardier Model CL–600–2C10 (Regional Jet Series 700 & 701) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL–600–2C10 (Regional Jet Series 700 & 701) series airplanes. This action requires a revision to the Airplane Flight Manual (AFM) to prohibit operations into known or forecast icing conditions under certain conditions. This action also requires an inspection to detect damage of the wing anti-ice (WAI) ducts to determine if the external shrouds of the ducts are open or cracked, and replacement of any damaged duct with a new duct or a duct with the same part number. This action also provides for an optional terminating action for the AFM revision and inspection. This action is necessary to prevent the WAI ducts from collapsing, cracking, or rupturing, which could cause leakage of hot air in the under-floor pressurized area of the fuselage when the anti-ice system is turned on. Such leakage of hot air results in insufficient heat for the anti-ice system and consequent aerodynamic degradation. This action is intended to address the identified unsafe condition.

DATES: Effective June 27, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of June 27, 2003.

Comments for inclusion in the Rules Docket must be received on or before July 14, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-98-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-iarcomment@faa.gov. Comments sent via the Internet must contain "Docket No. 2003-NM-98-AD" in the subject line and need not be submitted in triplicate. Comments sent via fax or the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in this AD may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Parrillo, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7505; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION: Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain Bombardier Model CL-600-2C10 (Regional Jet Series 700 & 701) series airplanes. TCCA advises that it has received several reports of failure of the wing anti-ice (WAI) ducts. Failure analysis indicates that the WAI ducts, located in the under-floor pressurized area, can collapse due to insufficient strength for the applied differential pressure. This condition, if not corrected, could result in cracks or

rupture of the WAI ducts, and consequent leakage of hot air in the under-floor pressurized area of the fuselage when the anti-ice system is turned on. Such leakage of hot air results in insufficient heat for the anti-ice system and consequent aerodynamic degradation.

TCCA Airworthiness Directive

TCCA issued airworthiness directive CF-2003-07, effective on March 25, 2003, to ensure the continued airworthiness of these airplanes in Canada. The Canadian airworthiness directive requires an amendment to the Master Minimum Equipment List (MMEL)/Minimum Equipment List (MEL) to prohibit operations into known or forecast icing conditions under certain conditions, and accomplishment of the actions specified in CRJ 700/900 Series Regional Jet (Bombardier) Alert Service Bulletin A670BA-30-007 (described below).

Explanation of Relevant Service Information

The manufacturer has issued CRJ 700/900 Series Regional Jet (Bombardier) Alert Service Bulletin A670BA-30-007, Revision A, dated April 15, 2003. The alert service bulletin describes procedures for a detailed inspection to detect damage of the four WAI ducts and to determine if the external shrouds of the ducts are open or cracked, and replacement of any damaged duct with a new duct or a duct with the same part number (P/N) that is free of any dent or other handling damage. The alert service bulletin also describes procedures for eventual replacement of all four WAI ducts with new ducts.

TCCA classified this service bulletin as mandatory and issued Canadian airworthiness directive CF-2003-07 to ensure the continued airworthiness of these airplanes in Canada.

FAA's Conclusions

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCCA has kept the FAA informed of the situation described above. The FAA has examined the findings of TCCA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, this AD is being issued to prevent the WAI ducts from collapsing, cracking, or rupturing, and consequent leakage of hot air in the under-floor pressurized area of the fuselage when the anti-ice system is turned on. Such leakage of hot air results in insufficient heat for the anti-ice system and consequent aerodynamic degradation. This AD requires a revision to the Limitations Section of the Airplane Flight Manual (AFM) to prohibit operations into known or forecast icing conditions under certain conditions. This AD also requires accomplishment of the actions specified in the service bulletin described previously, except as described below.

Differences Between This AD and Service Bulletin/Canadian Airworthiness Directive

Operators should note that, although the service bulletin specifies that the manufacturer may be contacted for disposition of certain conditions of the surrounding equipment and structure of the external shroud of the WAI ducts, this AD requires the inspection of those areas to be accomplished per a method approved by either the FAA or TCCA (or its delegated agent). In light of the type of inspection that will be required to address the identified unsafe condition, and in consonance with existing bilateral airworthiness agreements, the FAA has determined that, for this AD, an inspection approved by either the FAA or TCAA (or its delegated agent) will be acceptable for compliance with this AD.

The Canadian airworthiness directive requires an amendment to the MMEL/MEL to prohibit operations into known or forecast icing conditions under certain conditions. In the United States, the MMEL and the MEL are not developed or approved as part of the certification requirements of the airplane. Therefore, in order to prohibit operations into known or forecast icing conditions under certain conditions, the FAA has determined that it is necessary to address the identified unsafe condition by requiring a revision to the Limitations Section of the AFM. In accordance with 14 CFR 121.628(b)(2), this AD has the effect of overriding the MMEL/MEL, so it has the same effect as the Canadian airworthiness directive.

Interim Action

The FAA is considering further rulemaking action to supersede this AD to require replacement of all four WAI ducts with new ducts per CRJ 700/900 Series Regional Jet (Bombardier) Alert Service Bulletin A670BA-30-007, which would terminate the inspection and AFM requirements of this AD. However, the planned compliance time for the replacement is sufficiently long so that notice and opportunity for prior public comment will be practicable.

Changes to 14 CFR Part 39/Effect on the AD

On July 10, 2002, the FAA issued a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's airworthiness directives system. The regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance (AMOC). Because we have now included this material in part 39, only the office authorized to approved AMOCs is identified in each individual AD.

Determination of Rule's Effective Date

Since a situation exists that requires the immediate adoption of this regulation, it is found that notice and opportunity for prior public comment hereon are impracticable, and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

Although this action is in the form of a final rule that involves requirements affecting flight safety and, thus, was not preceded by notice and an opportunity for public comment, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a

request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2003-NM-98-AD." The postcard will be date stamped and returned to the commenter.

Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration

amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. Section 39.13 is amended by adding the following new airworthiness directive:

2003-12-06 Bombardier, Inc. (Formerly Canadair): Amendment 39-13191. Docket 2003-NM-98-AD.

Applicability: Model CL-600-2C10 (Regional Jet Series 700 & 701) series airplanes, serial numbers 10004 through 10119 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent the wing anti-ice (WAI) ducts from collapsing, cracking, or rupturing, consequent leakage of hot air in the under-floor pressurized area of the fuselage when the anti-ice system is turned on, insufficient heat for the anti-ice system, and aerodynamic degradation, accomplish the following:

Referenced Service Information

(a) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of CRJ 700/900 Series Regional Jet (Bombardier) Alert Service Bulletin A670BA-30-007, Revision A, dated April 15, 2003, including Appendices A and B, dated March 18, 2003.

Airplane Flight Manual (AFM) Revision

(b) Within 48 hours after the effective date of this AD, revise the Limitations Section of the CRJ 700 AFM to include the following (this may be accomplished by inserting a copy of this AD into the AFM):

"1. Anti-Ice Bleed Leak Detection Controller (AILC) Channels (see Note 1):

Flight with "WING A/I FAULT" status message on the engine indication and crew alerting system (EICAS) is not authorized, except as follows:

One may be inoperative as indicated by "WING A/I FAULT" status message on EICAS provided:

(a) Wing Anti-Ice switch is selected OFF, and

(b) Operations are not conducted into known or forecast icing conditions.

2. Wing/Fuselage Anti-Ice Bleed Leak Detection Loops (see Note 1):

Flight with Wing/Fuselage Anti-Ice Bleed Leak Detection Loops inoperative is not authorized, except as follows:

One loop (A or B) may be inoperative provided:

(a) Wing Anti-Ice switch is selected OFF, and

(b) Operations are not conducted into known or forecast icing conditions.

Note 1: This limitation supersedes the Master Minimum Equipment List (MMEL)."

Detailed Inspection and Corrective Actions if Necessary

(c) Within 150 flight hours after the effective date of this AD, do a detailed inspection to detect damage of the four WAI ducts and to determine if the external shrouds of the WAI ducts are open or cracked, per the alert service bulletin.

(1) If no discrepancy is found, no further action is required by this AD.

(2) If any external shroud of a WAI duct is found open or cracked, before further flight, inspect the surrounding equipment and structure per a method approved by the Manager, New York Aircraft Certification Office, FAA, or Transport Canada Civil Aviation (TCCA) (or its delegated agent).

(3) If any damaged WAI duct is found, before further flight, replace the WAI duct with a new duct or a duct with the same part number (P/N) that is free of any dent, crease, or other handling damage, per the alert service bulletin.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Optional Terminating Action

(d) Replacement of all four WAI ducts with new ducts having P/N GG670-80504-5 or -6, or P/N GG670-80312-3 or -4, as applicable, per the service bulletin, terminates the requirements of this AD. After doing the replacement, the AFM revision required by paragraph (b) of this AD may be removed.

Reporting Requirement

(e) Submit a report of the results of the inspection required by paragraph (c) of this AD per the alert service bulletin specified in paragraph (c) of this AD. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(1) If the inspection was done after the effective date of this AD: Submit the report within 14 days after the inspection.

(2) If the inspection was accomplished prior to the effective date of this AD: Submit the report within 14 days after the effective date of this AD.

Alternative Methods of Compliance

(f) In accordance with 14 CFR 39.19, the Manager, New York ACO, FAA, is authorized to approve alternative methods of compliance for this AD.

Incorporation by Reference

(g) Unless otherwise specified in this AD, the actions must be done per CRJ 700/900 Series Regional Jet (Bombardier) Alert Service Bulletin A670BA-30-007, Revision A, dated April 15, 2003, including

Appendices A and B, dated March 18, 2003. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 2: The subject of this AD is addressed in Canadian airworthiness directive CF-2003-07, effective on March 25, 2003.

Effective Date

(h) This amendment becomes effective on June 27, 2003.

Issued in Renton, Washington, on June 5, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-14676 Filed 6-11-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 97-ANE-06-AD; Amendment 39-13190; AD 2003-12-05]

RIN 2120-AA64

Airworthiness Directives; McCauley Propeller Systems 1A103/TCM Series Propellers

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD), that is applicable to McCauley Propeller Systems 1A103/TCM series propellers. That AD currently requires an initial inspection for cracks in the propeller hub in accordance with a dye penetrant inspection procedure, replacement of propellers with cracks that do not meet acceptable limits, rework of propellers with cracks that meet acceptable limits, and repetitive inspections of all affected propellers. This amendment allows additional rework operations to be performed at more than one bolt hole location. This amendment is prompted by the need to clarify the requirement to use a steel backing plate and Mylar gasket during installation of the propeller, and to relax the replacement requirements. The actions specified in

the proposed AD are intended to prevent propeller separation due to hub fatigue cracking, which can result in loss of control of the airplane.

DATES: Effective July 17, 2003. The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of July 17, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from McCauley Propeller Systems, 3535 McCauley Drive, PO Drawer 5053, Vandalia, OH 45377-5053; telephone: 937-890-5246; fax: 937-890-6001. This information may be examined, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Timothy Smyth, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, Small Airplane Directorate, 2350 East Devon Avenue, Room 323, Des Plaines, IL 60018; telephone: (847) 294-7132; fax: (847) 294-7834.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 97-06-16, Amendment 39-9973 (62 FR 16064, April 4, 1997), which is applicable to McCauley Propeller Systems 1A103/TCM series propellers, was published in the **Federal Register** on September 27, 2002 (67 FR 61043). That action proposed to require:

- An initial inspection for cracks in the propeller hub in accordance with a dye penetrant inspection procedure.
- Replacement of propellers with cracks that do not meet acceptable limits.
- Rework of propellers with cracks that meet acceptable limits.
- Painting of the propeller hub before installation of the propeller.
- Repetitive inspections of all affected propellers.
- Installation of a steel backing plate and Mylar gasket during installation of the propeller.

These actions must be done in accordance with McCauley Propeller Systems Alert Service Bulletin (ASB) 221C, dated September 7, 1999.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

One commenter agrees with the NPRM as written.