

operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus: Docket 2002–NM–119–AD.

Applicability: Model A300 B4–600 series airplanes, Model A300 B4–600R series airplanes, Model A300 C4–605R Variant F airplanes, and Model A300 F4–605R airplanes; as listed in Airbus Service Bulletin A300–28–6066, dated November 8, 2000; and Airbus Service Bulletin A300–28–6070, Revision 1, dated March 22, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent short circuits between 115 Volts Alternating Current (VAC) wiring and certain fuel system electrical wire runs with subsequent overheating of the cadensicon sensor thermistor or fuel level sensor, which could be great enough to ignite fuel vapors in the fuel tank and cause an explosion, accomplish the following:

Modification

(a) Within 4,000 flight hours after the effective date of this AD, modify elements of the electrical wiring to separate the cadensicon wiring from the 115 VAC wiring, in accordance with Airbus Service Bulletin A300–28–6066, dated November 8, 2000.

(b) Within 4,000 flight hours after the effective date of this AD, modify elements of the electrical wiring to separate the 115 VAC supply wiring of the fuel gauging system, in accordance with Airbus Service Bulletin A300–28–6070, Revision 1, dated March 22, 2002.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, is authorized to approve alternative methods of compliance for this AD.

Note: The subject of this AD is addressed in French airworthiness directives 2002–172(B) and 2002–171(B), both dated April 3, 2002.

Issued in Renton, Washington, on August 29, 2003.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–22704 Filed 9–5–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2000–NM–192–AD]

RIN 2120–AA64

Airworthiness Directives; McDonnell Douglas Model MD–11 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM)

that proposed a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD–11 series airplanes. That action would have required an inspection to detect arcing damage of the electrical cables leading to the terminal strips and surrounding structure in the wing areas inboard of the pylons 1 and 3 and the No. 2 engine; and corrective actions, if necessary. That action also would have required revising the cable connection stackup of the terminal strips on the wings and No. 2 engine. Since the issuance of the NPRM, the Federal Aviation Administration (FAA) has received new data indicating that the identified unsafe condition specified in NPRM does not exist on the affected airplanes. Accordingly, the proposed rule is withdrawn.

FOR FURTHER INFORMATION CONTACT:

Brett Portwood, Aerospace Engineer, Systems and Equipment Branch, ANM–130L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (562) 627–5350; fax (562) 627–5210.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model MD–11 series airplanes, was published in the **Federal Register** as a Notice of Proposed Rulemaking (NPRM) on February 20, 2001 (66 FR 10844). The proposed rule would have required an inspection to detect arcing damage of the electrical cables leading to the terminal strips and surrounding structure in the wing areas inboard of the pylons 1 and 3 and the No. 2 engine; and corrective actions, if necessary. The proposed rule also would have required revising the cable connection stackup of the terminal strips on the wings and No. 2 engine. That action was prompted by an incident in which arcing occurred between the power feeder cables and support bracket of the terminal strips on a McDonnell Douglas Model MD–11 series airplane. The proposed actions were intended to prevent arcing damage to the terminal strips and damage to the adjacent structure in the wing areas inboard of the pylons 1 and 3 and the No. 2 engine, which could result in a fire inboard of the pylons 1 and 3 or the No. 2 engine.

Actions That Occurred Since the NPRM Was Issued

Since the issuance of that NPRM, the results of an FAA analysis have revealed that there is a lack of materials and fuels in the vicinity of the terminal strips and

surrounding structure in the wing areas inboard of the pylons 1 and 3 and the No. 2 engine, and that a fire in that area is highly unlikely. The probable result is that a power feed arc in the pylon area would typically damage and pit the feeder line and, perhaps, damage and pit the terminal bracket at the chafing location. As the arc current level increases, the electrical power system differential fault protection would detect this condition and disconnect electrical loads supplied to that particular feeder. In addition, the flightcrew would be alerted to this condition, allowing the operator/owner to correct the problem at the next maintenance interval. On the basis of this analysis, we have determined that the potential arcing on the terminal strips in the wing areas inboard of the pylons 1 and 3 and the No. 2 engine does not constitute an unsafe condition.

FAA's Conclusions

Upon further consideration, we have determined that the identified unsafe condition does not exist on the affected airplanes. Accordingly, the proposed rule is hereby withdrawn.

Withdrawal of this NPRM constitutes only such action, and does not preclude the agency from issuing another action in the future, nor does it commit the agency to any course of action in the future.

Regulatory Impact

Since this action only withdraws a notice of proposed rulemaking, it is neither a proposed nor a final rule and therefore is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, the notice of proposed rulemaking, Docket 2000–NM–192–AD, published in the **Federal Register** on February 20, 2001 (66 FR 10844), is withdrawn.

Issued in Renton, Washington, on August 29, 2003.

Vi L. Lipski,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. 03–22707 Filed 9–5–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002–NM–336–AD]

RIN 2120–AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB–135 and –145 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Supplemental notice of proposed rulemaking; reopening of comment period.

SUMMARY: This document revises an earlier proposed airworthiness directive (AD), applicable to certain EMBRAER Model EMB–135 and –145 series airplanes, that would have required operators to inspect the pitot-true air temperature (TAT) relays and the full authority digital engine control (FADEC) electronic interface resistor modules to detect contamination; perform corrective action if necessary; clean the relay/connector pins and sockets; modify the seal between the cockpit console panels and the storm window; and/or install a new protective frame (protective sheets) at the cockpit relay supports. This new action revises the applicability of the proposed rule to add airplanes. The actions specified by this new proposed AD are intended to detect and correct oxidation of the pitot-TAT relay, which could result in increased resistance and overheating of the relay and consequent smoke in the cockpit; and to detect and correct oxidation of the FADEC electronic interface resistor modules, which could result in in-flight uncommanded engine power roll back to idle. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by October 3, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2002–NM–336–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain “Docket No. 2002–NM–336–AD” in the

subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343–CEP 12.225, Sao Jose dos Campos—SP, Brazil. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–1175; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to