

the decision to accept or reject such offer must be provided to the previous owner within 15 days of receipt of the offer.

(2) If the System institution accepts the offer to lease the property at less than the appraised rental value, it must notify the previous owner and lease the property to the previous owner.

(3) If the institution rejects the offer, the System institution must notify the previous owner of this decision. The previous owner has 15 days after receipt of the notice in which to agree to lease the property at such rate or under such terms and conditions. The System institution may not lease the property to any other person:

(i) At a rate equal to or less than that offered by the previous owner; or

(ii) On different terms and conditions than those that were extended to the previous owner without first informing the previous owner by certified mail and providing an opportunity to lease the property at such rate or under such terms and conditions.

§ 617.7620 What should the System institution do when it decides to sell acquired agricultural real estate at a public auction?

System institutions electing to sell or lease acquired agricultural real estate or a portion of it through a public auction, competitive bidding process, or other similar public offering:

(a) Must notify the previous owner, by certified mail, of the availability of such property. The notice must contain the minimum amount, if any, required to qualify a bid as acceptable to the institution and any terms or conditions to which such sale or lease will be subject;

(b) If the System institution receives two or more qualified bids in the same amount, the bids are the highest received, and one of the qualified bids is from the previous owner, the institution must accept the offer by the previous owner; and

(c) The System institution must not discriminate against a previous owner in these proceedings.

§ 617.7625 Whom should the System institution notify?

Each certified mail notice requirement in this section is fully satisfied by mailing one certified mail notice to the last known address of the previous owner or owners.

§ 617.7630 Does this Federal requirement affect any state property laws?

The rights provided under section 4.36 of the Act and this section do not affect any right of first refusal under the

law of the state in which the property is located.

Dated: January 29, 2003.

Jeanette C. Brinkley,
Secretary, Farm Credit Administration Board.
[FR Doc. 03-2506 Filed 2-3-03; 8:45 am]
BILLING CODE 6705-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-178-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747SP, and 747SR Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747-100, 747SP, and 747SR series airplanes. This proposal would require repetitive inspections to find fatigue cracking between the seal ribs of the front spar web of the wing, and repair of cracked structure. This proposal also provides for an optional modification of a certain area. This action is necessary to find and fix such fatigue cracking, which could result in fuel leakage into the area of the inboard engines, and consequent increased risk of a fire. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by March 21, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-178-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-178-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, PO Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT:

Tamara L. Anderson, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Transport Airplane Directorate, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6421; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-178-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-178-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received a report indicating that an operator found a 24-inch crack in the front spar web of the right wing between front spar station inboard (FSSI) 637 through 662 on a Boeing Model 747-100 series airplane having accumulated 14,830 total flight cycles and 85,116 total flight hours. Metallurgical analysis of the cracked section of the web revealed three cracks originating from a hole common to a rib post located on the front spar at FSSI 656 (wing station 642). The cracks were initiated by fatigue at the hole and were spread by fatigue for a short distance; then the cracks separated by a combination of fatigue and ductile separation. The cracks resulted in a fuel leak which was found after post-flight inspection revealed fire damage to the exhaust sleeve of the inboard engine turbine. Another operator reported finding a crack in the web at approximately FSSI 694, just outboard of a web section recently replaced per AD 99-10-09, amendment 39-11162 (64 FR 25194, June 15, 1999). Such fatigue cracking, if not found and fixed, could result in fuel leakage into the area of the inboard engines and consequent increased risk of a fire.

Related Rulemaking

This AD is related to the following rulemaking actions, which require the actions in the related service bulletins specified in Boeing Special Attention Service Bulletin 747-57-2313, Revision 1, including Appendices A and B, dated February 21, 2002:

- AD 95-10-16, amendment 39-9233 (60 FR 27008, June 21, 1995). That AD references Boeing Alert Service Bulletin 747-54A2159, dated November 3, 1994, as the appropriate source of service information for accomplishment of the modification of the nacelle strut and wing structure. That AD is applicable to certain Boeing Model 747 series airplanes equipped with Pratt & Whitney Model JT9D series engines (excluding Model JT9D-70 engines). The AD requires modification of the nacelle strut and wing structure, inspections and checks to detect discrepancies, and correction of discrepancies. The modification specified in the AD also constitutes terminating action for the repetitive

inspections required by certain other ADs, including AD 98-15-21, amendment 39-10672 (63 FR 39487, July 23, 1998), which references Boeing Service Bulletin 747-57A2266 as the appropriate source of service information for accomplishment of the specified actions; and AD 90-17-18, amendment 39-6702 (55 FR 33279, August 15, 1990), which references Boeing Service Bulletin 747-57A2259 as the appropriate source of service information for accomplishment of the specified actions.

- AD 99-10-09, amendment 39-11162. That AD references Boeing Service Bulletin 747-57A2303, Revision 1, dated September 25, 1997, as the appropriate source of service information for accomplishment of the actions specified. That AD is applicable to certain Boeing Model 747-100, -200, and 747-SP series airplanes and military type E-4B airplanes, and requires repetitive inspections to detect cracking of the wing front spar web, and repair of cracked structure. That AD also provides for optional terminating action for the repetitive inspections.

Explanation of Relevant Service Information

We have reviewed and approved Boeing Special Attention Service Bulletin 747-57-2313, Revision 1, including Appendices A and B, dated February 21, 2002. The service bulletin describes procedures for repetitive inspections to find fatigue cracking of the front spar web of the wing, and repair of cracked structure, as follows:

- For airplanes on which the optional modification specified in AD 99-10-09 has not been done, the affected area is divided into two zones (A and B). Zone A is the area previously modified per the requirements specified in AD 95-10-16 for the wing front spar; and Zone B is the remaining area between FSSI 628 and 711.

- For airplanes on which the optional modification specified in AD 99-10-09 has been done, the affected area is divided into three zones (A, B, and C). Zone A is the area previously modified per the requirements specified in AD 95-10-16 for the wing front spar, and is not affected by the requirements specified in AD 99-10-09; Zone C is the area affected by AD 99-10-09; and Zone B is the remaining area between FSSI 628 and 711.

- The inspection specified in Part 1 of the service bulletin is for Zone A, B, or C, as applicable. If no cracking is found, the inspections are repeated at the intervals specified in Figure 1 of the service bulletin. If cracking is found, the inspections are also repeated at the

intervals specified in Figure 1 after the cracking is repaired.

- The modification specified in Part 2 of the service bulletin is for Zone B only. The modification includes removing the existing fasteners of the web to chord, web to rib post, and web to stiffener; straightening the holes; and doing an open-hole rotating probe high frequency eddy current inspection for cracking in the web. If no cracking is found, the service bulletin directs oversizing the holes and installing tension type fasteners in the holes; if any cracking is found, the service bulletin specifies contacting the manufacturer for repair instructions.

The service bulletin recommends prior or concurrent accomplishment of Boeing Service Bulletins 747-57A2259, 747-57A2266, and 747-54A2159. Those service bulletins are referenced in the related rulemaking described previously.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described above, except as discussed below.

Difference Between Service Information and Proposed Rule

Although the service bulletin specifies that the manufacturer may be contacted for disposition of certain repair conditions, this proposal would require the repair of those conditions to be done per a method approved by the FAA, or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the FAA to make such findings.

Cost Impact

There are approximately 109 airplanes of the affected design in the worldwide fleet. The FAA estimates that 59 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 25 work hours per airplane to accomplish the proposed inspections, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$88,500, or \$1,500 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD

action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Should an operator elect to do the optional modification of Zone B, it would take approximately 480 work hours to accomplish at an average labor rate of \$60 per work hour. Parts cost would be approximately \$16,652. Based on these figures, the cost impact of the proposed modification is estimated to be \$45,452 per airplane.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

BOEING: Docket 2001–NM–178–AD.

Applicability: Model 747–100, 747SP, and 747SR series airplanes, as listed in Boeing Special Attention Service Bulletin 747–57–2313, Revision 1, including Appendices A and B, dated February 21, 2002; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To find and fix fatigue cracking between the seal ribs of the front spar web of the wing, which could result in fuel leakage into the area of the inboard engines, and consequent increased risk of a fire; accomplish the following:

Compliance Times

(a) Where the compliance times in the service bulletin specify a compliance time interval calculated "after the release of this service bulletin," this AD requires compliance within the interval specified in the service bulletin "after the effective date of this AD." In addition, where the compliance time for the initial inspection in Tables 1 through 3 of Figure 1 of the service bulletin specifies "flight hours," this AD requires a compliance time of "total flight hours."

Initial and Repetitive Inspections

(b) Do detailed, high frequency eddy current and ultrasonic inspections to find cracking of the front spar web of the wing as specified in paragraphs (b)(1) and (b)(2) of this AD, per the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–57–2313, Revision 1, including Appendices A and B, dated February 21, 2002.

(1) Do the applicable initial or post-modification inspection at the times specified in the inspections in Tables 1 through 3 of Figure 1 of the Accomplishment Instructions or Appendix A of the service bulletin.

(2) After doing the applicable initial or post-modification inspection specified in paragraph (b)(1) of this AD: Repeat that inspection within the applicable intervals specified in Tables 1 through 3 of Figure 1 of the Accomplishment Instructions or Appendix A of the service bulletin.

Repair

(c) If any cracking is found during any inspection required by this AD: Before further flight, repair per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved, the approval must specifically reference this AD.

Optional Modification

(d) Accomplishment of the modification of Zone B per Part 2 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 747–57–2313, Revision 1, including Appendices A and B, dated February 21, 2002, would extend the threshold recommended in Tables 1 through 3 of Figure 1 of the Accomplishment Instructions or Appendix A of the service bulletin for the repetitive inspections of Zone B, to the new threshold specified in Tables 1 through 3 of Figure 1 of the service bulletin.

Previously Accomplished Inspections and Modifications

(e) Inspections and modifications done before the effective date of this AD per Boeing Special Attention Service Bulletin 747–57–2313, including Appendices A and B, dated April 19, 2001, are considered acceptable for compliance with the applicable actions specified in this AD.

Note 2: Boeing Special Attention Service Bulletin 747–57–2313, Revision 1, including Appendices A and B, dated February 21, 2002, recommends prior or concurrent accomplishment of Boeing Service Bulletins 747–57A2259; 747–57A2266; and 747–54A2159. The modifications in those service bulletins are required by AD 95–10–16, amendment 39–9233.

Alternative Methods of Compliance

(f) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

Special Flight Permit

(g) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on January 29, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-2495 Filed 2-3-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-AWA-2]

RIN 2120-AA66

Proposed Modification of the Tampa Class B Airspace Area; FL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This action withdraws a notice of proposed rulemaking (NPRM) published in the **Federal Register** on November 18, 1998. In that action, the FAA proposed to modify the Tampa, FL, Class B airspace area by renaming two existing subareas, configure the boundaries of three subareas, and create an additional subarea. However, the conditions that prompted the development of the proposal did not fully materialize. Therefore, the FAA has determined that withdrawal of the proposed rule is warranted in order to best serve aviation safety and the efficient management of aircraft operations in the Tampa terminal area.

DATES: This withdrawal is made as of February 4, 2003.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace and Rules Division, ATA-400, Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

The basis for the proposed modification of the Tampa Class B airspace area was a 1991 recommendation by the Defense Base Realignment and Closure Commission that MacDill Air Force Base (AFB) be closed and the 56th Tactical Fighter Wing located there be deactivated. That action prompted the FAA to conduct a staff study of the Tampa terminal area to determine if any modifications to the Tampa Class B airspace area were warranted. The staff study resulted in a recommendation to raise the floor of Class B airspace over Tampa Bay south

of MacDill AFB to the boundary of Sarasota-Bradenton Class C airspace area from the current 1,200 feet mean sea level (MSL) to 3,000 feet MSL. The airspace floor in that area was established at 1,200 feet MSL in 1990 as an additional safety measure between civil aircraft operating in the vicinity of Tampa International Airport and the F-16 fighter aircraft based at MacDill AFB.

In 1995, however, the Commission amended its findings and recommended that MacDill AFB remain open and continue to host an active flying mission. The F-16 unit, formerly assigned to the base, was replaced by an air refueling wing comprised of KC-135 heavy jet aircraft.

The decision that MacDill AFB would remain open with a continuing flying mission was acknowledged in the NPRM. The FAA elected to proceed with the proposal to modify the Class B airspace area because it was anticipated that the termination of the fighter mission would lead to fewer operations at MacDill AFB, as well as less high-speed, low-altitude military aircraft operations over Tampa Bay.

It is with this in mind that, on November 18, 1998, the FAA published an NPRM in the **Federal Register** (63 FR 64016) proposing to amend 14 CFR part 71 to modify the Tampa, Florida Class B airspace area. Interested parties were invited to participate in the rulemaking process by submitting written data, views, or arguments regarding the proposal.

The FAA received a total of nine comments on the proposal. The Aircraft Owners and Pilots Association (AOPA) wrote in support of the proposal stating that the elimination of Class B airspace below 3,000 feet MSL as proposed would result in more efficient use of the airspace by segments of the general aviation community. The United States Air Force (USAF) submitted two comments opposing the proposal. The USAF was concerned that the proposal to raise the floor of Class B airspace area, from 1,200 feet MSL to 3,000 feet MSL, south of MacDill AFB would pose a hazard to flight operations in the area. Another commenter also opposed the proposal stating that the existing 1,200-foot floor is necessary based on the amount of aircraft operations in the area, the number of airports located within a few miles of each other, and weather conditions over Tampa Bay that reduce long-range visibility much of the time. Five other commenters supported the proposal stating that the changes would benefit general aviation.

As a result of the NPRM, however, questions arose regarding the impacts of the change on the efficiency and safety

of operations in the Tampa terminal area if the floor of Class B airspace area was raised from the current 1,200 feet MSL to 3,000 feet MSL, as proposed. These concerns were based on the fact that MacDill AFB did not close and that the airspace over Tampa Bay encompasses high density traffic operating to and from six airports in the vicinity.

Airspace Study

In January 2002, the FAA conducted a thorough review of the proposed Tampa, FL, Class B airspace area modifications to better evaluate these concerns. The review included an analysis of traffic flows within the Tampa Approach Control airspace, with special emphasis given to that segment of Class B airspace from MacDill AFB south to the boundary of the Sarasota-Bradenton Class C airspace area. In its review, the FAA considered the following information: MacDill AFB remains open and hosts a variety of aircraft operations including KC-135 heavy jets, aviation elements of the National Oceanic and Atmospheric Administration and the Department of Agriculture, and routine transient aircraft. In addition, fighter aircraft from other locations frequently deploy to, and operate from, MacDill AFB to conduct training in the nearby off-shore and over-land military special use airspace areas. The MacDill AFB aircraft operations count for the year 2001 totaled more than 30,000 operations, contributing to the overall complexity of airspace in the Tampa terminal area.

The Tampa Class B airspace area was configured to provide Class B airspace protection for air carrier aircraft serving the Tampa International Airport (the primary airport) and to enhance the management of air traffic operations in this high-density terminal area. Air traffic control makes extensive use of the Class B airspace segment over Tampa Bay to ensure the safe and efficient management of aircraft operations in the terminal area. Raising the floor of Class B airspace to 3,000 feet MSL, as proposed, would place a significant portion of traffic in the Tampa terminal area outside of Class B airspace during critical phases of flight. For example, arrivals to Runways 36L/36R at Tampa International Airport are descended to 2,600 feet MSL to be at the approach intercept altitude. This altitude is 1,000 feet above the approach intercept altitude of 1,600 feet MSL used for Runway 04 at MacDill AFB. This altitude difference provides the required instrument flight rules separation between Tampa and MacDill arrivals. Aircraft departing Runway 22