

unlikely to occur and takes appropriate steps to safeguard the interests of affected members.

- An employee of the credit union has obtained unauthorized access to sensitive member information maintained in either paper or electronic form;
- A cyber intruder has broken into an credit union's unencrypted database that contains sensitive member information;
- Computer equipment such as a laptop computer, floppy disk, CD-ROM, or other electronic media containing sensitive member information has been lost or stolen;
- A credit union has not properly disposed of member records containing sensitive member information; or
- The credit union's third party service provider has experienced any of the incidents described above, in connection with the credit union's sensitive member information.

Examples of When Notice Is Not Expected

A credit union is not expected to give notice when it becomes aware of an incident of unauthorized access to member information, and the credit union, after an appropriate investigation, can reasonably conclude that misuse of the information is unlikely to occur and takes appropriate steps to safeguard the interests of affected members. For example, a credit union would not need to notify affected members in connection with the following incidents:

- The credit union is able to retrieve sensitive member information that has been stolen, and reasonably concludes, based upon its investigation of the incident, that it has done so before the information has been copied, misused or transferred to another person who could misuse it;
- The credit union determines that sensitive member information was improperly disposed of, but can establish that the information was not retrieved or used before it was destroyed;
- A hacker accessed files that contain only member names and addresses; or
- A laptop computer containing sensitive member information is lost, but the data is encrypted and may only be accessed with a secure token or similarly secure access device.

[FR Doc. 03-27312 Filed 10-29-03; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-38-AD]

RIN 2120-AA64

Airworthiness Directives; Pacific Aerospace Corporation, Ltd. Models FU24-954 and FU24A-954 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Pacific Aerospace Corporation, Ltd. Models FU24-954 and FU24A-954 airplanes. This proposed AD would require you to perform repetitive detailed visual inspections of the forward vertical fin base for cracks. If any cracks or discrepancies are found, you must repair the structure before further flight and notify the FAA. This proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for New Zealand. We are issuing this proposed AD to detect and correct cracks in the vertical fin base, which could result in loss of the fin and loss of aircraft control.

DATES: We must receive any comments on this proposed AD by December 8, 2003.

ADDRESSES: Use one of the following to submit comments on this proposed AD:

- *By mail:* FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-38-AD, 901 Locust, Room 506, Kansas City, Missouri 64106.
- *By fax:* (816) 329-3771.
- *By e-mail:* 9-ACE-7-

Docket@faa.gov. Comments sent electronically must contain "Docket No. 2003-CE-38-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-38-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, Small Airplane Directorate, 901 Locust, Room 302, Kansas City, MO 64106; telephone: 816-329-4146; facsimile: 816-329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

How Do I Comment on This Proposed AD?

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-38-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed,

stamped postcard with the docket number written on it. We will date-stamp your postcard and mail it back to you.

Are There Any Specific Portions of This Proposed AD I Should Pay Attention to?

We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. If you contact us through a nonwritten communication and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend this proposed AD in light of those comments and contacts.

Discussion

What Events Have Caused This Proposed AD?

The CAA, which is the airworthiness authority for New Zealand, notified the FAA of an unsafe condition that may exist on all Pacific Aerospace Corporation, Ltd. Models FU24-954 and FU24A-954 airplanes. The CAA reports a recent fatal accident where the aircraft's fin separated in flight. Initial investigation of this accident indicates that the forward fin structure failed from fatigue cracks that were concealed beneath the rubber abrasion protection fitted to the fin.

What Are the Consequences if the Condition Is Not Corrected?

Failure to detect cracks in the vertical fin base could result in loss of the fin and loss of aircraft control.

Is There Service Information That Applies to This Subject?

No.

What Action Did the CAA Take?

The CAA issued New Zealand AD Number DCA/FU24/173, dated 23 April 2002, in order to ensure the continued airworthiness of these airplanes in New Zealand.

Was This in Accordance With the Bilateral Airworthiness Agreement?

These Pacific Aerospace Corporation, Ltd. Models FU24-954 and FU24A-954 airplanes are manufactured in New Zealand and are type-certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement.

Per this bilateral airworthiness agreement, the CAA has kept us

informed of the situation described above.

FAA's Determination and Requirements of This Proposed AD

What Has FAA Decided?

We have examined the CAA's findings, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since the unsafe condition described previously is likely to exist or develop on other Pacific Aerospace Corporation, Ltd. Models FU24-954 and FU24A-954 airplanes of the same type design that are registered in the United States, we are proposing AD action to detect cracks

in the vertical fin base, which could result in loss of the fin and loss of aircraft control.

What Would This Proposed AD Require?

This proposed AD would require you to perform repetitive detailed visual inspections of the forward vertical fin base for cracks. If any cracks or discrepancies are found, you must repair the structure before further flight and notify the FAA.

How Does the Revision to 14 CFR Part 39 Affect This Proposed AD?

On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. This regulation now includes

material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How Many Airplanes Would This Proposed AD Impact?

We estimate that this proposed AD affects 2 airplanes in the U.S. registry.

What Would Be the Cost Impact of This Proposed AD on Owners/Operators of the Affected Airplanes?

We estimate the following costs to accomplish this proposed inspection:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
8 work hours est. \$60 per hour = \$480 ..	No parts needed for inspection	\$480 per airplane	\$960

The FAA has no method of determining the number of repairs each owner/operator would incur over the life of each of the affected airplanes based on the results of the proposed inspections. We have no way of determining the number of airplanes that may need such repair. The extent of damage may vary on each airplane.

Regulatory Findings

Would This Proposed AD Impact Various Entities?

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

Would This Proposed AD Involve a Significant Rule or Regulatory Action?

For the reasons discussed above, I certify that this proposed AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposed AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-38-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Pacific Aerospace Corporation, Ltd.: Docket No. 2003-CE-38-AD.

When Is the Last Date I Can Submit Comments on This Proposed AD?

(a) We must receive comments on this proposed airworthiness directive (AD) by December 8, 2003.

What Other ADs Are Affected by This Action?

(b) None.

What Airplanes Are Affected by This AD?

(c) This AD affects the following airplane models and serial numbers that are certificated in any category: Pacific Aerospace Corporation, Ltd. Models FU24-954 and FU24A-954 airplanes, all serial numbers, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of a recent fatal accident where the aircraft's fin separated in flight. The actions specified in this AD are intended to detect and correct cracks in the vertical fin base, which could result in loss of the fin or loss of control of the aircraft.

What Must I Do To Address This Problem?

(e) To address this problem, you must accomplish the following:

Actions	Compliance	Procedures
(1) Perform visual inspection of the forward area at the base of the fin for cracks.	Initially inspect within the next 50 hours time-in-service (TIS) after the effective date of this AD. Repetitively inspect every 100 hours TIS thereafter.	Inspect from the bottom of the fin up to the first external strap, paying particular attention to the skin in the area of the rivets that join the fin skin to bulkhead, part number (P/N) 242305, and aft to the first vertical lap joint. To do this inspection, remove any rubber abrasion protection that is fitted in this area, including any sealant. You must also remove the fin leading edge fairing, P/N 242321.
(2) Repair any cracks that are found during the inspection.	Prior to further flight after doing any inspection required in paragraph (e)(1) of this AD.	Obtain FAA-approved repair scheme from manufacturer and notify FAA at the address and phone number in paragraph (f) of this AD.

What About Alternative Methods of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.13. Send your request to the Manager, FAA, Small Airplane Directorate. For information on any already approved alternative methods of compliance, contact Karl Schletzbaum, Aerospace Engineer, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, MO 64106; telephone: 816-329-4146; facsimile: 816-329-4090.

Is There Other Information That Relates to This Subject?

(g) CAA airworthiness directive DCA/FU24/173, dated April 23, 2002, also addresses the subject of this AD.

Issued in Kansas City, Missouri, on October 22, 2003.

Michael Gallagher,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-27212 Filed 10-29-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-216-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300 B2 and B4 Series Airplanes; Model A300 B4-600, B4-600R, and F4-600R (Collectively Called A300-600) Series Airplanes; and Model A310 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Airbus Model A300 B2 and B4

series airplanes; Model A300 B4-600, B4-600R, and F4-600R (collectively called A300-600) series airplanes; and Model A310 series airplanes. This proposal would require various modifications and repetitive inspections of the throttle control system, and follow-on actions if necessary. This action is necessary to prevent hard points in the throttle control system that could lead to jamming of the throttle control cable. Such jamming could result in an asymmetric thrust condition and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by December 1, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-216-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2001-NM-216-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer,

International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to