

- Ferry flight with pitch elevators disconnected,
- Take-off with flaps retracted.

Compliance Method Number 2

Crew Training Required

1. General

The general information in Section 1 is applicable.

2. Limitations

The limitations in Section 2 are applicable.

3. Normal Procedures

The normal procedures in Section 3 are applicable with the addition of the following:

The Captain must be the pilot flying and the pre-takeoff briefing must include the following takeoff procedure (refer to point 5).

4. Emergency Procedures

The emergency procedures in Section 4 are applicable.

5. Procedures Following Failures

The procedures following failures in Section 5 are applicable with the addition of the following:

TAKEOFF SEQUENCE

In case of difficulties to rotate, the Captain (CPT) should request the non-flying pilot's (NFP's) assistance. In that case, on CPT order, NFP pulls the control column until 5° pitch attitude is reached, then NFP releases the controls.

PERFORMANCES

The performances in Section 6 for dry runways and in Section 7.03 for non-dry runways (advisory materials) are applicable with the addition of the following for takeoff computations:

Increase TOD by 70 m.

6. Appendices and Supplements

Data of Section 7 are applicable with the addition of the following:

For the dispatch cases:

- Apply takeoff penalties due to the system failure,
- Then apply takeoff penalties due to the use of fluid Type II or IV.

Dispatch is not authorized in the following cases:

- Ferry flight with pitch elevators disconnected,
- Take-off with flaps retracted."

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Operations Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in French airworthiness directives 2000-448-053(B) R2 and 2000-449-082(B) R2, both dated September 19, 2001.

Issued in Renton, Washington, on February 14, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-4243 Filed 2-21-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-245-AD]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model 717-200 airplanes. This proposal would require modification of the longeron-to-frame installation of the upper center fuselage. This action is necessary to prevent fatigue cracking of the longerons of the upper center fuselage, which could result in reduced structural integrity of the fuselage. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by April 10, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-245-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain

"Docket No. 2001-NM-245-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California.

FOR FURTHER INFORMATION CONTACT:

Maureen Moreland, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5238; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001–NM–245–AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2001–NM–245–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

Discussion

The FAA has received a report indicating that Boeing Stress Engineering has found that the material thickness for longerons L–5L to L–5R, located in the upper center fuselage of Boeing Model 717–200 airplanes, is undersized. Investigation revealed that this could cause fatigue cracking of the longerons of the upper center fuselage after the accumulation of 30,000 total flight cycles on the airplane. Such fatigue cracking could result in reduced structural integrity of the fuselage.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Service Bulletin 717–53–0001, including Evaluation Form, dated March 20, 2001, which describes procedures for modification of the longeron-to-frame installation of the main frame of the upper center fuselage between stations Y=655.000 and Y=813.000, at longerons L–5L to L–5R. The modification includes fabricating the angles and installing support angles and doublers. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Difference Between Proposed Rule and Service Bulletin

Operators should note that, although the service bulletin recommends accomplishing the modification "at a scheduled heavy maintenance period when manpower, materials, and

facilities are available," the FAA has determined that such an imprecise compliance time would not address the identified unsafe condition in a timely manner. In developing an appropriate compliance time for this AD, the FAA considered not only the manufacturer's recommendation, but the degree of urgency associated with addressing the subject unsafe condition, the average utilization of the affected fleet, and the time necessary to perform the modification. In light of all of these factors, the FAA finds a compliance time of "Before the accumulation of 30,000 total flight cycles or within 10 years after the effective date of the AD, whichever is first," for completing the required actions to be warranted, in that it represents an appropriate interval of time allowable for affected airplanes to continue to operate without compromising safety.

Cost Impact

There are approximately 56 airplanes of the affected design in the worldwide fleet. The FAA estimates that 38 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 108 work hours per airplane to accomplish the proposed modification, and that the average labor rate is \$60 per work hour. Required parts cost would be minimal. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$246,240, or \$6,480 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions. The manufacturer may cover the cost of replacement parts associated with this proposed AD, subject to warranty conditions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal

would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 2001–NM–245–AD.

Applicability: Model 717–200 airplanes, manufacturer's fuselage numbers 5001 through 5056 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking of the longerons of the upper center fuselage, which

could result in reduced structural integrity of the fuselage, accomplish the following:

(a) Before the accumulation of 30,000 total flight cycles or within 10 years after the effective date of this AD, whichever is first: Modify the longeron-to-frame installation of the upper center fuselage between stations Y=655.000 and Y=813.000, at longerons L-5L to L-5R (includes fabrication of the angles and installation of support angles and doublers), per Boeing Service Bulletin 717-53-0001, excluding Evaluation Form, dated March 20, 2001.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

Special Flight Permit

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on February 14, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 03-4242 Filed 2-21-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-282-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-600, 737-700, 737-700C, 737-800, 737-900, 757, and 767 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Boeing Model 737-600, 737-700, 737-700C, 737-800, 737-900, 757, and 767 series airplanes. This proposal would require revising the Airplane Flight Manual (AFM) to advise the flightcrew

to don oxygen masks as a first and immediate step when a cabin altitude warning occurs. This action is necessary to prevent incapacitation of the flightcrew due to lack of oxygen, which could result in loss of control of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by April 10, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-282-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-282-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. **FOR FURTHER INFORMATION CONTACT:** Donald Eiford, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6465; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to

change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-282-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-282-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On October 25, 1999, a Learjet Model 35 airplane operating under part 135 of the Federal Aviation Regulations (14 CFR part 135) departed Orlando International Airport en route to Dallas, Texas. Air traffic control lost communication with the airplane near Gainesville, Florida. Air Force and National Guard airplanes intercepted the airplane, but the flightcrews of the chase airplanes indicated that the windows of the Model 35 airplane were apparently frosted over, which prevented the flightcrews of the chase airplanes from observing the interior of the Model 35 airplane. The flightcrews of the chase airplanes reported that they did not observe any damage to the airplane. Subsequently, the Model 35 airplane ran out of fuel and crashed in South Dakota. To date, causal factors of the accident have not been determined. However, lack of the Learjet flightcrew's response to air traffic control poses the possibility of flightcrew incapacitation and raises concerns with the pressurization and oxygen systems.

Recognizing these concerns, the FAA initiated a special certification review (SCR) to determine if pressurization and