

approval, it must first publish a document in the **Federal Register** providing a 60-day comment period and otherwise consult with members of the public and affected agencies concerning each proposed collection of information. OMB has promulgated regulations describing what must be included in such a document. Under OMB's regulation (at 5 CFR 1320.8(d)), an agency must ask for public comment on the following:

(i) Whether the proposed collection of information is necessary for the proper performance of the functions of the agency, including whether the information will have practical utility;

(ii) The accuracy of the agency's estimate of the burden of the proposed collection of information, including the validity of the methodology and assumptions used;

(iii) How to enhance the quality, utility, and clarity of the information to be collected;

(iv) How to minimize the burden of the collection of information on those who are to respond, including the use of appropriate automated, electronic, mechanical, or other technological collection techniques or other forms of information technology, e.g., permitting electronic submission of responses.

In compliance with these requirements, NHTSA asks for public comments on the following proposed collection of information:

Title: Designation of Agent for Service of Process.

OMB Control Number: 2127-0040.

Requested Expiration Date of Approval: Three years from the approval date.

Type of Request: Extension of previously approved collection.

Affected Public: Business or other for-profit.

Form Number: N/A.

Abstract: This collection of information applies to motor vehicle and motor vehicle equipment manufacturers located outside of the United States ("foreign manufacturers"). Section 110(e) of the National Traffic and Motor Vehicle Safety Act of 1966 (49 U.S.C. 30164) requires a foreign manufacturer offering a motor vehicle or motor vehicle equipment for importation into the United States to designate a permanent resident of the United States as its agent upon whom service of notices and processes may be made in administrative and judicial proceedings. These designations are required to be filed with NHTSA. NHTSA requires this information in case it needs to advise a foreign manufacturer of a safety related defect in its products so that the manufacturer

can, in turn, notify purchasers and correct the defect. This information also enables NHTSA to serve a foreign manufacturer with all administrative and judicial processes, notices, orders, decisions and requirements.

When NHTSA amended the regulation implementing that statutory requirement, codified at 49 CFR Part 551, subpart D, NHTSA included an appendix containing a suggested designation form for use by foreign manufacturers and their agents. The purpose of the suggested designation format was to simplify the information collection and submission process, and thereby reduce the burden imposed on each covered manufacturer by 49 CFR Part 551, subpart D. To further streamline the information collection process, NHTSA has set up a customer Web site that may be accessed at <http://www.nhtsa.dot.gov/cars/rules/manufacture/agent/customer.html>.

Estimated Annual Burden: 120 hours.

Estimated Number of Respondents: 240 respondents.

The Comments are invited on: Whether the proposed collection of information is necessary for the proper performance of the functions of the Department, including whether the information will have practical utility; the accuracy of the Department's estimate of the burden of the proposed information collection; ways to enhance the quality, utility and clarity of the information to be collected; and ways to minimize the burden of the collection of information on respondents, including the use of automated collection techniques or other forms of information technology.

Issued on: March 9, 2009.

John Donaldson,

Assistant Chief Counsel for Legislation and General Law.

[FR Doc. E9-5394 Filed 3-11-09; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2008-0119; Notice 2]

Goodyear Tire & Rubber Company, Grant of Petition for Decision of Inconsequential Noncompliance

Goodyear Tire & Rubber Company (Goodyear), has determined that certain passenger car tires manufactured from 2007 until March 2008 did not fully comply with paragraph S5.5(f) of Federal Motor Vehicle Safety Standards (FMVSS) No. 139 *New Pneumatic*

Radial Tires for Light Vehicles.

Goodyear has filed an appropriate report pursuant to 49 CFR Part 573, *Defect and Noncompliance Responsibility and Reports.*

Pursuant to 49 U.S.C. 30118(d) and 30120(h) and the rule implementing those provisions at 49 CFR Part 556, Goodyear has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety. Notice of receipt of the petition was published, with a 30-day public comment period, on June 26, 2008 in the **Federal Register** (73 FR 36372). No comments were received. To view the petition and all supporting documents log onto the Federal Docket Management System Web site at: <http://www.regulations.gov/>. Then follow the online search instructions to locate docket number "NHTSA-2008-0119."

For further information on this decision, contact Mr. George Gillespie, Office of Vehicle Safety Compliance, the National Highway Traffic Safety Administration (NHTSA), telephone (202) 366-5299, facsimile (202) 366-7002.

Affected are approximately 82,636 Dunlop SP Sport Signature passenger car tires that were manufactured from 2007 until March 2008 in the following sizes:

205/55R16 91V,
225/55R16 95V,
205/50R17 93V,
215/55R16 93V,
P215/55R17 93V,
205/65R15 94V,
P205/60R16 91V.

Paragraph S5.5(f) of FMVSS No. 139 requires in pertinent part:

S5.5 Tire markings. Except as specified in paragraphs (a) through (i) of S5.5, each tire must be marked on each sidewall with the information specified in S5.5(a) through (d) and on one sidewall with the information specified in S5.5(e) through (i) according to the phase-in schedule specified in S7 of this standard. The markings must be placed between the maximum section width and the bead on at least one sidewall, unless the maximum section width of the tire is located in an area that is not more than one-fourth of the distance from the bead to the shoulder of the tire. If the maximum section width falls within that area, those markings must appear between the bead and a point one-half the distance from the bead to the shoulder of the tire, on at least one sidewall. The markings must be in letters and numerals not less than 0.078 inches high and raised above or sunk below the tire surface not less than 0.015 inches * * *

(f) The actual number of plies in the sidewall, and the actual number of plies in the tread area, if different; * * *

Goodyear explains that the noncompliance is that the sidewall marking incorrectly identifies the number of plies in the tread of the tire. Specifically, the tires in question were inadvertently manufactured with "Tread 3 Polyester + 2 Steel" marked on the sidewall. The labeling should have been "Tread 2 Polyester + 2 Steel + 2 Polyester". (Emphasis added).

Goodyear states that it discovered the mold labeling error that caused the non-compliance during a routine quality audit.

Goodyear makes the argument that the subject tires were manufactured with the correct number of plies in the tread and only the sidewall marking is incorrect.

Goodyear also contends that all of the markings related to tire service (load capacity, corresponding inflation pressure, etc.) are correct and that the mislabeling of these tires is inconsequential to motor vehicle safety because the tires meet or exceed all applicable Federal Motor Vehicle Safety performance standards.

Goodyear also points out that NHTSA has previously granted petitions for sidewall marking noncompliances that it believes are similar to the instant noncompliance.

Goodyear also stated that it will correct the problem that caused these errors so that they will not be repeated in future production.

NHTSA Decision

The agency agrees with Goodyear that the noncompliance is inconsequential to motor vehicle safety. The agency believes that the true measure of inconsequentiality to motor vehicle safety in this case is that there is no effect of the noncompliance on the operational safety of vehicles on which these tires are mounted. The safety of people working in the tire retread, repair, and recycling industries must also be considered.

Although tire construction affects the strength and durability, neither the agency nor the tire industry provides information relating tire strength and durability to the number of plies and types of ply cord material in the tread and sidewall. Therefore, tire dealers and customers should consider the tire construction information along with other information such as the load capacity, maximum inflation pressure, and tread wear, temperature, and traction ratings, to assess performance capabilities of various tires. In the agency's judgment, the incorrect labeling of the tire construction information will have an inconsequential effect on motor vehicle

safety because most consumers do not base tire purchases or vehicle operation parameters on the number of plies in a tire.

The agency also believes the noncompliance will have no measurable effect on the safety of the tire retread, repair, and recycling industries. The use of steel cord construction in the sidewall and tread is the primary safety concern of these industries. In this case, since the tire sidewalls are marked correctly for the number of steel plies, this potential safety concern does not exist.

In consideration of the foregoing, NHTSA has decided that Goodyear has met its burden of persuasion that the subject FMVSS No. 139 labeling noncompliance is inconsequential to motor vehicle safety. Accordingly, Goodyear's petition is granted and the petitioner is exempted from the obligation of providing notification of, and a remedy for, the subject noncompliance under 49 U.S.C. 30118 and 30120.

Authority: 49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: March 4, 2009.

Daniel C. Smith,

Associate Administrator for Enforcement.

[FR Doc. E9-5277 Filed 3-11-09; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2008-0087; Notice 2]

Michelin North America, Grant of Petition for Decision of Inconsequential Noncompliance

Michelin North America, Inc. (MNA), has determined that certain light vehicle tires that it manufactured during the period beginning September 22, 2007 through October 26, 2007 (DOT weeks 3707 and 4207), do not fully comply with paragraphs S5.5 & S5.5(c) of 49 CFR 571.139 Federal Motor Vehicle Safety Standard (FMVSS) No. 139 *New Pneumatic Radial Tires for Light Vehicles*. MNA has filed an appropriate report pursuant to 49 CFR Part 573, *Defect and Noncompliance Responsibility and Reports*. Notice of receipt of a petition was published, with a 30-day comment period, on May 12, 2008, in the **Federal Register** (73 FR 27024). No comments were received. To view the petition and all supporting documents log onto the Federal Docket Management System Web site at:

<http://www.regulations.gov/>. Then follow the online search instructions to locate docket number "NHTSA-2008-0087."

For further information on this decision, contact Mr. George Gillespie, Office of Vehicle Safety Compliance, the National Highway Traffic Safety Administration (NHTSA), telephone (202) 366-5299, facsimile (202) 366-7002.

Affected are approximately 3,385 Michelin brand P235/55R17 98H MXV4 PLUS tires, produced September 22, 2007 through October 26, 2007 (DOT weeks 3707 and 4207). Paragraphs S5.5 & S5.5(c) of 49 CFR 571.139 require in pertinent part that:

S5.5 Tire markings. Except as specified in paragraphs (a) through (i) of S5.5, each tire must be marked on each sidewall with the information specified in S5.5(a) through (d) and on one sidewall with the information specified in S5.5(e) through (i) according to the phase-in schedule specified in S7 of this standard. The markings must be placed between the maximum section width and the bead on at least one sidewall, unless the maximum section width of the tire is located in an area that is not more than one-fourth of the distance from the bead to the shoulder of the tire. If the maximum section width falls within that area, those markings must appear between the bead and a point one-half the distance from the bead to the shoulder of the tire, on at least one sidewall. The markings must be in letters and numerals not less than 0.078 inches high and raised above or sunk below the tire surface not less than 0.015 inches.

S5.5(c) The maximum permissible inflation pressure, subject to the limitations of S5.5.4 through S5.5.6 of this standard.

MNA explained that the subject tires were manufactured with an incorrect maximum pressure value (350kPa (51 PSI)) marked on the outboard (reference) sidewall while the correct maximum pressure value (300 kPa (44 PSI)) was marked on the inboard sidewall. MNA expressed its belief that both maximum pressure values marked on the tires are acceptable choices for this tire. MNA also believes that the noncompliance exists because two maximum pressure values have been applied to the same tire.

MNA defends its belief that the noncompliance is inconsequential to motor vehicle safety by stating the following reasons:

(1) Performance requirements—The subject tires meet or exceed all of the minimum performance requirements of FMVSS No. 139.

(2) Maximum Pressure Value—Paragraph S5.5.4 of FMVSS No. 139 limits the choices for the allowed maximum inflation pressure to 240, 280, 290, 300, 330, 340, 350, or 390 kPa