

Proposed Rules

Federal Register

Vol. 74, No. 7

Monday, January 12, 2009

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

SMALL BUSINESS ADMINISTRATION

13 CFR Parts 121, 125, 127 and 134

RIN 3245-AF80

The Women-Owned Small Business Federal Contract Assistance Procedures—Eligible Industries

AGENCY: U.S. Small Business Administration (SBA).

ACTION: Proposed rule, notice of reopening of comment period.

SUMMARY: SBA is reopening the comment period for an additional 60 days.

DATES: Comments on the proposed rule on The Women-Owned Small Business Federal Contract Assistance Procedures—Eligible Industries, must be received on or before March 13, 2009.

ADDRESSES: You may submit comments, identified by 3245-AF80, by any of the following methods:

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Mail, Hand Delivery/Courier:* Dean Koppel, Assistant Director, Policy, Planning and Research, Office of Government Contracting, (202) 205-6460, U.S. Small Business Administration, 409 3rd Street, SW., Washington, DC 20416.

- All comments will be posted on <http://www.regulations.gov>. If you wish to submit confidential business information (CBI) as defined in the User Notice at <http://www.regulations.gov>, please submit the comments to Dean Koppel and highlight the information that you consider to be CBI and explain why you believe this information should be held confidential. SBA will make a final determination as to whether the comments will be published or not.

FOR FURTHER INFORMATION CONTACT: Dean Koppel, Assistant Director, Policy, Planning and Research, Office of Government Contracting, (202) 205-6460.

SUPPLEMENTARY INFORMATION: On October 1, 2008, SBA published in the **Federal Register** a proposed rule on The Women-Owned Small Business Federal Contract Assistance Procedures—Eligible Industries (73 FR 57014). The proposed rule sought comments from the public on a data issue involving the Women-Owned Small Business (WOSB) Federal Contract Assistance Procedures, which were finalized on October 1, 2008 (73 FR 56940). Specifically, SBA was seeking comments on two data sets: (1) The Central Contractor Registration (CCR) data set which was used in the RAND report to determine the representation of WOSBs in Federal procurement in the various industries, and (2) a non-public Survey of Business Owners (SBO) data set from the Economic Census, which was not previously used in the RAND report to determine the representation of WOSBs in Federal procurement in the various industries. This request for comments was intended to stimulate dialogue on available data sets and would be evaluated to determine which data set will provide the soundest basis to identify industries in which WOSBs are underrepresented in Federal procurement.

The original comment period was from October 1, 2008, through October 31, 2008. There is significant Congressional and public interest in extending the comment period. In addition, SBA is reviewing the relevance of the standard for disparity studies discussed in the Federal Circuit's decision in *Rothe Development Corporation v. Department of Defense*. Therefore, SBA is reopening the comment period until March 13, 2009. SBA believes that all affected parties would find it beneficial to have more time to review the proposed rule and prepare their comments.

Authority: 15 U.S.C. 634.

Calvin Jenkins,

Acting Associate Administrator for Government Contracting and Business Development.

[FR Doc. E9-407 Filed 1-9-09; 8:45 am]

BILLING CODE 8025-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1364; Directorate Identifier 2008-NM-103-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 737-300, -400, and -500 series airplanes. This proposed AD would require modifying the control power wiring of the normal supply fan and the low flow sensor for the equipment cooling system of the electronic flight instrument system (EFIS). This proposed AD results from a report of loss of both the normal EFIS cooling supply and the indication of EFIS cooling loss due to a single failure of the battery bus, causing eventual power-down of the EFIS displays; the standby attitude indication is also powered by this battery bus. We are proposing this AD to prevent loss of all attitude indications from both the standby indicator and EFIS displays, which could decrease the ability of the flightcrew to maintain the safe flight and landing of the airplane.

DATES: We must receive comments on this proposed AD by February 26, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Suk Jang, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6511; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1364; Directorate Identifier 2008-NM-103-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will

consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received a report of loss of both the normal electronic flight instrument system (EFIS) cooling supply and the indication of EFIS cooling loss due to a single failure of the battery bus, causing eventual power-down of the EFIS displays; the standby attitude indication is also powered by this battery bus. A single failure of the battery bus can cause loss of attitude indications from both the standby attitude indicator and EFIS displays. An indication of battery bus failure is not displayed on Boeing Model 737-300, -400, and -500 airplanes. The battery bus energizes the standby horizon, the normal supply fan for the equipment cooling system for the EFIS, and the cooling air flow sensor. If the fan does not operate, the EFIS will start to get hot, and when it gets too hot it will automatically stop operation by first going to mono-chromatic, and then, after 60 minutes or more, it will power-down. The supply fan off light will not illuminate to indicate that the fan has failed because it is also powered by the battery bus, which lost power. When this condition occurs, the flightcrew could be left without any attitude indication. Loss of all attitude indications from both the standby indicator and EFIS displays could decrease the ability of the flightcrew to maintain safe flight and landing of the airplane.

Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 737-21A1156, Revision 2, dated December 11, 2008. The service

bulletin describes procedures for modifying the control power wiring of the normal supply fan and the low flow sensor for the equipment cooling system of the EFIS. The modification includes the following procedures:

- Rerouting the wire for Group 1 airplanes identified in Boeing Alert Service Bulletin 737-21A1156, Revision 1, on which the length of the wire in the W018 wire bundle at the P18 load control center is adequate. If the length of the wire is inadequate, install new wire.
- Rerouting the wire for Group 2 airplanes identified in Boeing Alert Service Bulletin 737-21A1156, Revision 1, on which the length of the wire in the W018 wire bundle at the P18 load control center is adequate. If the length of the wire is inadequate, install new wire.
- Modifying wire bundle W044 between the P6 top disconnect panel and the P6-1 panel for Group 3 airplanes identified in Boeing Alert Service Bulletin 737-21A1156, Revision 1.
- Modifying wire bundle W036 between the P5 forward overhead panel and the mid-center ceiling panel for Group 4 airplanes identified in Boeing Alert Service Bulletin 737-21A1156, Revision 1.

FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs. This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD would affect 263 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action/airplane group	Work hours	Average labor rate per hour	Parts	Cost per product	Number of U.S.-registered airplanes	Fleet cost
Groups 1 & 2 modification	3	\$80	0	\$240	153	\$36,720
Group 4 modification	2	80	0	160	113	18,080

Currently, there are no Group 3 airplanes on the U.S. Register. However, if an affected airplane is imported and placed on the U.S. Register in the future, the required actions would take about 5

work hours, at an average labor rate of \$80 per work hour. Based on these figures, we estimate the cost of this AD for Group 3 airplanes to be \$400 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Boeing: Docket No. FAA-2008-1364; Directorate Identifier 2008-NM-103-AD.

Comments Due Date

(a) We must receive comments by February 26, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Boeing Model 737-300, -400, and -500 series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 737-21A1156, Revision 2, dated December 11, 2008.

Unsafe Condition

(d) This AD results from a report of loss of both the normal electronic flight instrument system (EFIS) cooling supply and the indication of EFIS cooling loss due to a single failure of the battery bus, causing eventual power-down of the EFIS displays; the standby attitude indication is also powered by this battery bus. We are issuing this AD to prevent loss of all attitude indications from both the standby indicator and EFIS displays, which could decrease the ability of the flightcrew to maintain the safe flight and landing of the airplane.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Modification

(f) Within 24 months after the effective date of this AD: Modify the control power wiring of the normal supply fan and the low flow sensor for the equipment cooling system of the EFIS, by doing all the applicable actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 737-21A1156, Revision 2, dated December 11, 2008.

Credit for Actions Done Using Previous Service Information

(g)(1) Actions done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 737-21A1156, Revision 1, dated October 23, 2007, are acceptable for compliance with the corresponding requirements of this AD.

(2) For Groups 1 and 2 airplanes identified in Boeing Alert Service Bulletin 737-21A1156, Revision 1, dated October 23, 2007: Actions done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 737-21A1156, dated June 20, 2006, are acceptable for compliance with the corresponding requirements of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, ATTN: Suk Jang, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6511; fax (425) 917-6590; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on December 18, 2008.

Stephen P. Boyd,

Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-314 Filed 1-9-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1363; Directorate Identifier 2008-NM-104-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 767-200, -300, and -300F Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 767-200, -300, and -300F series airplanes. This proposed AD would require repetitive inspections for fatigue cracking and corrosion of the upper link fuse pin of the nacelle struts, and related investigative and corrective actions if necessary. This proposed AD would also provide terminating action for the repetitive inspections. This proposed AD results from two reports of cracked upper link fuse pins. We are proposing this AD to prevent fatigue cracking or corrosion of the upper link fuse pin, which could result in failure of the fuse pin and consequent reduced structural integrity of the nacelle strut and possible separation of the strut and engine from the airplane during flight.

DATES: We must receive comments on this proposed AD by February 26, 2009.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.