

DATES: Comments must be received on or before April 1, 2009.

ADDRESSES: Documents reflecting this FAA action may be reviewed at 2300 East Devon Avenue, Des Plaines, Illinois, or at City of Chicago Department of Aviation, 10610 Zemke Road, Chicago, Illinois.

FOR FURTHER INFORMATION CONTACT:

James G. Keefer, Manager, Chicago Airports District Office, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois, 60018. Telephone Number 847-294-7336/FAX Number 847-294-7046.

SUPPLEMENTARY INFORMATION: The FAA invites public comment on the request to release property at Chicago Midway International Airport under the provisions of AIR 21. The following is a brief overview of the request:

The City of Chicago, the owner of Chicago Midway International Airport, requests the release of certain parcels of land from airport property for the following purposes: (1) To enable the exchange of certain city-owned airport land for other City-owned non-airport land contiguous to airport property; (2) to reflect the relocation of certain public roadways for airport development; and (3) to release certain city-owned airport land that is no longer used or needed for airport purposes. Neither the use nor the ownership of the property will change as a result of this request. The requested release will bring the airport Exhibit A map into conformance with its existing land use.

The City of Chicago Department of Aviation has requested to release to the City of Chicago Department of Transportation, for use by the Chicago Transit Authority approximately 2.02 acres of city-owned airport land, located south of vacated West 59th Street, north of relocated West 59th Street and east of the airport's southern entrance roads, in exchange for approximately 2.18 acres of City-owned non-airport land, located north of vacated West 59th Street, east of the airport terminal and west of the Chicago Transit Authority's Orange Line train station, will be added to the airport. The City also requests the release of airport land used for relocated public roadways consisting of approximately 6.77 acres.

The relocated public roadways include portions of South Cicero Avenue between West 53rd Street and West 61st Street and portions of West 59th Street between the Beltline Railroad and South Cicero Avenue. The airport has received approximately 15.53 acres from the vacation of former public roadways, including the roadways that were relocated. The City

wants to release Parcel 10 and easements for Parcels 1 and 4. The parcel and easements, originally acquired for airport navigational aid purposes are no longer needed. Parcel 10, consisting of approximately 0.18 acres, was acquired with Federal financial assistance in 1958 for navigational aids that were eventually located elsewhere. Parcel 10 is located approximately 1555 feet northwest of the airport, it is beyond the end of the runway safety zone, and it is not needed for any airport purposes. The City will return the fair market value proceeds of Parcel 10 to the Chicago Airport system.

Issued in Des Plaines, Illinois, on February 17, 2009.

James G. Keefer,

Manager, Chicago Airports District Office.

[FR Doc. E9-4350 Filed 2-27-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Highway Administration

Final Federal Agency Actions on Proposed Highway in North Carolina

AGENCY: Federal Highway Administration (FHWA), DOT.

ACTION: Notice; correction.

SUMMARY: This notice corrects an error in the FHWA notice published on February 17, 2009, at 74 FR 7535. The notice announced that actions taken by the United States Army Corps of Engineers (USACE) and other Federal agencies were final within the meaning of 23 U.S.C. 139(I)(1). The actions related to a proposed highway project, the Triangle Parkway, which begins at NC 540 in Wake County and ends at I-40 in Durham County, North Carolina. The Triangle Parkway is also known as State Transportation Improvement Program Project U-4763B. Those actions granted licenses, permits, and approvals for the project.

FOR FURTHER INFORMATION CONTACT: Mr. George Hoops, P.E., Major Projects Engineer, Federal Highway Administration, 310 New Bern Avenue, Suite 410, Raleigh, North Carolina, 27601-1418, Telephone: (919) 747-7022; e-mail: george.hoops@fhwa.dot.gov. (Regular business hours are 8 a.m. to 5 p.m.). Ms. Jennifer Harris, P.E., Staff Engineer, North Carolina Turnpike Authority, 5400 Glenwood Avenue, Suite 400, Raleigh, North Carolina, 27612, Telephone: (919) 571-3004; e-mail: jennifer.harris@ncturnpike.org. (Regular business hours are 8 a.m. to 5 p.m.). Mr. Eric Alsmeyer, Project Manager, U.S.

Army Corps of Engineers, Raleigh Regulatory Field Office, 3331 Heritage Trade Drive, Suite 105, Wake Forest, North Carolina, 27587, Telephone: (919) 554-4884, extension 23; e-mail: Eric.C.Alsmeier@usace.army.mil (Regular business hours are 8 a.m. to 5 p.m.).

SUPPLEMENTARY INFORMATION: On February 17, 2009, at 74 FR 7535, the FHWA issued a notice announcing that the USACE had taken final action within the meaning of 23 U.S.C. 139(I)(1) by issuing permits and approvals for the Triangle Parkway, a 3.4-mile long, multi-lane, fully access-controlled, new location roadway. The **SUPPLEMENTARY INFORMATION** section of that notice listed an incorrect Department of the Army Permit Number. The purpose of this notice is to correct the Department of the Army Permit Number. The correct Department of the Army Permit Number is 200620445.

(Catalog of Federal Domestic Assistance Program Number 20.205, Highway Planning and Construction. The regulations implementing Executive Order 12372 regarding intergovernmental consultation on Federal programs and activities apply to this program.)

Authority: 23 U.S.C. 139(I)(1).

Issued on: February 20, 2009.

George Hoops,

Major Projects Engineer, Federal Highway Administration, Raleigh, North Carolina.

[FR Doc. E9-4269 Filed 2-27-09; 8:45 am]

BILLING CODE 4910-RY-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2008-0133; Notice 2]

Hyundai Motor Company, Grant of Petition for Decision of Inconsequential Noncompliance

Hyundai Motor Company (Hyundai), has determined that certain replacement seat belt assemblies sold for various model and model year Hyundai vehicles, including 2008 model year vehicles, did not fully comply with paragraphs S4.1(k) and S4.1(l) of 49 CFR 571.209 Federal Motor Vehicle Safety Standards (FMVSS) No. 209 *Seat Belt Assemblies*. Hyundai has filed an appropriate report pursuant to 49 CFR Part 573, *Defect and Noncompliance Responsibility and Reports*.

Pursuant to 49 U.S.C. 30118(d) and 30120(h) and the rule implementing those provisions at 49 CFR Part 556, Hyundai has petitioned for an

exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety. Notice of receipt of the petition was published, with a 30-day public comment period, on August 20, 2008 in the **Federal Register** (73 FR 49238). No comments were received. To view the petition and all supporting documents log onto the Federal Docket Management System (FDMS) Web site at: <http://www.regulations.gov/>. Then follow the online search instructions to locate docket number "NHTSA-2008-0133."

For further information on this decision, contact Ms. Claudia Covell, Office of Vehicle Safety Compliance, the National Highway Traffic Safety Administration (NHTSA), telephone (202) 366-5293, facsimile (202) 366-7002.

Affected are an unknown number of replacement seat belt assemblies sold for various model and model year Hyundai vehicles prior to May 9, 2008.

Paragraphs S4.1(k) and S4.1(l) of FMVSS No. 209 require:

(k) Installation instructions. A seat belt assembly, other than a seat belt assembly installed in a motor vehicle by an automobile manufacturer, shall be accompanied by an instruction sheet providing sufficient information for installing the assembly in a motor vehicle. The installation instructions shall state whether the assembly is for universal installation or for installation only in specifically stated motor vehicles, and shall include at least those items specified in SAE Recommended Practice J800c, "Motor Vehicle Seat Belt Installations," November 1973. If the assembly is for use only in specifically stated motor vehicles, the assembly shall either be permanently and legibly marked or labeled with the following statement, or the instruction sheet shall include the following statement:

This seat belt assembly is for use only in [insert specific seating position(s), e.g., "front right"] in [insert specific vehicle make(s) and model(s)].

(l) Usage and maintenance instructions. A seat belt assembly or retractor shall be accompanied by written instructions for the proper use of the assembly, stressing particularly the importance of wearing the assembly snugly and properly located on the body, and on the maintenance of the assembly and periodic inspection of all components. The instructions shall show the proper manner of threading webbing in the hardware of seat belt assemblies in which the webbing is not permanently fastened. Instructions for a nonlocking retractor shall include a caution that the webbing must be fully extended from the retractor during use of the seat belt assembly unless the retractor is attached to the free end of webbing which is not subjected to any tension during restraint of an occupant by the assembly. Instructions for Type 2a shoulder belt shall

include a warning that the shoulder belt is not to be used without a lap belt.

Hyundai explains that the subject replacement seat belt assemblies were sold without the installation, usage, and maintenance instructions required by paragraphs S4.1(k) and S4.1(l) of FMVSS 209.

Hyundai makes the argument that the replacement seat belt assemblies in question are only made available to Hyundai authorized dealerships for their use or subsequent resale and that the Hyundai parts ordering process used by its dealers clearly identifies the correct replacement part required by model year, model, and seating position. Furthermore, Hyundai states that its replacement seat belt assemblies are designed to be installed properly only in their intended application.

Hyundai additionally states that technicians at Hyundai dealerships that replace seat belts have access to the installation instruction information available in Hyundai Shop Manuals. Installers other than Hyundai dealership technicians also have seat belt installation information available because Hyundai Shop Manual information, including seat belt replacement information, is made available to the general public on the Hyundai Service Web site (<http://www.hmaservice.com>) which provides free access to every Hyundai Shop Manual, including information about seat belt installation.

Hyundai additionally argues that a significant portion of paragraph S4.1(k) appears to address a concern with proper installation of aftermarket seat belts into vehicles that were not originally equipped with these restraints. Hyundai also notes that SAE J800c, which is cited in the regulation, involves installation of "universal type seat belt assemblies," particularly where no seat belt had previously been installed, and that these concerns do not apply to replacement seat belts. The vehicles involved in this petition have uniquely designed seat belt components and replacement seat belt assemblies are installed into the identical location from which the original parts were removed.

Hyundai also states that proper seat belt usage instructions are clearly explained in the Owner's Manual that is included with each new vehicle. Information concerning maintenance, periodic inspection for wear and function of the seat belts, as well as for their proper usage is included in the vehicle Owner Manual and this information equally applies to replacement seat belt assemblies.

Hyundai first became aware of the noncompliance when it was contacted

by NHTSA in response to a consumer inquiry received by NHTSA.

Hyundai also stated that it has corrected the problem that caused these errors so that they will not be repeated in future production.

In summation, Hyundai states that it believes that because the noncompliances are inconsequential to motor vehicle safety that no corrective action is warranted.

NHTSA Decision

To help ensure proper selection, installation, usage, and maintenance of seat belt assemblies, paragraph S4.1(k) of FMVSS No. 209 requires that installation, usage, and maintenance instructions be provided with seat belt assemblies, other than those installed by an automobile manufacturer.

First, we note that the subject seat belt assemblies are only made available to Hyundai authorized dealerships for their use or subsequent resale. Because the parts ordering process used by Hyundai authorized dealerships clearly identifies the correct service part required by model year, model, and seating position, NHTSA believes that there is little likelihood that an inappropriate seat belt assembly will be provided for a specific seating position within a Hyundai vehicle.

Second, we note that technicians at Hyundai dealerships have access to the seat belt assembly installation instruction information in Hyundai Shop Manuals. In addition, installers other than Hyundai dealership technicians can access the installation instructions on the Hyundai Web sites and through other aftermarket service information compilers. We also believe that Hyundai is correct in stating that the seat belt assemblies are designed to be installed properly only in their intended application. Thus, we conclude that sufficient safeguards are in place to prevent the installation of an improper seat belt assembly.

NHTSA recognizes the importance of having installation instructions available to installers and use and maintenance instructions available to consumers. The risk created by this noncompliance is that someone who purchased an assembly is unable to obtain the necessary installation information resulting in an incorrectly installed seat belt assembly. However, because the seat belt assemblies are designed to be installed properly only in their intended application and the installation information is widely available to the public, it appears that there is little likelihood that installers will not be able to access the installation instructions. Furthermore, we note that

Hyundai has stated that they are not aware of any customer field reports of service seat belt assemblies being incorrectly installed in the subject applications, nor aware of any reports requesting installation instructions. These findings suggest that it is unlikely that seat belts have been improperly installed.

In addition, although 49 CFR Part 571.209 paragraph S4.1(k) requires certain instructions specified in SAE Recommended Practice J800c be included in seat belt replacement instructions, that requirement applies to seat belts intended to be installed in seating positions where seat belts do not already exist. The subject seat belt assemblies are only intended to be used for replacement of original equipment seat belts; therefore, the instructions do not apply to the subject seat belt assemblies.¹

With respect to seat belt usage and inspection instructions, we note that this information is available in the Owner Handbooks that are included with each new vehicle as well as free of charge on the Hyundai Web sites and apply to the replacement seat belt assemblies installed in these vehicles. Thus, with respect to usage and maintenance instructions, it appears that Hyundai has met the intent of S4.1(l) of FMVSS No. 209 for the subject vehicles using alternate methods for notification.

NHTSA has granted similar petitions for noncompliance with seat belt assembly installation and usage instruction standards. Refer to Ford Motor Company (73 FR 11462, March 3, 2008); Mazda North America Operations (73 FR 11464, March 3, 2008); Ford Motor Company (73 FR 63051, October 22, 2008); Subaru of America, Inc. (65 FR 67471, November 9, 2000); Bombardier Motor Corporation of America, Inc. (65 FR 60238, October 10, 2000); TRW, Inc. (58 FR 7171, February 4, 1993); and Chrysler Corporation, (57 FR 45865, October 5, 1992). In all of these cases, the petitioners demonstrated that the noncompliant seat belt assemblies were properly installed, and due to their respective replacement parts ordering systems, improper replacement seat belt assembly selection and installation would not be likely to occur.

In consideration of the foregoing, NHTSA has decided that Hyundai has met its burden of persuasion that the seatbelt installation and usage instruction noncompliances described

are inconsequential to motor vehicle safety. Accordingly, Hyundai's application is granted, and it is exempted from providing the notification of noncompliance that is required by 49 U.S.C. 30118, and from remedying the noncompliance, as required by 49 U.S.C. 30120. All products manufactured or sold on and after May 9, 2008, must comply fully with the requirements of FMVSS No. 209.

Authority: 49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: February 24, 2009.

Daniel C. Smith,

Associate Administrator for Enforcement.

[FR Doc. E9-4275 Filed 2-27-09; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF THE TREASURY

Financial Crimes Enforcement Network

Proposed Renewal Without Change; Comment Request; Anti-Money Laundering Programs for Various Financial Institutions

AGENCY: Financial Crimes Enforcement Network, Department of the Treasury.

ACTION: Notice and request for comments.

SUMMARY: As part of our continuing effort to reduce paperwork and respondent burden, we invite comment on a proposed renewal, without change, to information collections found in existing regulations requiring money services businesses, mutual funds, operators of credit card systems, dealers in precious metals, stones, or jewels, and certain insurance companies to develop and implement written anti-money laundering programs reasonably designed to prevent those financial institutions from being used to facilitate money laundering and the financing of terrorist activities. This request for comments is being made pursuant to the Paperwork Reduction Act of 1995, Public Law 104-13, 44 U.S.C. 3506(c)(2)(A).

DATES: Written comments are welcome and must be received on or before May 1, 2009.

ADDRESSES: Written comments should be submitted to: Financial Crimes Enforcement Network, P.O. Box 39, Vienna, VA 22183, Attention: Anti-Money Laundering Program Comments. Comments also may be submitted by electronic mail to the following Internet address: regcomments@fincen.gov, again with a caption, in the body of the text,

“Attention: Anti-Money Laundering Program Comments.”

FOR FURTHER INFORMATION CONTACT: Financial Crimes Enforcement Network, Regulatory Policy and Programs Division at (800) 949-2732, option 6.

SUPPLEMENTARY INFORMATION:

Abstract: The Director of the Financial Crimes Enforcement Network is the delegated administrator of the Bank Secrecy Act. The Act authorizes the Director to issue regulations to require all financial institutions defined as such in the Act to maintain or file certain reports or records that have been determined to have a high degree of usefulness in criminal, tax, or regulatory investigations or proceedings, or in the conduct of intelligence or counter-intelligence activities, including analysis, to protect against international terrorism, and to implement anti-money laundering programs and compliance procedures.¹

Regulations implementing section 5318(h)(1) of the Act are found in part at 31 CFR 103.125, 103.130, 103.135, 103.137, and 103.140. In general, the regulations require financial institutions, as defined in 31 U.S.C. 5312(a)(2) and 31 CFR 103.11 to establish, document, and maintain anti-money laundering programs as an aid in protecting and securing the U.S. financial system.

1. **Titles:** Anti-money laundering programs for money services businesses (31 CFR 103.125), Anti-money laundering programs for mutual funds (31 CFR 103.130), Anti-money laundering programs for operators of credit card systems (31 CFR 103.135).

Office of Management and Budget Control Number: 1506-0020.

Abstract: Money services businesses, mutual funds, and operators of credit card systems are required to develop and implement written anti-money laundering programs. A copy of the written program must be maintained for five years.

Current Action: There is no change to existing regulations.

Type of Review: Extension of a currently approved information collection.

Affected Public: Business and other for-profit institutions.

Burden: Estimated Number of Respondents: 203,006.

¹ Public Law 91-508, as amended and codified at 12 U.S.C. 1829b, 12 U.S.C. 1951-1959 and 31 U.S.C. 5311-5332. Language expanding the scope of the Bank Secrecy Act to intelligence or counter-intelligence activities to protect against international terrorism was added by section 358 of the Uniting and Strengthening America by Providing Appropriate Tools Required to Intercept and Obstruct Terrorism (USA PATRIOT) Act of 2001, Public Law No. 107-56.

¹ Subaru of America, Inc.; Grant of Application for Decision of Inconsequential Non-Compliance (65 FR 67472).