

hours after the effective date of this AD, whichever occurs later.

(ii) Within 20,000 flight cycles or 60,000 flight hours after the most recent inspection required by paragraph (g) or (h) of this AD, whichever occurs first.

(2) For airplanes on which the inspection required by paragraph (g) of this AD has not been done as of the effective date of this AD: Do the inspection before the accumulation of 15,000 total flight hours, or within 6,000 flight hours after the effective date of this AD, whichever occurs later.

Paperwork Reduction Act Burden Statement

(o) A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave., SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

Credit for Actions Accomplished in Accordance With Previous Service Information

(p) Actions done before the effective date of this AD in accordance with Boeing Alert Service Bulletin 747-28A2204, Revision 2, dated September 1, 2005, are acceptable for compliance with the corresponding requirements of this AD.

Alternative Methods of Compliance (AMOCs)

(q)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to ATTN: Tung Tran, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6505; fax (425) 917-6590. Information may be e-mailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your Principal Maintenance Inspector or Principal Avionics Inspector, as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(3) AMOCs approved previously in accordance with AD 97-26-07, Amendment 39-10250, are approved as alternative methods of compliance with the corresponding requirements of this AD. Compliance time extensions approved previously in accordance with AD 97-26-07,

are not approved as alternative methods of compliance for the compliance times required by paragraph (n) of this AD.

Material Incorporated by Reference

(r) You must use Boeing Alert Service Bulletin 747-28A2204, Revision 3, dated March 11, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin 747-28A2204, Revision 3, dated March 11, 2010, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal-register/code-of-federal-regulations/ibr_locations.html.

Issued in Renton, Washington, on July 1, 2011.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011-17404 Filed 7-14-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0695; Directorate Identifier 2011-SW-001-AD; Amendment 39-16740; AD 2011-14-05]

RIN 2120-AA64

Airworthiness Directives; MD Helicopters, Inc. Model MD900 Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD) for MD Helicopters, Inc. (MDHI) Model MD900 helicopters. That AD currently requires visually inspecting the main rotor lower hub assembly (lower hub) for a crack, and if you find a crack,

before further flight, replacing the unairworthy lower hub with an airworthy lower hub. Additionally, within 10 days of finding a cracked lower hub, the existing AD requires reporting the finding to the Los Angeles Aircraft Certification Office (LAACO). That AD was prompted by two reports of cracks detected in the hub in the area near the flex beam bolt hole locations during maintenance on two MDHI Model MD900 helicopters. Since we issued that AD, we determined that one manufacturer had incorrectly inserted flanged bushings into the lower hub bore that resulted in local corrosion, leading to fatigue cracking. Examination of lower hubs from the other manufacturer shows correct bushing installation. Therefore, this amendment limits the applicability to the affected lower hubs; retains the visual inspection but at a different compliance time; adds an eddy current inspection; retains the requirement to replace a cracked lower hub with an airworthy lower hub before further flight; and removes the requirement to report to the LAACO. The actions specified by this AD are intended to detect a crack in the lower hub and prevent failure of the lower hub and subsequent loss of control of the helicopter.

DATES: This AD is effective August 1, 2011.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of August 1, 2011.

We must receive any comments on this AD by September 13, 2011.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- Fax: 202-493-2251.

- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615, Mesa, AZ 85215-9734, telephone 1-800-388-3378, fax 480-346-6813, or at <http://www.mdhelicopters.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Eric Schrieber, Aviation Safety Engineer, FAA, Los Angeles Aircraft Certification Office, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712-4137, telephone (562) 627-5348, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion

On August 19, 2010, we issued Emergency AD (EAD) 2010-18-51. That EAD was prompted by two reports of cracks detected in the lower hub near the flex beam bolt hole location during maintenance. That EAD required, within 4 hours time-in-service (TIS), visually inspecting the lower hub for a crack and, if you find a crack, before further flight, replacing the lower hub with an airworthy lower hub and, within 10 days, reporting a cracked lower hub to the LAACO. We superseded EAD 2010-18-51 with EAD 2010-18-52, issued August 23, 2010, upon discovering a typographical error in the "Applicability" section of the EAD in the lower hub part number (P/N). EAD 2010-18-52 contained the same requirements as EAD 2010-18-51 but corrected the P/N for the lower hub.

Actions Since That AD Was Issued

Since we issued the AD, 5 additional lower hubs were found cracked. We determined that one manufacturer of lower hubs with serial numbers (S/Ns) beginning with 5009 (*e.g.*, 5009-XXXX) had incorrectly inserted flanged bushings into the lower hub bore. This condition resulted in local corrosion leading to fatigue cracking. Examination of lower hubs from the other manufacturer shows correct bushing installation.

Relevant Service Information

We reviewed MDHI Service Bulletin SB900-117, dated January 14, 2011 (SB). The SB specifies an initial 100-hour and recurring 300-hour visual and eddy current inspections of the lower hub for a crack and, if there is a crack, replacing the lower hub with an airworthy lower hub. The inspections would be done at the stated intervals or at the next annual inspection, whichever occurs first. The SB also specifies replacing an affected lower hub within 3 years after the date of the SB.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other helicopters of this same type design.

AD Requirements

This AD requires a visual inspection, and if necessary, an eddy current inspection of the lower hub for a crack. If there is a crack, the AD requires replacing the lower hub with an airworthy lower hub. This AD requires accomplishing these actions by following specified portions of the service information described previously, except as discussed under "Differences Between the AD and the Service Information."

Change to Existing AD

This superseding AD changes the compliance time for the visual inspection and adds an eddy current inspection of the lower hub for a crack. This AD also removes the reporting requirement to the LAACO and the requirement for an OMB control number. This AD also reduces the applicability to only those helicopters with certain serial-numbered lower hubs installed.

Differences Between the AD and the Service Information

This AD does not require contacting the manufacturer or returning the lower hub assembly with a certain report. This AD also does not require the 300-hour inspection or replacing the lower hub within 3 years from the date of the SB because these actions do not fit our

criteria for a Final rule, request for comments.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because the previously described unsafe condition can adversely affect the structural integrity and controllability of the helicopter. The inspection is required within 100 hours TIS or during the annual inspection, whichever occurs first, unless done within the last 200 hours TIS. Since the affected helicopters could reach 100 hours TIS within 1 month, we find that notice and opportunity for prior public comment are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not provide you with notice and an opportunity to provide your comments before it becomes effective. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2011-0695 and directorate identifier 2011-SW-001-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 12 helicopters of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work hour to visually inspect the hub.	1 work-hour x \$85 per hour = \$85.	N/A	\$85	\$1,020.

ESTIMATED COSTS—Continued

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work hour to eddy current inspect the lower hub [new action].	1 work-hour x \$85 per hour = \$85.	N/A	\$85	\$1,020.
Required parts and labor to replace a lower hub.	11 work hours x 85 per hour = \$935.	\$12,480 per hub	\$13,415	\$160,980.
Total	\$1,105	\$12,480	\$13,585	\$163,020 assuming the lower hubs are replaced for the entire fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2010–18–52, Amendment 39–16515 (75 FR 69862, November 16, 2010) and adding the following new AD:

2011–14–05 MD HELICOPTERS, INC.:
Amendment 39–16740; Docket No. FAA–2011–0695; Directorate Identifier 2011–SW–001–AD.

Effective Date

- (a) This AD is effective August 1, 2011.

Affected ADs

- (b) This AD supersedes AD 2010–18–52, Amendment 39–16515, Docket No. FAA–2010–1126; Directorate Identifier 2010–SW–078–AD.

Applicability

- (c) Model MD900 helicopters with main rotor lower hub assembly (lower hub), part number (P/N) 900R2101008–107, serial numbers (S/Ns) that begin with 5009, certificated in any category.

Unsafe Condition

- (d) This amendment is prompted by the determination that a certain manufacturer had incorrectly inserted the flanged bushings into the lower hub bore. The actions specified by this AD are intended to detect a crack in the lower hub and prevent failure of the hub and subsequent loss of control of the helicopter.

Compliance

- (e) Within 100 hours time-in-service (TIS) or during the next annual inspection, whichever occurs first, unless done within the last 200 hours TIS:

(1) Visually inspect the sides and bottom of the area between the arms for the centering bearing and the areas adjacent to the bushings of the lower hub assembly for a crack. If there is a crack, before further flight, replace the lower hub with an airworthy lower hub.

(2) If the lower hub is not replaced as a result of the visual inspection required by paragraph (e)(1) of this AD, eddy current inspect the lower hub for a crack by following the Accomplishment Instructions, paragraphs 2.A(2) through 2.A.(10), of MD Helicopters Inc. Service Bulletin SB900–117, dated January 14, 2011 (SB). If there is a crack, before further flight, replace the lower hub with an airworthy hub.

(f) The eddy current inspection required by paragraph (e)(2) of this AD must be done by a Level II technician with ASNT–TC–1A, CEN EN 4179, MIL–STD–410, NAS410, or equivalent certification in eddy current inspections. The technician must have done an eddy current inspection in the last 12 months.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office (LAACO), FAA, has the authority to approve AMOCs for this AD, if requested, using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the LAACO, send it to the attention of the person identified in the Additional Information section of this AD.

(2) Before using any approved AMOC, we request that you notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

Additional Information

(h) For more information about this AD, contact Eric Schrieber, Aviation Safety Engineer, FAA, Los Angeles Aircraft Certification Office, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712–4137, telephone (562) 627–5348, fax (562) 627–5210.

Material Incorporated by Reference

- (i)(1) Inspect the main rotor lower hub assembly for a crack by following the specified portions of MD Helicopter, Inc. Service Bulletin SB 900–117, dated January

14, 2011. The Director of the Federal Register approved the incorporation by reference of the service information, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact MD Helicopters Inc., Attn: Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615, Mesa, AZ 85215-9734, telephone 1-800-388-3378, fax 480-346-6813, or at <http://www.mdhelicopters.com>.

(3) Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas, or at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Subject

(j) The Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code is 6220: Main Rotor Head.

Issued in Fort Worth, Texas, on June 21, 2011.

Kim Smith,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2011-17421 Filed 7-14-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0307; Directorate Identifier 2010-NM-111-AD; Amendment 39-16747; AD 2011-14-12]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Saab Aerosystems Model SAAB 2000 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

A report has been received of an incident where one of the two bolts attaching the actuator mounting bracket to the MLG [main landing gear] Shock Strut was found loose, leading to failure of the other attachment bolt, subsequently resulting in failure of the bracket.

This condition, if not detected and corrected, could prevent the MLG to extend to the full down-and-locked position, possibly resulting in MLG collapse upon landing or during roll-out, with consequent damage to the aeroplane and injury to the occupants.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective August 19, 2011.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 1, 2011.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on April 8, 2011 (76 FR 19719). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

A report has been received of an incident where one of the two bolts attaching the actuator mounting bracket to the MLG Shock Strut was found loose, leading to failure of the other attachment bolt, subsequently resulting in failure of the bracket.

This condition, if not detected and corrected, could prevent the MLG to extend to the full down-and-locked position, possibly resulting in MLG collapse upon landing or during roll-out, with consequent damage to the aeroplane and injury to the occupants.

To correct this potentially unsafe condition, SAAB has published Service Bulletin (SB) 2000-32-073, describing a [detailed] inspection of the attachment bolts [and nuts] to detect any loose bolts [and nuts], follow-up corrective action(s), depending on findings, and the installation of the correct number of washers.

For the reasons described above, this EASA AD requires the accomplishment of the actions described in SAAB SB 2000-32-073.

Required actions, if any loose parts are found, include replacing the bolt with a

new bolt, and then doing a detailed inspection of the bolts for uniform or fretting corrosion; a detailed inspection of the actuator mounting bracket and shock struts for damage, cracks, and signs of corrosion; and doing corrective actions if necessary. Corrective actions include removing corrosion, replacing affected bolts with new bolts, tightening loose nuts, repairing, and installing the correct number of washers. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 8 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$1,039 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$8,992, or \$1,124 per product.

In addition, we estimate that any necessary follow-on actions would take about 10 work-hours and require parts costing \$1,039, for a cost of \$1,889 per