

Done in Washington, DC, this 7th day of September 2011.

Kevin Shea,

Acting Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 2011-23432 Filed 9-13-11; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0604; Directorate Identifier 2011-NE-21-AD; Amendment 39-16791; AD 2011-18-09]

RIN 2120-AA64

Airworthiness Directives; Lycoming Engines Model IO-720-A1B Reciprocating Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain model IO-720-A1B Lycoming Engines reciprocating engines. This AD requires a crankshaft inspection for certain parts that may be installed. This AD was prompted by the failure of a crankshaft due to incorrect parts installed. We are issuing this AD to prevent engine crankshaft failure and damage to the airplane.

DATES: This AD is effective September 29, 2011.

We must receive comments on this AD by October 31, 2011.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (*phone:* 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (*phone:* 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; *phone:* 516-228-7337; *fax:* 516-794-5531; *e-mail:* Norman.perenson@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We received a report of a crankshaft failing after a repair station installed a crankshaft that had improper counterweight washers installed. The repair station has determined that two additional engines require inspection, to determine if the crankshaft they installed has the same improper washers. However, the two engines which have not been inspected, cannot be located. This condition, if not corrected, could result in engine crankshaft failure and damage to the airplane.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist in other products of the same type design.

AD Requirements

This AD requires removing four cylinders from each affected engine and inspecting the engine crankshaft counterweight washers.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because a crankshaft with improper damper washers installed, failed after 440 hours of operation. The location of the two additional engines that require inspection, and the unknown current time-since-overhaul on those engines, warrants immediate notice to advise the current or subsequent owner of the need to inspect the engines before further flight. Therefore, we find that notice and opportunity for prior public comment

are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2011-0604 and Directorate Identifier 2011-NE-21-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD will affect two Lycoming Engines model IO-720-A1B reciprocating engines, installed on airplanes of U.S. registry. We also estimate that the inspection will take about 0.5 work-hour per engine to perform, and that the average labor rate is \$85 per work-hour. Required parts would cost \$0 per engine. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$170.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2011-18-09 Lycoming Engines (formerly Textron Lycoming Division, AVCO Corporation): Amendment 39-16791; Docket No. FAA-2011-0604; Directorate Identifier 2011-NE-21-AD.

Effective Date

- (a) This AD is effective September 29, 2011.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to Lycoming Engines reciprocating engines, model IO-720-A1B, serial number L-1457-54A and serial number L-1458-54A. These engines were last known to be installed in a Beech U-8F (Queen Air) N51779 and operating in the southern U.S. and Mexico.

Unsafe Condition

- (d) This AD was prompted by the failure of a crankshaft due to incorrect parts

installed. We are issuing this AD to prevent engine crankshaft failure and damage to the airplane.

Compliance

- (e) Comply with this AD before further flight after the effective date of this AD, unless already done.

Crankshaft Inspection

- (f) Remove the four cylinders from one side of the engine. Guidance on removing the cylinders can be found in the Lycoming Engines Overhaul Manual.

(g) Each counterweight has two rollers that should be held in place by washers, Lycoming part number (P/N) 71907. The washers can be identified as having three holes each, with a diameter of 0.185 inch. These washers are located at the front and rear of each counterweight for a total of four P/N 71907 washers per counterweight. The eight counterweights are located at the top and bottom of each crankshaft cheek, totaling 32 washers per crankshaft.

(h) Rotate the crankshaft to inspect the holes in washers at the front and rear of each counterweight as well as the top and bottom of each cheek.

(i) If each hole, in each of the 32 washers, measures 0.185 inch, then no further action is required. Reinstall the cylinders and test the engine. Guidance on reinstalling and testing can be found in the Lycoming Engines Overhaul Manual.

(j) If any of the 32 washers have one or more holes that do not measure 0.185 inch, then remove the crankshaft assembly and replace it with a serviceable crankshaft assembly. Scrap the non-conforming crankshaft.

Special Flight Permits

- (k) Special flight permits are authorized only if the engine has less than 400 hours time since overhaul.

Alternative Methods of Compliance (AMOCs)

(l) The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(m) For more information about this AD, contact Norm Perenson, Aerospace Engineer, New York Aircraft Certification Office, FAA, Engine & Propeller Directorate, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7337; fax: 516-794-5531; e-mail: Norman.perenson@faa.gov.

Material Incorporated by Reference

- (n) None.

Issued in Burlington, Massachusetts, on August 18, 2011.

Peter A. White,

Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2011-22244 Filed 9-13-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket No. USCG-2011-0825]

RIN 1625-AA00

Safety Zone; Head of the Cuyahoga, Cuyahoga River, Cleveland, OH

AGENCY: Coast Guard, DHS.

ACTION: Temporary final rule.

SUMMARY: The Coast Guard is establishing a temporary safety zone on the Cuyahoga River, Cleveland, OH. This safety zone is intended to restrict vessels from a portion of the Cuyahoga River during the Head of the Cuyahoga. This temporary safety zone is necessary to protect spectators and vessels from the hazards associated with a rowing regatta.

DATES: This rule is effective on September 17, 2011 from 7 a.m. to 4 p.m.

ADDRESSES: Documents indicated in this preamble as being available in the docket are part of docket USCG-2011-0825 and are available online by going to <http://www.regulations.gov>, inserting USCG-2011-0825 in the "Keyword" box, and then clicking "Search." This material is also available for inspection or copying at the Docket Management Facility (M-30), U.S. Department of Transportation, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: If you have questions on this temporary rule, call or e-mail MST3 Rory Boyle, Marine Events Coordinator, U.S. Coast Guard Sector Buffalo, at Coast Guard; telephone 716-843-9343, e-mail Rory.c.Boyle@USCG.mil. If you have questions on viewing the docket, call Renee V. Wright, Program Manager, Docket Operations, telephone 202-366-9826.

SUPPLEMENTARY INFORMATION:

Regulatory Information

The Coast Guard is issuing this temporary final rule without prior notice and opportunity to comment pursuant to authority under section 4(a) of the Administrative Procedure Act (APA) (5 U.S.C. 553(b)). This provision authorizes an agency to issue a rule without prior notice and opportunity to comment when the agency for good cause finds that those procedures are