

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2012-1032; Directorate Identifier 2012-NM-079-AD]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Saab Aerosystems Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Saab AB, Saab Aerosystems Model SAAB 2000 airplanes. This proposed AD was prompted by reports of chafing on the bottom panel of the center cabin. This proposed AD would require doing a general visual inspection to determine if certain fasteners are installed, and related investigative and corrective actions. We are proposing this AD to detect and correct any chafing on the bottom panel of the center cabin, which could affect the structural integrity of the affected wing-to-fuselage connection.

DATES: We must receive comments on this proposed AD by November 16, 2012.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-1032; Directorate Identifier 2012-NM-079-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2012-0068, dated April 25, 2012 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

On two SAAB 2000 aeroplanes, signs of chafing have been found on the bottom panel of the centre cabin between fuselage station (STA) 562 and STA 622. The investigation results have shown that the chafing is caused by certain Hi Lok fasteners, installed as a repair during production, through the upper wing skin panel.

This condition, if not detected and corrected, could affect the structural integrity of the affected wing-to-fuselage connection.

To address this potential unsafe condition, SAAB issued Service Bulletin (SB) 2000-53-057 to provide instructions for a general visual inspection to detect chafing in the area between the upper wing skin and the cabin centre bottom panel and to verify if there are Hi Lok fasteners installed with the collar up.

For the reasons described above, this [EASA] AD requires a one-time inspection of the designated area, the accomplishment of corrective action(s) [repair], depending on findings, and the reporting of all inspection results * * *.

This [EASA] AD is considered an interim action and further AD action may follow.

Related investigative actions include measuring the distance between the fastener and bottom panel and a boroscope inspection for chafing and damage of the bottom panel. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Saab AB, Saab Aerosystems has issued Service Bulletin 2000-53-057, dated November 22, 2011. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This AD and the MCAI or Service Information

Saab Service Bulletin 2000-53-057, dated November 22, 2011, specifies to contact the manufacturer for repair instructions, but this proposed AD would require doing the repair using a method that we approve.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 10 products of U.S. registry. We also estimate that it would take about 4 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$3,400, or \$340 per product.

We have received no definitive data that would enable us to provide a cost estimate for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Saab AB, Saab Aerosystems: Docket No. FAA-2012-1032; Directorate Identifier 2012-NM-079-AD.

(a) Comments Due Date

We must receive comments by November 16, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aerosystems Model SAAB 2000 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of chafing on the bottom panel of the center cabin. We are issuing this AD to detect and correct any chafing on the bottom panel of the center cabin, which could affect the structural integrity of the affected wing-to-fuselage connection.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection

Within 12 months after the effective date of this AD, do a general visual inspection of the area between the upper part of the wing skin and the center bottom panel to determine if any Hi Lok fasteners are installed with the collar up, and do all applicable related investigative actions, in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000-53-057, dated November 22, 2011.

(h) Repair

If any chafing or damage is found during any inspection required by paragraph (g) of this AD: Before further flight, repair in accordance with a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA) (or its delegated agent).

(i) Reporting

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g) of this AD to Saab AB, Saab Aerosystems, in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000-53-057, dated November 22, 2011, at the applicable time

specified in paragraph (h)(1) or (h)(2) of this AD. The report must include the inspection results, the airplane serial number, and the number of landings and flight hours on the airplane.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(k) Related Information

(1) Refer to MCAI EASA Airworthiness Directive 2012-0068, dated April 25, 2012;

and Saab Service Bulletin 2000–53–057, dated November 22, 2011; for related information.

(2) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on September 21, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–24173 Filed 10–1–12; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2012–1033; Directorate Identifier 2010–NM–266–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede an existing airworthiness directive (AD) that applies to all Airbus Model A330–200 and –300 series airplanes, and Model A340–200 and –300 series airplanes. The existing AD currently requires repetitive inspections to detect discrepancies of the transfer tubes and the collar of the ball nut of the trimmable horizontal stabilizer actuator (THSA), and corrective action if necessary; repetitive inspections for discrepancies of the ball screw assembly, and corrective action if necessary; repetitive greasing of the THSA ball nut, and replacement of the THSA if necessary; and modification or replacement (as applicable) of the ball nut assembly, which would end certain repetitive inspections. Since we issued that AD, we have determined the repetitive inspections of the ball screw assembly (and corrective action if necessary) and repetitive greasing is needed for additional THSA nuts. This proposed AD would remove certain inspections, revise certain actions, and add airplanes to the applicability. We are proposing this AD to prevent degraded operation of the THSA, which

could result in reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by November 16, 2012.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493–2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For Airbus service information identified in this proposed AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet: <http://www.airbus.com>. For TRW Aeronautical Systems, SAMM Avionique, and Lucas Aerospace service information identified in this proposed AD, contact Goodrich Corporation, Actuation Systems, Stafford Road, Fordhouses, Wolverhampton WV10 7EH, England; telephone +44 (0) 1902 624938; fax +44 (0) 1902 788100; email techpubs.wolverhampton@goodrich.com; Internet <http://www.goodrich.com/TechPubs.Y>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA,

1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1138; fax 425–227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2012–1033; Directorate Identifier 2010–NM–266–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On March 17, 2005, we issued AD 2005–07–04, Amendment 39–14028 (70 FR 16104, March 30, 2005). That AD required actions intended to address an unsafe condition on the products listed above. Since we issued AD 2005–07–04, the European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2010–0192 (corrected), dated October 11, 2010; and EASA Airworthiness Directive 2010–0193 (corrected), dated October 11, 2010; (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Several cases of transfer tube disconnection from the ball-nut of the trimmable horizontal stabilizer actuator (THSA) part number (P/N) 47172 and 47147–400 were detected on the ground during greasing and maintenance.

This condition is caused by water ingress into the ball-nut resulting in the jamming of the ball transfer circuit when the water freezes.

If the three (independent) ball circuits fail, then the THSA will operate on a fail-safe nut. This nut (which operates without balls) would then jam after several movements on the screw of the THSA.

This degraded operation is not detectable in the cockpit by the crew as long as the THSA does not jam and could damage the ball screw and the fail-safe nut.

To detect this unsafe condition, [Dirección General de Aviación Civil] DGAC France AD F–2001–356 [and F–2001–357] was issued to require repetitive inspections of the transfer tubes and their collars in order to detect at