

financial company supervised by the Board, if the company is a U.S. company, this amount will be the average of the nonbank financial company's total consolidated assets as reported for the assessment period on such regulatory or other reports as are applicable to the nonbank financial company determined by the Board; if the company is a foreign company, this amount will be the average of the nonbank financial company's total combined assets of U.S. operations, net of intercompany balances and transactions between U.S. domiciled affiliates, branches and agencies, as reported for the assessment period on such regulatory or other reports as determined by the Board as applicable to the nonbank financial company.

§ 246.5 Notice of assessment and appeal.

(a) *Notice of Assessment.* The Board shall issue a notice of assessment to each assessed company no later than June 30 of each calendar year following the assessment period, provided, however, that for the 2012 assessment period, the Board shall issue a notice of assessment as soon as reasonably practical after publication of the final rule in the **Federal Register**.

(b) *Appeal Period.*

(1) Each assessed company will have thirty calendar days from June 30, or, for the 2012 assessment period, thirty calendar days from the Board's issuance of a notice of assessment for that assessment period, to submit a written statement to appeal the Board's determination:

(i) That the company is an assessed company; or

(ii) Of the company's total assessable assets.

(2) The Board will respond with the results of its consideration to an assessed company that has submitted a written appeal within 15 calendar days from the end of the appeal period in paragraph (b)(1) of this section.

§ 246.6 Collection of assessments; payment of interest.

(a) *Collection date.* Each assessed company shall remit to the Federal Reserve the amount of its assessment using the Fedwire Funds Service by September 15 of the calendar year following the assessment period, or, for the 2012 assessment period, by a date specified in the notice of assessment for that assessment period.

(b) *Payment of interest.*

(1) If the Board does not receive the total amount of an assessed company's assessment by the collection date for any reason not attributable to the Board, the assessment will be delinquent and

the assessed company shall pay to the Board interest on any sum owed to the Board according to this rule (delinquent payments).

(2) Interest on delinquent payments will be assessed beginning on the first calendar day after the collection date, and on each calendar day thereafter up to and including the day payment is received. Interest will be simple interest, calculated for each day payment is delinquent by multiplying the daily equivalent of the applicable interest rate by the amount delinquent. The rate of interest will be the United States Treasury Department's current value of funds rate (the "CVFR percentage"); issued under the Treasury Fiscal Requirements Manual and published quarterly in the **Federal Register**. Each delinquent payment will be charged interest based on the CVFR percentage applicable to the quarter in which all or part of the assessment goes unpaid.

By order of the Board of Governors of the Federal Reserve System, August 15, 2013.

Robert deV. Frierson,

Secretary of the Board.

[FR Doc. 2013-20306 Filed 8-22-13; 8:45 am]

BILLING CODE P

FEDERAL DEPOSIT INSURANCE CORPORATION

12 CFR Part 390

Regulations Transferred From the Office of Thrift Supervision

CFR Correction

■ In Title 12 of the Code of Federal Regulations, Parts 300 to 499, revised as of January 1, 2013, in Appendix A to Subpart Z of Part 390, at the bottom of page 1015, reinstate footnotes 10 through 12, and at the bottom of page 1019, reinstate footnotes 28 through 32, to read as follows:

Appendix A to Subpart Z to Part 390—Risk-Based Capital Requirements—Internal-Ratings-Based and Advanced Measurement Approaches

* * * * *

¹⁰ Entities include securities, insurance and other financial subsidiaries, commercial subsidiaries (where permitted), and significant minority equity investments in insurance, financial and commercial entities.

¹¹ Representing 50 percent of the amount, if any, by which total expected credit losses as calculated within the IRB approach exceed eligible credit reserves, which must be deducted from tier 1 capital.

¹² Including 50 percent of the amount, if any, by which total expected credit losses as calculated within the IRB approach exceed

eligible credit reserves, which must be deducted from tier 2 capital.

* * * * *

²⁸ Net unsecured credit exposure is the credit exposure after considering the benefits from legally enforceable netting agreements and collateral arrangements, without taking into account haircuts for price volatility, liquidity, etc.

²⁹ This may include interest rate derivative contracts, foreign exchange derivative contracts, equity derivative contracts, credit derivatives, commodity or other derivative contracts, repo-style transactions, and eligible margin loans.

³⁰ At a minimum, a State savings association must provide the disclosures in Table 11.7 in relation to credit risk mitigation that has been recognized for the purposes of reducing capital requirements under this appendix. Where relevant, State savings associations are encouraged to give further information about mitigants that have not been recognized for that purpose.

³¹ Credit derivatives that are treated, for the purposes of this appendix, as synthetic securitization exposures should be excluded from the credit risk mitigation disclosures and included within those relating to securitization.

³² Counterparty credit risk-related exposures disclosed pursuant to Table 11.6 should be excluded from the credit risk mitigation disclosures in Table 11.7.

* * * * *

[FR Doc. 2013-20707 Filed 8-22-13; 8:45 am]

BILLING CODE 1505-01-D

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0335; Directorate Identifier 2012-NM-187-AD; Amendment 39-17549; AD 2013-16-11]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A330-300, A340-200, and A340-300 series airplanes. This AD was prompted by a determination that ballscrew rupture could occur on certain trimmable horizontal stabilizer actuators (THSAs). This AD requires repetitive THSA ballscrew shaft integrity tests, and replacement if necessary. We are issuing this AD to detect and correct ballscrew rupture, which, along with corrosion on the ballscrew lower splines, may lead to

loss of transmission of THSA torque loads from the ballscrew to the tie-bar and consequent THSA blowback, which could result in loss of control of the airplane.

DATES: This AD becomes effective September 27, 2013.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 27, 2013.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. The NPRM was published in the **Federal Register** on May 2, 2013 (78 FR 25664). The NPRM proposed to correct an unsafe condition for the specified products. The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2012-0210, dated October 11, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

Since the issuance of EASA AD 2012-0061 which addresses the corrosion identified in service on THSA [part number] P/N 47147-500 and P/N 47147-700 at the level of the ballscrew lower splines, further analyses have been conducted to determine the need for any additional action.

The ballscrew lower splines are not loaded in normal operation, only in case of ballscrew rupture. Analysis results have shown that such rupture could happen during the current inspection interval imposed by the Maintenance Review Board Report (MRBR), task 274000-12.

Corrosion on the lower splines, in case of ballscrew rupture, may lead to loss of transmission of THSA torque loads from the ballscrew to the tie-bar and consequent THSA blowback, which could result in loss of control of the aeroplane.

For the reasons described above, this [EASA] AD requires reduction of the check interval of MRBR task 274000-12.

Required actions include repetitive THSA ballscrew shaft integrity tests. Corrective actions include replacement of the THSA. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (78 FR 25664, May 2, 2013) or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting this AD as proposed—except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 25664, May 2, 2013) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 25664, May 2, 2013).

Costs of Compliance

We estimate that this AD affects 30 products of U.S. registry. We also estimate that it takes 7 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the AD on U.S. operators to be \$17,850, or \$595 per product.

In addition, we estimate that any necessary follow-on actions take about 8 work-hours and require parts costing up to \$722,556, for a cost of up to \$723,236 per product. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition

that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the MCAI, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2013-16-11 Airbus: Amendment 39-17549. Docket No. FAA-2013-0335; Directorate Identifier 2012-NM-187-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective September 27, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes; and Model A340–211, –212, –213, –311, –312, and –313 airplanes; certificated in any category; all manufacturer serial numbers; if fitted with a trimmable horizontal stabilizer actuator (THSA) having part number (P/N) 47147–500 or P/N 47147–700.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Reason

This AD was prompted by a determination that ballscrew rupture could occur on certain THSAs. We are issuing this AD to detect and correct ballscrew rupture, which, along with corrosion on the ballscrew lower splines, may lead to loss of transmission of THSA torque loads from the ballscrew to the tie-bar and consequent THSA blowback, which could result in loss of control of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Repetitive Integrity Tests

At the later of the times specified in paragraph (g)(1) or (g)(2) of this AD, as applicable, do a THSA ballscrew shaft integrity test, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330–27–3191, dated June 7, 2012; or Airbus Mandatory Service Bulletin A340–27–4186, dated June 7, 2012; as applicable. Repeat the integrity test thereafter at intervals not to exceed 12,000 flight hours or 4,400 flight cycles, whichever occurs first.

(1) At the latest of the times specified in paragraph (g)(1)(i), (g)(1)(ii), or (g)(1)(iii) of this AD.

(i) Within 12,000 flight hours since the airplane's first flight; or

(ii) Within 12,000 flight hours since the most recent THSA ballscrew shaft integrity test was done as specified in maintenance review board report (MRBR) Task 274000–12; or

(iii) Within 12,000 flight hours since the most recent THSA ballscrew shaft integrity test was done, as specified in Airbus Mandatory Service Bulletin A330–27–3179 or Airbus Mandatory Service Bulletin A340–27–4175, as applicable. (These service bulletins specify testing in case of type II or type III findings).

(2) Within 1,000 flight hours after the effective date of this AD, but without exceeding the latest of the times specified in paragraph (g)(2)(i), (g)(2)(ii), or (g)(2)(iii) of this AD.

(i) 16,000 flight hours since the airplane's first flight.

(ii) 16,000 flight hours since the most recent THSA ballscrew shaft integrity test was done, as specified in MRBR task 274000–12.

(iii) 16,000 flight hours since the most recent THSA ballscrew shaft integrity test was done, as specified in Airbus Mandatory Service Bulletin A330–27–3179, or Airbus Mandatory Service Bulletin A340–27–4175, as applicable. (These service bulletins specify testing in case of type II or type III findings).

(h) Replacement

If the result from any test required by paragraph (g) of this AD is not correct, as specified in the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330–27–3191, dated June 7, 2012; or Airbus Mandatory Service Bulletin A340–27–4186, dated June 7, 2012; as applicable: Before further flight, replace the THSA with a serviceable THSA, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330–27–3191, dated June 7, 2012; or Airbus Mandatory Service Bulletin A340–27–4186, dated June 7, 2012; as applicable. Replacement of a THSA, as required by this paragraph, with a THSA having P/N 47147–500 or P/N 47147–700, is not terminating action for the repetitive tests required by paragraph (g) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone (425) 227–1138; fax (425) 227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information European Aviation Safety Agency Airworthiness Directive 2012–0210, dated October 11, 2012, for related information, which can be found

in the AD docket on the internet at <http://www.regulations.gov>.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Mandatory Service Bulletin A330–27–3191, dated June 7, 2012.

(ii) Airbus Mandatory Service Bulletin A340–27–4186, dated June 7, 2012.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 1, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013–19161 Filed 8–22–13; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2013–0341; Directorate Identifier 2012–SW–025–AD; Amendment 39–17557; AD 2013–16–19]

RIN 2120–AA64

Airworthiness Directives; Eurocopter France Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter France (Eurocopter) Model EC120B and EC130B4 helicopters with a certain emergency flotation gear (float) installed. This AD requires inspecting the float for chafing of the fabric covering and adding protectors to the float installation to prevent contact between the float and the protruding