

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-03-06 The Boeing Company:
Amendment 39-17743; Docket No. FAA-2013-0866; Directorate Identifier 2013-NM-131-AD.

(a) Effective Date

This AD is effective April 9, 2014.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE (http://rgl.faa.gov/Regulatory_and_Guidance_Library/rqstc.nsf/0/2C6E3DBDDD36F91C862576A4005D64E2?OpenDocument&Highlight=st01219se) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of cracks found in the aft support fitting for the main landing gear (MLG) beam, and the rear spar upper chord and rear spar web. We are issuing this AD to detect and correct such cracks, which could grow and result in a fuel leak and possible fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections: Group 1

For airplanes identified in Group 1 of Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013: At the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013, except as required by paragraph (i) of this AD, do inspections and applicable corrective actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Inspections: Groups 2-7

For airplanes identified in Groups 2 through 7 of Boeing Special Attention

Service Bulletin 737-57-1318, dated May 15, 2013: At the applicable time specified in paragraph 1.E., “Compliance,” of Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013, except as required by paragraph (i) of this AD, do high frequency eddy current inspections to detect cracking of the aft support fitting for the MLG beam, and the rear spar upper chord and rear spar web in the area of rear spar station 224.14, as applicable, in accordance with Option 1, 2, or 3 of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013.

(1) If no crack is found, repeat the inspection thereafter at the time specified in paragraph 1.E., “Compliance,” of Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013, as applicable. Accomplishment of the inspection of the 12 fastener holes (locations 1-12) in accordance with Option 2, Action 3; or Option 3, Action 3; as specified in note (b) of tables 2 through 5 of paragraph 1.E., “Compliance,” of Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013; terminates only the corresponding inspections that include note (b) in the “Repeat Interval” column of the applicable table.

(2) If any crack is found during any inspection required by paragraph (g) or (g)(1) of this AD, repair before further flight using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Exception to Service Information Specifications

Where Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA), which has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

For more information about this AD, contact Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6440; fax: 425-917-6590; email: nancy.marsh@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 737-57-1318, dated May 15, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 18, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-02521 Filed 3-4-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0702; Directorate Identifier 2012-NM-181-AD; Amendment 39-17753; AD 2014-03-15]

RIN 2120-AA64

Airworthiness Directives; 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding airworthiness directive (AD) 2008-14-

16 for certain 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328–100 and 328–300 airplanes. AD 2008–14–16 required installing warning placards on the inside of the passenger door and service doors and modifying the hinge supports and support struts of the passenger doors. This new AD continues to require the actions required by AD 2008–14–16 and also requires replacing the fasteners which were installed as part of the modification with new fasteners of the correct length, adds new airplanes, and removes one airplane. This AD was prompted by reports that certain fasteners, which were installed as part of the modification, are the wrong length. We are issuing this AD to prevent incidents of inadvertent opening and possible detachment of a passenger door in-flight, resulting in damage to airframe and systems and loss of control of the airplane.

DATES: This AD becomes effective April 9, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 9, 2014.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of August 21, 2008 (73 FR 40955, July 17, 2008).

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0702>; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D–82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; email gsc.op@328support.de; Internet <http://www.328support.de>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW, Renton, WA 98057–3356; telephone (425) 227–1175; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008). AD 2008–14–16 applied to certain 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Model 328–100 and 328–300 airplanes. The NPRM published in the **Federal Register** on August 27, 2013 (78 FR 52872). The NPRM was prompted by reports that certain fasteners, which were installed as part of the modification, are the wrong length. The NPRM proposed to continue to require installing warning placards on the inside of the passenger door and service doors and modifying the hinge supports and support struts of the passenger doors. The NPRM also proposed to require replacing the fasteners which were installed as part of the modification with new fasteners of the correct length, adds new airplanes, and removes one airplane. We are issuing this AD to prevent incidents of inadvertent opening and possible detachment of a passenger door in-flight, resulting in damage to airframe and systems and loss of control of the airplane.

The European Aviation Safety Agency (EASA), which is the aviation authority for Member States of the European Community, has issued EASA Airworthiness Directive 2012–0183R1, dated September 28, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

At least one incident occurred where, immediately after take-off, the passenger door of a Dornier 328 aeroplane completely opened. The flight crew reportedly had no cockpit indication or audible chime prior to this event. The aeroplane returned to the departure airfield and made an uneventful emergency landing. Substantial damage to the door, handrails, door hinge arms and fuselage skin were found.

The subsequent investigation could not find any deficiency in the design of the main cabin door locking mechanism. In addition, no technical failure could be determined that precipitated the event. The flight data recorder showed that the door was closed and locked before take-off and opened shortly afterwards. Although final proof could not be obtained, the most likely way in which the door opened was that the door handle was inadvertently operated during the take-off run.

In response to the incident, AvCraft (the TC holder at the time) developed a placard

set to warn the occupants against touching the door handle, as well as a structural modification of the passenger door hinge supports described in [Dornier 328 Support Services] Service Bulletin (SB) SB–328–52–460 and SB–328J–52–213 to make certain that the door does not separate from the aeroplane when inadvertently opened during flight, allowing a safe descent and landing.

EASA issued AD 2007–0199 (<http://ad.easa.europa.eu/ad/2007-0199>) to require the installation of warning placards and modification as detailed in these SB instructions.

Since that [EASA] AD [2007–0199] was issued, 328 Support Services GmbH (the current type certificate holder) have determined that certain fasteners, identified by Part Number (P/N) NAS6703U1 and P/N NAS6703U2, which were installed as part of the modification, have the wrong length and must be replaced.

For the reasons described above, this [EASA] AD retains the requirements of EASA AD 2007–0199, which is superseded, and requires replacement of the affected fasteners by the ones that have the correct length.

This [EASA] AD has been revised to correct and clarify the actions required by paragraph (3).

This AD also adds new airplanes and removes one airplane from the applicability of this AD. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0702>.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (78 FR 52872, August 27, 2013), or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (78 FR 52872, August 27, 2013) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (78 FR 52872, August 27, 2013).

Costs of Compliance

We estimate that this AD affects 35 airplanes of U.S. registry.

The actions that are required by AD 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008), and retained in this AD take about 38 work-hours per product, at an average labor rate of \$85 per work-hour. Required parts cost about \$11,961 per product. Based on these figures, the estimated cost of the

actions that were required by AD 2008–14–16 is \$15,191 per product.

We also estimate that it will take about 25 work-hours per product to comply with the new basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$74,375, or \$2,125 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that

authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov/>#!/docketDetail;D=FAA-2013-0702; or in person at the Docket Management

Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008), and adding the following new AD:

2014–03–15 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH): Amendment 39–17753. Docket No. FAA–2013–0702; Directorate Identifier 2012–NM–181–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective April 9, 2014.

(b) Affected ADs

This AD supersedes AD 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008).

(c) Applicability

This AD applies to 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model 328–100 airplanes, serial numbers 3005 through 3101 inclusive, 3103, 3104, 3106, 3109, 3110, 3112, 3113, 3115, 3117, and 3119.

(2) Model 328–300 airplanes, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 11, Placards and Markings; and Code 52, Doors.

(e) Reason

This AD was prompted by reports that certain fasteners, which were installed as part of a modification, are the wrong length. We are issuing this AD to prevent incidents

of inadvertent opening and possible detachment of a passenger door in-flight, resulting in damage to airframe and systems and loss of control of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Retained Installation and Modification for Airplanes Identified in AD 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008) With Revised Service Information

This paragraph restates the requirements of paragraph (f) of AD 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008), with revised service information.

(1) For Model 328–100 airplanes, serial numbers 3005 through 3098 inclusive, 3100, 3106, 3109, 3110, 3112, 3113, 3115, 3117, and 3119; and Model 328–300 airplanes, having serial numbers 3102, 3105, 3108, 3111, 3114, 3116, 3118, and 3120 through 3224 inclusive: Within 30 days after August 21, 2008, (the effective date of AD 2008–14–16, Amendment 39–15611 (73 FR 40955, July 17, 2008)), install warning placards on the inside of the passenger door and service doors, in accordance with the Accomplishment Instructions of the service information specified in paragraph (g)(1)(i) or (g)(1)(ii) of this AD, as applicable.

(i) Dornier Service Bulletin SB–328–11–454, dated May 3, 2004 (for Model 328–100 airplanes).

(ii) Dornier Service Bulletin SB–328J–11–209, dated May 3, 2004 (for Model 328–300 airplanes).

(2) For Model 328–100 airplanes, serial numbers 3005 through 3098 inclusive, 3100, 3106, 3109, 3110, 3112, 3113, 3115, 3117, and 3119; and Model 328–300 airplanes, having serial numbers 3102, 3105, 3108, 3111, 3114, 3116, 3118, and 3120 through 3224 inclusive: Within 12 months after August 21, 2008, the effective date of AD 2008–14–16, Amendment 39–15611 (73 FR 0955, July 17, 2008), modify the hinge supports and support struts of the passenger doors, in accordance with the Accomplishment Instructions of the service information specified in paragraphs (g)(2)(i) through (g)(2)(iv) of this AD, as applicable. As of the effective date of this AD only the service information specified in paragraph (g)(2)(ii) or (g)(2)(iv) of this AD, as applicable, may be used.

(i) Dornier Service Bulletin SB–328–52–460, dated February 4, 2005 (for Model 328–100 airplanes).

(ii) 328 Support Services Service Bulletin SB–328–52–460, Revision 2, dated March 1, 2012 (for Model 328–100 airplanes).

(iii) Dornier Service Bulletin SB–328J–52–213, dated February 4, 2005, (for Model 328–300 airplanes).

(iv) 328 Support Services Service Bulletin SB–328J–52–213, Revision 1, dated August 17, 2011 (for Model 328–300 airplanes).

(h) New Installation and Modification for Newly Added Airplanes

For airplanes not identified in paragraph (g) of this AD, do the actions required by paragraphs (h)(1) and (h)(2) of this AD.

(1) Within 30 days after the effective date of this AD, install warning placards on the inside of the passenger door and service doors, in accordance with the Accomplishment Instructions of Dornier Service Bulletin SB-328-11-454, dated May 3, 2004 (for Model 328-100 airplanes); or Dornier Service Bulletin SB-328J-11-209, dated May 3, 2004 (for Model 328-300 airplanes); as applicable.

(2) Within 12 months after the effective date of this AD, modify the hinge supports and support struts of the passenger doors, in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-52-460, Revision 2, dated March 1, 2012 (for Model 328-100 airplanes); or 328 Support Services Service Bulletin SB-328J-52-213, Revision 1, dated August 17, 2011 (for Model 328-300 airplanes); as applicable.

(i) New Replacement of Fasteners for All Airplanes

For airplanes on which 26 part number NAS6703U1 fasteners were installed as specified in the service information in paragraphs (g)(2)(i) and (g)(2)(iii) of this AD: Within 6 months after the effective date of this AD, replace the 20 affected part number NAS6703U1 fasteners with new fasteners having part number NAS6703U2, in accordance with the Accomplishment Instructions of 328 Support Services Service Bulletin SB-328-52-460, Revision 2, dated March 1, 2012 (for Model 328-100 airplanes); or 328 Support Services Service Bulletin SB-328J-52-213, Revision 1, dated August 17, 2011 (for Model 328-300 airplanes); as applicable.

Note 1 to paragraph (i) of this AD: 328 Support Services Service Bulletin SB-328-52-460, Revision 2, dated March 1, 2012, and 328 Support Services Service Bulletin SB-328J-52-213, Revision 1, dated August 17, 2011, identify 20 of 26 part number NAS6703U1 fasteners requiring to be replaced due to incorrect length.

(j) Credit for Previous Actions

This paragraph provides credit for certain actions required by paragraph (g) and (h)(2) of this AD, if those actions were performed before the effective date of this AD using 328 Support Services Service Bulletin SB-328-52-460, Revision 1, dated August 17, 2011, which is not incorporated by reference.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356;

telephone (425) 227-1175; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directive 2012-0183R1, dated September 28, 2012, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0702>.

(2) Service information identified in this AD that is not incorporated by reference in this AD may be obtained at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on April 9, 2014.

(i) 328 Support Services Service Bulletin SB-328-52-460, Revision 2, dated March 1, 2012.

(ii) 328 Support Services Service Bulletin SB-328J-52-213, Revision 1, dated August 17, 2011.

(4) The following service information was approved for IBR on August 21, 2008 (73 FR 40955, July 17, 2008).

(i) Dornier Service Bulletin SB-328-11-454, dated May 3, 2004.

(ii) Dornier Service Bulletin SB-328J-11-209, dated May 3, 2004.

(iii) Dornier Service Bulletin SB-328-52-460, dated February 4, 2005.

(iv) Dornier Service Bulletin SB-328J-52-213, dated February 4, 2005.

(5) For service information identified in this AD, contact 328 Support Services GmbH, Global Support Center, P.O. Box 1252, D-82231 Wessling, Federal Republic of Germany; telephone +49 8153 88111 6666; fax +49 8153 88111 6565; email gsc.op@328support.de; Internet <http://www.328support.de>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 31, 2014.

John P. Piccola,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-02995 Filed 3-4-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0351; Directorate Identifier 2009-SW-049-AD; Amendment 39-17770; AD 2014-04-11]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters (Type Certificate Previously Held by Eurocopter France) (Airbus Helicopters)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS350B, BA, B1, B2, B3, and D, and Model AS355E, F, F1, F2, and N helicopters with certain tail rotor (T/R) blades. This AD requires installing additional rivets to secure each T/R blade trailing edge tab (tab), and inspecting for evidence of debonding of the tab after the rivets are installed. This AD was prompted by reports of T/R blade tab debonding. The actions of this AD are intended to prevent loss of a T/R blade tab, which could result in excessive vibration and loss of control of the helicopter.

DATES: This AD is effective April 9, 2014.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of April 9, 2014.

ADDRESSES: For service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region,