

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2014-0488; Directorate Identifier 2014-NM-141-AD; Amendment 39-17919; AD 2014-15-17]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes. This AD requires revising the airplane flight manual to incorporate temporary revisions that introduce additional limitations for operation of taxi and landing lights. This AD was prompted by a determination that there is a potential for fuel leakage from auxiliary power unit (APU) boost pump component installations in the right-hand landing lights compartment. We are issuing this AD to advise the flightcrew of the limitations for taxi lights and landing lights to prevent heat generated by the taxi lights and landing lights on the ground reaching the auto-ignition temperature of the fuel, which could potentially ignite any fuel or fumes present in the right-hand landing lights compartment.

DATES: This AD becomes effective July 31, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 31, 2014.

We must receive comments on this AD by September 15, 2014.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0488; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Morton Lee, Aerospace Engineer, Propulsion and Services Branch, ANE-173, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7355; fax 516-794-5531.

SUPPLEMENTARY INFORMATION:**Discussion**

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2014-17, dated June 17, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes. The MCAI states:

Bombardier Inc. has determined that there is a potential for fuel leakage from the auxiliary power unit (APU) boost pump component installations in the right hand landing lights compartment. On a hot day, the temperatures in the landing light compartment as result of the heat generated by the taxi lights and/or the landing lights on the ground, can reach the auto-ignition temperature of the fuel and may ignite any fuel/fumes present in the right hand landing light compartment.

In order to mitigate the potential safety hazard, Bombardier Inc. has revised the Aircraft Flight Manual (AFM) through Temporary Revisions (TRs) 604/38 and 605/

20 to introduce additional limitations for operation of the landing/taxi lights on the ground.

This [Canadian] AD is being issued to mandate compliance with the revised AFM limits for landing/taxi light operations per the TR 604/38 and TR 605/20, as applicable for the affected aeroplanes.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0488.

Relevant Service Information

Bombardier has issued the following service information:

- Temporary Revision (TR) 604/38, dated June 16, 2014, to the Bombardier Challenger CL-604 Airplane Flight Manual, PSP 604-1; and
- TR 605/20, dated June 16, 2014, to the Bombardier Challenger CL-605 Airplane Flight Manual, PSP 605-1.

The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

“Contacting the Manufacturer” Paragraph in This AD

Since late 2006, we have included a standard paragraph titled “Airworthy Product” in all MCAI ADs in which the FAA develops an AD based on a foreign authority's AD.

We have become aware that some operators have misunderstood or misinterpreted the Airworthy Product paragraph to allow the owner/operator to use messages provided by the manufacturer as approval of deviations during the accomplishment of an AD-mandated action. The Airworthy Product paragraph does not approve messages or other information provided by the manufacturer for deviations to the requirements of the AD-mandated actions. The Airworthy Product paragraph only addresses the requirement to contact the manufacturer for corrective actions for the identified unsafe condition and does not cover

deviations from other AD requirements. However, deviations to AD-required actions are addressed in 14 CFR 39.17, and anyone may request the approval for an alternative method of compliance to the AD-required actions using the procedures found in 14 CFR 39.19.

To address this misunderstanding and misinterpretation of the Airworthy Product paragraph, we have changed the paragraph and retitled it "Contacting the Manufacturer." This paragraph now clarifies that for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the FAA, TCCA, or Bombardier, Inc.'s TCCA Design Approval Organization (DAO).

The Contacting the Manufacturer paragraph also clarifies that, if approved by the DAO, the approval must include the DAO-authorized signature. The DAO signature indicates that the data and information contained in the document are TCCA-approved, which is also FAA-approved. Messages and other information provided by the manufacturer that do not contain the DAO-authorized signature approval are not TCCA-approved, unless TCCA directly approves the manufacturer's message or other information.

This clarification does not remove flexibility previously afforded by the Airworthy Product paragraph. Consistent with long-standing FAA policy, such flexibility was never intended for required actions. This is also consistent with the recommendation of the Airworthiness Directive Implementation Aviation Rulemaking Committee to increase flexibility in complying with ADs by identifying those actions in manufacturers' service instructions that are "Required for Compliance" with ADs. We continue to work with manufacturers to implement this recommendation. But once we determine that an action is required, any deviation from the requirement must be approved as an alternative method of compliance.

We also have decided not to include a generic reference to either the "delegated agent" or "DAH with State of Design Authority design organization approval," but instead we have provided the specific delegation approval granted by the State of Design Authority for the DAH in the Contacting the Manufacturer paragraph of this AD.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to

the flying public justifies waiving notice and comment prior to adoption of this rule because heat generated by the taxi lights and landing lights on the ground could reach the auto-ignition temperature of the fuel, which could potentially ignite any fuel or fumes present in the right-hand landing lights compartment. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0488; Directorate Identifier 2014-NM-141-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 169 airplanes of U.S. registry.

We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$14,365, or \$85 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with

promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-15-17 Bombardier, Inc.: Amendment 39-17919. Docket No. FAA-2014-0488; Directorate Identifier 2014-NM-141-AD.

(a) Effective Date

This AD becomes effective July 31, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model CL-600-2B16 (CL-604 Variant) airplanes,

certificated in any category, serial numbers 5301 through 5665 inclusive, and 5701 and subsequent.

(d) Subject

Air Transport Association (ATA) of America Code 28, Fuel; and 33, Lights.

(e) Reason

This AD was prompted by a determination that there is a potential for fuel leakage from auxiliary power unit (APU) boost pump component installations in the right-hand landing lights compartment. We are issuing this AD to advise the flightcrew of the limitations for taxi lights and landing lights to prevent heat generated by the taxi lights and landing lights on the ground reaching the auto-ignition temperature of the fuel, which could potentially ignite any fuel or fumes present in the right-hand landing lights compartment.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Airplane Flight Manual (AFM) Revision

Within 24 hours after the effective date of this AD, revise the AFM to incorporate the applicable temporary revisions (TRs) specified in paragraphs (g)(1) and (g)(2) of this AD. Operate the airplane according to the procedures in the TRs specified in paragraph (g)(1) or (g)(2) of this AD, as applicable. The AFM revision required by paragraph (g) of this AD may be done by inserting a copy of TR 604/38, Taxi and Landing Lights, dated June 16, 2014, into the Bombardier Challenger CL-604 AFM, PSP 604-1; or a copy of TR 605/20, Taxi and Landing Lights, dated June 16, 2014, into the Bombardier Challenger CL-605 AFM, PSP 605-1. When these TRs have been included in the general revisions of the applicable AFM, the general revisions may be inserted in the AFM and the TRs may be removed, provided the relevant information in the general revision is identical to that included in TR 604/38, Taxi and Landing Lights, dated June 16, 2014; or TR 605/20, Taxi and Landing Lights, dated June 16, 2014; as applicable.

(1) TR 604/38, Taxi and Landing Lights, dated June 16, 2014, to the Bombardier Challenger CL-604 AFM, PSP 604-1 (for Bombardier Model CL-600-2B16 (604 Variant) airplanes, serial numbers 5301 through 5665 inclusive).

(2) TR 605/20, Taxi and Landing Lights, dated June 16, 2014, to the Bombardier Challenger CL-605 Airplane Flight Manual PSP 605-1 (for Bombardier Model CL-600-2B16 (604 Variant) airplanes, serial numbers 5701 and subsequent).

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-173, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal

inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2014-17, dated June 17, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0488.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Temporary Revision (TR) 604/38, Taxi and Landing Lights, dated June 16, 2014, to the Bombardier Challenger CL-604 Airplane Flight Manual, PSP 604-1.

(ii) TR 605/20, Taxi and Landing Lights, dated June 16, 2014, to the Bombardier Challenger CL-605 Airplane Flight Manual, PSP 605-1.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 24, 2014.

Ross Landes,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-17910 Filed 7-30-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2013-0987; Airspace Docket No. 13-AWP-19]

Establishment of Class E Airspace; Needles, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace at the Needles VHF Omni-Directional Radio Range Tactical Air Navigation Aid (VORTAC), Needles, CA, to facilitate vectoring of Instrument Flight Rules (IFR) aircraft under control of Los Angeles Air Route Traffic Control Center (ARTCC). This improves the safety and management of IFR operations within the National Airspace System.

DATES: Effective date, 0901 UTC, November 13, 2014. The Director of the Federal Register approves this incorporation by reference action under 1 CFR Part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.9X, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/code-of-federal-regulations/ibr-locations.html>.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15. For further information, you can contact the Airspace Policy and ATC Procedures Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783.

FOR FURTHER INFORMATION CONTACT: Bill Nugent, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601