

Revision 01, dated March 31, 2014: Within 6,600 flight hours after the effective date of this AD, do a general visual inspection for tube misalignment on the pitot number 1 and pitot number 2 tube assemblies; do all applicable corrective actions; and install a new tube ribbon heater on the pitot number 1 and pitot number 2 tube assemblies; in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145–30–0056, Revision 01, dated March 31, 2014. Do all applicable corrective actions before further flight.

(2) For airplanes identified as Group 1 in Embraer Service Bulletin 145LEG–30–0021, dated March 31, 2014: Within 5,000 flight hours or 48 months after the effective date of this AD, whichever occurs first, do a general visual inspection for tube misalignment on the pitot number 1 and pitot number 2 tube assemblies; do all applicable corrective actions; and install a new tube ribbon heater on the pitot number 1 and pitot number 2 tube assemblies; in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145LEG–30–0021, dated March 31, 2014. Do all applicable corrective actions before further flight.

(h) Inspection, Corrective Action, and Replacement

(1) For airplanes identified as Group 2 in Embraer Service Bulletin 145–30–0056, Revision 01, dated March 31, 2014: Within 6,600 flight hours after the effective date of this AD, do a general visual inspection for tube misalignment on the pitot number 1 and pitot number 2 tube assemblies; do all applicable corrective actions; and replace the tube ribbon heater with a new tube ribbon heater on the pitot number 1 and pitot number 2 tube assemblies; in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145–30–0056, Revision 01, dated March 31, 2014. Do all applicable corrective actions before further flight.

(2) For airplanes identified as Group 2 in Embraer Service Bulletin 145LEG–30–0021, dated March 31, 2014: Within 5,000 flight hours or 48 months after the effective date of this AD, whichever occurs first, do a general visual inspection for tube misalignment on the pitot number 1 and pitot number 2 tube assemblies; do all applicable corrective actions; and replace the tube ribbon heater with a new tube ribbon heater on the pitot number 1 and pitot number 2 tube assemblies; in accordance with the Accomplishment Instructions of Embraer Service Bulletin 145LEG–30–0021, dated March 31, 2014. Do all applicable corrective actions before further flight.

(i) Airplane Flight Manual (AFM) Revision

(1) For airplanes identified in paragraphs (c)(1) and (c)(3) of this AD: Within 60 days after the effective date of this AD, revise the AFM to include the information in the “Unreliable Airspeed Procedure” in the Emergency/Abnormal Procedures section and the “Unreliable Airspeed Tables” (corresponding to the airplane configuration) in the Performance section, as specified in Embraer Temporary Revision (TR) 40.2, dated April 4, 2014, to Volume 1, of the

Embraer EMB–145 Aircraft Operations Manual (AOM) AOM–145/1114 (“Embraer TR 40.2”).

(2) For airplanes identified in paragraphs (c)(2) and (c)(4) of this AD: Within 60 days after the effective date of this AD, revise the AFM to include the information in the “Unreliable Airspeed Procedure” in the Emergency/Abnormal Procedures section and the “Unreliable Airspeed Tables” (corresponding to the airplane configuration) in the Performance section, as specified in Embraer TR 19.1, dated April 22, 2014, to Volume 1 of the Embraer EMB–145 AOM AOM–2014135/1542 (“Embraer TR 19.1”).

(j) AFM Revision Method of Compliance

The AFM revisions required by paragraphs (i)(1) and (i)(2) of this AD may be done by inserting Embraer AOM TR 40.2 or Embraer AOM TR 19.1, as applicable, into the AFM. When the applicable Embraer AOM TR has been included in general revisions of the AFM, the general revisions may be inserted in the AFM, provided the relevant information in the general revision is identical to that in Embraer AOM TR 40.2 or Embraer AOM TR 19.1, as applicable, and the applicable Embraer AOM TR may be removed from the AFM.

(k) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraphs (g)(1) and (h)(1) of this AD, if those actions were performed before the effective date of this AD using Embraer Service Bulletin 145–30–0056, dated December 19, 2013.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1175; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the Agência Nacional de Aviação Civil (ANAC); or ANAC’s authorized Designee. If approved by the ANAC Designee, the approval must include the Designee’s authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Brazilian Airworthiness Directive 2016–03–01, effective March 11, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9049.

(2) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227–901 São Jose dos Campos—SP—Brasil; telephone +55 12 3927–5852 or +55 12 3309–0732; fax +55 12 3927–7546; email distrib@embraer.com.br; Internet <http://www.flyembraer.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on August 18, 2016.

Dorr M. Anderson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–20684 Filed 8–29–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–9051; Directorate Identifier 2016–NM–035–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A300 B4–603, B4–620, and B4–622 airplanes; Model A300 B4–605R and A300 B4–622R airplanes; and Model A300 C4–605R Variant F airplanes. This proposed AD was prompted by an in-service detection of cracks in the fuselage skin lap joints. This proposed AD would require an ultrasonic inspection of certain skin lap joints, and repair if necessary. We are proposing this AD to detect and correct cracks in certain skin lap joints. Such cracking could result in reduced structural integrity of the airplane.

DATES: We must receive comments on this proposed AD by October 14, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202–493–2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9051; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–2125;

fax 425–227–1149; email dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2016–9051; Directorate Identifier 2016–NM–035–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016–0557, dated March 18, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A300 B4–603, B4–620, and B4–622 airplanes; Model A300 B4–605R and A300 B4–622R airplanes; and Model A300 C4–605R Variant F airplanes. The MCAI states:

Prompted by in-service detection on Airbus A300–600 aeroplanes of cracks in certain fuselage skin lap joints, several studies were launched to understand the phenomenon and provide the corrective actions. More recently, new analyses were performed and the results identified that a new area has to be inspected at the skin lap joint below Stringer (STR) 28 at Frame (FR) 72 to FR 76.

This condition, if not detected and corrected, could result in reduced structure integrity of the aeroplane.

To address this unsafe condition, Airbus published Service Bulletin (SB) A300–53–6184 [dated November 12, 2015] to introduce inspections and applicable corrective actions for the affected areas.

For the reason described above, this [EASA] AD requires repetitive Special Detail Inspections (SDI) of the affected skin lap joint and, depending on findings, accomplishment of applicable corrective action(s) [repairs].

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9051.

Related Service Information Under 1 CFR Part 51

We reviewed Airbus Service Bulletin A300–53–6184, November 12, 2015. The service information describes procedures for an ultrasonic inspection of the skin lap joint below stringer 28 at FR 72 to FR 76, and repair if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Costs of Compliance

We estimate that this proposed AD affects 29 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Cost per product	Cost on U.S. operators
Ultrasonic inspection	6 work-hours × \$85 per hour = \$510 per inspection cycle.	\$510 per inspection cycle	\$14,790 per inspection cycle.

We have no way to determine the costs to do any necessary repairs that would be required based on the results of the proposed inspection. We have no way of determining the number of airplanes that might need these repairs.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII,

Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2016–9051; Directorate Identifier 2016–NM–035–AD.

(a) Comments Due Date

We must receive comments by October 14, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Model A300 B4–603, B4–620, and B4–622 airplanes; Model A300 B4–605R and A300 B4–622R airplanes; and Model A300 C4–605R Variant F airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by an in-service detection of cracks in the fuselage skin lap joints. We are issuing this AD to detect and correct cracks in the skin lap joint below stringer 28 at frame (FR) 72 to FR 76. Such cracking could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Before 29,500 flight cycles since the first flight of the airplane or within 2,000 flight cycles after the effective date of this AD, whichever occurs later, do an ultrasonic inspection for cracks of the skin lap joint below stringer 28 at FR 72 to FR 76 and do all applicable repairs before further flight, in accordance with the Accomplishment Instruction of Airbus Service Bulletin A300–53–6184, November 12, 2015, except as required by paragraph (h) of this AD. Repeat the ultrasonic inspection thereafter at intervals not to exceed 5,400 flight cycles.

(h) Exceptions to Service Information Specified Paragraph (g) of This AD

Where Airbus Service Bulletin A300–53–6184, November 12, 2015, specifies to contact Airbus for repair instructions, and specifies that action as “RC” (Required for Compliance), this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–2125; fax 425–227–1149; email dan.rodina@faa.gov. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight

standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the EASA; or Airbus’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (h) of this AD: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016–0557, dated March 18, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9051.

(2) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on August 19, 2016.

Dorr M. Anderson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–20685 Filed 8–29–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–9050; Directorate Identifier 2016–NM–086–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.