

AD 2018–0212 (October 12, 2018), this AD requires using the effective date of this AD.

(2) Where paragraph (2) of EASA ADs 2018–0212 and 2018–0212R1 specifies replacing “with instructions provided by Airbus,” for this AD, the replacement must be done using a method approved in accordance with the procedures specified in paragraph (i)(2) of this AD.

(3) Where paragraphs (1) and (3) of EASA ADs 2018–0212 and 2018–0212R1 specify flight cycles (FC), this AD requires using “total flight cycles.”

(4) The “Remarks” sections of EASA ADs 2018–0212 and 2018–0212R1 do not apply.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA AD 2018–0212 or EASA AD 2018–0212R1 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference

(IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018–0212, dated September 28, 2018.

(ii) European Aviation Safety Agency (EASA) AD 2018–0212R1, dated March 28, 2019.

(3) For EASA AD 2018–0212 and EASA AD 2018–0212R1, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find these EASA ADs on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view these EASA ADs at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. EASA AD 2018–0212 and EASA AD 2018–0212R1 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1068.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 10, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–13059 Filed 6–19–19; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0407; Product Identifier 2019–NM–075–AD; Amendment 39–19648; AD 2019–11–02]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2017–16–10, which applied to all The Boeing Company Model 777 airplanes. AD 2017–16–10 required repetitive inspections of the left and right side underwing longerons for any crack, and related investigative and corrective

actions if necessary. This AD retains the requirements of AD 2017–16–10, reduces certain compliance times for certain airplanes, and removes airplanes from the applicability. This AD was prompted by reports of cracks on the underwing longerons. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 5, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 5, 2019.

The FAA must receive any comments on this AD by August 5, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; phone: 562–797–1717; internet: <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0407.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0407; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Eric Lin, Aerospace Engineer, Airframe

Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3523; email: eric.lin@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued AD 2017-16-10, Amendment 39-18987 (82 FR 39513, August 21, 2017) ("AD 2017-16-10"), for all The Boeing Company Model 777 airplanes. AD 2017-16-10 required repetitive inspections of the left and right side underwing longerons for any crack, and related investigative and corrective actions if necessary. AD 2017-16-10 resulted from reports of cracks on the underwing longerons. The FAA issued AD 2017-16-10 to address cracks in the underwing longerons, which could result in fuel leakage into the forward cargo area and consequent increased risk of a fire or, in a more severe case, could adversely affect the structural integrity of the airplane.

Actions Since AD 2017-16-10 Was Issued

Since we issued AD 2017-16-10, the FAA has determined that it is necessary to reduce certain compliance times for certain airplanes to address the unsafe condition. The FAA has also determined that it is necessary to remove certain airplanes from the applicability because the unsafe condition has been addressed in production on line numbers 1523, and 1525 and subsequent. The FAA is issuing this AD to address cracks in the underwing longerons, which could result in fuel leakage into the forward cargo area and consequent increased risk of a fire or, in a more severe case, could adversely affect the structural integrity of the airplane.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Boeing Alert Service Bulletin 777-53A0081, Revision

2, dated March 29, 2019. This service information describes procedures for repetitive detailed inspections, ultrasonic inspections, high frequency eddy current (HFEC) inspections of the left and right side underwing longerons, a surface HFEC inspection of the external surface of the fuselage skin, and applicable on-condition actions. On condition actions include replacement of the left or right underwing longeron, as applicable. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

The FAA is issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

Although this AD does not explicitly restate the requirements of AD 2017-16-10, this AD retains all of the requirements of AD 2017-16-10. Those requirements are referenced in the service information identified previously, which, in turn, is referenced in paragraph (g) of this AD. This AD reduces certain compliance times for certain airplanes and removes airplanes from the applicability. This AD also requires accomplishment of the actions identified as "RC" (required for compliance) in the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, described previously.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0407.

FAA's Justification and Determination of the Effective Date

There are currently no U.S. operators affected by the new reduced compliance times required by this AD. Therefore, we find good cause that notice and opportunity for prior public comment are unnecessary. In addition, for the reason(s) stated above, the FAA finds that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written data, views, or arguments about this final rule. Send your comments to an address listed under the ADDRESSES section. Include the docket number FAA-2019-0407 and Product Identifier 2019-NM-075-AD at the beginning of your comments. The agency specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this final rule. The agency will consider all comments received by the closing date and may amend this final rule because of those comments.

The FAA will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact the agency receives about this final rule.

Costs of Compliance

The FAA estimate that this AD affects 214 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Option 1: Detailed Inspection (retained actions from AD 2017-16-10).	4 work-hours × \$85 per hour = \$340 per inspection cycle.	\$0	\$340 per inspection cycle	\$72,760 per inspection cycle.
Option 2: Detailed and HFEC or Ultrasonic Inspection (retained actions from AD 2017-16-10).	12 work-hours × \$85 per hour = \$1,020 per inspection cycle.	\$0	\$1,020 per inspection cycle	\$218,280 per inspection cycle.

The new requirements of this AD (reduced compliance times) do not currently affect U.S. operators and,

therefore, add no additional economic burden.

The FAA estimates the following costs to do any necessary replacements

that would be required based on the results of the inspections. The agency has no way of determining the number

of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Left side or right side underwing longeron replacement.	102 work-hours × \$85 per hour = \$8,670 per side.	\$31,000 per side	\$39,670 per side.

The FAA has received no definitive data that would enable us to provide cost estimates for the on-condition actions, other than the replacement, specified in this AD.

According to the manufacturer, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA has determined that this AD will not have federalism implications

under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2017-16-10, Amendment 39-18987 (82 FR 39513, August 21, 2017), and adding the following new AD:

2019-11-02 The Boeing Company:
Amendment 39-19648; Docket No. FAA-2019-0407; Product Identifier 2019-NM-075-AD.

(a) Effective Date

This AD is effective July 5, 2019.

(b) Affected ADs

This AD replaces AD 2017-16-10, Amendment 39-18987 (82 FR 39513, August 21, 2017) ("AD 2017-16-10").

(c) Applicability

This AD applies to The Boeing Company Model 777-200, -200LR, -300, -300ER, and

777F series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by reports of cracks on the underwing longerons. The FAA is issuing this AD to address cracks in the underwing longerons, which could result in fuel leakage into the forward cargo area and consequent increased risk of a fire or, in a more severe case, could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraph (h) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, do all applicable actions identified as "RC" (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019. Replacing an underwing longeron, including doing all applicable on-condition actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, except as required by paragraph (h)(2) of this AD, terminates the repetitive inspections specified in tables 1 through 6 and table 15 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, for that longeron only.

(h) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, uses the phrase "the Revision 2 date of this service bulletin," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Service Bulletin 777-53A0081, Revision 2, dated March 29, 2019, specifies contacting Boeing for repair instructions: This AD requires doing the repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(i) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777–53A0081, dated September 8, 2016, or Boeing Alert Service Bulletin 777–53A0081, Revision 1, dated May 1, 2017.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2017–16–10 are approved as AMOCs for the corresponding provisions of Boeing Alert Service Bulletin 777–53A0081, Revision 2, dated March 29, 2019, that are required by paragraph (g) of this AD.

(5) Except as specified by paragraph (h)(2) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(5)(i) and (j)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

(1) For more information about this AD, contact Eric Lin, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA

98198; phone and fax: 206–231–3523; email: eric.lin@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; phone: 562–797–1717; internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 777–53A0081, Revision 2, dated March 29, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; phone: 562–797–1717; internet: <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 5, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019–13058 Filed 6–19–19; 8:45 am]

BILLING CODE 4910–13–P

RAILROAD RETIREMENT BOARD**20 CFR Part 200****RIN 3220–AB67****General Administration: Designation of Central and Field Organization; Internal Organization**

AGENCY: Railroad Retirement Board.

ACTION: Final rule.

SUMMARY: The Railroad Retirement Board (Board) amends its regulations to update the members of the Executive Committee, update the responsibilities of the Executive Committee members, and update office titles.

DATES: This rule becomes effective June 20, 2019.

ADDRESSES: Stephanie Hillyard, Secretary to the Board, Railroad Retirement Board, 844 N Rush Street, Chicago, Illinois 60611–1275.

FOR FURTHER INFORMATION CONTACT: Marguerite P. Dadabo, Assistant General Counsel, (312) 751–4945, TTD (312) 751–4701.

SUPPLEMENTARY INFORMATION: The Railroad Retirement Board (Board) amends its regulations in regard to the Board's policy on internal organization. The regulations amended are all contained in § 200.1(b). In § 200.1(b)(1) of the Board's regulations, the Board removes the language that states “the General Counsel also serves as the Senior Executive Officer,” and increases the number of members of the Executive Committee from six to seven members by adding as a member the Director of Field Service. A description of the Director of Field Service's responsibilities is added to § 200.1(b)(2). Finally, under § 200.1(b)(3), the office name of the Washington/Legislative Office is changed to the Office of Legislative Affairs. Section 200.1(b)(3) of the regulation also removes the Office of Planning, and renames the Bureau of Quality Assurance to the Program Evaluation and Management Services (PEMS).

This change was published as a proposed rule on April 27, 2017, and comments were invited to be submitted by June 26, 2017. See 82 FR 19330 (April 27, 2017). No comments were submitted, and the final rule is essentially the same as the proposed rule.

The Board, with the concurrence of the Office of Management and Budget, has determined that this is not a significant regulatory action under Executive Order 12866, as amended. Therefore, no regulatory impact analysis is required. There are no changes to the information collections associated with § 200.1(b).

List of Subjects in 20 CFR Part 200

Railroad employees, Railroad retirement, General administration.

For the reasons set out in the preamble, the Railroad Retirement Board amends title 20, chapter II, subchapter A, part 200 of the Code of Federal Regulations as follows:

PART 200—GENERAL ADMINISTRATION

■ 1. The authority citation for part 200 continues to read as follows: