

recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (k) Related Information

(1) For information about EASA AD 2019-0093, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); Internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this EASA AD at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. EASA AD 2019-0093 may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0498.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206-231-3229.

Issued in Des Moines, Washington, on June 25, 2019.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-14046 Filed 7-2-19; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0521; Product Identifier 2019-NM-047-AD]

RIN 2120-AA64

#### Airworthiness Directives; Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Saab AB, Saab Aeronautics Model SAAB 2000 airplanes. This proposed AD was prompted by reports of cracks in the o-ring groove of magnetic fuel level indicators. This proposed AD would require a one-time detailed inspection of the magnetic fuel level

indicator for cracks and replacement of cracked magnetic fuel level indicators. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by August 19, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email [saab2000.techsupport@saabgroup.com](mailto:saab2000.techsupport@saabgroup.com); internet <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0521; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0521; Product

Identifier 2019-NM-047-AD" at the beginning of your comments. The agency specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The agency will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2019-0053, dated March 14, 2019 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Saab AB, Saab Aeronautics Model SAAB 2000 airplanes. The MCAI states:

Occurrences have been reported where, during maintenance, magnetic fuel level indicators were found with cracks in the O-ring groove. Investigation results indicate that these cracks may be due to over-torque during installation of the unit, although the applicable Aircraft Maintenance Manual instructs that the proper nut torque is between 2.8 and 3.4 Nm.

This condition, if not detected and corrected, could lead to failure of an indicator, possibly resulting in a puncture of the fuel tank bottom, with consequent fuel leakage and risk of fuel starvation.

To address this potential unsafe condition, SAAB issued the SB [service bulletin] to provide inspection instructions.

For the reason described above, this [EASA] AD requires a one-time inspection of affected parts and, depending on findings, accomplishment of applicable corrective action(s).

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0521.

#### Related Service Information Under 14 CFR Part 51

Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems) has issued Service Bulletin 2000-28-027, dated January 15, 2019. This service information describes procedures for a one-time detailed inspection of the magnetic fuel level indicator for cracks and replacement of cracked magnetic fuel level indicators. This service information is reasonably available because the interested parties

have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**FAA’s Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI and service information referenced above. The

agency is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Proposed Requirements of This NPRM**

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between this Proposed AD and the MCAI or Service Information.”

**Differences Between This Proposed AD and the MCAI or Service Information**

Saab Service Bulletin 2000–28–027, dated January 15, 2019, specifies to return faulty parts to the manufacturer. This proposed AD would not include that requirement.

**Costs of Compliance**

The FAA estimates that this proposed AD affects 11 airplanes of U.S. registry. The agency estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510 .....	\$0	\$510	\$5,610

The agency estimates the following costs to do any necessary on-condition action that would be required based on

the results of any required actions. The agency has no way of determining the

number of aircraft that might need this on-condition action:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
2 work-hours × \$85 per hour = \$170 .....	\$20,000	\$20,170

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to

issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Will not affect intrastate aviation in Alaska; and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems):** Docket No. FAA–2019–0521; Product Identifier 2019–NM–047–AD.

**(a) Comments Due Date**

The FAA must receive comments by August 19, 2019.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Saab AB, Saab Aeronautics Model SAAB 2000 airplanes, certificated in any category, all manufacturer serial numbers.

**(d) Subject**

Air Transport Association (ATA) of America Code 28, Fuel.

**(e) Reason**

This AD was prompted by reports of cracks in the o-ring groove of magnetic fuel level indicators. The FAA is issuing this AD to address this condition, which, if not detected and corrected, could result in a severe fuel leak and consequent risk of fuel starvation.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Definitions**

(1) For the purposes of this AD, an affected part is any magnetic fuel level indicator having part number 35081587.

(2) For the purposes of this AD, a serviceable part is an affected part that is new (not previously installed); or an affected part that, before installation, has passed an inspection in accordance with the instructions of Saab Service Bulletin 2000–28–027, dated January 15, 2019.

**(h) Inspection**

Within 3,000 flight hours or 24 months, whichever occurs first after the effective date of this AD, remove and perform a one-time detailed inspection of each affected part for cracks in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000–28–027, dated January 15, 2019.

**(i) Corrective Action**

If, during the inspection required by paragraph (h) of this AD, any crack is detected on an affected part, before further flight, replace that affected part with a serviceable part in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000–28–027, dated January 15, 2019.

**(j) No Parts Return**

Although Saab Service Bulletin 2000–28–027, dated January 15, 2019, specifies to return faulty parts to the manufacturer, this AD does not require returning the faulty parts to the manufacturer.

**(k) Parts Installation Limitation**

As of the effective date of this AD, it is allowed to install on any airplane an affected part, provided that it is a serviceable part as defined in paragraph (g)(2) of this AD.

**(l) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may

be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

**(m) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2019–0053, dated March 14, 2019, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0521.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3220.

(3) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email [saab2000.techsupport@saabgroup.com](mailto:saab2000.techsupport@saabgroup.com); internet <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on June 24, 2019.

**Dionne Palermo,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019–14048 Filed 7–2–19; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF THE TREASURY****Internal Revenue Service****26 CFR Part 1**

**[REG–121508–18]**

**RIN 1545–BO97**

**Multiple Employer Plans**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This document sets forth proposed regulations relating to the tax qualification of plans maintained by more than one employer. These plans,

maintained pursuant to section 413(c) of the Internal Revenue Code (Code), are often referred to as multiple employer plans or MEPs. The proposed regulations would provide an exception, if certain requirements are met, to the application of the “unified plan rule” for a defined contribution MEP in the event of a failure by an employer participating in the plan to satisfy a qualification requirement or to provide information needed to determine compliance with a qualification requirement. These proposed regulations would affect MEPs, participants in MEPs (and their beneficiaries), employers participating in MEPs, and MEP plan administrators.

**DATES:** Comments and requests for a public hearing must be received by October 1, 2019.

**ADDRESSES:** Submit electronic submissions via the Federal eRulemaking Portal at [www.regulations.gov](http://www.regulations.gov) (indicate IRS and REG–121508–18) by following the online instructions for submitting comments. Once submitted to the Federal eRulemaking Portal, comments cannot be edited or withdrawn. The Department of the Treasury (Treasury Department) and the IRS will publish for public availability any comment received to its public docket, whether submitted electronically or in hard copy. Send hard copy submissions to: CC:PA:LPD:PR (REG–121508–18), Room 5203, Internal Revenue Service, P.O. Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG–121508–18), Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue NW, Washington, DC 20224.

**FOR FURTHER INFORMATION CONTACT:**

Concerning the regulations, Pamela Kinard at (202) 317–6000 or Jamie Dvoretzky at (202) 317–4102; concerning submission of comments or to request a public hearing, email or call Regina Johnson at [notice.comments@irs.counsel.treas.gov](mailto:notice.comments@irs.counsel.treas.gov), (202) 317–5190, or (202) 317–6901 (not toll-free numbers).

**SUPPLEMENTARY INFORMATION:****Background**

This document sets forth proposed amendments to the Income Tax Regulations (26 CFR part 1) under section 413(c) of the Internal Revenue Code (Code). Section 413(c) provides rules for the qualification of a plan maintained by more than one