

(d) Other Federal Regional Commissions are those authorized under Title V of the Public Works and Economic Development Act of 1965. Grants by these commissions are handled in accordance with a separate Project Management Agreement between the respective Regional Commission and RHS for each Commission grant administered by RHS (guide 1 of part 1942, subpart G). The agreement should be prepared by the RHS State Director and the appropriate Commission official when the State Director receives a notice from the Commission of the amount of the grant to be made.

(e) When the Agency has funds in the project, no charge will be made for administering grant funds.

(f) When RHS has no loan or grant funds in the project, an administrative charge will be made pursuant to the Economy Act of 1932, as amended (31 U.S.C. 1535). A fee of 5 percent of the first \$50,000 and 1 percent of any amount over \$50,000 will be paid RHS by the commission.

§§ 3570.94–3570.99 [Reserved]

§ 3570.100 OMB control number.

According to the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. The valid OMB control number for this information collection is 0575–0173.

Dated: March 28, 1997.

Inga Smulkstys,

Deputy Under Secretary, Operations and Management, Rural Development.

Dated: March 28, 1997.

Dallas R. Smith,

Acting Under Secretary, Farm and Foreign Agricultural Service.

[FR Doc. 97–8743 Filed 4–4–97; 8:45 am]

BILLING CODE 3410–XV–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96–NM–105–AD; Amendment 39–9988; AD 97–07–14]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A320 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD),

applicable to certain Airbus Model A320 series airplanes, that requires modification of an area on the front spar of the wing center section by installing shims and new fasteners to reinforce pressure floor fittings. This amendment is prompted by a report from the manufacturer indicating that full-scale fatigue testing on the test model revealed fatigue cracking in this area. The actions specified by this AD are intended to prevent fatigue cracking in this area, which can reduce the structural integrity of fuselage frame 36 and the wing center section.

DATES: Effective May 12, 1997.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 12, 1997.

ADDRESSES: The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tim Backman, Aerospace Engineer, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (206) 227–2797; fax (206) 227–1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Airbus Model A320 series airplanes was published in the **Federal Register** on January 21, 1997 (62 FR 2982). That action proposed to require modification of an area on the front spar of the wing center section by installing shims and new fasteners to reinforce pressure floor fittings.

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

Cost Impact

The FAA estimates that 5 Airbus Model A320 series airplanes of U.S. registry will be affected by this AD, that it will take approximately 13 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$576 per airplane. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$6,780, or \$1,356 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS
DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

97-07-14 Airbus Industrie: Amendment 39-9988. Docket 96-NM-105-AD.

Applicability: Model A320 series airplanes as listed in Airbus Service Bulletin A320-57-1013, Revision 1, dated September 29, 1992; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD.

The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue cracking in the rib flange of the front spar side of the wing center section, and consequent reduced structural integrity of fuselage frame 36 and the wing center section, accomplish the following:

(a) Prior to the accumulation of 16,000 total landings, or within 3 months after the effective date of this AD, whichever occurs later, modify the rib flange on the front spar of the wing center section by installing shims and new fasteners to reinforce pressure floor fittings, in accordance with Airbus Service Bulletin A320-57-1013, Revision 1, dated September 29, 1992.

Note 2: Modification of the rib flange accomplished prior to the effective date of this AD in accordance with Airbus Service Bulletin A320-57-1013, dated April 12, 1989, is considered acceptable for

compliance with the modification required by this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The modification shall be done in accordance with Airbus Service Bulletin A320-57-1013, Revision 1, dated September 29, 1992, which contains the following list of effective pages:

Page No.	Revision level shown on page	Date shown on page
1-3	1	September 29, 1992.
4-11	Original	April 12, 1989.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on May 12, 1997.

Issued in Renton, Washington, on March 27, 1997.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 97-8422 Filed 4-4-97; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 96-NM-127-AD; Amendment 39-9987; AD 97-07-13]

RIN 2120-AA64

**Airworthiness Directives;
Construcciones Aeronauticas, S.A.
(CASA) Model CN-235 Series
Airplanes**

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain CASA Model CN-235 series airplanes, that requires replacement of the center wing attachment rods with new rods. This amendment is prompted by a report from the manufacturer indicating that these rods failed during a full-scale fatigue test. The actions specified by this AD are intended to prevent fatigue failure of these rods, which consequently could reduce the structural integrity of the wing-to-fuselage attachment.

DATES: Effective May 12, 1997.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of May 12, 1997.

ADDRESSES: The service information referenced in this AD may be obtained from Construcciones Aeronauticas, S.A., Getafe, Madrid, Spain. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Greg Dunn, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2799; fax (206) 227-1149.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain CASA Model CN-235 series airplanes was published in the **Federal Register** on January 27, 1997 (62 FR 3834). That action proposed to require replacement of the center wing attachment rods with new rods.