

actions would be required to be accomplished in accordance with the service bulletin described previously.

#### Cost Impact

The FAA estimates that 77 series airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 14 work hours per airplane (7 work hours per engine) to accomplish the proposed replacements, and that the average labor rate is \$60 per work hour. Required parts would be provided by the manufacturer or vendor at no cost to the operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$64,680, or \$840 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

#### Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Airbus Industrie:** Docket 2000-NM-22-AD.

**Applicability:** Model A320-232 and -233 series airplanes, certificated in any category, except those airplanes on which Airbus Modification 27146 or 28006 has been installed, or on which Airbus Service Bulletin A320-73-1067 has been accomplished.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent an inadvertent increase in thrust, which could result in reduced controllability of the airplane during final approach, accomplish the following:

#### Replacement

(a) Within 12 months after the effective date of this AD, replace the fuel metering units (FMU) of each engine with new FMU's in accordance with Airbus Service Bulletin A320-73-1067, dated August 11, 1999.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

#### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in French airworthiness directive 2000-005-143(B), dated January 12, 2000.

Issued in Renton, Washington, on March 21, 2000.

**Donald L. Riggan,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 00-7458 Filed 3-24-00; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-23-AD]

RIN 2120-AA64

#### Airworthiness Directives; Saab Model SAAB SF340A and SAAB 340B Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB SF340A and SAAB 340B series airplanes. This proposal would require replacing the smoke detectors in the cargo compartment with new, improved smoke detectors. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent false smoke warnings from the cargo compartment smoke detectors, which could result in aborted takeoffs, diversions of flight routes, and emergency evacuation of flight crew and passengers.

**DATES:** Comments must be received by April 26, 2000.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-23-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Saab Aircraft AB, SAAB Aircraft .. Product Support, S-581.88, Linköping, Sweden. This information may be examined at the FAA, Transport

Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:**

Norman B. Martenson, Manager, International Branch, ANM-116, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2110; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-23-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-23-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

The Luftfartsverket (LFV), which is the airworthiness authority for Sweden, recently notified the FAA that an unsafe condition may exist on certain Saab Model SAAB SF340A and SAAB 340B series airplanes. The LFV advises that in-service experience has indicated that the smoke detectors in the cargo compartment may generate false smoke warnings. Investigation revealed that, during certain environmental conditions (high humidity), a certain type of smoke

detector (Fenwall) is apt to generate false smoke warnings. Such warnings could result in aborted takeoffs, diversions of flight routes, and emergency evacuation of flight crew and passengers.

**Explanation of Relevant Service Information**

The manufacturer has issued SAAB Service Bulletin 340-26-023, dated December 21, 1999, which describes procedures for replacing the smoke detectors in the cargo compartment with new, improved smoke detectors. The improved smoke detectors are less susceptible to humidity, thereby minimizing false smoke warnings. The LFV classified this service bulletin as mandatory and issued Swedish airworthiness directive 1-151, dated December 28, 1999, in order to assure the continued airworthiness of these airplanes in Sweden.

**FAA's Conclusions**

These airplane models are manufactured in Sweden and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LFV has kept the FAA informed of the situation described above. The FAA has examined the findings of the LFV, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

**Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require replacing the smoke detectors in the cargo compartment with new, improved smoke detectors. The actions would be required to be accomplished in accordance with the service bulletin described previously.

**Cost Impact**

The FAA estimates that 289 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 2 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost between \$4,022 and \$2,011 per airplane. Based on these figures, the cost impact of the proposed AD on U.S.

operators is estimated to be between \$4,142, or \$2,131 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

**Regulatory Impact**

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**SAAB Aircraft AB:** Docket 2000-NM23-AD.

*Applicability:* Model SAAB SF340A series airplanes, manufacturer's serial numbers 004 through 159 inclusive; and Model SAAB 340B series airplanes, manufacturer's serial numbers 160 through 459 inclusive; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent false smoke warnings from the cargo compartment smoke detectors, which could result in aborted takeoffs, diversions of flight routes, and emergency evacuation of flight crew and passengers, accomplish the following:

#### Replacement

(a) Within 2 years after the effective date of this AD, replace the smoke detectors in the cargo compartment with new, improved smoke detectors, in accordance with Saab Service Bulletin 340-26-023, dated December 21, 1999.

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

#### Special Flight Permits

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Note 3:** The subject of this AD is addressed in Swedish airworthiness directive 1-151, dated December 28, 1999.

Issued in Renton, Washington, on March 21, 2000.

**Donald L. Riggan,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 00-7457 Filed 3-24-00; 8:45 am]

**BILLING CODE 4910-13-P**

## SECURITIES AND EXCHANGE COMMISSION

### 17 CFR Parts 230, 240, 243, and 249

[Release Nos. 33-7815, 34-42552, IC-24343, File No. S7-31-99]

RIN 3235-AH82

### Selective Disclosure and Insider Trading

**AGENCY:** Securities and Exchange Commission.

**ACTION:** Proposed rule; extension of comment period.

**SUMMARY:** The Securities and Exchange Commission is extending the comment period for its proposed rules regarding selective disclosure and insider trading, contained in Release No. 33-7787, 64 FR 72590 (Dec. 28, 1999). The original comment period ends March 29, 2000. The new deadline for submitting public comments is April 28, 2000.

**DATES:** Public comments are due on or before April 28, 2000.

**ADDRESSES:** Please send three copies of your comment letter to Jonathan G. Katz, Secretary, Securities and Exchange Commission, 450 5th Street, N.W., Washington, D.C. 20549-0609. Comments can also be sent electronically to the following e-mail address: rule-comments@sec.gov. Your comment letter should refer to File No. S7-31-99. If e-mail is used, include this file number on the subject line. Anyone can inspect and copy the comment letters in the Commission's Public Reference Room at 450 5th St., N.W., Washington, D.C. 20549. Electronically submitted comments will be posted on the Commission's Internet web site (<http://www.sec.gov>).

**FOR FURTHER INFORMATION CONTACT:** Richard A. Levine, Assistant General Counsel, Sharon Zamore, Senior Counsel, or Elizabeth Nowicki, Attorney, Office of the General Counsel, at (202) 942-0890.

**SUPPLEMENTARY INFORMATION:** On December 20, 1999, the Securities and Exchange Commission (Commission) issued a proposal for new rules to address three issues: the selective disclosure by issuers of material nonpublic information; whether insider trading liability depends on a trader's "use" or "knowing possession" of material nonpublic information; and when the breach of a family or other non-business relationship may give rise to liability under the misappropriation theory of insider trading. The proposals are designed to promote the full and fair disclosure of information by issuers, and to clarify and enhance existing

prohibitions against insider trading. The deadline for submitting public comments established by the proposing release was March 29, 2000. The Commission has received requests to extend the deadline. We are therefore extending the comment period to April 28, 2000 so that commenters have adequate time to address the issues raised by the proposing release.

By the Commission.

Dated: March 21, 2000.

**Margaret H. McFarland**

*Deputy Secretary*

[FR Doc. 00-7433 Filed 3-24-00; 8:45 am]

**BILLING CODE 8010-01-P**

## FEDERAL COMMUNICATIONS COMMISSION

### 47 CFR Part 73

[DA No. 00-553, MM Docket No. 00-43, RM-9833]

### Radio Broadcasting Services; Ebro, FL

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule.

**SUMMARY:** This document requests comments on a petition for rule making filed on behalf of Washington County Communications requesting the allotment of Channel 236A at Ebro, Florida, as the community's first local broadcast service. Channel 236A can be allotted to Ebro with a site restriction 3.3 kilometers (2.0 miles) northwest of the community at coordinates 30-28-15 and 85-53-45.

**DATES:** Comments must be filed on or before May 1, 2000, and reply comments on or before May 16, 2000.

**ADDRESSES:** Federal Communications Commission, Washington, DC 20554. In addition to filing comments with the FCC, interested parties should serve the petitioner's counsel, as follows: Bruce Eisen, Kaye, Scholer, Fierman, Hays & Handler, LLP, 901 15th Street, NW, Suite 901, Washington, DC 20005.

**FOR FURTHER INFORMATION CONTACT:** Kathleen Scheuerle, Mass Media Bureau, (202) 418-2180.

**SUPPLEMENTARY INFORMATION:** This is a summary of the Commission's Notice of Proposed Rule Making, MM Docket No. 00-43, adopted March 1, 2000, and released March 10, 2000. The full text of this Commission decision is available for inspection and copying during normal business hours in the Commission's Reference Center, Washington, DC. The complete text of this decision may also be purchased