

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Bombardier Inc. (Formerly de Havilland, Inc.): Docket 98-NM-380-AD.

Applicability: DHC-8-100 and -300 series airplanes, serial numbers 215 through 341 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent damage to bonded skin panels to go undetected, which could result in failure of the bonded skin panels, and consequent loss of controllability of the airplane; accomplish the following:

Revision to Aircraft Log Book and Airworthiness Limitations List

(a) Within 30 days after the effective date of this AD, perform the actions required by paragraphs (a)(1), (a)(2), and (a)(3) of this AD.

(1) Revise the Aircraft Log Book to correct the airplane Production Modification List in accordance with the Accomplishment Instructions in Part A of Section III of Bombardier Service Bulletin S.B. 8-51-2, Revision 'A,' dated September 19, 1998.

(2) Perform an inspection to determine which bonded skin panels on the airplane require bonding integrity inspections (BI) in accordance with the Accomplishment Instructions in Part B of Section III of Bombardier Service Bulletin S.B. 8-51-2, Revision 'A,' dated September 19, 1998.

(3) Revise the Airworthiness Limitations List of the Approved Maintenance Plan by inserting the bonding integrity inspections identified as de Havilland Maintenance Task 5500/01 and de Havilland Maintenance Task 5700/01 into the Airworthiness Limitations List. Except as provided by paragraph (e) of this AD: After the actions specified in paragraph (a)(3) of this AD have been accomplished, no alternative replacement times or structural inspection intervals may be approved for the bonded panels of the empennage and wings specified in de Havilland Maintenance Task 5500/01 and de Havilland Maintenance Task 5700/01.

On-Condition Repetitive Inspections

(b) For airplanes on which the bonded skin panels require BI's, as determined in paragraph (a)(2) of this AD: At the next required maintenance visit, but no later than 12 months after the effective date of this AD, perform an initial ultrasonic bond inspection to detect disbonding of the skin panels, in accordance with Part 5, sections 55-00-01 and/or 57-30-01, of Bombardier Production Support Manual (PSM) 1-8-7A, dated December 15, 1998 (for Model DHC-8-100 series airplanes); or Part 5, sections 55-00-01 and 57-30-01 of Bombardier PSM 1-83-7A, dated April 30, 1999 (for Model DHC-8-300 series airplanes); as applicable. Thereafter, repeat the ultrasonic inspection at the interval specified in the applicable PSM.

On-Condition Repair

(c) Except as provided by paragraph (d) of this AD, if any disbonding is detected during any inspection required by paragraph (b) of this AD, prior to further flight, repair in accordance with Part 5, sections 55-00-01 and 57-30-01 of Bombardier PSM 1-8-7A, dated December 15, 1998 (for Model DHC-8-100 series airplanes); or Part 5, sections 55-00-01 and 57-30-01 of Bombardier PSM 1-83-7A, dated April 30, 1999 (for Model DHC-8-300 series airplanes); as applicable.

(d) If any disbonding is detected during any inspection required by paragraph (b) of this AD; and the applicable service information specifies to contact Bombardier for appropriate action: Prior to further flight, repair in accordance with a method approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. For a repair method to be approved by the Manager, New York ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive.

Issued in Renton, Washington, on March 27, 2000.

Donald L. Riggan,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-8020 Filed 3-30-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 99-NM-26-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-1A11 (CL-600) and CL-600-2A12 (CL-601) Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Bombardier Model CL-600-1A11 (CL-600) and CL-600-2A12 (CL-601) series airplanes. This proposal would require modification of the main landing gear (MLG) brake units and inboard MLG wheels; and a revision to the Airplane Flight Manual (AFM) to include the increased cooling times for the modified brakes. This proposal also would allow, for certain cases, removal of the inboard and/or outboard wheel discs by installation of a placard to limit airplane operation on the ground and a revision to the AFM to include information for operating the airplane with the wheel discs removed. This proposal is prompted by issuance of mandatory continuing airworthiness information by a foreign civil airworthiness authority. The actions specified by the proposed AD are intended to prevent water freezing on the brake while the airplane is in flight due to water, slush, or snow from the runway entering into the brake assemblies during takeoff, and consequently, a tire burst during landing of the airplane.

DATES: Comments must be received by May 1, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-26-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York.

FOR FURTHER INFORMATION CONTACT: James E. Delisio, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, Engine and Propeller Directorate, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York

11581; telephone (516) 256-7521; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 99-NM-26-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 99-NM-26-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain Bombardier Model CL-600-1A11 (CL-600) and CL-600-2A12 (CL-601) series airplanes. TCCA advises that a tire burst occurred on a number of airplanes during landing. Investigation revealed that the existing design of the main landing gear (MLG) allows water, slush, or snow from the runway to enter into the brake assemblies during takeoff. This condition, if not corrected, could result in the water freezing on the brake while the airplane is in flight, and consequently, a tire burst during landing of the airplane.

Explanation of Relevant Service Information

Bombardier has issued Canadair Challenger Service Bulletins 600-0369, Revision 4, dated June 27, 1984, including Attachment 1, dated December 6, 1983, and Attachment 2, dated January 11, 1984 [for Model CL-600-1A11 (CL-600) series airplanes]; and 601-0024, Revision 3, dated November 27, 1984, including Attachment 1, dated June 21, 1984, Attachment 2, dated December 6, 1983, and Attachment 3, dated January 11, 1984 [for Model CL-600-2A12 (CL-601) series airplanes]. These service bulletins describe procedures for modification of the MLG brake units and inboard MLG wheels; and a revision to the Normal and Limitation Sections of the Airplane Flight Manual (AFM) to include the increased cooling times for the brakes. The modification involves installation of a wheel disc on each inboard MLG wheel; replacement of screws securing the wheel disc on each outboard MLG wheel with longer screws; installation of a water barrier shield and water deflector to each MLG brake unit assembly; removal of balance weights, if fitted, from the main wheel assemblies; and reidentification of brake unit and main wheel assemblies. For certain airplanes, a sealing cap is also installed on each MLG trailing arm aperture.

Bombardier also has issued Canadair Challenger Service Bulletins 600-0662, dated November 30, 1995 [for Model CL-600-1A11 (CL-600) series airplanes]; and 601-0467, dated November 30, 1995 [for Model CL-600-2A12 (CL-601) series airplanes]. These service bulletins describe procedures for removal of the inboard and/or outboard wheel discs by installation of a placard to limit airplane operation on the ground and a revision to the Normal Procedures Section of the AFM to include information for operating the airplane with the wheel discs removed.

Accomplishment of the actions specified in the service bulletins is intended to adequately address the identified unsafe condition. TCCA classified these service bulletins as mandatory and issued Canadian airworthiness directive CF-84-04R2, dated July 24, 1998, in order to assure the continued airworthiness of these airplanes in Canada.

FAA's Conclusions

These airplane models are manufactured in Canada and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral

airworthiness agreement. Pursuant to this bilateral airworthiness agreement, TCCA has kept the FAA informed of the situation described above. The FAA has examined the findings of TCCA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously.

Cost Impact

The FAA estimates that 131 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 33 work hours [for Model CL-600-1A11 (CL-600) series airplanes] or 26 work hours [for Model CL-600-2A12 (CL-601) series airplanes] per airplane to accomplish the proposed modification, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$2,977 per airplane. Based on these figures, the cost impact of this action proposed by this AD on U.S. operators is estimated to be \$649,367 or \$4,957 per airplane [for Model CL-600-1A11 (CL-600) series airplanes], and \$594,347 or \$4,537 per airplane [for Model CL-600-2A12 (CL-601) series airplanes].

It would take approximately 1 work hour per airplane to accomplish the proposed AFM revision, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the AFM revision proposed by this AD on U.S. operators is estimated to be \$7,860, or \$60 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Should an operator elect to accomplish the optional placard installation and AFM revision, it would take approximately 5 work hours per airplane to accomplish these actions, at an average labor rate of \$60 per work hour. Required parts would cost

approximately \$75 per airplane. Based on these figures, the cost impact of these actions is estimated to be \$375 per airplane, per modification cycle.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Bombardier, Inc. (Formerly Canadair):

Docket 99-NM-26-AD.

Applicability: Model CL-600-1A11 (CL-600) series airplanes, serial numbers 1004 through 1066 inclusive and 1068 through 1085 inclusive; and Model CL-600-2A12 (CL-601) series airplanes, serial numbers

3001 through 3050 inclusive; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent water freezing on the brake while the airplane is in flight due to water, slush, or snow from the runway entering into the brake assemblies during takeoff, and consequently, a tire burst during landing of the airplane, accomplish the following:

Modification and AFM Revision

(a) Except as required by paragraph (b) of this AD, within 300 flight cycles after the effective date of this AD, accomplish the actions required by paragraphs (a)(1) and (a)(2) of this AD in accordance with the Accomplishment Instructions of Canadair Challenger Service Bulletins 600-0369, Revision 4, dated June 27, 1984, including Attachment 1, dated December 6, 1983, and Attachment 2, dated January 11, 1984 [for Model CL-600-1A11 (CL-600) series airplanes]; or 601-0024, Revision 3, dated November 27, 1984, including Attachment 1, dated June 21, 1984, Attachment 2, dated December 6, 1983, and Attachment 3, dated January 11, 1984 [for Model CL-600-2A12 (CL-601) series airplanes]; as applicable.

(1) Modify the main landing gear (MLG) brake units and inboard MLG wheels.

Note 2: Part A of the Accomplishment Instructions of Canadair Challenger Service Bulletin 600-0369, Revision 4, dated June 27, 1984, including Attachment 1, dated December 6, 1983, and Attachment 2, dated January 11, 1984; has been accomplished on airplane serial number 1072 in production.

(2) Revise the Normal Procedures Section of the FAA-approved Airplane Flight Manual (AFM) to include the brake cooling times for the modification specified in paragraph (a)(1) of this AD. This AFM revision may be accomplished by inserting the applicable AFM revision listed in the applicable service bulletin listed in paragraph (a) of this AD. Subsequent AFM revisions may be inserted in the AFM provided that the brake cooling information is identical to the applicable AFM revision listed in the applicable service bulletin listed in paragraph (a) of this AD.

(b) Operation of the airplane from contaminated runways (i.e., wet, snow covered, or slush covered surfaces) is prohibited until the actions required by paragraph (a) of this AD are accomplished.

Optional Placard Installation and AFM Revision

(c) For airplanes that do not operate from a wet runway where the ambient temperature is below 10 degrees Celsius: It is permissible to remove the inboard and/or outboard wheel discs upon accomplishment of the actions specified in paragraphs (c)(1) and (c)(2) of this AD, in accordance with Canadair Challenger Service Bulletins 600-0662, dated November 30, 1995 [for Model CL-600-1A11 (CL-600) series airplanes]; or 601-0467, dated November 30, 1995 [for Model CL-600-2A12 (CL-601) series airplanes]; as applicable. The placard and AFM revision required by paragraphs (c)(1) and (c)(2) of this AD may be removed upon reinstallation of the inboard and outboard wheel discs.

(1) Install a placard on the instrument panel that states the following: "WHEEL DISCS ARE REMOVED—REFER TO AFM FOR LIMITATIONS"

(2) Revise the Limitations Section of the AFM to include information for operating the airplane with the wheel discs removed. This AFM revision may be accomplished by inserting the applicable AFM revision specified in the applicable service bulletin listed in paragraph (a) of this AD. Subsequent AFM revisions may be inserted in the AFM provided that the information for operating the airplane with the wheel discs removed is identical to the applicable AFM revision specified in the applicable service bulletin listed in paragraph (a) of this AD.

Alternative Methods of Compliance

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(e) Special flight permits may be issued in accordance with §§21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Canadian airworthiness directive CF-84-CF-84-04R2, dated July 24, 1998.

Issued in Renton, Washington, on March 24, 2000.

Donald L. Riggin,

Acting Manager Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-8019 Filed 3-30-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 48

[PS-6-95; REG-209753-95]

RIN 1545-AT18

Diesel Fuel Excise Tax; Dye Injection Systems

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Partial withdrawal of notice of proposed rulemaking.

SUMMARY: This document withdraws the notice of proposed rulemaking as it relates to diesel fuel dye injection systems which was published on March 14, 1996. It affects certain enterers, refiners, terminal operators, and throughputters.

FOR FURTHER INFORMATION CONTACT: Frank Boland, (202) 622-3130 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

On March 14, 1996, the IRS issued proposed regulations (PS-6-95; REG-209753-95) relating to diesel fuel dye injection systems and the measurement of taxable fuel (61 FR 10490). The Treasury Department does not have any plans at the present time to issue final regulations relating to dye injection systems.

List of Subjects in 26 CFR Part 48

Excise taxes, Reporting and recordkeeping requirements.

Withdrawal of Notice of Proposed Rulemaking

Accordingly, under the authority of 26 U.S.C. 7805, the notice of proposed rulemaking as it relates to dye injection systems that was published in the **Federal Register** on March 14, 1996 (61 FR 10490) is withdrawn.

Robert E. Wenzel,

Deputy Commissioner of Internal Revenue.

[FR Doc. 00-7352 Filed 3-30-00; 8:45 am]

BILLING CODE 4830-01-U

DEPARTMENT OF THE INTERIOR

Office of Surface Mining Reclamation and Enforcement

30 CFR Part 934

[SPATS No. ND-040-FOR; ND State Program Amendment XXIX]

North Dakota Regulatory Program

AGENCY: Office of Surface Mining Reclamation and Enforcement, Interior.

ACTION: Proposed rule; public comment period and opportunity for public hearing on proposed amendment.

SUMMARY: Office of Surface Mining Reclamation and Enforcement (OSM) is announcing receipt of a proposed amendment to the North Dakota regulatory program (hereinafter, the "State program") under the Surface Mining Control and Reclamation Act of 1977 (SMCRA). North Dakota proposes revisions to its revegetation policy document, "Standards for Evaluation of Revegetation Success and Recommended Procedures for Pre- and Postmining Vegetation Assessments," as discussed in **SUPPLEMENTARY INFORMATION, II. Proposed Amendment**. It intends to revise its program to improve operational efficiency.

DATES: We will accept written comments on this amendment until 4:00 p.m., m.s.t. May 1, 2000. If requested, we will hold a public hearing on the amendment on April 25, 2000. We will accept requests to speak until 4:00 p.m., m.s.t. on April 17, 2000.

ADDRESSES: You should mail or hand deliver written comments and requests to speak at the hearing to Guy Padgett at the address listed below.

You may review copies of the North Dakota program, this amendment, a listing of any scheduled public hearings, and all written comments received in response to this document at the addresses listed below during normal business hours, Monday through Friday, excluding holidays. You may receive one free copy of the amendment by contacting OSM's Casper Field Office.

Guy Padgett, Director, Casper Field Office, Office of Surface Mining Reclamation and Enforcement, 100 East "B" Street, Casper, Wyoming 82601-1918