

(ii) To approve a prior notice, under § 211.10(a)(15) of Regulation K (12 CFR part 211), to engage in dealing in equity securities outside the United States, provided that the proposal raises no significant legal, supervisory, or policy issue.

(iii) To approve a prior notice, under § 211.10(a)(15)(iv)(B) of Regulation K (12 CFR part 211), to use internal hedging models, provided that the proposal raises no significant legal, supervisory, or policy issue.

(iv) To approve a prior notice, under § 211.10(a)(18) of Regulation K (12 CFR part 211), to engage in futures commission merchant activities on an mutual exchange or clearinghouse that requires members to guarantee or otherwise contract to cover losses suffered by the other members, provided that the Board has previously approved the exchange, the application is on the same terms and conditions on which the Board based its approval of the exchange, and no significant legal, supervisory, or policy issue is raised.

(12) *Change in foreign bank home state.* With respect to a foreign bank's change of home state under § 211.22(b) of Regulation K (12 CFR part 211) and provided no significant legal, supervisory, or policy issue is raised—

(i) To waive the notice period; or
(ii) To determine not to object to the notice.

(13) *Waiver of 30-day prior notification period.* To waive the 30-day prior notification period with respect to a foreign bank's change of home state under § 211.22(c)(1) of Regulation K (12 CFR part 211).

(14) *Offices of foreign banks.* (i) To approve the establishment of a branch, agency, commercial lending company, or representative office by a foreign bank in the United States, pursuant to § 211.24(a)(1) of Regulation K (12 CFR part 211), if the Board has already determined that the foreign bank is subject to consolidated comprehensive supervision and provided that the application raises no significant legal, supervisory, or policy issue.

(ii) To allow a foreign bank to establish a temporary office of a branch or agency, pursuant to § 211.24(a)(5) of Regulation K (12 CFR part 211), provided there is no direct public access to such office and no significant legal, supervisory, or policy issue is raised.

(15) *Agreement with foreign bank concerning deposits of out-of-home-state branch.* To enter into an agreement or undertaking with a foreign bank that it shall receive only such deposits at its out-of-home-state branch as would be permissible for an Edge corporation

under section 5 of the International Banking Act (12 U.S.C. 3103).

(e) * * *

(12) *Public welfare investments.* (i) To permit a state member bank to make a public welfare investment in accordance with paragraph 23 of section 9 of the Federal Reserve Act (12 U.S.C. 338a), provided that the proposal satisfies 12 CFR 208.22(b)(1) and no significant legal, supervisory, or policy issue is raised; and

(ii) To determine, in connection with acting on a proposal pursuant to delegated authority as set forth in paragraph (e)(12)(i) of this section, that the aggregate amount of a state member bank's public welfare investments will not pose a significant risk to the deposit insurance fund in accordance with paragraph 23 of section 9 of the Federal Reserve Act (12 U.S.C. 338a).

* * * * *

By order of the Board of Governors of the Federal Reserve System, June 26, 2019.

Ann Misback,

Secretary of the Board.

[FR Doc. 2019-13970 Filed 7-2-19; 8:45 am]

BILLING CODE 6210-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0185; Product Identifier 2018-NM-178-AD; Amendment 39-19658; AD 2019-12-03]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. This AD was prompted by a determination that new and more restrictive airworthiness limitations are necessary for operational checks of the landing gear alternate extension system (AES). This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 7, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 7, 2019.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0185.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0185; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. The NPRM published in the **Federal Register** on March 28, 2019 (84 FR 11656). The NPRM was prompted by a determination that new and more restrictive airworthiness limitations are

necessary for operational checks of the landing gear AES. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive airworthiness limitations.

The FAA is issuing this AD to address a deficiency in the existing maintenance or inspection program, as applicable, that does not meet the certification criteria for all critical AES failure modes, which could reduce the ability of the flightcrew to maintain the safe flight and landing of the airplane.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2018-31, dated November 28, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes. The MCAI states:

During the Bombardier Maintenance Review Board (MRB) inspection escalation interval project, it was discovered that the current interval of 8000 hours air time and previous interval of 6000 hours air time for the MRB Task 320100-203 “Operational Check of the Landing Gear Alternate Extension System (AES)” does not meet the certification criteria to cover for all critical AES failure modes [which could reduce the ability of the flightcrew to maintain the safe flight and landing of the airplane]. For this reason, a new Certification Maintenance Requirement (CMR) task needs to be implemented in the maintenance program at a shorter interval of 1600 hours air time.

This [Canadian] AD mandates a new CMR task for an operational check of the AES with interval of 1600 hours air time.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0185.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. The Air Line Pilots Association, International (ALPA) indicated its support for the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Bombardier has issued CRJ Regional Jet (Bombardier) Temporary Revision ALI-0652, dated July 9, 2018. This service information describes airworthiness limitations for a CMR task related to operational checks of the landing gear AES.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 536 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the FAA recognizes that this number may vary from operator to operator. In the past, the FAA has estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the FAA estimates the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019-12-03 Bombardier, Inc.: Amendment 39-19658; Docket No. FAA-2019-0185; Product Identifier 2018-NM-178-AD.

(a) Effective Date

This AD is effective August 7, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Bombardier, Inc., Model CL-600-2C10 (Regional Jet Series 700, 701 & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by a determination that new and more restrictive airworthiness

limitations are necessary for operational checks of the landing gear alternate extension system (AES). The FAA is issuing this AD to address a deficiency in the existing maintenance or inspection program, as applicable, that does not meet the certification criteria for all critical AES failure modes, which could reduce the ability of the flightcrew to maintain the safe flight and landing of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 30 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in CRJ Regional Jet (Bombardier) Temporary Revision ALI-0652, dated July 9, 2018. The initial compliance time for doing the tasks is at the time specified in figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) of this AD – Compliance Times

Airplane Flight Hours	Compliance Time
For airplanes with 4,400 flight hours or less since the last inspection done in accordance with Maintenance Review Board (MRB) Task 320100-203	Within 1,760 flight hours from the effective date of this AD
For airplanes with more than 4,400 flight hours since the last inspection done in accordance with MRB Task 320100-203	Within 880 flight hours from the effective date of this AD

(h) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (i)(1) of this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch,

FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-31, dated November 28, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0185.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyacos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) CRJ Regional Jet (Bombardier) Temporary Revision ALI-0652, dated July 9, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9,

Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on June 12, 2019.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-14153 Filed 7-2-19; 8:45 am]

BILLING CODE 4910-13-P