

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

99-10-03 British Aerospace Airbus Limited (Formerly British Aerospace Commercial Aircraft Limited, British Aerospace Aircraft Group): Amendment 39-11157. Docket 98-NM-307-AD.

Applicability: All Model BAC 1-11 200 and 400 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the flap control lever, which could result in restricted flap movement and consequent reduced controllability of the airplane, accomplish the following:

(a) Within 12 months after the effective date of this AD, perform a one-time detailed visual inspection of the flap control lever to detect cracking, and to identify the type of aluminum alloy from which the flap control lever is made, in accordance with British Aerospace Alert Service Bulletin 27-A-PM6041, Issue 1, dated August 21, 1998.

(1) If no crack is detected and the lever is made of L97 or L99 aluminum alloy, no further action is required by this AD.

(2) If no crack is detected, and the lever is made of L53 aluminum alloy or the material of the flap control lever cannot be identified, repeat the inspection thereafter at intervals not to exceed 24 months; or prior to further flight, replace the flap control lever with a flap control lever made of L97 or L99 aluminum alloy, in accordance with the alert service bulletin. Following such replacement, no further action is required by this AD.

(3) If any crack is detected, prior to further flight, replace the flap control lever with a

flap control lever made of L97 or L99 aluminum alloy, in accordance with the alert service bulletin. After the replacement, no further action is required by this AD.

Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

Special Flight Permits

(c) Special flight permits may be issued in accordance with § 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(d) The inspections and replacement shall be done in accordance with British Aerospace Alert Service Bulletin 27-A-PM6041, Issue 1, dated August 21, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from British Aerospace, Service Support, Airbus Limited, P.O. Box 77, Bristol BS99 7AR, England. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in British airworthiness directive 003-08-98.

(e) This amendment becomes effective on June 9, 1999.

Issued in Renton, Washington, on April 28, 1999.

D.L. Riggins,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 99-11223 Filed 5-4-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-ASW-10]

Revision of Class E Airspace; Shreveport, LA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This amendment revises the Class E airspace at Shreveport, LA. The development of a Nondirectional Radio Beacon (NDB) or Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP), at Shreveport Regional Airport, Shreveport, LA has made this rule necessary. This action is intended to provide adequate controlled airspace extending upward from 700 feet or more above the surface for Instrument Flight Rules (IFR) operations to Shreveport Regional Airport, Shreveport, LA.

DATES: Effective 0901 UTC, September 9, 1999.

Comments must be received on or before June 21, 1999.

ADDRESSES: Send comments on the rule in triplicate to Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, Southwest Region, Docket No. 99-ASW-10, Fort Worth, TX 76193-0520.

The official docket may be examined in the Office of the Regional Counsel, Southwest Region, Federal Aviation Administration, 2601 Meacham Boulevard, Room 663, Fort Worth, TX, between 9:00 AM and 3:00 PM, Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the Airspace Branch, Air Traffic Division, Federal Aviation Administration, Southwest Region, Room 414, Fort Worth, TX.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone 817-222-5593.

SUPPLEMENTARY INFORMATION: This amendment to 14 CFR part 71 revises the Class E airspace at Shreveport, LA. The development of a NDB or GPS SIAP, at Shreveport Regional Airport, Shreveport, LA has made this rule necessary. This action is intended to provide adequate controlled airspace extending upward from 700 feet or more about the surface for Instrument Flight Rules (IFR) operations to Shreveport Regional Airport, Shreveport, LA.

Class E airspace designations are published in Paragraph 6005 of FAA Order 7400.9F, dated September 10, 1998, and effective September 16, 1998, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the order.

The Direct Final Rule Procedure

The FAA anticipates that this regulation will not result in adverse or negative comment and therefore is

issuing it as a direct final rule. A substantial number of previous opportunities provided to the public to comment on substantially identical actions have resulted in negligible adverse comments or objections. Unless a written adverse or negative comment, or a written notice of intent to submit an adverse or negative comment is received within the comment period, the regulation will become effective on the date specified above. After the close of the comment period, the FAA will publish a document in the **Federal Register** indicating that no adverse or negative comments were received and confirming the date on which the final rule will become effective. If the FAA does receive, within the comment period, an adverse or negative comment, or written notice of intent to submit such a comment, a document withdrawing the direct final rule will be published in the **Federal Register**, and a notice of proposed rulemaking may be published with a new comment period.

Comments Invited

Although this action is in the form of a final rule and was not preceded by a notice of proposed rulemaking, comments are invited on this rule. Interested persons are invited to comment on this rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified under the caption **ADDRESSES**. All communications received on or before the closing date for comments will be considered, and this rule may be amended or withdrawn in light of the comments received. Factual information that supports the commenter's ideas and suggestions is extremely helpful in evaluating the effectiveness of this action and determining whether additional rulemaking action is needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this action will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 99-ASW-10." The postcard

will be date stamped and returned to the commenter.

Agency Findings

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

Further, the FAA has determined that this regulation is noncontroversial and unlikely to result in adverse or negative comments and only involves an established body of technical regulations that require frequent and routine amendments to keep them operationally current. Therefore, I certify that this regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. Since this rule involves routine matters that will only affect air traffic procedures and air navigation, it does not warrant preparation of a Regulatory Flexibility Analysis because the anticipated impact is so minimal.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9F, *Airspace Designations and Reporting Points*, dated September 10, 1998, and effective

September 16, 1998, is amended as follows:

Paragraph 6005: Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ASW LA E5 Shreveport, LA [Revised]

Shreveport Regional Airport, Shreveport, LA (Lat. 32°26'48" N., long. 93°49'32" W.)
Shreveport, Barksdale AFB, LA (Lat. 32°30'07" N., long. 93°39'46" W.)
Shreveport Downtown Airport, LA (Lat. 32°32'24" N., long. 93°44'41" W.)

That airspace extending upward from 700 feet above the surface within a 9.4-mile radius of Shreveport Regional Airport and within a 8-mile radius of Barksdale AFB and within a 8.1-mile radius of Shreveport Downtown Airport.

* * * * *

Issued in Fort Worth, TX, on April 19, 1999.

Albert L. Viselli,

Acting Manager, Air Traffic Division, Southwest Region.

[FR Doc. 99-11294 Filed 5-4-99; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-ASW-09]

Revision of Class E Airspace; Galveston, TX

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Direct final rule; request for comments.

SUMMARY: This amendment revises the Class E airspace extending upward from the surface within a 4.1-mile radius of Scholes Field, Galveston, TX. Increased air traffic operations and instrument approaches have made this rule necessary. This action is intended to provide continuous controlled airspace for aircraft operating in the vicinity of Scholes Field, Galveston, TX.

DATES: Effective 0901 UTC, September 9, 1999.

Comments must be received on or before June 21, 1999.

ADDRESSES: Send comments on the rule in triplicate to Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, Southwest Region, Docket No. 99-ASW-09, Fort Worth, TX 76193-0520.

The official docket may be examined in the Office of Regional Counsel, Southwest Region, Federal Aviation Administration, 2601 Meacham Boulevard, Room 663, Fort Worth, TX,