

valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Avenue SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI EASA AD No.: 2011-0191, dated September 30, 2011; DG Flugzeugbau GmbH Technical Note No. 500/05, dated September 19, 2011; and DG Flugzeugbau GmbH Working Instruction No. 1 for TN348/20, Issue 3, dated September 13, 2011, for related information. For service information related to this AD, contact DG Flugzeugbau GmbH, Otto-Lilienthal-Weg 2, 76646 Bruchsal, Federal Republic of Germany; telephone: +49 (0) 7251 3020140; fax: +49 (0) 7251 3020149; Internet: <http://www.dg-flugzeugbau.de/tech-mitteilungen-e.html>; email: dirks@dg-flugzeugbau.de. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on January 10, 2012.

John Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-745 Filed 1-13-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-0018; Directorate Identifier 2011-CE-042-AD]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Pilatus Aircraft Ltd. Models PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/C1-H2 airplanes. This proposed

AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as loose elevator and rudder hinge bolts caused by incorrect torquing and locking of the bolts could lead to in-flight failure of the elevator or rudder attachment. If not corrected, this failure could result in loss of control of the airplane. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by March 2, 2012.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact PILATUS AIRCRAFT LTD., Customer Liaison Manager, CH-6371 STANS, Switzerland; telephone: +41 (0) 41 619 65 80; fax: +41 (0) 41 619 65 76; Internet: <http://www.pilatus-aircraft.com>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901

Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-0018; Directorate Identifier 2011-CE-042-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2011-0230, dated December 9, 2011 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A case of loss of elevator and rudder hinge bolts on a PC-6 aeroplane has been reported.

The results of the investigations indicate that the elevator and rudder hinge bolt loss are suspected to have been caused by an incorrect torque and locking of the bolts.

This condition, if not detected and corrected, could lead to in-flight failure of the elevator or rudder attachment, possibly resulting in loss of control of the aeroplane.

For the reasons described above, this AD requires the installation of a new locking screw and the modification of the installation of the hinge bolt.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Pilatus Aircraft Ltd. has issued PC-6 Service Bulletin No. 55-001, Rev. No. 1, dated November 25, 2011. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation

in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 50 products of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$100 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$26,250, or \$525 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and

Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Pilatus Aircraft Ltd.: Docket No. FAA-2011-0018; Directorate Identifier 2011-CE-042-AD.

(a) Comments Due Date

We must receive comments by March 2, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Models PC-6, PC-6-H1, PC-6-H2, PC-6/350, PC-6/350-H1, PC-6/350-H2, PC-6/A, PC-6/A-H1, PC-6/A-H2, PC-6/B-H2, PC-6/B1-H2, PC-6/B2-H2, PC-6/B2-H4, PC-6/C-H2, and PC-6/CI-H2 airplanes, all manufacturer serial numbers (MSN), and MSN 2001 through 2092, certificated in any category. These airplanes are also identified as Fairchild Republic Company PC-6 airplanes, Fairchild Industries PC-6 airplanes, Fairchild Heli Porter PC-6 airplanes, or Fairchild-Hiller Corporation PC-6 airplanes.

(d) Subject

Air Transport Association of America (ATA) Code 55: Stabilizer.

(e) Reason

This AD was prompted by loose elevator and rudder hinge bolts caused by incorrect torquing and locking of the bolts. We are issuing this AD to prevent in-flight failure of the elevator or rudder attachment, which could result in loss of control of the airplane.

(f) Actions and Compliance

Unless already done, do the following actions:

(1) *For airplanes that have not been modified before the effective date of this AD*

following Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 55-001 at initial issue, within 2 months after the effective date of this AD, install new elevator and rudder hinge bolt locking screws and modify the installation of the hinge bolt following the Accomplishment Instructions in Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 55-001, Rev. No. 1, dated November 25, 2011.

(2) *For airplanes that have been modified before the effective date of this AD following Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 55-001 at initial issue, within 6 months after the effective date of this AD, install new elevator and rudder hinge bolt locking screws following the Accomplishment Instruction of Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 55-001, Rev. No. 1, dated November 25, 2011.*

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2011-0230, dated December 9, 2011, and Pilatus Aircraft Ltd.

PC-6 Service Bulletin No. 55-001, Rev. No. 1, dated November 25, 2011, for related information. For service information related to this AD, contact PILATUS AIRCRAFT LTD., Customer Liaison Manager, CH-6371 STANS, Switzerland; telephone: +41 (0) 41 619 65 80; fax: +41 (0) 41 619 65 76; Internet: <http://www.pilatus-aircraft.com>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri on January 10, 2012.

John Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-746 Filed 1-13-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[REG-113903-10]

RIN 1545-BJ59

Allocation and Apportionment of Interest Expense

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rulemaking by cross-reference to temporary regulations and notice of public hearing.

SUMMARY: In the Rules and Regulations section in this issue of the **Federal Register**, the IRS is issuing temporary regulations that provide guidance relating to the allocation and apportionment of interest expense. The temporary regulations provide guidance concerning the allocation and apportionment of interest expense by corporations owning a 10 percent or greater interest in a partnership, as well as the allocation and apportionment of interest expense using the fair market value asset method. The temporary regulations also update the interest allocation regulations to conform to the changes made to the applicable law by the legislation commonly referred to as the Education Jobs and Medicaid Assistance Act (EJMAA), enacted on August 10, 2010 (Pub. L. 111-226, 124 Stat. 2389 (2010)), which affect corporations owning certain foreign corporations engaged in the conduct of a trade or business in the United States. The text of those temporary regulations published in this issue of the **Federal Register** also serves as the text of these proposed regulations. This document

also provides a notice of public hearing on these proposed regulations.

DATES: Written or electronic comments must be received by March 13, 2012. Outlines of topics to be discussed at the public hearing scheduled for April 3, 2012, at 10 a.m. must be received by March 13, 2012.

ADDRESSES: Send submissions to CC:PA:LPD:PR (REG-113903-10), room 5203, Internal Revenue Service, PO Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG-113903-10), Courier's desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC 20044, or sent electronically, via the Federal eRulemaking Portal at www.regulations.gov (IRS REG-113903-10). The public hearing will be held in the IRS Auditorium, Internal Revenue Building, 1111 Constitution Avenue NW., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Concerning the regulations, Jeffrey L. Parry, (202) 622-3850; concerning submissions of comments, the hearing, and/or to be placed on the building access list to attend the hearing Olufunmilayo Taylor (202) 622-7180 (not toll-free numbers).

SUPPLEMENTARY INFORMATION:

Background and Explanation of Provisions

Temporary regulations in the Rules and Regulations section of this issue of the **Federal Register** contain amendments to the Income Tax Regulations (26 CFR part 1) which provide rules under section 861 relating to the affiliation of certain foreign corporations for purposes of section 864, the allocation and apportionment of interest expense by corporations owning a 10 percent or greater interest in a partnership, and the allocation and apportionment of interest expense using the fair market value method. The text of those regulations also serves as the text of these proposed regulations. The preamble to the temporary regulations explains the temporary regulations and these proposed regulations. The regulations affect taxpayers that allocate and apportion interest expense under section 864.

Special Analyses

It has been determined that this notice of proposed rulemaking is not a significant regulatory action as defined in Executive Order 12866. Therefore, a regulatory assessment is not required. It has also been determined that section

553(b) of the Administrative Procedure Act (5 U.S.C. chapter 5) does not apply to these regulations, and because the regulations do not impose a collection of information on small entities, the Regulatory Flexibility Act (5 U.S.C. chapter 6) does not apply. Pursuant to section 7805(f), these regulations have been submitted to the Chief Counsel for Advocacy of the Small Business Administration for comment on its impact on small business.

Comments and Public Hearing

Before these proposed regulations are adopted as final regulations, consideration will be given to any electronic or written comments (a signed original and eight (8) copies) that are submitted timely to the IRS. The IRS and the Treasury Department request comments on all aspects of the proposed rules. All comments will be available for public inspection and copying.

A public hearing has been scheduled for April 3, 2012, in the IRS auditorium, Internal Revenue Building, 1111 Constitution Avenue NW., Washington, DC. Due to building security procedures, visitors must enter at the Constitution Avenue entrance. In addition, all visitors must present photo identification to enter the building. Because of access restrictions, visitors will not be admitted beyond the immediate entrance more than 30 minutes before the hearing starts. For information about having your name placed on the building access list to attend the hearing, see the **FOR FURTHER INFORMATION CONTACT** section of this preamble.

The rules of 26 CFR 601.601(a)(3) apply to the hearing. Persons who wish to present oral comments at the hearing must submit electronic or written comments by March 13, 2012, and an outline of the topics to be discussed and the time to be devoted to each topic (signed original and eight (8) copies) by March 13, 2012. A period of 10 minutes will be allotted to each person for making comments.

An agenda showing the scheduling of the speakers will be prepared after the deadline for receiving outlines has passed. Copies of the agenda will be available free of charge at the hearing.

Drafting Information

The principal author of these regulations is Jeffrey L. Parry of the Office of Chief Counsel (International). However, other personnel from the IRS and the Treasury Department participated in their development.