

Harland Ltd. by completing the Inspection Results Proforma following the instructions of paragraph 3.C.(2) of SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014. You can find contact information for Short Brothers & Harland Ltd. in paragraph (h) of this AD.

(5) From the effective date of this AD, you may install a sliding tube on an NLG provided that, before next flight after installation, the NLG sliding tube passes the inspections in paragraphs (f)(1) and (f)(2) of this AD following the instructions of paragraph 3 of SAFRAN Messier-Buggatti-Dowty Service Bulletin No. 32–17M, dated November 1, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(h) Related Information

MCAI European Aviation Safety Agency (EASA) AD No.: 2014–0246, dated November 12, 2014; and Shorts Service Bulletin Number 32–74, dated November 1, 2014, for related information. You may examine the MCAI on the Internet at <http://>

www.regulations.gov by searching for and locating Docket No. FAA–2014–1001. For Short Brothers & Harland Ltd. service information identified in this proposed AD, contact Airworthiness, Short Brothers PLC, P.O. Box 241, Airport Road, Belfast, BT3 9DZ Northern Ireland, United Kingdom; phone: +44–2890–462469, fax: +44–2890–733647, email: michael.mulholland@aero.bombardier.com, Internet: None; and for Messier-Buggatti-Dowty service information contact Messier-Dowty Limited, Cheltenham Road, Gloucester GL2 9QH, ENGLAND; phone: +44(0)1452 712424; fax: +44(0)1452 713821; email: americacsc@safranmbd.com, Internet: <http://www.safranmbd.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on December 2, 2014.

Robert Busto,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014–28700 Filed 12–5–14; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2014–1002; Directorate Identifier 2014–CE–033–AD]

RIN 2120–AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Pacific Aerospace Limited (PAL) Model 750XL airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as PAL Model 750XL airplanes manufactured with only one attitude indicator. A second attitude indicator is required for flights under instrument flight rules. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by January 22, 2015.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493–2251.
- Mail: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Pacific Aerospace Limited, Airport Road, Private Bag 3027, Hamilton 3240, New Zealand; telephone: +64 7 843 6144; fax: +64 7 843 6134; email: pacific@aerospace.co.nz; Internet: <http://www.aerospace.co.nz/>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–1002; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4146; fax: (816) 329–4090; email: karl.schletzbaum@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2014–1002; Directorate Identifier 2014–CE–033–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory,

economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Civil Aviation Authority (CAA), which is the airworthiness authority for New Zealand, has issued AD DCA/750XL/17A, dated November 6, 2014 (referred to after this as “the MCAI”), to correct an unsafe condition for Pacific Aerospace Limited Model 750XL airplanes and was based on mandatory continuing airworthiness information originated by an aviation authority of another country. The MCAI states:

This AD with effective date 10 November 2014 is prompted by a recent determination that certain PAL750XL aircraft were inadvertently manufactured with instrument panels with only one Attitude Indicator (AI). A second AI is required for PAL750XL operating under Instrument Flight Rules (IFR).

The AD mandates the installation of either a second AI, or the enablement of Reversionary Attitude mode in the Sandel Electronic Horizontal Situation Indicator (EHSI), if fitted, when operating under IFR.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1002.

Relevant Service Information

Pacific Aerospace Limited has issued Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/074, Issue 2, dated November 4, 2014. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 17 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$3,500 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$68,170, or \$4,010 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This proposed regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

Pacific Aerospace Limited: Docket No. FAA-2014-1002; Directorate Identifier 2014-CE-033-AD.

(a) Comments Due Date

We must receive comments by January 22, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pacific Aerospace Limited Model 750XL airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 34: Navigation.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as Pacific Aerospace Limited Model 750XL airplanes manufactured with instrument panels with only one attitude indicator. A second attitude indicator is required to operate under instrument flight rules (IFR). A reversionary attitude indicator reduces the probability of a single point failure, which could result in loss of control. We are issuing this proposed AD to install a reversionary attitude indicator before operating in IFR conditions.

(f) Actions and Compliance

Unless already done, before the next flight requiring instrument flight rules (IFR) after the effective date of this AD, install a second attitude indicator into the right hand instrument panel or enable the reversionary mode on a Sandel SN3500 electronic horizontal situation indicator (EHSI), if installed, whichever is applicable, following the ACCOMPLISHMENT INSTRUCTIONS in Pacific Aerospace Limited Mandatory Service Bulletin PACSB/XL/074, Issue 2, dated November 4, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Karl Schletzbaum, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090; email: karl.schletzbaum@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI Civil Aviation Authority (CAA) AD DCA/750XL/17A, dated November 6, 2014, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-1002. For service information related to this AD, contact Pacific Aerospace Limited, Airport Road, Private Bag 3027, Hamilton 3240, New Zealand; telephone: +64 7 843 6144; fax: +64 7 843 6134; email: pacific@aerospace.co.nz; Internet: <http://www.aerospace.co.nz/>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on December 2, 2014.

Robert Busto,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-28699 Filed 12-5-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE**National Oceanic and Atmospheric Administration****50 CFR Part 622**

[Docket No. 141104927-4927-01]

RIN 0648-BE61

Fisheries of the Caribbean, Gulf of Mexico, and South Atlantic; Reef Fish Resources of the Gulf of Mexico; Commercial Reef Fish Fishery of the Gulf of Mexico; Control Date

AGENCY: National Marine Fisheries Service (NMFS), National Oceanic and

Atmospheric Administration (NOAA), Commerce.

ACTION: Advanced notice of proposed rulemaking; request for comments.

SUMMARY: This document announces the establishment of a control date of January 1, 2015, that the Gulf of Mexico Fishery Management Council (Council) may use if it decides to create additional restrictions limiting participation in the individual fishing quota (IFQ) program for the grouper and tilefish component of the commercial sector of the reef fish fishery in the Gulf of Mexico (Gulf) exclusive economic zone. Anyone entering the program after the control date will not be assured of future access should a management regime that limits participation in the program be prepared and implemented. NMFS invites comments on the establishment of this control date.

DATES: Written comments must be received on or before January 7, 2015.

ADDRESSES: You may submit comments on the proposed rule identified by “NOAA-NMFS-2014-0140” by any of the following methods:

- *Electronic Submission:* Submit all electronic public comments via the Federal e-Rulemaking Portal. Go to www.regulations.gov/#/docketDetail;D=NOAA-NMFS-2014-0140, click the “Comment Now!” icon, complete the required fields, and enter or attach your comments.
- *Mail:* Submit written comments to Susan Gerhart, Southeast Regional Office, NMFS, 263 13th Avenue South, St. Petersburg, FL 33701.

Instructions: Comments sent by any other method, to any other address or individual, or received after the end of the comment period, may not be considered by NMFS. All comments received are a part of the public record and will generally be posted for public viewing on www.regulations.gov without change. All personal identifying information (e.g., name, address, etc.), confidential business information, or otherwise sensitive information submitted voluntarily by the sender will be publicly accessible. NMFS will accept anonymous comments (enter “N/A” in the required fields if you wish to remain anonymous). Attachments to electronic comments will be accepted in Microsoft Word, Excel, or Adobe PDF file formats only.

FOR FURTHER INFORMATION CONTACT: Susan Gerhart, telephone: 727-824-5305, or email: Susan.Gerhart@noaa.gov.

SUPPLEMENTARY INFORMATION: The IFQ program for Gulf grouper and tilefish species (Gulf Grouper and Tilefish IFQ

Program) was implemented on January 1, 2010 (74 FR 44732, August 31, 2009). The species included in the IFQ program are deep-water groupers (yellowedge grouper, misty grouper, warsaw grouper, snowy grouper, speckled hind, plus scamp under certain circumstances); red grouper, gag, and other shallow-water groupers (black grouper, scamp, yellowfin grouper, rock hind, red hind, yellowmouth grouper, plus warsaw grouper and speckled hind under certain circumstances); and tilefishes (goldface tilefish, blackline tilefish, anchor tilefish, blueline tilefish, and tilefish). The program includes a provision that, beginning January 1, 2015, all U.S. citizens or permanent resident aliens are eligible to receive transfers of grouper and tilefish IFQ shares or allocation. A Gulf commercial reef fish permit will still be required to harvest, land, and sell grouper and tilefish. This document is to inform current and potential participants of the Gulf Grouper and Tilefish IFQ program that possession of IFQ shares or allocation after this date may not ensure participation under future management of the program. The Council could consider options that include re-establishing a requirement to possess a Gulf commercial reef fish permit to receive shares or allocation under the program. If the Council prepares an amendment to the Fishery Management Plan (FMP) for Reef Fish Resources in the Gulf to restrict participation in the Gulf Grouper and Tilefish IFQ Program in relation to this control date, an analysis of the specific biological, economic, and social effects of the action will be prepared at that time.

Publication of the control date in the **Federal Register** informs participants of the Council’s considerations, and gives notice to anyone entering the fishery after the control date that they would not be assured of future access to the Gulf Grouper and Tilefish IFQ Program should management changes be implemented that would restrict participation. Implementation of any such changes would require preparation of an amendment to the FMP and publication of a notice of availability and proposed rule in the **Federal Register** with pertinent public comment periods.

Since the first control date document of November 1, 1989, 54 FR 46755 (November 7, 1989), the Council has established a total of six control dates for various aspects of the reef fish fishery. As stated in the documents, they were intended to provide additional notice to the public that the Council was considering certain future management actions potentially