

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

PILATUS Aircraft Ltd.: Docket No. FAA–2015–0132; Directorate Identifier 2014–CE–038–AD.

(a) Comments Due Date

We must receive comments by March 16, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to PILATUS Aircraft Ltd. Model PC–7 airplanes, all serial numbers, that

(1) have not incorporated the actions of any version of PILATUS PC–7 Service Bulletin No: 21–006, which allows for the installation of a different air conditioning compressor mounted at a different location and thus making the unsafe condition nonexistent; and

(2) are certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 21: Air Conditioning.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the potential for a spring on the compressor clutch plate to shear the oil cooler inlet-hose due to the close routing of these parts without a protective cover. We are issuing this AD to correct the unprotected routing of the oil cooler inlet-hose, which could lead to damage of the oil hose resulting in an engine oil spill into the engine bay.

(f) Actions and Compliance

Unless already done, within the next 120 days after the effective date of this AD, install a cover assembly on the attachment points of the compressor following the Accomplishment Instructions in PILATUS PC–7 Service Bulletin No: 21–012, dated November 4, 2014.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority

(or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(h) Related Information

Refer to MCAI Federal Office of Civil Aviation (FOCA) AD HB–2014–008, dated December 9, 2014; and any version of PILATUS PC–7 Service Bulletin No: 21–006, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–0132. For service information related to this AD, contact PILATUS AIRCRAFT LTD., Customer Technical Support (MCC), P.O. Box 992, CH–6371 Stans, Switzerland; phone: +41 (0)41 619 67 74; fax: +41 (0)41 619 67 73; email: Techsupport@pilatus-aircraft.com; internet: <http://www.pilatus-aircraft.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued in Kansas City, Missouri, on January 20, 2015.

Robert Busto,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–01556 Filed 1–28–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2014–0780; Directorate Identifier 2014–NM–168–AD]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM); reopening of comment period.

SUMMARY: This document announces the reopening of the comment period for the above-referenced NPRM, which proposed the adoption of a new airworthiness directive (AD) that applies to The Boeing Company Model 747 airplanes equipped with a main deck side cargo door (MDSCD). The NPRM proposed to require revising the airplane flight manual to incorporate limitations for carrying certain payloads. This reopening of the comment period is necessary to ensure that all interested persons have ample opportunity to submit any written relevant data, views, or arguments regarding the proposed requirements of the NPRM.

DATES: We must receive comments on this NPRM (79 FR 71037, December 1, 2014) by March 2, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0780; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD action, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Steven C. Fox, Senior Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6425; fax: 425-917-6590; email: steven.fox@faa.gov.

SUPPLEMENTARY INFORMATION: We proposed to amend 14 CFR part 39 by

adding a notice of proposed rulemaking (NPRM) that would apply to The Boeing Company Model 747 airplanes equipped with an MDSCD. The NPRM was published in the **Federal Register** on December 1, 2014 (79 FR 71037). The NPRM proposed to require revising the airplane flight manual to incorporate limitations for carrying certain payloads. The NPRM also invites comments on its overall regulatory, economic, environmental, and energy aspects.

Events Leading to the Reopening of the Comment Period

Since we issued the NPRM (79 FR 71037, December 1, 2014), several commenters have requested that the comment period be extended/reopened to provide additional time to comment on the merits of the proposal.

FAA's Determination

We found it appropriate to reopen the comment period to give all interested persons additional time to examine the proposed requirements of the NPRM (79 FR 71037, December 1, 2014) and submit comments. We have determined that reopening the comment period for 30 days will not compromise the safety of these airplanes.

Extension of Comment Period

The comment period for Docket No. FAA-2014-0780, Directorate Identifier 2014-NM-168-AD, has been revised. The comment period now closes March 2, 2015.

No other part of the regulatory information has been changed; therefore, the NPRM (79 FR 71037, December 1, 2014) is not republished in the **Federal Register**.

Issued in Renton, Washington, on January 16, 2015.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-01577 Filed 1-28-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF VETERANS AFFAIRS

38 CFR Part 36

RIN 2900-AP25

Loan Guaranty: Adjustable Rate Mortgage Notification Requirements and Look-Back Period

AGENCY: Department of Veterans Affairs.

ACTION: Proposed rule.

SUMMARY: This document proposes to amend the Department of Veterans

Affairs (VA) Loan Guaranty Service (LGY) regulations that govern adjustable rate mortgages made in conjunction with the Home Loan Guaranty program. These revisions would align VA's disclosure and interest rate adjustment requirements with the implementing regulations of the Truth in Lending Act (TILA), as recently revised by the Consumer Financial Protection Bureau (CFPB). Specifically, the rule would amend the timing, content, and format requirements for the disclosures provided to borrowers prior to an interest-rate adjustment. The proposed regulation would also require that an interest-rate adjustment correspond with the interest rate index available 45 days prior to the adjustment. This proposed rulemaking would ensure VA's consistency with other applicable consumer finance and housing regulations governing adjustable rate mortgages.

DATES: Comments must be received by VA on or before March 30, 2015.

ADDRESSES: Written comments may be submitted through www.Regulations.gov; by mail or hand-delivery to Director, Regulation Policy and Management (02REG), Department of Veterans Affairs, 810 Vermont Ave. NW., Room 1068, Washington, DC 20420; or by fax to (202) 273-9026. Comments should indicate that they are submitted in response to "RIN 2900-AP25, Loan Guaranty: Adjustable Rate Mortgage Notification Requirements and Look-Back Period." Copies of comments received will be available for public inspection in the Office of Regulation Policy and Management, Room 1068, between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday (except holidays). Please call (202) 461-4902 for an appointment. (This is not a toll-free number.) In addition, during the comment period, comments may be viewed online through the Federal Docket Management System at www.regulations.gov.

FOR FURTHER INFORMATION CONTACT: John Bell III, Assistant Director for Loan Policy (262), Veterans Benefits Administration, Department of Veterans Affairs, 810 Vermont Ave. NW., Washington, DC 20420, (202) 632-8786. (This is not a toll-free number.)

SUPPLEMENTARY INFORMATION: VA's regulations governing adjustable rate mortgages are set forth at 38 CFR 36.4312(d). VA proposes two amendments in this rulemaking to ensure VA regulations remain aligned with TILA and the implementing regulations set forth by the CFPB. First, VA proposes amending 38 CFR