

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus Helicopters: Docket No. FAA–2017–0419; Directorate Identifier 2015–SW–077–AD.

(a) Applicability

This AD applies to the following helicopters, certificated in any category:

- (1) Model AS332L2 helicopters with a main rotor (M/R) blade attachment pin (attachment pin) part number (P/N) 332A31–2123–00 or P/N 332A31–2115–20 installed; and

- (2) Model EC225LP helicopters with an attachment pin P/N 332A31–3204–20 installed.

(b) Unsafe Condition

This AD defines the unsafe condition as corrosion or a crack in an attachment pin. This condition could result in loss of an M/R blade and subsequent loss of control of the helicopter.

(c) Comments Due Date

We must receive comments by July 10, 2017.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

- (1) For Model AS332L2 helicopters, within 410 hours time-in-service (TIS), and for Model EC225LP helicopters within 660 hours TIS, remove each attachment pin and inspect the protective coating on the inside of the attachment pin for scratches and missing protective coating.

- (i) If there is a scratch or any missing protective coating, sand the attachment pin to remove the varnish in the area depicted as “Area A” in Figure 1 of Airbus Helicopters Alert Service Bulletin (ASB) No. AS332–05.00.99, Revision 0, dated December 22, 2014 (AS332–05.00.99), or Airbus Helicopters ASB No. EC225–05A040, Revision 0, dated December 22, 2014 (EC225–05A040), as applicable to your model helicopter.

- (ii) Using a 10X or higher power magnifying glass, inspect for corrosion and pitting at the chamfer. An example of pitting is shown in the Accomplishment Instructions, paragraph 3.B.3., Note 1, of AS332–05.00.99, and paragraph 3.B.2., Note 1, of EC225–05A040. If there is any corrosion, remove the corrosion. If there is any pitting, replace the attachment pin. Do not sand the attachment pin to remove a corrosion pit.

- (iii) Using a 10X or higher power magnifying glass, inspect the inside and outside of the attachment pin for a crack in the areas depicted as “Area A” and “Area B” in Figure 1 of AS332–05.00.99 or EC225–05A040, as applicable to your model helicopter. Pay particular attention to the chamfer in “Area A.” If there is a crack, remove the attachment pin from service.

- (2) Thereafter, for Model AS332L2 helicopters, at intervals not to exceed 825 hours TIS or 26 months, whichever occurs first; and for Model EC225LP helicopters, at intervals not to exceed 1,320 hours TIS or 26 months, whichever occurs first; perform the actions specified in paragraph (e)(1) of this AD. Corrosion may be removed from an attachment pin as specified in paragraph (e)(1)(ii) of this AD a maximum of four times. If there is a fifth occurrence of corrosion on an attachment pin, before further flight, remove the attachment pin from service.

- (3) Do not install an attachment pin P/N 332A31–2123–00, P/N 332A31–2115–20, or P/N 332A31–3204–20 on any helicopter unless you have complied with the actions in paragraph (e)(1) of this AD.

(f) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: David Hatfield, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5116; email 9-ASW-FTW-AMOC-Requests@faa.gov.

- (2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2015–0016, dated January 30, 2015. You may view the EASA AD on the Internet at <http://www.regulations.gov> in the AD Docket.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

Issued in Fort Worth, Texas, on April 27, 2017.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2017–09378 Filed 5–10–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket Number USCG–2017–0331]

RIN 1625–AA00

Safety Zone; Thunder on the Outer Harbor; Buffalo Outer Harbor, Buffalo, NY

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish a temporary safety zone for certain waters of the Buffalo Outer Harbor during the Thunder on the Outer Harbor boat races. This proposed rulemaking would prohibit persons and vessels from being in the safety zone unless authorized by the Captain of the Port Buffalo or a designated representative. We invite your comments on this proposed rulemaking.

DATES: Comments and related material must be received by the Coast Guard on or before June 16, 2017.

ADDRESSES: You may submit comments identified by docket number USCG–2017–0331 using the Federal eRulemaking Portal at <http://www.regulations.gov>. See the “Public Participation and Request for Comments” portion of the **SUPPLEMENTARY INFORMATION** section for further instructions on submitting comments.

FOR FURTHER INFORMATION CONTACT: If you have questions about this proposed rulemaking, call or email LT Michael Collet, Chief of Waterways Management, U.S. Coast Guard Sector Buffalo; telephone 716–843–9343, email SectorBuffaloMarineSafety@uscg.mil.

SUPPLEMENTARY INFORMATION:

I. Table of Abbreviations

CFR Code of Federal Regulations
 DHS Department of Homeland Security
 FR Federal Register
 NPRM Notice of proposed rulemaking
 U.S.C. United States Code

II. Background, Purpose, and Legal Basis

United States Coast Guard Sector Buffalo was notified by Niagara Frontier Antique and Classic Boats along with BR Guest Inc. that there would be a boat race held on July 22 and 23, 2017 from 10:00 a.m. to 4:00 p.m. on the Buffalo Outer Harbor. Hazards from the boat race include high speed vessels. The Captain of the Port Buffalo (COTP) has determined that potential hazards associated with the Thunder on the Outer Harbor boat race would be a safety concern for anyone within the designated course encompassed by all waters of the Outer Harbor, Buffalo, NY starting at position 42°52'21" N. and 078°53'14" W. then West to 42°52'15" N. and 078°53'32" W. then South to 42°51'41" N. and 078°53'02" W. then East to 42°51'46" N. and 078°52'45" W. (NAD 83) then returning to the point of origin.

The purpose of this rulemaking is to ensure the safety of vessels and the navigable waters within the above stated points before, during, and after the scheduled event. The Coast Guard proposes this rulemaking under authority in 33 U.S.C. 1231.

III. Discussion of Proposed Rule

The COTP proposes to establish a temporary safety zone, enforced intermittently, from 9:45 a.m. to 4:15 p.m. on July 22 and 23, 2017. The safety zone will encompass all waters of the Outer Harbor, Buffalo, NY starting at position 42°52'21" N. and 078°53'14" W. then West to 42°52'15" N. and 078°53'32" W. then South to 42°51'41" N. and 078°53'02" W. then East to 42°51'46" N. and 078°52'45" W. (NAD 83) then returning to the point of origin. The duration of the zone is intended to ensure the safety of vessels and these navigable waters before, during, and after the scheduled 10:00 a.m. to 4:00 p.m. boat races. No vessel or person would be permitted to enter the safety zone without obtaining permission from the COTP or a designated representative. The regulatory text we are proposing appears at the end of this document.

IV. Regulatory Analyses

We developed this proposed rule after considering numerous statutes and Executive orders related to rulemaking. Below we summarize our analyses

based on a number of these statutes and Executive orders and we discuss First Amendment rights of protestors.

A. Regulatory Planning and Review

Executive Orders 12866 and 13563 direct agencies to assess the costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits. Executive Order 13563 emphasizes the importance of quantifying both costs and benefits, of reducing costs, of harmonizing rules, and of promoting flexibility. Executive Order 13771 ("Reducing Regulation and Controlling Regulatory Costs"), directs agencies to reduce regulation and control regulatory costs and provides that "for every one new regulation issued, at least two prior regulations be identified for elimination, and that the cost of planned regulations be prudently managed and controlled through a budgeting process."

This NPRM has not been designated a "significant regulatory action," under Executive Order 12866. Accordingly, the NPRM has not been reviewed by the Office of Management and Budget.

As this rule is not a significant regulatory action, this rule is exempt from the requirements of Executive Order 13771. See OMB's Memorandum titled "Interim Guidance Implementing Section 2 of the Executive Order of January 30, 2017 titled 'Reducing Regulation and Controlling Regulatory Costs'" (February 2, 2017).

This regulatory action determination is based on the size, location, duration, and time-of-day of the safety zone. Vessel traffic would be able to safely transit around this safety zone, which would impact a small designated area of the Buffalo Outer Harbor, by transiting a short distance in Lake Erie. The safety zone would also have built in times where vessels will be able to transit though between race heats. Moreover, the Coast Guard would issue a Broadcast Notice to Mariners via VHF-FM marine channel 16 about the zone, and the rule would allow vessels to seek permission to enter the zone.

B. Impact on Small Entities

The Regulatory Flexibility Act of 1980, 5 U.S.C. 601–612, as amended, requires Federal agencies to consider the potential impact of regulations on small entities during rulemaking. The term "small entities" comprises small businesses, not-for-profit organizations that are independently owned and operated and are not dominant in their fields, and governmental jurisdictions with populations of less than 50,000. The Coast Guard certifies under 5 U.S.C.

605(b) that this proposed rule would not have a significant economic impact on a substantial number of small entities.

While some owners or operators of vessels intending to transit the safety zone may be small entities, for the reasons stated in section IV.A above this proposed rule would not have a significant economic impact on any vessel owner or operator.

If you think that your business, organization, or governmental jurisdiction qualifies as a small entity and that this rule would have a significant economic impact on it, please submit a comment (see **ADDRESSES**) explaining why you think it qualifies and how and to what degree this rule would economically affect it.

Under section 213(a) of the Small Business Regulatory Enforcement Fairness Act of 1996 (Pub. L. 104–121), we want to assist small entities in understanding this proposed rule. If the rule would affect your small business, organization, or governmental jurisdiction and you have questions concerning its provisions or options for compliance, please contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section. The Coast Guard will not retaliate against small entities that question or complain about this proposed rule or any policy or action of the Coast Guard.

C. Collection of Information

This proposed rule would not call for a new collection of information under the Paperwork Reduction Act of 1995 (44 U.S.C. 3501–3520).

D. Federalism and Indian Tribal Governments

A rule has implications for federalism under Executive Order 13132, Federalism, if it has a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. We have analyzed this proposed rule under that Order and have determined that it is consistent with the fundamental federalism principles and preemption requirements described in Executive Order 13132.

Also, this proposed rule does not have tribal implications under Executive Order 13175, Consultation and Coordination with Indian Tribal Governments, because it would not have a substantial direct effect on one or more Indian tribes, on the relationship between the Federal Government and Indian tribes, or on the distribution of power and responsibilities between the Federal Government and Indian tribes.

If you believe this proposed rule has implications for federalism or Indian tribes, please contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section.

E. Unfunded Mandates Reform Act

The Unfunded Mandates Reform Act of 1995 (2 U.S.C. 1531–1538) requires Federal agencies to assess the effects of their discretionary regulatory actions. In particular, the Act addresses actions that may result in the expenditure by a State, local, or tribal government, in the aggregate, or by the private sector of \$100,000,000 (adjusted for inflation) or more in any one year. Though this proposed rule would not result in such an expenditure, we do discuss the effects of this rule elsewhere in this preamble.

F. Environment

We have analyzed this proposed rule under Department of Homeland Security Management Directive 023–01 and Commandant Instruction M16475.ID, which guide the Coast Guard in complying with the National Environmental Policy Act of 1969 (42 U.S.C. 4321–4370f), and have made a preliminary determination that this action is one of a category of actions that do not individually or cumulatively have a significant effect on the human environment. This proposed rule involves an intermittently enforced safety zone lasting 6.5 hours per day that would prohibit entry into the boundaries created by points starting at position 42°52′21″ N. and 078°53′14″ W. then West to 42°52′15″ N. and 078°53′32″ W. then South to 42°51′41″ N. and 078°53′02″ W. then East to 42°51′46″ N. and 078°52′45″ W. (NAD 83) then returning to the point of origin. Normally such actions are categorically excluded from further review under paragraph 34(g) of Figure 2–1 of Commandant Instruction M16475.ID. A preliminary Record of Environmental Consideration (REC) supporting this determination is available in the docket where indicated under the **ADDRESSES** section of this preamble. We seek any comments or information that may lead to the discovery of a significant environmental impact from this proposed rule.

G. Protest Activities

The Coast Guard respects the First Amendment rights of protesters. Protesters are asked to contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section to coordinate protest activities so that your message can be received without

jeopardizing the safety or security of people, places, or vessels.

V. Public Participation and Request for Comments

We view public participation as essential to effective rulemaking, and will consider all comments and material received during the comment period. Your comment can help shape the outcome of this rulemaking. If you submit a comment, please include the docket number for this rulemaking, indicate the specific section of this document to which each comment applies, and provide a reason for each suggestion or recommendation.

We encourage you to submit comments through the Federal eRulemaking Portal at <http://www.regulations.gov>. If your material cannot be submitted using <http://www.regulations.gov>, contact the person in the **FOR FURTHER INFORMATION CONTACT** section of this document for alternate instructions.

We accept anonymous comments. All comments received will be posted without change to <http://www.regulations.gov> and will include any personal information you have provided. For more about privacy and the docket, you may review a Privacy Act notice regarding the Federal Docket Management System in the March 24, 2005, issue of the **Federal Register** (70 FR 15086).

Documents mentioned in this NPRM as being available in the docket, and all public comments, will be in our online docket at <http://www.regulations.gov> and can be viewed by following that Web site's instructions. Additionally, if you go to the online docket and sign up for email alerts, you will be notified when comments are posted or a final rule is published.

List of Subjects in 33 CFR Part 165

Harbors, Marine safety, Navigation (water), Reporting and record keeping requirements, Security measures, Waterways.

For the reasons discussed in the preamble, the Coast Guard proposes to amend 33 CFR part 165 as follows:

PART 165—REGULATED NAVIGATION AREAS AND LIMITED ACCESS AREAS

■ 1. The authority citation for part 165 continues to read as follows:

Authority: Authority: 33 U.S.C. 1231; 50 U.S.C. 191; 33 CFR 1.05–1, 6.04–1, 6.04–6, and 160.5; Department of Homeland Security Delegation No. 0170.1.

■ 2. Add § 165.T09–0331 to read as follows:

§ 165.T09–0331 Safety Zone; Thunder on the Outer Harbor; Buffalo Outer Harbor, Buffalo, NY.

(a) *Location.* The safety zone will encompass all waters of the Outer Harbor, Buffalo, NY starting at position 42°52′21″ N. and 078°53′14″ W. then West to 42°52′15″ N. and 078°53′32″ W. then South to 42°51′41″ N. and 078°53′02″ W. then East to 42°51′46″ N. and 078°52′45″ W. (NAD 83) then returning to the point of origin.

(b) *Enforcement Period.* This rule is effective from 9:45 a.m. until 4:15 p.m. on July 22, 2017, and from 9:45 a.m. until 4:15 p.m. on July 23, 2017.

(c) *Regulations.*

(1) In accordance with the general regulations in § 165.23 of this part, entry into, transiting, or anchoring within this safety zone is prohibited unless authorized by the Captain of the Port Buffalo or his designated on-scene representative.

(2) This safety zone is closed to all vessel traffic, except as may be permitted by the Captain of the Port Buffalo or his designated on-scene representative.

(3) The “on-scene representative” of the Captain of the Port Buffalo is any Coast Guard commissioned, warrant or petty officer who has been designated by the Captain of the Port Buffalo to act on his behalf.

(4) Vessel operators desiring to enter or operate within the safety zone must contact the Captain of the Port Buffalo or his on-scene representative to obtain permission to do so. The Captain of the Port Buffalo or his on-scene representative may be contacted via VHF Channel 16. Vessel operators given permission to enter or operate in the safety zone must comply with all directions given to them by the Captain of the Port Buffalo, or his on-scene representative.

Dated: May 2, 2017.

J.S. DuFresne,

Captain, U.S. Coast Guard, Captain of the Port Buffalo.

[FR Doc. 2017–09563 Filed 5–10–17; 8:45 am]

BILLING CODE 9110–04–P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA–R05–OAR–2015–0802; FRL–9962–07–Region 5]

Air Plan Approval; Ohio; Volatile Organic Compound Control Rules

AGENCY: Environmental Protection Agency (EPA).